

22/03/2002

ASE, REC. BY:

REF: CS/smo18016810 / T14bn2 Special Instruction:

Surveyor

Tawfik

ASSIGNMENT (Office)

From (Person):

Gniah Pau Loong

of

Smo

Date/Time: 14/09/2018 9:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 7721K

Insured:

GRC 7852Y

at Workshop m/s

Mova

Tel:

67723893

of

15 Fun Tung Rd

Policy No:

DBMTHCVE 000152

Claim No:

CMTD1803927

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP1

H.O.D. Endorsement:

Date/Time:

14/09/2018 9:20am

Person Contacted:

Nithu

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBA 7721K - X
	GRC 7852Y - X
19/9/18 @ 3:43pm	revised to Gniah Pau Loong via Maimien
	Unup sum 6150- (Red: 3681.25, 37%)

Surveyor

Tamplin

REF:

SMD

ASSIGNMENT

2022 May

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop m/s

of

Insured.

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

A30K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GBA2721K.

Yr Regn:

2007, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C.

2982

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

233608

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STFHT 02P 00000 3752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/115

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/9/18

Survey held at

Moore Farm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 OCT 2018

Date/Time, File Pass to?

29/10 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

250

10

260

TP

61507-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 19 Sep 2018

Preliminary Advice

Insured Vehicle No	: GBC7852Y	Accident Date	: 10/09/2018
TP Vehicle No	: GBA2721K	Assignment Date	: 14/09/2018
Make	: TOYOTA HIACE	Est. Duration of Repair	: 6
Date of Inspection	: 14/09/2018		
Inspection At	: MOVA		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,831.25
Revised Amount	:S\$	6,871.00
Check Items (Estimated)	:S\$	831.75
Total	:S\$	7,702.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		14 Sep 2018 09:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H								
Main Claimant:	UMW EQUIPMENT & ENGINEERING PTE LTD, Co. Reg. No.: 197602568D								
Vehicle Reg. No.:	GBA2721K	Date of Loss:	10/09/2018 17:00 - :59						
Claim Type:	TP / CMTD1803927	Policy/Cover Note No.:	D18MTHCVE000152 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBC7852Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]								
Driver/Custodian (Insured):	CHAN PIENG YENG (), NRIC: S7273334G, Tel: +6591796428								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
SOMPO_SG (14/09/2018): TP SURVEY									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 14 September, 2018 9:18 AM
To: nitha; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: 'Alan Chng'; 'Crystal'; Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1803927/GPL - LIA(LKK)/ GBC7852Y & GBA2721K DOA 10/09/18 AT JLN BUKIT MERAH

Our Claim Reference: CMTD1803927/GPL
Your Reference: GBA2721K

Hi Nitha,

We acknowledged receipt of your claim documents.

Please be informed that Gnoh Pau Loong is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for GBA2721K on a without Prejudice Basis and without any admission of liability basis.

Please submit with your report via merimen upon completion of survey to my colleague, Mr. Pau Loong.

Aside to Pau Loong,

Please refer to the liability request from Mova Automotive Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: nitha [mailto:nitha@nova.com.sg]
Sent: Thursday, September 13, 2018 7:02 PM
To: Claims - Motor Survey
Cc: 'Alan Chng'; 'Crystal'
Subject: TP CLAIMS - GBA2721K AGAINST GBC7852Y DOA 10/09/18 AT JLN BUKIT MERAH
Importance: High

Dear Sir/Madam,
Good day

REF : GBC7852Y

Kindly assist revert officer in charge and liability and arrange surveyor for the above mention case.

Best Regards,

Nitha

Claims Officer
Nova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 29 October 2018 2:50 PM
To: Alan Chng
Cc: SUR
Subject: RE: finalization for veh no:GBA2721K

Dear Alan,

Confirm repair cost lump sum \$6150 & 6 working days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Alan Chng <tuckmeng@mova.com.sg>
Sent: Tuesday, 16 October 2018 2:11 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: finalization for veh no:GBA2721K

Dear Taufikh,

Please refer the attach to confirm the COR & working days.

Repair cost lump sum \$6150 & 6 working days, please confirm & reply by email.

Thanks!

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

2568D

Vehicle Details

Vehicle No.:

GBA2721K

Vehicle to be Exported:

Yes

Intended Deregistration Date:

13 Sep 2018

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE MANUAL

Primary Colour:

White

Manufacturing Year:

2007

Engine No.:

1KD1628914

Chassis No.:

JTFHT02P000003752

Maximum Power Output:

-

Open Market Value:

\$24,590.00

Original Registration Date:

07 May 2007

First Registration Date:

07 May 2007

Transfer Count:

0

Actual ARF Paid:

\$0.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

06 May 2022

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$22,263.00

COE Rebate Amount:

\$16,237.00

Total Rebate Amount:**\$16,237.00****Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 13 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2018 15:23
Date Of Accident	10/09/2018 16:40
Exact Location Of Accident	JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA2721K
Insured/Policyholder	
Name Of Registered Owner	UMW EQUIPMENT & ENGINEERING PTE LTD
Co Reg No	197602568D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62653155

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	PHONG POH SIONG (PENG BAIXIONG)
NRIC No	S8204344F
Date Of Birth	27/01/1982
Occupation	OUTDOOR
Date Of Driving Pass	18/10/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98385469
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 112 BUKIT BATOK WEST AVE 6 #08-152
Postcode	650112
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC7852Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of that report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore, and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my requests by email;
 - (iv) settling/trying my claims (including the mailing of correspondence, statements, documents, reports, or notes to the insurers) which could involve disclosure of certain personal data about me to third parties delivery of the same as well as on the electronic transfer of documents (email packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by way of the insurers and/or GIA to their third party service providers or agent (including their lawyers/law firm) which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in processing and settling claims;
- (e) the information so collected under (b) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in settling, investigating, controlling or managing legal, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

UMW EQUIPMENT & ENGINEERING PTE LTD
108 INTERNATIONAL ROAD, SINGAPORE 629173
TEL : 6265 3155 FAX : 62661083

Policyholder's Signature
 Date & Time: 11/4/12, 14:55 hr

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Signing Centre Personnel's Signature
 Name:
 NRIC No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE	GBA2721K	ACCIDENT DATE & TIME	16.9.12 1640pm
CONTACT NUMBER	96385469	& MAIL ADDRESS	
LOCATION	Jln Bukit Merah		
I was travelling along lower delta rd the following time towards Jalan Bukit Merah. I stopped behind the stop line while the vehicle B4BC 7252Y hit the rear of my car. Vehicle involved			
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION			
Please state ☐ I Claim Own Policy ☒ I Claim Third Party ☐ I Claim OD/TPA at repair workshop ☐ I Reporting Only			

DECLARATION

(We declare the foregoing particulars are true in every respect)

UMW EQUIPMENT & ENGINEERING PTE LTD
108 INTERNATIONAL ROAD, SINGAPORE 628173
TEL : 6265 3155 FAX : 62661083

Policyholder's Signature

Date & Time: 11/9/12 1415hrs

Driver's Signature

(If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature

Name:
 NRIC/ID No.:

Estimate

13/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- GBA2721K

Veh Model :- TOYOTA HIACE

Estimate# :- CK417969

Claim # :-

ACC. Date :- 10/09/18

Terms :- C.O.D Days

Remarks :-

Alan 9689276

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	410.00	410.00
2.	REAR BUMPER SIDE BRACKET	2 PC	30.00	60.00
3.	TAILGATE	1 PC	2,380.00	2,380.00
4.	TAILGATE LOCK	1 PC	380.00	380.00
5.	TAILGATE GARNISH	1 PC	230.00	230.00
6.	TAILGATE INNER BOARD	1 PC	310.00	310.00
7.	TAILGATE WINDSCREEN GLASS	1 PC	1,438.00	1,438.00
8.	TAILGATE LOGO	1 PC	45.00	45.00
9.	TAILLAMP <i>LH-CR ✓, RH - AN</i>	2 PC	380.00	760.00
10.	TAILGATE RUBBER	1 PC	385.00	385.00
11.	EDN PANEL OUTER <i>— plus fo</i>	1 PC	799.00	799.00
12.	END PANEL INNER	1 PC	658.00	658.00
13.	REAR CONER PANEL COVER	2 PC	60.00	120.00
LIST TOTAL S\$				7,975.00
25% DISCOUNT S\$				-1,993.75
				5,981.25
SPECIAL NET ITEMS :				
1.	TAILGATE (70KM/H) STICKER	1 PC	15.00	15.00
2.	TAILGATE (GREEN) STICKER	1 PC	15.00	15.00
3.	TAILGATE NUMBER PLATE	1 PC	50.00	50.00
4.	REAR PARKING SENSOR	1 PC	200.00	200.00
5.	REAR WINDSCREEN SEALANT	1 PC	40.00	40.00
6.	ACCIDENT TOWING	1 PC	60.00	60.00
7.	LH REAR FENDER STICKER	1 PC	300.00	300.00
SPECIAL NET TOTAL S\$				680.00
LABOUR :				
TO INSPECT RR LIGHTING WATER & LEAKAGE TEST				30 40.00
TO REMOVE & INSTALL REAR WINDSCREEN				✓ 120.00
TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE				60 100.00
TO REMOVE & INSTALL CARPET, BOARD, GARNISHES & ETC IN ORDER TO CUT OFF END PANEL				60 200.00
TO CUT OFF END PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS				800 1,200.00
TO SET VEHICLE CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF PANEL				X 300.00 X mn
TO APPLY BODY JOINT SEALANT ON CUTTING AREAS				40 60.00
TO APPLY RUST PROOF ON AFFECTED AREAS				60 150.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

13/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Page # :- 1 132589

Veh # :- GBA2721K

Veh Model :- TOYOTA HIACE

Estimate# :- CK417969

Claim # :-

ACC. Date :- 10/09/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA018

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY PPAINT ON REPLACED, REPAIRED AREAS		800	1,000.00 ✓
	LABOUR TOTAL S\$			3,170.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 9,831.25

GST @ 7 % 688.19

AMOUNT DUE S\$ 10,519.44

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
wp'

Resurvey after repair
6 days

sur & lkkauto.com

14/9/18 @ 1630

\$6150
6clup



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

13/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- GBA2721K

Veh Model :- TOYOTA HIACE

Estimate# :- CK417969

Claim # :-

ACC. Date :- 10/09/18

Terms :- C.O.D Days

Remarks :-

Alan 96869276

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	410.00	410.00
2.	REAR BUMPER SIDE BRACKET	2 PC	30.00	60.00
3.	TAILGATE	1 PC	2,380.00	2,380.00
4.	TAILGATE LOCK	1 PC	380.00	380.00
5.	TAILGATE GARNISH	1 PC	230.00	230.00
6.	TAILGATE INNER BOARD	1 PC	310.00	310.00
7.	TAILGATE WINDSCREEN GLASS	1 PC	1,438.00	1,438.00
8.	TAILGATE LOGO	1 PC	45.00	45.00
9.	TAILLAMP	1 PC	380.00	380.00
10.	TAILGATE RUBBER	1 PC	385.00	385.00
11.	EDN PANEL OUTER	1 PC	799.00	799.00
12.	END PANEL INNER	1 PC	658.00	658.00
13.	REAR CONER PANEL COVER	2 PC	60.00	120.00
LIST TOTAL S\$				7,975.00
25% DISCOUNT S\$				-1,993.75
				5,981.25
SPECIAL NET ITEMS :				
1.	TAILGATE (70KM/H) STICKER	1 PC	15.00	15.00
2.	TAILGATE (GREEN) STICKER	1 PC	15.00	15.00
3.	TAILGATE NUMBER PLATE	1 PC	50.00	50.00
4.	REAR PARKING SENSOR	1 PC	200.00	200.00
5.	REAR WINDSCREEN SEALANT	1 PC	40.00	40.00
6.	ACCIDENT TOWING	1 PC	60.00	60.00
7.	LH REAR FENDER STICKER	1 PC	300.00	300.00
SPECIAL NET TOTAL S\$				680.00
LABOUR :				
TO INSPECT RR LIGHTING WATER & LEAKAGE TEST				30 40.00
TO REMOVE & INSTALL REAR WINDSCREEN				✓ 120.00
TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE				60 100.00
TO REMOVE & INSTALL CARPET, BOARD, GARNISHES & ETC IN ORDER TO CUT OFF END PANEL				60 200.00
TO CUT OFF END PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS				800 1,200.00
TO SET VEHICLE CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF PANEL				X 300.00
TO APPLY BODY JOINT SEALANT ON CUTTING AREAS				40 60.00
TO APPLY RUST PROOF ON AFFECTED AREAS				60 150.00

SIN-530



Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

13/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Page # :- 1 132589

Veh # :- GBA2721K

Veh Model :- TOYOTA HIACE

Estimate# :- CK417969

Claim # :-

ACC. Date :- 10/09/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA018

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			800 1,000.00
	LABOUR TOTAL S\$			3,170.00

LC-1970

E. & O.E

NON-TAX AMOUNT \$

AMOUNT S\$	9,831.25
------------	----------

GST @ 7 %	688.19
-----------	--------

AMOUNT DUE S\$	10,519.44
----------------	-----------

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

$$\begin{array}{r} P-6937 \\ - 258 \\ \hline P-5202.75 \\ SM-530.00 \\ + LC-1970.00 \\ \hline 7702.75 \\ - 206 \\ \hline 6162.20 \end{array}$$

Tamlin 97495749
wp
Reentry after repair
6 days
sur @ lhamanfo.com
14/9/18 @ 1630

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18016810/T1TBN2

Date: 01/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE000152
Claimant Vehicle No :	GBA2721K	Insured Vehicle No :	GBC7852Y
Date of Loss:	10/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1803927

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA2721K	Engine No:	1KD1628914
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P000003752
Reg. Date:	07/05/2007 (Man. Year: 2007)	Odometer:	233008 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,601.25	5,672.75	928.50	14.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	2,030.00	1,200.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,831.25	7,702.75	2,128.50	21.65
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	9,831.25	6,150.00	3,681.25	37.44
+ GST 7.00/7.00% (S\$)	688.19	430.50	257.69	37.44
Nett Amount (S\$)	10,519.44	6,580.50	3,938.94	37.44

INSPECTION

Date of Assignment:	14/09/2018	
Date Inspected:	14/09/2018 Inspected At:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building Singapore 159419

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Nov 2018)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA2721K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	410.00 FL	*410.00 FL
2	2		*REAR BUMPER SIDE BRACKET	Necessary	60.00 FL	*60.00 FL
3	1		*TAILGATE	Bent	2,380.00 FL	*2,380.00 FL
4	1		*TAILGATE LOCK	Bent	380.00 FL	*380.00 FL
5	1		*TAILGATE GARNISH	Cut	230.00 FL	*230.00 FL
6	1		*TAILGATE INNER BOARD	Deformed	310.00 FL	*310.00 FL
7	1		*TAILGATE WINDSCREEN GLASS	Cracked	1,438.00 FL	*1,438.00 FL
8	1		*TAILGATE LOGO	Necessary	45.00 FL	*45.00 FL
9	1		*TAILLAMP	N/s Cracked/O/s Not Necessary	760.00 FL	*380.00 FL
10	1		*TAILGATE RUBBER	Cut	385.00 FL	*385.00 FL
11	1		*END PANEL OUTER	Bent	799.00 FL	*799.00 FL
12	1		*END PANEL INNER	Repair	658.00 FL	*- FL
13	2		*REAR CORNER PANEL COVER	Deformed	120.00 FL	*120.00 FL
14	1		*TAILGATE (70KM/H) STICKER	Necessary	15.00 FS	*15.00 FS
15	1		*TAILGATE (GREEN) STICKER	Necessary	15.00 FS	*15.00 FS
16	1		*TAILGATE NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*REAR PARKING SENSOR	Missing	200.00 FS	*200.00 FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*LH REAR FENDER STICKER	Necessary	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,595.00	7,407.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,993.75	1,734.25
Total Parts (\$\$)	6,601.25	5,672.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT TOWING	New	60.00	60.00
2	TO INSPECT RR LIGHTING WATER & LEAKAGE TEST	New	40.00	30.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & TRANSFER ITEMS TO NEW TAIL GATE	New	100.00	60.00
5	TO REMOVE & INSTALL CARPET,BOARD,GARNISHES & ETC IN ORDER TO CUT OFF END PANEL	New	200.00	60.00
6	TO CUT OFF END PANEL,STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,200.00	800.00
7	TO SET VEHICLE CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF PANEL	New	300.00	-
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00	40.00
9	TO APPLY RUST PROOF ON AFFECTED AREAS	New	150.00	60.00
10	TO SPRAY PAINT ON REPLACED,REPAIRED AREAS	New	1,000.00	800.00
Gross Labour Cost (\$\$)			3,230.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >