

ASS. REC. BY:

REF: CS/CTU8016814/Kvbez

Special Instructions:

Surveyor

Melm

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT

Date/Time:

14/09/2018 7:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 2778A

Insured:

SKT 1097D

at Workshop m/s

TC Autodinic

Tel:

of

1 Sixth Lk Yung

Rd

Survey @ 17 Lor 8 T. Payoh

Policy No:

DMP/LSN3022111800

Claim No:

SNM18D04376 CD

Sum Insured:

Excess:

Make of Vch:

D.O.A.

09/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

14/09/2018 10am

Person Contacted:

Mr. Ho

Vehicle-IN LOU

Date/Time	Action/Instruction (✓) Estimate
	SKW 2778A - X
	SKT 1097D - X
29/11/18	87691.40 Confirm by email (Red 250.50, 250)

ASSIGNMENT

From: Date: 20.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKW 2778A

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

Mr. Affendi

10am - 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lump Sum:

1.31

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW 2778A

Yr Regn

10 / 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MS Qashgari

CC

1197

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

63092

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STNFEASTHU 1485188

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

9/9/18

D.O.I.

21/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& M


The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/11 File sent to Customer

RECEIVED 29 NOV 2018.


 29/11/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 29/11 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

7691.40

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

270

Transportation

) \$ + RE \$

) Photos

) Other

TOTAL

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		14 Sep 2018 09:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	JIM BEE LENG, ID: S7375222A			[Created by insurer]					
Main Claimant:	HARRIS DAMELZA VIRGINA								
Vehicle Reg. No.:	SKW2778A	Date of Loss:	09/09/2018 12:00 - :59						
Claim Type:	TP / SNM18D04376C02	Policy/Cover Note No.:	DMPCSN3022111800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT1097D	Policy No. (Claimant):							
		Excess:	\$0.00						
Repairer:	TC AutoClinic Pte Ltd (Lok Yang) 1 SIXTH LOK YANG ROAD, 628099 Pioneer - Tel: 6262 2212								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638966192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]								
Adj Asg. Remarks:	EST \$17,343.90, CASE WITH SJE								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
View All Search Tasks Create New Task Complete									
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 15:02
Date Of Accident	09/09/2018 12:20
Exact Location Of Accident	7.5KM ON CTE TOWARDS AYE LANE 2.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW2778A
Insured/Policyholder	
Name Of Registered Owner	HARRIS DAMELZA VIRGINIA
NRIC No	S8014696E
Email Address	DAMELZA.HARRIS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96667478
Alternative Phone No	OFFICE-96667478
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T CVT ABS 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100435053-02
Cover Note Number	
Driver	
Name of Driver	KRISTIAN MARK OLSER
NRIC No	S7920484F
Date Of Birth	18/07/1979
Occupation	INDOOR
Date Of Driving Pass	23/12/2013
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98783744
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	491 YIO CHU KANG ROAD #08-02
Postcode	787078
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : DAMELZA HARRIS OLSEN GENDER: : FEMALE
Passenger 2	NAME: : RYDER MIKAEL OLSEN GENDER: : MALE
Passenger 3	NAME: : LEVI MIKAEL OLSEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA6935G
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	MPV
Vehicle Category	PRIVATE CAR
Name of Driver	KAMARUDIN
NRIC/Passport Number	
Contact Number	96692941

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKT1097D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHAN
NRIC/Passport Number
Contact Number 81991833
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SGK8681R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHANG
NRIC/Passport Number
Contact Number 91791777
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident occurred on the claim process.
2. This report must be completed by the policyholder and/or the insured driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims, and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 10/09/18

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10/09/18

TAN CHONG MOTOR SALES PTE LTD
17 Toa Payoh Lorong 8
Singapore 310254
Tel: 6352 0755 Fax: 6358 4922

Reporting Centre Personnel's Signature
Name: APTENAI J.
NRIC/IN No.: S13581889

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At approximately 12:00pm, I was driving a car on the C10 (T) road towards the direction of the road. I was not going behind (by the road) and I was not hitting a person but a car (motorcycle) in front of me.

We were the second from the front in the collision.

I got out of the car to assess the damage, took pictures and noted down the exact details of all the other driver's vehicles as advised by the EMS recovery staff person.

Our car sustained damage to both the front and back including the engine plate.

Nothing else was injured.

My older son, aged 9, has some complaints of neck and shoulder pain as a result of the collision. My wife and young son have mild neck pain. We have not yet seen a doctor for this.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time: 1/20/18

Driver's Signature:

(If driver is not the policyholder)

Date & Time: 1/20/18

TAN CHONG MOTOR SALES PTE LTD

17 Tou Payoh Loring 8

Singapore 310254

Tel: 8332 0354 Fax: 8332 0325

Reporting Centre Personnel's Signature:

Name: ALENA J.

NRIC/IN No: 213381886

TC AUTOCLINIC PTE LTD
1 SIXTH LOM YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 156/TC/TC/HO/2018
DATE : 11-SEP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MISS HARRIS DANIELA VIRGINIA
ADDRESS : 491 YIO CHU KANG ROAD
#06-02
S(787078)
TELEPHONE NO : 96667478

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : CHINA TAIPING 3RD PARTY DIRECT
VEHICLE NO : SKN2778A
MODEL CODE : YRLARBJ110EA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA1189249A
CHASSIS NO : SJMFLA313U1485188
MILEAGE : 1 KM
DATE IN : 11/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO TUE HENG
ACCIDENT DATE : 09/09/2018

TE AUTOCLINIC PTE LTD
1 SIFIN JOE YANG ROAD
SINGAPORE 620099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE WITH NO INJURY

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FRI	FOCUS & ADJUST H/LAMP, WHEEL HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	nn 48.00	X ✓
2 FPI	SUPPLY & INSTALL RUBBER PLATE & HOLDER INCLUDING PARTS-FRONT AND REAR	120.00	4 60
3 RCI	REPLACE REVERSE CAMERA, FINISHED MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	2 ✓
4 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @ \$120.00 EACH X 2 PORTIONS	240.00	7 120 ✓
5 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	2 ✓
6 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @ \$100.00 EACH X 2 PORTIONS	200.00	X 100
7 22/001	REMOVE/INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION, REPAIR L/R FENDER & RR FENDER	1400.00	750 560 ✓
8 22/002	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, BACK DOOR, L/R REAR FENDER AND RR REAR FENDER	1750.00	750 500 625 ✓
9 22/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	X
10 22/004	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	✓ ✓
11 22/005	RENEW BACK DOOR WINDSCREEN GLASS	240.00	✓ ✓
12 22/006	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	150.00	7 ✓
13 22/007	CHECK REAR LIGHTING AND WIRING SYSTEM	20.00	✓ ✓
14 22/008	REMOVE/INSTALL FRONT BUMPER AND AFFECTED PORTION, REPAIR RAD SUPPORT PANEL, BONNET, L/R & RR FENDER	840.00	280 280
15 22/009	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL, BONNET, L/R FRONT FENDER AND RR FRONT FENDER	1500.00	350 350
16 22/011	SEARCH FOR	2.00	✓ ✓
17 22/012	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	X X
TOTAL LABOUR CHARGES		7140.00	

TO AUTOCLINIC PTE LTD
1 FIFTH LOR YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE WORK NO RM22718A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SUPPLYOR'S RECOMMENDATION
------	----------	---------------	-------------------	---------------------------

TC AUTOCLINIC PTE LTD
1 SIXTH LEX YANG ROAD
SINGAPORE 438899

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKM2778A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	GUIDE-AIR, FRONT RH	21558-4K01A	Sm 23.50	X	
2	GUIDE-AIR, FRONT LH	21559-4K06A	Sm 63.00	X	
3	AIR GUIDE-RADIATOR, LOWER	21579-4K21A			Sm 94.50 X
4	BRACKET-RADIATOR HOUSING, UPPER	21542-4K00A			Sm 14.60 X
5	HALE ASSY-HOOD LOCK	65601-4K00A	R 67.60	X	
6	EMBLEM-FRONT	62890-4K00A	un 73.60	? X	
7	GRILLE-RADIATOR	62310-4K01A	Sm 490.30	? X	
8	RH FRONT BUMPER STAY	F2214-4E00A	R 173.10	X	
9	LH FRONT BUMPER STAY	F2215-4E00A	R 123.70	X	
10	ARMATURE ASSY-FRONT BUMPER, UPPER	F2030-4E00A	Sm 675.40	? X	
11	ENERGY ABSORBER-FRONT BUMPER, UPPER	62090-4E01D	Sm 195.70	X	
12	ARMATURE ASSY-FRONT BUMPER, LOWER	62030-RV51A	Sm 337.70	X	
13	ENERGY ABSORBER-FRONT BUMPER, LOWER @S1.20EACH X2PCS	62090-4E00C	Sm 126.40	X	
14	RH FRONT BUMPER SIDE BRACKET	62222-4E00A	Sm 20.90	X	
15	LH FRONT BUMPER SIDE BRACKET	62223-4E00A	Sm 20.90	X	
16	FRONT BUMPER CLIP @S1.20EACH X4PCS	01553-05933	un 6.80	X X	
17	COVER-BUMPER BRACKET	622A0-4E00A	R 18.30	X	
18	FRONT BUMPER FASCIA	62022-4E00H	CM 614.60	X	
19	HEADLAMP ASSY-RH	26010-4E00A	Sm 559.00	X	
20	HEADLAMP ASSY-LH	26060-4E00A	Sm 559.00	X	
21	CLIP-REAR LUGGAGE PLATE @S1.20EACH X2PCS	01553-05933	un 2.40	X	
22	CLIP-REAR LUGGAGE PLATE @S1.20EACH X4PCS	01554-00181	un 4.80	X	
23	PLATE-LUGGAGE, REAR	84992-4E00R	Sm 63.50	? X	
24	DRAPETER-AIR @S1.20EACH X2PCS	76004-JD00R	Sm 124.60	X	
25	LOCK ASSY-REAR DOOR	80502-4E01B	R 116.70	X	

TC AUTOCLINIC PTE LTD
1 STETH LOR PARK ROAD
SINGAPORE 238055

MATERIAL LIST FOR ACCIDENT VEHICLE REPAIR AND EXC27786

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 WERTHER STRIP-BACK DOOR	90836-4EAB0	Sen	158.70		
27 STAY ASSET-BACK DOOR 85289-80EACH X2PCS	90456-4EAB0	Sen	419.60		
28 BUMPER RUBBER-BACK DOOR 806150EACH X2PCS	90878-4EAB0	Sen	13.00		
29 EMBLEM-REAR	90892-4EAB0	Mc	87.00	✓	
30 EMBLEM-REAR	90890-4EAB0	Mc	59.70	✓	
31 REAR W/SCHIRM SEALANT	SEALANT - 4			Mc	80.00 ✓
32 RUDDER-DUN 8560.20EACH X2PCS	G2716-89901	Mc	120.40	✓	
33 GLASS-BACK DOOR WINDSCREEN with moly	90300-4EAB0	Mc	930.00	✓	
34 DOOR-BACK	K0100-HV0HH	By	2936.80	✓	
35 LH REAR BUMPER STAY	H5211-4EAB0	Sen	126.00	X	
35 RH REAR BUMPER STAY	H5210-4EAB0	Sen	126.00	X	
37 REAR BUMPER REINFORCEMENT	H5030-4EAB0	R	519.20	7 X	
38 REAR BUMPER ENERGY ABSORBER	85090-4EAB0	Sen	126.40	7 X	
39 RH REAR BUMPER SIDE BRACKET	85220-4EAB0	Sen	35.90	X	
40 LH REAR BUMPER SIDE BRACKET	85221-4EAB0	Sen	35.90	X	
41 RETAINER-REAR BUMPER SIDE, LH	79185-4EAB0	Sen	23.80	X	
42 RETAINER-REAR BUMPER SIDE, RH	79184-4EAB0	Sen	23.80	X	
43 REAR BUMPER CLIP \$57.40EACH X3PCS	85284-2D00A	Mc	22.20	✓	
44 REAR BUMPER CLIP \$51.20EACH X4PCS	81553-05933	Mc	4.80	✓	
45 CANOE RIVET-REAR BUMPER \$56.50EACH X2PCS	76882-0H009	Mc	6.50	✓	
46 REVERSE SENSOR(4EYE)	SENSOR-4-PUR			Sen	250.00 X
47 FINISHER-REAR BUMPER	85071-4EAB0	Sen	16.80	X X	
48 REAR BUMPER FACIA	85022-4EAB0	Mc	717.00	✓	
49 REAR END PANEL	G9310-4EAB0	R	482.60	X	

TC AUTOCENTRE PTE LTD
1 SIXTH FLOOR TANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE BODY NO. 58627786

DEMANDED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
50 LAMP ASSEMBLY-REAR CORNER, RH	26556-4126A	Sm 323.70	X	
51 LAMP ASSEMBLY-REAR CORNER, LH	26555-4126A	Sm 323.70	X	
SUB TOTAL		12206.00	0.00	439.10
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		2441.20	0.00	0.00
GRAND TOTAL		9764.80	0.00	439.10
OVERALL TOTAL		10203.90		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts photos are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Damaged parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12343.90

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 29 November 2018 10:27 AM
To: 'Ho Yue Meng'; Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: Photos before and after paint and Finalised Bill for SKW2778A

Dear Mr Ho,

WITHOUT PREJUDICE

Confirmed amount \$7691.40 before GST @ 5 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ho Yue Meng <ho_yue_meng@tanchong.com>
Sent: Wednesday, 28 November 2018 11:00 AM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Photos before and after paint and Finalised Bill for SKW2778A
Importance: High

Dear Mr Kenneth,

Please find attached photos before and after paint for SKW2778A.

Also, please find attached finalised bill for SKW2778A.

Total Repair Days : 5 Days

Owner is claiming LOU.

Please advise when we can make the invoice to China Taiping.

Thank-you.

Best Regards
YM Ho
TC Autoclinic Pte Ltd
No 1 Sixth Lok Yang Road
Singapore 628099

Veron Chen (LKKAUTO)

From: Ho Yue Meng <ho_yue_meng@tanchong.com>
Sent: Thursday, 22 November 2018 12:00 PM
To: Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: Photos For SKW2778A
Attachments: SKW2778A - DIAGRAM.pdf; IMG_5888_1.JPG; IMG_5889_1.JPG; IMG_5890_1.JPG; IMG_5891_1.JPG; IMG_5892_1.JPG; IMG_5893_1.JPG; IMG_5894_1.JPG; IMG_5895_1.JPG; IMG_5896_1.JPG; IMG_5897_1.JPG; IMG_5898_1.JPG; IMG_5899_1.JPG; IMG_5900_1.JPG; IMG_5901_1.JPG; IMG_5902_1.JPG; IMG_5903_1.JPG; IMG_5904_1.JPG; CHECKED - SKW2778A.pdf

Importance: High

Dear Mr Kenneth,

Please refer to attached photos for SKW2778A.

Also, please refer to attached diagram and checked items for SKW2778A.

Please be informed as follows ;

- (1) The Front Bumper and LH Front Headlamp is damaged and need to be changed.
- (2) The Back Door windscreen glass comes complete with the moulding as moulding is not sold separately. Therefore, the back door windscreen glass need to be changed once the back door is changed (refer diagram).
- (3) The Rear Bumper is 2 tone colour (with silver paint below the rear bumper). Therefore, the spray painting labour is 1.5 panel.
- (4) We have adjusted the labour accordingly. Please check and advise.

Best Regards
YM Ho
TC Autoclinic Pte Ltd
No 1 Sixth Lok Yang Road
Singapore 628099
DID : 67038432

MODEL: J11E



TC AUTOCLINIC PTE LTD
1 BIRTH LOR YANG ROAD
SINGAPORE 528099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE HISS NO 000778A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SUPERVISOR'S RECOMMENDATION
1	FM1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	40.00	X - REC
2	MP1	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT AND REAR	120.00	4 360/-
3	RC1	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	7 1200/-
4	RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120.00 EACH X 2 PORTIONS	240.00	7 → 2120/-
5	RS1	REPLACE REVERSE SENSOR, MECHANICAL ADJUSTMENT & FUNCTION TEST	110.00	? 1100/-
6	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100.00 EACH X 2 PORTIONS	200.00	X 5100/-
7	11/001	REMOVE/INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION. REPAIR LH FENDER & RH FENDER	1400.00	700 2800 x 2 days 2 560/-
8	11/002	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	1750.00	750 500 2 625/-
9	11/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	X
10	11/004	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	✓
11	11/005	RENEW BACK DOOR WINDSCREEN GLASS	240.00	✓
12	11/006	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	150.00	7 150
13	11/007	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	✓
14	11/008	REMOVE/INSTALL FRONT BUMPER AND AFFECTED PORTION. REPAIR RAD SUPPORT PANEL, BONNET, LHF & RHF FENDER	840.00	250 → 280/-
15	11/009	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL, BONNET, LH FRONT FENDER AND RH FRONT FENDER	1500.00	350 → 2500/-
16	11/011	SEARCH FR	2.00	✓
17	11/012	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	? X
TOTAL LABOUR CHARGES			7140.00	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANN ROAD
SINGAPORE 420099

MATERIAL LIST FOR ACCIDENT VEHICLE HIRE NO 02W2788

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			QTY	LIST	S/RECYC HOMAGES
1	GUIDE-AIR, FRONT RH	21558-4E81A	1	23.50	X
2	GUIDE-AIR, FRONT LH	21559-4E86A	1	63.00	X
3	AIR GUIDE-RADIATOR, LOWER	21579-4E31A			1 94.50 X
4	BRACKET-RADIATOR MOUNTING, UPPER	21542-4E88A			1 14.60 X
5	HALE ASSY-HOOD LOCK	65601-4E88A	1	67.60	X
6	EMBLEM-FRONT	62890-4E80A		71.60	?
7	GRILLE-RADIATOR	62310-4E81A		498.30	?
8	RH FRONT BUMPER STAY	F2214-4E88A	1	173.30	X
9	LH FRONT BUMPER STAY	F2215-4E88A	1	123.70	X
10	ARMATURE ASSY-FRONT BUMPER, UPPER	F2030-4E88A		675.40	?
11	ENERGY ABSORBER-FRONT BUMPER, UPPER	62090-4E81B	1	195.70	X
12	ARMATURE ASSY-FRONT BUMPER, LOWER	62030-4E851A	1	337.70	X
13	ENERGY ABSORBER-FRONT BUMPER, LOWER \$562.20EACH #2PC	62090-4E80C	1	126.40	X
14	RH FRONT BUMPER SIDE BRACKET	62222-4E80A	1	20.90	X
15	LH FRONT BUMPER SIDE BRACKET	62223-4E80A	1	20.90	X
16	FRONT BUMPER CLIP \$51.20EACH #4PCS	01553-05933		4.80	?
17	COVER-BUMPER BRACKET	622A9-4E80A	1	19.30	X
18	FRONT BUMPER FASCIA	62022-4E80H		614.60	?
19	HEADLAMP ASSY-RH	26010-4E80A	1	559.00	X
20	HEADLAMP ASSY-LH	26060-4E80A	1	559.00	X
21	CLIP-REAR LUGGAGE PLATE \$51.20EACH #2PCS	01553-05933	2	2.40	X
22	CLIP-REAR LUGGAGE PLATE \$51.20EACH #4PCS	01554-00161	4	6.80	X
23	PLATE-LUGGAGE, REAR	84992-4E80A	1	63.50	?
24	DRAFTER-AIR \$562.30EACH #2PCS	76864-3D00A	1	124.60	X
25	LOCK ASSY-DACK DOOR	90502-4E81B	1	116.70	X

TC AUTOCLINIC PTE LTD
1 SIXTH LOR YANG ROAD
SINGAPORE 410059

MATERIAL LIST FOR ACURAGE VEHICLE MAKE NO 00000000

S/NO	PARTS DESCRIPTION	PARTS NUMBER	QUANTITIES & PRICES		
			NETT	LIST	REMARKS
26	WEATHER STRIP-REAR DOOR	90830-4E000	158.70		
27	STAY ASSY-REAR DOOR 85205-80EACH X2PCS	90450-4E000	419.60		
28	BUMPER RUBBER-REAR DOOR 856.50EACH X2PCS	90878-4E000	13.00		
29	EMBLEM-REAR	90892-4E000	87.00		
30	EMBLEM-REAR	90890-4E000	59.70		
31	REAR W/SCHIEB SEALANT	STALANT - 4			80.00
32	RUBBER-DUN 8560.20EACH X2PCS	Q2716-89901	120.40		
33	GLASS-REAR DOOR WINDSCREEN	90300-4E000	930.00		
34	DOOR-REAR	80100-HV000	2936.80		
35	LH REAR BUMPER STAY	H5211-4E000	126.00		
36	RH REAR BUMPER STAY	H5210-4E000	126.00		
37	REAR BUMPER REINFORCEMENT	H5030-4E000	619.20		
38	REAR BUMPER ENERGY ABSORBER	85090-4E000	126.40		
39	RH REAR BUMPER SIDE BRACKET	85220-4E000	35.90		
40	LH REAR BUMPER SIDE BRACKET	85221-4E000	35.90		
41	RETAINER-REAR BUMPER SIDE, LH	79185-4E000	23.80		
42	RETAINER-REAR BUMPER SIDE, RH	79184-4E000	23.80		
43	REAR BUMPER CLIP 857.40EACH X3PCS	85284-3D000	22.20		
44	REAR BUMPER CLIP 851.20EACH X4PCS	01553-05933	14.80		
45	CANOE RIVET-REAR BUMPER 856.50EACH X2PCS	76882-00000	6.50		
46	REVERSE SENSOR(4EYE)	SENSOR-4-FUR			250.00
47	FINISHER-REAR BUMPER	85071-4E000	16.80		
48	REAR BUMPER FACIA	85022-4E000	717.00		
49	REAR END PANEL	09110-4E000	482.60		

TC AUTOCLINIC PTE LTD
1 SIRTH LOK YANG ROAD
SINGAPORE 628099

FINALISED : ACCIDENT/BODY REPAIRS

REFERENCE : 190/IC/TC/NO/2018
DATE : 11-SEP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MISS HARRIS DANIELA VIRGINIA
ADDRESS : 491 YIO CHU KANG ROAD
#08-02
S(787078)
TELEPHONE NO : 96667478

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : CHINA TAIPING 3RD PARTY DIRECT
VEHICLE NO : SHW2778A
MODEL CODE : FRLARDEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2189249A
CHASSIS NO : SJMFEAJ11U1485188
MILEAGE : 63092 KM
DATE IN : 11/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 09/09/2018

"Finalised Bill"

To: LKIC

Attn: Mr Kenneth

5 days

over claim cost

Best Regards
Ym W

TC AUTOCLINIC PTE LTD
1 BIRTH LOK YANG ROAD
SINGAPORE 638999

LABOUR CHARGES FOR ACCIDENT VEHICLE WITH NO INJURY

SL/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01M	**COMPLETE WAXING OF VEHICLE		
2	FHI	FOCUS & ADJUST H/LAMP, RIGHT HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
3	HPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT	120.00	80.00
4	RCI	REPLACE REVERSE CAMERA, FINISHED MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	120.00
5	RPI	PERFORM MUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120.00
6	RST	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100.00
8	SI/001	REMOVE/INSTALL REAR BUMPER, BACK DOOR AND AFFECTED PORTION.	1400.00	560.00
9	SI/002	RESPRAY PAINT REAR BUMPER AND BACK DOOR	1750.00	525.00
10	SI/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	.00
11	SI/004	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	80.00
12	SI/005	RENEW BACK DOOR WINDSCREEN GLASS	240.00	240.00
13	SI/006	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	150.00	150.00
14	SI/007	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	20.00
15	SI/008	REMOVE/INSTALL FRONT BUMPER AND AFFECTED PORTION.	840.00	280.00
16	SI/009	RESPRAY PAINT FRONT BUMPER	1500.00	250.00
17	SI/011	SEARCH FEE	2.00	2.00
18	SI/012	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	.00
TOTAL LABOUR CHARGES			7140.00	1765.00

TC AUTOCLINIC PTE LTD
1 SIXTH LOE YANG ROAD
SINGAPORE 620099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMN2778A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REAR END PANEL	G9110-4EAMA	482.60		X
2	FINISHER-REAR BUMPER	H5071-4EAGA	16.80		X
3	REVERSE SENSOR(4XYS)	SENSOR-4-PUM			250.00 X
4	RETAINER-REAR BUMPER SIDE, RH	79184-4EAGA	23.80		X
5	RETAINER-REAR BUMPER SIDE, LH	79185-4EAGA	23.80		X
6	LH REAR BUMPER SIDE BRACKET	H5221-4EAGA	35.90		X
7	RH REAR BUMPER SIDE BRACKET	H5220-4EAGA	35.90		X
8	REAR BUMPER ENERGY ABSORBER	H5090-4EAGB	126.40		X
9	LH REAR BUMPER STAY	H5211-4EAMA	126.00		X
10	BUMPER RUBBER-BACK DOOR @\$6.50EACH X2PCS	90878-4EAGA	13.00		X
11	LOCK ASSY-BACK DOOR	90502-4EALB	116.70		X
12	DRAFTER-AIR @\$62.30EACH X2PCS	76804-JD00A	124.60		X
13	REAR BUMPER CLIP @\$1.20EACH X4PCS	01553-05933	4.80		OK
14	WEATHER STRIP-BACK DOOR	90830-4EAGB	159.70		X
15	STAY ASSY-BACK DOOR @\$209.00EACH X2PCS	90450-4EAGA	419.60		X
16	EMBLEM-REAR	90892-4EAGA	87.00		OK
17	EMBLEM-REAR	90890-4EAGA	59.70		OK
18	REAR W/SCREEN SEALANT	SEALANT - 4			80.00 OK
19	RUBBER-DUM @\$60.20EACH X2PCS	G2716-09901	120.40		OK
20	GLASS-BACK DOOR WINDSCREEN	90300-4EAGD	930.00		OK
21	DOOR-BACK	K0100-HVGNB	2936.80		OK
22	RH REAR BUMPER STAY	H5210-4EAMA	126.00		X
23	REAR BUMPER REINFORCEMENT	H5030-4EAMA	619.20		X
24	REAR BUMPER CLIP @\$7.40EACH X3PCS	H5284-JD00A	22.20		OK
25	CANOE RIVET-REAR BUMPER @\$6.50EACH X2PCS	76882-0H000	6.50		OK

TC AUTOCLINIC PTE LTD
1 SIXTH LANE YANG ROAD
SINGAPORE 620999

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SW2778A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	REAR BUMPER FASCIA	85022-4EA0H	717.00		OK
27	GUIDE-AIR, FRONT RH	21558-4ED1A	23.50		X
28	GUIDE-AIR, FRONT LH	21559-4ED6A	63.00		X
29	AIR GUIDE-RADIATOR, LOWER	21579-4EJ1A		94.50	X
30	BRACKET-RADIATOR MOUNTING, UPPER	21542-4E80A		14.60	X
31	HALE ASSY-HOOD LOCK	65601-4EA0A	67.60		X
32	ENDLEH-FRONT	62890-4EA0A	73.60		X
33	GRILLE-RADIATOR	62310-4EA1A	498.30		X
34	RH FRONT BUMPER STAY	F2214-4EAMH	173.10		X
35	LH FRONT BUMPER STAY	F2215-4EAMH	123.70		X
36	ARMATURE ASSY-FRONT BUMPER, UPPER	F2030-4ENRH	675.40		X
37	ENERGY ABSORBER-FRONT BUMPER, UPPER	62090-4EA1B	155.70		X
38	ARMATURE ASSY-FRONT BUMPER, LOWER	62030-HV51A	337.70		X
39	ENERGY ABSORBER-FRONT BUMPER, LOWER \$562.20EACH X2PCS	62090-4EA0C	124.40		X
40	RH FRONT BUMPER SIDE BRACKET	62222-4EA0A	20.90		X
41	LH FRONT BUMPER SIDE BRACKET	62223-4EA0A	20.90		X
42	FRONT BUMPER CLIP \$51.20EACH X4PCS	01553-05933	4.80		X
43	COVER-BUMPER BRACKET	622A0-4EA0A	19.30		X
44	FRONT BUMPER FASCIA	62022-4EA0H	616.60		OK
45	HEADLAMP ASSY-RH	26010-4EA0A	559.00		X
46	HEADLAMP ASSY-LH	26060-4EA0A	559.00		OK
47	CLIP-REAR LUGGAGE PLATE \$51.20EACH X2PCS	01553-05933	2.40		X
48	CLIP-REAR LUGGAGE PLATE \$51.20EACH X4PCS	01554-00181	4.80		X
49	PLATE-LUGGAGE, REAR	84992-4EA0A	63.50		X

TC AUTOCLINIC PTE LTD
 1 SIXTH LOE YANG ROAD
 SINGAPORE 670999

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SW2778A

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
50	LAMP ASSY-REAR COMBI,RH	26558-4EAG8	123.70			X
51	LAMP ASSY-REAR COMBI,LH	26555-4EAG8	123.70			X
SUB TOTAL			6058.00	0.00	80.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1211.60	0.00	0.00	
GRAND TOTAL			4846.40	0.00	80.00	
OVERALL TOTAL			4926.40			

LEGEND: REMARKS(OK) - APPROVED, REMARKS(X) - NOT APPROVED

TC AUTOCLINIC PTE LTD
1 NINTH LOR YANG ROAD
SINGAPORE 628099

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO 2EN2778A

NETT ITEM	6058.00
LESS 20.00%	-1211.60
NETT AMOUNT	4846.40
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	00.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	00.00
TOTAL LABOUR CHARGES	2765.00
TOTAL SPARE PARTS CHARGES	4926.40
TOTAL CHARGES	7691.40
ADD 7 % GST	538.40
GRAND TOTAL	8229.80



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-139536
Date of Request: 10/09/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

SK W 2773 A → SKT1097D

Dear Sir/Madam,

Enquiry Date: 10/09/2018
Enquiry By: Eric Koh Yong Lang
TP Vehicle No: SKT1097D
Accident Date: 09/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	11 Sep 2018		14 Sep 2018 09:40 Edit Adj Rpt	\$57,691.40 Edit Estimates	\$57,691.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JIM BEE LENG , ID: S7375222A									
Main Claimant: HARRIS DAMELZA VIRGINA									
Vehicle Reg. No.: SKW2778A		Date of Loss: 09/09/2018 12:00 - :59 [34 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04376C02		Policy/Cover Note No.: DMPCSN3022111800 (Comprehensive)							
Vehicle Reg. No. (Insured): SKT1097D		Policy No. (Claimant):							
		Excess: \$50.00							
Repairer: TC AutoClinic Pte Ltd (Lok Yang) 1 SIXTH LOK YANG ROAD, 628099 Pioneer - Tel: 6262 2212									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/09/2018]									
Adj Asp. Remarks: EST \$17,343.90, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW2778A (SNM18D04376C02)
[SKT1097D]
TP
HARRIS DAMELZA VIRGINA
Sep 9 2018 12:00PM
[JIM BEE LENG]
TC AutoClinic Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 17:14	Accident Statement	Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	10/09/18 16:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	10/09/18 16:41	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 10:20	General View	Load PDF	
2	29/11/18 10:21	Reinspection Photo (1)	Load PDF	
3	29/11/18 10:21	Reinspection Photo (2)	Load PDF	
Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 17:13	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	10/09/18 17:14	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
3	10/09/18 17:14	OWNER'S NRIC + DRIVING LICENCE AND DRIVERS' NRIC + DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/09/18 09:39	EMAIL FM TC	Load PDF	
2	14/09/18 09:39	REPAIR EST	Load PDF	
3	14/09/18 09:39	OI GIA	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 17:14	Accident Statement	Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 16:41	Accident Photo	Load JPG	☒
2	10/09/18 16:41	Accident Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
3	10/09/18 16:41	Accident Photo	 Load JPG	☒
4	10/09/18 16:41	Accident Photo	 Load JPG	☒
5	10/09/18 16:41	Accident Photo	 Load JPG	☒
6	10/09/18 16:41	Accident Photo	 Load JPG	☒
7	10/09/18 16:41	CHASSIS NUMBER	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/18 17:13	Sketch Plan	 Load TIF	
2	10/09/18 17:14	CERTIFICATE OF INSURANCE	 Load TIF	
3	10/09/18 17:14	OWNER'S NRIC + DRIVING LICENCE AND DRIVERS' NRIC + DRIVING LICENCE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18016814/KVBE2

Date: 04/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3022111800

Claimant Vehicle
No: SKW2778AInsured Vehicle
No: SKT1097D

Date of Loss: 09/09/2018

Nature of Claim: TP

Claim
No: SNM18D04376C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW2778A

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR
(A)

Engine No: HRA2189249A

Reg. Date: 24/10/2015 (Man. Year: 2015)

Chassis No: SJNFEAJ11U1485188

Colour: Metallic Grey

Odometer: 63092 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,203.90	4,926.40	5,277.50	51.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,140.00	2,765.00	4,375.00	61.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,343.90	7,691.40	9,652.50	55.65
+ GST 7.00/7.00% (S\$)	1,214.07	538.40	675.67	55.65
Nett Amount (S\$)	18,557.97	8,229.80	10,328.17	55.65

INSPECTION

Date of Assignment: 14/09/2018

Date Inspected: 21/11/2018 Inspected At:

17 LORONG 8 TOA PAYOH
Repairer : TC AutoClinic Pte Ltd (Lok
Yang)

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW2778A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUIDE-AIR, FRONT RH	Serviceable	23.50 FN	*- FN
2	1		*GUIDE-AIR, FRONT LH	Serviceable	63.00 FN	*- FN
3	1		*MALE ASSY-HOOD LOCK	Repair	67.60 FN	*- FN
4	1		*EMBLEM-FRONT	Not Necessary	73.60 FN	*- FN
5	1		*GRILLE-RADIATOR	Serviceable	498.30 FN	*- FN
6	1		*RH FRONT BUMPER STAY	Repair	173.10 FN	*- FN
7	1		*LH FRONT BUMPER STAY	Repair	123.70 FN	*- FN
8	1		*ARMATURE ASSY-FRONT BUMPER, UPPER	Serviceable	675.40 FN	*- FN
9	1		*ENERGY ABSORBER-FRONT BUMPER, UPPER	Serviceable	195.70 FN	*- FN
10	1		*ARMATURE ASSY-FRONT BUMPER, LOWER	Serviceable	337.70 FN	*- FN
11	2		*ENERGY ABSORBER-FRONT BUMPER, LOWER	Serviceable	124.40 FN	*- FN
12	1		*RH FRONT BUMPER SIDE BRACKET	Serviceable	20.90 FN	*- FN
13	1		*LH FRONT BUMPER SIDE BRACKET	Serviceable	20.90 FN	*- FN
14	4		*FRONT BUMPER CLIP	Not Necessary	4.80 FN	*- FN
15	1		*COVER-BUMPER BRACKET	Repair	19.30 FN	*- FN
16	1		*FRONT BUMPER FASCIA	Cracked	614.60 FN	*614.60 FN
17	1		*HEADLAMP ASSY-RH	Serviceable	559.00 FN	*- FN
18	1		*HEADLAMP ASSY-LH	MTG Cracked	559.00 FN	*559.00 FN
19	2		*CLIP-REAR LUGGAGE PLATE	Not Necessary	2.40 FN	*- FN
20	4		*CLIP-REAR LUGGAGE PLATE	Not Necessary	4.80 FN	*- FN
21	1		*PLATE-LUGGAGE, REAR	Serviceable	63.50 FN	*- FN
22	2		*DRAFTER-AIR	Serviceable	124.60 FN	*- FN
23	1		*LOCK ASSY-BACK DOOR	Repair	116.70 FN	*- FN
24	1		*WEATHER STRIP-BACK DOOR	Serviceable	158.70 FN	*- FN
25	2		*STAY ASSY-BACK DOOR	Serviceable	419.60 FN	*- FN
26	2		*BUMPER RUBBER-BACK DOOR	Serviceable	13.00 FN	*- FN
27	1		*EMBLEM-REAR	Necessary	87.00 FN	*87.00 FN
28	1		*EMBLEM-REAR	Necessary	59.70 FN	*59.70 FN
29	2		*RUBBER-DUM	Necessary	120.40 FN	*120.40 FN
30	1		*GLASS-BACK DOOR WINDSCREEN	MTG Necessary	930.00 FN	*930.00 FN
31	1		*DOOR-BACK	Bent	2,936.80 FN	*2,936.80 FN
32	1		*LH REAR BUMPER STAY	Serviceable	126.00 FN	*- FN
33	1		*RH REAR BUMPER STAY	Serviceable	126.00 FN	*- FN
34	1		*REAR BUMPER REINFORCEMENT	Repair	619.20 FN	*- FN
35	1		*REAR BUMPER ENERGY ABSORBER	Serviceable	126.40 FN	*- FN
36	1		*RH REAR BUMPER SIDE BRACKET	Serviceable	35.90 FN	*- FN
37	1		*LH REAR BUMPER SIDE BRACKET	Serviceable	35.90 FN	*- FN
38	1		*RETAINER-REAR BUMPER SIDE, LH	Serviceable	23.80 FN	*- FN
39	1		*RETAINER-REAR BUMPER SIDE, RH	Serviceable	23.80 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	3		*REAR BUMPER CLIP	Necessary	22.20 FN	*22.20 FN
41	4		*REAR BUMPER CLIP	Necessary	4.80 FN	*4.80 FN
42	1		*CANOE RIVET-REAR BUMPER	Necessary	6.50 FN	*6.50 FN
43	1		*FINISHER-REAR BUMPER	Serviceable	16.80 FN	*- FN
44	1		*REAR BUMPER FASCIA	Buckled	717.00 FN	*717.00 FN
45	1		*REAR END PANEL	Repair	482.60 FN	*- FN
46	1		*LAMP ASSY-REAR COMBI, RH	Serviceable	323.70 FN	*- FN
47	1		*LAMP ASSY-REAR COMBI, LH	Serviceable	323.70 FN	*- FN
48	1		*AIR GUIDE-RADIATOR, LOWER	Serviceable	94.50 FS	*- FS
49	1		*BRACKET-RADIATOR MOUNTING, UPPER	Serviceable	14.60 FS	*- FS
50	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
51	1		*REVERSE SENSOR (4EYE)	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	12,645.10	6,138.00
- Nett Item Discount on N Items 20.00/20.00% (S\$)	2,441.20	1,211.60
Total Parts (S\$)	10,203.90	4,926.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	New	48.00	48.00
2	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS - FRONT AND REAR	New	120.00	60.00
3	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	New	120.00	120.00
4	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00EACH x 2 PORTIONS	New	240.00	120.00
5	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
6	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00EACH x 2 PORTIONS	New	200.00	100.00
7	REMOVE / INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION. REPAIR LHR FENDER & RHR FENDER	New	1,400.00	560.00
8	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	New	1,750.00	625.00
9	REMOVE / INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	New	240.00	0.00
10	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	New	80.00	80.00
11	RENEW BACK DOOR WINDSCREEN GLASS	New	240.00	240.00
12	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	New	150.00	150.00
13	CHECK REAR LIGHTINGS AND WIRING SYSTEM	New	20.00	20.00
14	REMOVE / INSTALL FRONT BUMPER AND AFFECTED PORTION. REPAIR RAD SUPPORT PANEL, BONNET, LHF & RHF FENDER	New	840.00	280.00
15	SEARCH FRR	New	2.00	2.00
16	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	New	80.00	0.00
17	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL, BONNET, LH FRONT FENDER AND RH FRONT FENDER	New	1,500.00	250.00
Gross Labour Cost (S\$)			7,140.00	2,765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >