

Invoice

Page 1 of 1


**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-044377

Date of Request: 23/03/2018

Your Ref No: INS-H47-106137-18-YL

VISION LAW LLC
 133 New Bridge Road #18-01/02
 Chinatown Point
 Singapore 059413

Dear Sir/Madam,

Date of Accident: 14/03/2018

Vehicle No: GBG1721K

Place of Accident: FILTER LANE OF TAMPINES LINK TWDS TAMPINES AVE 10

Involving Vehicle No: XE3314P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XE3314P	FILTER LANE OF TAMPINES LINK TWDS TAMPINES AVE 10	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-044376
Date of Request: 23/03/2018
Your Ref No: INS-H47-106137-18-YL

VISION LAW LLC
133 New Bridge Road #18-01/02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 14/03/2018
Place of Accident: TAMPINES LINK TOWARDS TAMPINES
Client Vehicle No: GBG1721K

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
XE3314P	TAMPINES LINK & TAMPINES AVE 10	14/03/2018 18:10

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Invoice

Page 2 of 2



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-044376
Date of Request: 23/03/2018
Your Ref No: INS-H47-106137-18-YL

VISION LAW LLC
133 New Bridge Road #18-01/02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:
Date of Accident: 14/03/2018
Place of Accident: TAMPINES LINK TOWARDS TAMPINES
Client Vehicle No: GBG1721K

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque

Enquire Vehicle & Owner Information (Vehicle No. XE3314P As At 14 Mar 2018 / 17:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: H47

Current Owner Details

Owner ID Type: Company
Owner ID: 201401018N
Owner Name: SOON HUA BEE PTE LTD
Registered Address Type: HDB / HUDC
Registered Block/House No.: 201E
Registered Street Name: TAMPINES STREET 23
Registered Unit No.: # 04 - 100
Registered Building Name: -
Registered Postal Code: 527201

Current Vehicle Details

Vehicle No.: XE3314P
Make Description/Model: MITSUBISHI / FUSO FVS15JD2DEA
Insurance Company Name: AXA INSURANCE PTE LTD



華明噴漆廠 HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref :

17/5/2018

Our Ref :

Date:

VEHICLE NO :GBG 1721 K
MAKE / MODEL :TOYOTA HIACE
NAME :LIM SIEW PING
ADDRESS :BLK 449 TAMPINES ST 42
#10-88
S 520449

FINAL REPAIR BILL FOR VEHICLE NO. GBG 1721 K

LIST ITEMS

	QTY	COST (\$\$)
Rear tailgate	1	2311.6
Rear tailgate centre logo	1	57.8
Rear tailgate TOYOTA sticker	1	57.8
Rear tailgate HIACE sticker	1	55
Rear taiglate handle (garnish)	1	588.5
Rear bumper	1	696.2
Rear bumper side holder @ \$30.00	2	30
Rear bumper clips (set)	1	50
Rear RH lamp	1	29.6
Rear RH lamp lower cover	1	98.8
		<u>3975.3</u>
	Less 25% Disc	<u>993.83</u>
	Total	<u>2981.48</u>

Special Nett Items

Rear tailgate 70KM sticker	1	15
Rear windscreen sealant	1	50
	Total	<u>65</u>



華明噴漆廠

HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 254678/00M



Your Ref :

17/5/2018

Our Ref :

Date:.....

VEHICLE NO :GBG 1721 K
 MAKE / MODEL :TOYOTA HIACE
 NAME :LIM SIEW PING
 ADDRESS :BLK 449 TAMPINES ST 42
 #10-88
 S 520449

FINAL REPAIR BILL FOR VEHICLE NO. GBG 1721 K

Labour Cost

To remove and reinstall rear.windscreen	COST (\$\$)
	120
To remove and reinstall camera	60
To remove,repalce & repair consistent to the accident	700
To respray painting	800
To tuff kote	60
To remove and reinstall reverse sensor	60

Total 1800

Grand Total 4846.48

SGD: FOUR THOUSAND EIGHT HUNDRED FORTY SIX AND CENTS FORTY EIGHT ONLY



長江企業(私人)有限公司
Chiang Kang Enterprises Co. (Pte.) Ltd.



TAX INVOICE

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246 Fax: 6298 3864

RENTAL OF CARS, VANS, PICK-UPS & LORRIES

出租：汽車、廣告車、必甲與輕重型羅厘

GST Reg.No. 19-8304039-K

HIRER'S PARTICULARS

If Different From
Section 1)

I/We Kan Yoke Chuan

of Blk 449 Tampines St 42 #10-88, SC520489

S 91893783 Tel: 91893783

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from CHIANG KANG ENTERPRISES CO. (PTE.) LTD. hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

a) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$1500/- to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.

b) COMPREHENSIVE MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2000/- for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle. whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me or the terms and Conditions of Hire, hereinafter mentioned and printed at the back hereof:

Vehicle Regn No. 車輛註冊號碼 <u>G N 9443Y</u>		Rental Agreement 合同號碼 No. A <u>90793</u>	
Section 1) Hirer's And/Or Driver's Particulars 租車者/駕駛員個人記錄		租出日期及時間 Date & Time OUT <u>14-03-2018 1900hrs</u>	
姓名 Name: <u>Kan Yoke Chuan</u>		交車日期及時間 Date & Time IN <u>21-03-2018 1500hrs</u>	
地址 Address: <u>Blk 449 Tampines St 42 #10-88 SC520489</u>		Chargeable	Rates Amount
S		7	天 Days @ \$ <u>8840/-</u>
居民證/護照號碼 I/C No./Passport No. <u>S0092269B</u>		駕駛執照號碼 Driving Licence No.	星期 Weeks @ \$
居民證/護照種類 Type of I/C/Passport:		Pass 日期 Pass Date:	月 Month @ \$
出生日期 Date of Birth: <u>21-01-1952</u>		發出地 Place of Issue:	ADD 7% GST <u>858.80</u>
三號保險底金 \$1500/= a) Third Party Only Policy Excess \$1500/=		一號保險底金 \$2000/= b) Comprehensive Policy Excess \$2000/=	送車/費 Delivery Fees
車輛必須歸還車主於 Vehicle Must Be Returned To Owner's Office By:		總計 Total Charge	<u>8898.80</u>
備註與付款記錄 Remarks & Payment Records <u>Hug ming</u>		按金 Security Deposit	
		總金額 Total Payable	<u>8898.80</u>
		來銀 Amount Paid	
		收車費用 Collection Fees/Misc.	
IMPORTANT! For Singapore Use only!		超過/小時 Extra Hours @ \$	
出車油箱 Fuel Tank OUT <u>E 1/4 1/2 3/4 F</u>	出車油箱 Fuel Tank IN <u>E 1/4 1/2 3/4 F</u>	租費不包括汽油 Rates Do Not Include Fuel	添油 Refuelling
車牌號碼 Vehicle No. 1)	起 From:	至 To:	
車牌號碼 Vehicle No. 2)	起 From:	至 To:	
工具 Tools	輪胎 Spare Tyre	裝飾品 Accessories	加額費用 Total Additional Charges
車輛發出人 Vehicle Issued By:	車輛接收人 Vehicle Collected By:		
NOTE: 註 租車者或司機必須付所有停車及違反交通法例負起一切的責任。 HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING AND TRAFFIC VIOLATIONS.		總計 Grand Total	

租車者不准載沙或石灰
HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

我/我們同意以上及後頁租車公司所列的條款與條件。
I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

日期
Date:

租車者簽名
Signature of Hirer: Kan

FormTeam Consultancy Pte Ltd33 Ubi Avenue 3 #02-15 Vertex
Singapore 408868

Tel: 6509 1788 Fax: 6509 6221

UEN No: 200819280D

Bill To:Lim Siew Ping - GBG 1721K
C/O Hua Meng Spray Painting Workshop
Blk 1 Kaki Bukit Ave 6 #01-61/01-34
Autobay @ Kaki Bukit
Singapore 417883**Tax Invoice**

GST Reg No: 200819280D

Invoice No :	13031691
Date :	7/5/2018
Page :	1
Our Ref :	IND18-032020/TP/BX/c


Description	Amount (S\$)
PARTICULARS	S\$545.00
Vehicle Registration No : GBG 1721K Date of Accident : 14-Mar-2018 Date of Inspection : 16-Mar-2018	
SERVICES :	
Assessment with report (inclusive of transport charges and photographs etc)	
Total	S\$545.00
Add: 7% GST	S\$38.15
Total Inc GST	S\$583.15
Less: Deposit	S\$0.00
Balance Due	S\$583.15

We would appreciate your cheque crossed and make payable to :
FormTeam Consultancy Pte Ltd

E. & O. E

FormTeam Consultancy Pte Ltd

RECEIVED BY	DATE	COMPANY STAMP



FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : IND18-032020/TP/BX/cg

Your Reference: -

Date: **7-May-18**

TO : Lim Siew Ping
 C/O Hua Meng Spray Painting Workshop,
 1 Kaki Bukit Avenue 6 #01-61
 Singapore 417883

Assessment of Vehicle No : GBG 1721K
Date of Accident : 14-March-2018
Date of Inspection : 16-March-2018

We have carried out a physical assessment of GBG 1721K at M/S Hua Meng Spray Painting Workshop according to your instructions on 16-March-2018 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : GBG 1721K
 Make & Model : Toyota Hiace Van Turbo 5Dr MT
 Year of Registration : 2017
 Engine Capacity (cc) : 2982 cc
 Chassis No. : JTFHT02P300224553
 Engine No. : 1KD2719288
 Colour : White
 Mileage (km) : 2712

2. VEHICLE CONDITION

Body Paint : Good
 Steering : Serviceable
 Foot Brake : Serviceable
 Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Bridgestone 195 R15C - 90%
 LH Make/Size : Bridgestone 195 R15C - 90%

Rear

RH Make/Size : Bridgestone 195 R15C - 90%
 LH Make/Size : Bridgestone 195 R15C - 90%

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : IND18-032020/TP/BX/cg
Your Reference : -
Vehicle Number : GBG 1721K

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear RH portion**. Please see attached scheduled for details.



5. REMARKS

Market Value : Na
Salvage Value : Na
Repair Limit : Na

Estimated Amount : \$10,983.30
Adjusted Amount : \$4,846.48
Estimated Repair Days : 06 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : IND18-032020/TP/BX/cg
Your Reference : -
Vehicle Number : GBG 1721K

Page No. 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)		OUR ASSESSMENT (S\$)	
<u>PARTS (LIST ITEMS)</u>						
1	Rear Tailgate	Bent	2,311.60		2,311.60 DD ✓	
2	Rear Tailgate Hinges @\$105.00	Serviceable	210.00		-	
1	Rear Tailgate Upper Lock	Reuse	282.30		-	
1	Rear Tailgate Lower Lock	Serviceable	202.50		-	
1	Rear Tailgate Centre Logo	Necessary	57.80		57.80	
1	Rear Tailgate Toyota Sticker	Necessary	57.80		57.80 } NEC	
1	Rear Tailgate Hiace Sticker	Necessary	55.00		55.00	
1	Rear Tailgate 70Km Sticker	Refer To Special Nett	35.00		-	
1	Rear Tailgate Handle (Garnish)	Cut/Deformed	588.50		588.50 SCR ✓	
2	Rr Tailgate Shock Absorber @\$306.40	Serviceable	612.80		-	
1	Rear Tailgate Weatherstrip	Serviceable	120.20		-	
1	Rear Tailgate Inner Board	Serviceable	217.50		-	
1	Rear Bumper	Deformed	696.20		696.20 DD ✓	
2	Rear Bumper Side Holder @\$30.00	RH Necessary, LH Not Necessary	60.00		30.00 NEC ✓	
1	Rear Bumper Clips (Set)	Necessary	50.00		50.00 NEC ✓	
1	Rear End Panel	Repair	201.10		-	
1	Rear End Panel Inner Top Garnish	Reuse	103.00		-	
1	Rear RH Lamp	Cracked	29.60		29.60 CR ✓	
1	Rear RH Lamp Inner Panel	Repair	388.40		-	
1	Rear RH Lamp Lower Cover	Cut/Deformed	98.80		98.80 Xmt ✓	
1	Rear RH Lamp Lower Cover Holder	Reuse	55.00		-	
1	Rear RH Fender	Repair	2,211.30		-	
			8,644.40		3,975.30	
Less Discount :			25%	2,161.10	25%	993.83
Parts Total :			6,483.30		2,981.48	
<u>SPECIAL NETT ITEMS</u>						
1	Rear Tailgate 70Km Sticker	Necessary	-		15.00 NEC ✓	
1	Rear Windscreen Sealant	Necessary	50.00		50.00 NEC ✓	
Special Nett Total:			50.00		65.00	
Total Parts:			6,533.30		3,046.48	

FormTeam Consultancy Pte Ltd

Our Reference : IND18-032020/TP/BX/cg

Page No. 4

Your Reference : -

Vehicle Number : GBG 1721K

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	To remove and reinstall rear windscreen.	150.00	120.00
2	To remove and reinstall camera.	100.00	60.00
3	To remove, replace & repair consistent to the accident.	2,500.00	700.00 500
4	To respray painting.	1,400.00	800.00 600
5	To tuff kote.	150.00	60.00
6	To remove and reinstall reverse sensor.	150.00	60.00
	Labour Total :	4,450.00	1,800.00
	TOTAL (PARTS & LABOUR) :	10,983.30	4,846.48

Note : (For Part By Part Repair)

The workshop has agreed to undertake the
repair at our adjusted amount of

\$4,846.48**(SINGAPORE DOLLARS FOUR THOUSAND EIGHT HUNDRED FORTY SIX AND CENTS FORTY EIGHT ONLY)**

Chow Bo Xiong

Automobile Appraiser

Repair days 5


 21/9/2018

TG Lim


 21/9/18



TPPD LOD

Type

❗ Information

Message

TPPD LOD shared. Please check let me know if you need to conduct reinspection or would paper re survey be sufficient. This is Virtual account.

Reply

<< Service Request Details

Claim

S8M00AUIQ

Reference

CS3VASM18005022/Apa3s2-1  Loss Date

Request Date

March 14, 2018

Due Date

June 14, 2018

Vendor Name

LKKA AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Wait for None - Invoices paid

Add Invoice

Vehicle Information

Incident Vehicle Registration #

GBG1721K

Make

Service Address

TPVD TOYOTA

Model

HIACE

Primary Contact/Insured

SOON HUA BEE PTE LTD

BLK 201E TAMPINES STREET 23, #04-100, 527201, Singapore

633800083

Claim Handler

TAN Shirley

6568804834

chaigook.tan@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
KADRI Mateen	3/16/18 12:09 PM	4372.38	4372.38	In Review	Share	Clone



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	GBG1721K	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	06/16/2017
Mileage	2712	Age of Vehicle	0
Driver Details			
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2017		
Make	TPVD TOYOTA	Driver Name	KAW YOEK CHIANG
Model	HIACE	Date of Birth	January 21, 1952
Type		Age	66
Type of Paint		Occupation	Unknown
Chassis No	JTEHT02P300224553	Education Qualification	Other
Engine No	1KD2719288	Driving Experience	0
Engine Capacity	2982 cc	Driver License #	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	03/16/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195R15C	Rear Tyre Size	195R15C
Front left side	BRIDGESTONE 6mm	Rear left side	BRIDGESTONE 6mm
Front right side	BRIDGESTONE 6mm	Rear right side	BRIDGESTONE 6mm

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		5	
	2	REAR TAILGATE 70KM STICKER	Reviewing	15	NECESSARY	
	3	REAR WINDSCREEN SEALANT	Reviewing	50	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$4,372.38

Claim Amount \$4,372.38

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$1,733.70	\$2,907.38
Labour	\$120.00	\$1,400.00
Miscellaneous	\$15.00	\$65.00