

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRY%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		13	2			REAR BUMPER SIDE HOLDER			Necessary	15		25		22.5	Reviewing	
		14	1			SET REAR BUMPER CLIPS			Necessary	50		25		37.5	Reviewing	
		15	1			REAR END PANEL			Repair	0		25		0	Reviewing	
		16	1			REAR END PANEL INNER TOP GARNISH			Reused	0		25		0	Reviewing	
		17	1			REAR RH LAMP			Cracked	29.6		25		22.2	Reviewing	
		18	1			REAR RH LAMP INNER PANEL			Repair	0		25		0	Reviewing	
		19	1			REAR RH LAMP LOWER COVER			Serviceable	0		25		0	Reviewing	
		20	1			REAR RH LAMP LOWER COVER HOLDER			Reused	0		25		0	Reviewing	
		21	1			REAR RH FENDER			Repair	0		25		0	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RLR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO REMOVE AND REINSTALL REAR WINDSCREEN.	120	0	0	Reviewing		
		2		TO REMOVE AND REINSTALL CAMERA.	60	0	0	Reviewing		
		3		TO REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.	500	0	0	Reviewing		
		4		TO RESPRAY PAINTING.	600	0	0	Reviewing		
		5		TO TUFF KOTE.	60	0	0	Reviewing		
		6		TO REMOVE AND REINSTALL REVERSE SENSOR.	60	0	0	Reviewing		

Add

Approve

Deny

Submit All

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured		0	License Type		
Market Value		0	License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	BLK 449 TAMPINES ST 42, #10-881852, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	50092269B	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Virtual forward TPPD & BI LOD - Lim Siew Ping.pdf	Letters and Correspondence	Solicitor / Advocate	TAN Shirley	June 14, 2018
LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	April 6, 2018
PRE-REPAIR INSPECTION REPORT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 6, 2018
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 24, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 24, 2018
GIA REPORT OF XE3314P (INSO).PDF	Reports & Statement	GIA Report	KADRI Maleen	March 16, 2018
GIA REPORT OF GBG1721K (TP).PDF	Reports & Statement	GIA Report	KADRI Maleen	March 16, 2018
EMAIL (PRI).msg	Letters and Correspondence	Workshop	KADRI Maleen	March 16, 2018