

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8425 A

1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover ✕	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✕	\$ 58.00
1 pc	Rear bumper inner sponge ✕	\$ 114.00
1 pc	Rear bumper reinforcement ✕	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✕	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$ 36.00
1 pc	Rear bumper n/s reflector @ \$46.00 ✕	\$ 46.00
		\$ 1,907.00
	Less 10%	\$ 190.70
		\$ 1,716.30

S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 set	Reverse sensor ✕	\$ 280.00
1 pc	Rear bumper top protector	\$ 80.00 50
	Sundry	\$ 80.00 ✕
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 ✕
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$ 650.00 200
	To putty and spray painting on rear bumper, rear bumper lower cover, end panel	\$ 450.00 180
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 ✕
		\$ 3,694.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 11/11/18
13/9/18 1535L
20/9/18
4/10/18
After Repz photo