



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

Customer	: UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT18003881	Page	1
Registration No	: SFG1899J	Date	: 14. Sep 2018	Customer No.	: WU001
Chassis No	: JHMGK5850GX200416	Svc Advisor	: RUEBEN THOMAS	Engine No	: L15B31020147
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 14. Sep 2018 12:39:47 PM	Surveyor Name	:
Owner's Name	: HENG MYA KENG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 9/9/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST	
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: DH0M120024351600 OWNER: HENG MYA KENG ACC DATE: 09/09/2018 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :							
04711-T5A-000ZZ	FACE,FR.BUMPER <i>so/one</i>	1	494.70	25	371.02	25.97	396.99	
91506-TM8-003	CLIPBUMPER <i>neu</i>	17	2.00	25	25.50	1.79	27.29	
71102-T5A-000	LOWER GRILLEFR.BUMPER	1	27.50	25	20.62	1.44	22.06	
71110-T5A-000	SPOILERFR.BUMPER LIP	1	56.30	25	42.22	2.96	45.18	
71190-T5A-000	BRACKETL.HEADLIGHT	1	21.90	25	16.42	1.15	17.57	
71140-T5A-000	BRACKETR.HEADLIGHT	1	23.60	25	17.70	1.24	18.94	
71198-T5A-000	SPACERL.FR.BUMPER <i>3/4</i>	1	10.40	25	7.80	0.55	8.35	
71193-T5A-000	SPACERR.FR.BUMPER <i>3/4</i>	1	10.40	25	7.80	0.55	8.35	
71108-T5A-N00	GARNISHL.FR.BUMPER	1	23.30	25	17.47	1.22	18.69	
71103-T5A-N00	GARNISHR.FR.BUMPER	1	23.30	25	17.47	1.22	18.69	
71130-T5A-000ZZ	BEAM COMPFR.BUMPER	1	219.40	25	164.55	11.52	176.07	
60400-T5B-310ZZ	BULKHEAD COMPFR. <i>n</i>	1	374.30	25	280.72	19.65	300.37	
71120-TAS-003	GRILLE ASSYFR. <i>one</i>	1	288.90	25	216.67	15.17	231.84	
71105-T5A-000	COVERFR.GRILLE <i>one</i>	1	11.80	25	8.85	0.62	9.47	
75700-TA0-A00	EMBLEMFR. <i>neu</i>	1	25.90	25	19.42	1.36	20.78	
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05	
33150-T5A-J21	HEADLIGHT ASSYL.	1	1118.60	25	838.95	58.73	897.68	
33100-T5A-J21	HEADLIGHT ASSY,R.	1	1118.60	25	838.95	58.73	897.68	
08CLA-P9911LK8	COOLANTANTI-FREEZE	3	23.20	25	52.20	3.85	56.05	
					Sum Item	2987.18	207.72	3174.90
BOSUN	SUNDRIES <i>neu</i>	1	60.00	20	50.00	3.50	53.50	



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

Customer :	UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909	Document No. :	SQT18003881	Page	2
Registration No :	SFG1899J	Date :	14. Sep 2018	Customer No. :	WU001
Chassis No :	JHMGK5850GX200416	Svc Advisor :	RUEBEN THOMAS	Engine No :	L15B31020147
Model :	JAZZ 1.5VTIR CVT 18YM	Date Time :	14. Sep 2018 12:30:47 PM	Surveyor Name :	
Owner's Name :	HENG MYA KENG	Survey Date :		Authorisation Date :	
Ins Policy No. :					
Date of Accident :	9/9/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	80	100.00	7.00	107.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	200.00	7	200.00	14.00	214.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00	7	280.00	19.60	299.60
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	2400.00	1120	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2400.00	1350?	2400.00	168.00	2568.00
					Sum Labor	5430.00	380.10
							5,810.10

Survey By	<u>Marcus Hal</u>			
Date & Time	<u>17/9/18 @ 9.45am.</u>	Total Amount	8,397.18	557.82
Excess	<u>\$ 6021-</u>	Total (Inclusive of GST)		<u>8,985.00</u>
Status	<u>Not Authorized</u>			
Signature	<u>Luha ph. Seprepa. itiy</u>			
	<u>Sdy.</u>			

Printed on 14/9/2018 1:51:22 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s)