



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA9508X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **26843**
Reg No/Reg Date **SLA9508X / 23/03/2016**
Date In/Mileage **01/10/2018/ 40971**
Chassis No **WDD1760422J439185**
Engine No **27091030894044**
Make/Model **MB/MB A 180 (W176) "STYLE"**
Colour/Trim **026 650 Calcit Whit/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	04/10/2018/ 17:36	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : DMPHQ18-001352 // 11/09/2018				
DRIVE IN/TP VEHICLE NO. : 12/09/2018 // SKL8072X - CHINA				
DATE IN/DATE SURVEY: 01/10/2018 1515 // LKK - TAUFIKH				
DIRECT SETTLEMENT : 19/09/2018 // CHINA - CATHERINE				
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				600.00
RESPRAY REAR BUMPER				
A BPILAB			0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
X REAR BUMPER	1.00	1275.24	00.00	1275.24
X REAR BUMPER LOWER CHROME	1.00	127.76	00.00	127.76
X SPACER RING	2.00	6.42	00.00	12.84
X REAR BUMPER LOWER TRIM	1.00	204.21	00.00	204.21
A REAR BUMPER TRIM STRIP	1.00	140.03	00.00	140.03

Finalization

Confirmed & accepted by

7% GST on **Nett 3,820.08**
3820.08 267.41

Authorized signatory and company stamp

Total Payable 4,087.49

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA9508X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **26843**
Reg No/Reg Date **SLA9508X / 23/03/2016**
Date In/Mileage **01/10/2018/ 40971**
Chassis No **WDD1760422J439185**
Engine No **27091030894044**
Make/Model **MB/MB A 180 (W176) "STYLE"**
Colour/Trim **026 650 Calcit Whit/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	04/10/2018/ 17:35	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	REAR BUMPER LOWER TRIM				1.00	204.21	00.00	204.21
A	REAR BUMPER TRIM STRIP				1.00	140.03	00.00	140.03

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 344.24**
344.24 24.10
Total Payable 368.34

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg