

22/03/2002

ASS. REC. BY:

REF: CS/CT18016826/T1vbm2 Special Instruction:

ASSIGNMENT (Office)

SUVA/01

From (Person):

Catherine Tina

of

CTL

Date/Time: 14/09/2018 2pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLA 9508X

Insured:

SKL 8072X

at Workshop m/s

Cycle & Carriage

Tel:

of

Y88 Pandan Gap

Policy No:

DMP/CS/N3100151801

Claim No:

SNM18D04426(02)

Sum Insured:

Excess:

D.O.A. 11-09-2018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

14/09/2018 231pm

Person Contacted:

Kerlyn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 9508X - X

SKL 8072X - NA/CT18016024/h4

DA: 01/09/2018

11/10/18

Final fig \$ 3820.08 confirmed by email (Reel 2414.06, 3970)

Signature

Taylor

REF:

CT1

ASSIGNMENT

From:

Date:

17/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GI/A / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Kerlyn

Veh No:

SLA 9508 X

Yr Regn:

2016 Mod.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes 300 1980

G.V. 1555

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

40977

T/Radio: Insured / Std / NI / NA

Eng/No:

WDD17604225439185

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

GC Pardon Wip 11/10/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

11/10-typist

Report Format:

merimen

Lump Sum / I.B.I: (\$

3820.08

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

20

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 14:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	AZHARI BIN MOHD JADI, ID: S6812241D		
Main Claimant:	SOH YEE CHOW, BENJAMIN(SU YICHAO)		
Vehicle Reg. No.:	SLA9508X	Date of Loss:	11/09/2018 18:00 - :59
Claim Type:	TP / SNM18D04426C02	Policy/Cover Note No.:	DMPCSN3100151801 (Comprehensive)
Vehicle Reg. No. (Insured):	SKL8072X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 168 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]		
Adj Asg. Remarks:	EST \$6302.19, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 11 October 2018 12:03 PM
To: Mei Kwan (LKKAUTO); Kerlyn Ong (kerlyn.ong@cyclecarriage.com.sg)
Cc: SUR
Subject: RE: SLA9508X- DOA: 11/9/2018

Dear Kerlyn,

WITHOUT PREJUDICE

Confirm \$3,820.08 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 10 October 2018 2:02 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: SLA9508X

CS/CTI18016826/T1vb

-----Original Message-----

From: Kerlyn Ong <kerlyn.ong@cyclecarriage.com.sg>
Sent: Wednesday, 10 October, 2018 1:54 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SLA9508X

Taufikh,

Please proceed to finalize.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2018 21:15
Date Of Accident	11/09/2018 18:50
Exact Location Of Accident	ALONG PIE TOWARD ECP BEFORE EXIT 17
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA9508X
Insured/Policyholder	
Name Of Registered Owner	SOH YEE CHOW, BENJAMIN (SU YICHAO)
NRIC No	S7917318E
Email Address	BENJAMINSOH7777@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97661852
Alternative Phone No	OFFICE-97661852

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A180 FL STYLE (R17 HLG)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-001352
Cover Note Number	

Driver

Name of Driver	SOH YEE CHOW, BENJAMIN (SU YICHAO)
NRIC No	S7917318E
Date Of Birth	28/05/1979
Occupation	INDOOR
Date Of Driving Pass	26/04/1999
Driving Experience	19 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97661852
Fax Number	
Contact Number	OFFICE-97661852
EMail Address	BENJAMINSOH7777@YAHOO.COM.SG

Address

APT BLK 169C PUNGGOL FIELD #09-671 SINGAPORE 823169

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] BUKIT PANJANG N.P.C

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO:T/20180912/2049 LODGED AT BUKIT PANJANG N.P.C. ON THE 11/09/2018 AT ABOUT 1850HRS, I WAS DRIVING MY VEHICLE SLA9508X MERCEDES(WHITE) ALONG PIE FASTEST LANE TOWARDS ECP. AS I WAS APPROACHING EXIT 17, ONE CAR WHITE KIA(SLW6324M) IN FRONT OF MINE SUDDENLY APPLIED EMERGENCY BRAKES. I HAD TO STOP MY CAR AND MANAGE TO AVOID HITTING ONTO SLW6324M. SLW6324M THEN DROVE OFF. SUDDENLY, I FELT A AN IMPACT FROM THE REAR OF MY VEHICLE. I EXITED MY CAR AND DISCOVERED THAT A WHITE FORD(SKL8072X) KNOCK INTO THE REAR OF MY VEHICLE. THERE WAS ONE MORE SILVER CAB SHC6463Y THAT HIT ON TO SKL8072X'S REAR. AS SOON AS THE ACCIDENT HAPPENED, TWO CHINESE LADIES RAN FROM THE SIDE OF THE ROAD ACROSS THE EXPRESSWAY TO RENDEER ASSISTANCE AND ASKED IF WE NEEDED HELP. ANOTHER CAR SJS5420A A BLACK HONDA JASS ALSO STOPPED AND RENDER ASSISTANCE. WE SUDDENLY HAD PEOPLE OFFERING HELP, CLAIMING THAT THEY HAVE TOW TRUCKS AND WORKSHOPS READILY AVAILABLE. I WISH TO STATE THAT NO ONE WAS CONVEYED VIA THE AMBULANCE AND WE ALL MANAGED TO DRIVE OF AFTER EXCHANGING CONTACT DETAILS. I HAVE A FRONT AND REAR CCTV RECORDING OF THE WHOLE ACCIDENT. FROM THE ACCIDENT, IT DID CAPTURE THAT THE WHITE FORD MANAGED TO STOP IN TIME BEHIND ME BUT THE TAXI WAS THE ONE WHO CAUSED THE WHOLE ACCIDENT. I WENT TO THE DOCTOR AND WAS ISSUED THREE DAYS OF MC FOR NECK AND BODY PAIN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WILL UPLOAD VIDEO INTO MERIMEN ONCE INSURED SEND

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKL8072X

Vehicle Make/Model/Colour FORD/MONDEO 2.3 AUTO 4DR/WHITE

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver	MIKHAIL BIN AZHARI
NRIC/Passport Number	S9832602B
Contact Number	86880876
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC6463Y
Vehicle Make/Model/Colour	KIA/OPTIMA 1.7(A) DIESEL/SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SOH YEE CHOW, BENJAMIN (SU YICHAO)
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLA9508X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misstatement or omission may constitute an offence under the Insurance Act.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the Insurers of the GIA for archiving and that copies of this report will for a fee be made available upon request.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the Insurers' Records Management Centre.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that my insurer (collectively the "Personal Information") and any other personal information provided by me (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers of the GIA involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident (all Insurers) for the purpose(s) of processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim.
 - (b) I understand that my insurer (collectively the "Personal Information") and any other personal information provided by me (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers of the GIA involved in this accident (all Insurers) for the purpose(s) of processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim.
 - (c) I understand that my insurer (collectively the "Personal Information") and any other personal information provided by me (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers of the GIA involved in this accident (all Insurers) for the purpose(s) of processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim.
 - (d) I understand that my insurer (collectively the "Personal Information") and any other personal information provided by me (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers of the GIA involved in this accident (all Insurers) for the purpose(s) of processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim.

VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time _____ Driver's Signature (if driver is not the policyholder) / Date & Time _____

Witnessed by Reporting Centre
Personnel

Sketch Plan

PIE CHANG	→ SLA9508X
→ SKL8072X	
→ SHCG463Y	

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999



1/20180912/2049
T of 4
Report No: T20180912/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
12/09/2018 11:43

Vide Report No:

Station Diary No.
39

Informant's Particulars

Name of Informant:
SOH YEE CHOW, BENJAMIN

Address:
APT BLK 169C PUNGGOL FIELD #09-671 SINGAPORE
823169

Contact No.:
Home/Office: Mobile: 97661852

ID Type / ID No:
NRIC NO / S7917318E

Email:

Nationality:
SINGAPORE CITIZEN

Type of Informant:
Driver

Sex: Male Age: 39 Date of Birth: 28/05/1979

Institution / School Name:

Race:
Chinese

Language:
English

Occupation:
Cabin attendant/steward

Driving Licence Information:
Class: 3 Date of Expiry:

General Information of the Accident

Type of Accident:
Injury Others

Drink Drive:
No

Date/Time of Accident:
11/09/2018 18:50

Type of Location:
Straight Road

Location:
Along Road 1
PAN ISLAND EXPRESSWAY

Towards ECP before exit 17

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
One Way

Traffic Control:
Not Controlled

Traffic Volume:
Moderate

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC6463Y	Taxi	KIA		Silver		0
SKL8072X		FORD	MONDEO	White		1
SLA9508X	Car	MERCEDES BENZ	A180 FL STYLE (R17 HLG)	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Panjang N.P.C.
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

CONTINUATION OF REPORT



T/20180912/2049

2 of 4

Report No. T/20180912/2049

Details of Vehicle Insurance		Insurance No	Effective	Expiry Date
Vehicle No	Insurance Company	DMPPHQ18-001352	23/03/2018	22/03/2019
SLA9508X	EQ INSURANCE COMPANY LTD			

Details of Person Involved		Use of Pedestrian Crossing	
Any Pedestrian Involved: No		NA	
No. of Pedestrians Injured: NIL			
Driver Name	MIKHAIL BIN AZHARI	ID No	S9832602B
Related Vehicle	SKL8072X	Contact No	86880876
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver		ID No	
Name	SOH YEE CHOW, BENJAMIN	S7917318E	
Related Vehicle	SLA9508X (Car)	Contact No	97661852
Hospital/Clinic	HEALTHCARE MEDICAL @ RAILMALL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	12/09/2018	Date Discharge	12/09/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

on the 11/09/2018 at around 1850hrs, I was driving my vehicle SLA9508X Mercedes(White) along PIE fastest lane towards ECP. As I was approaching exit 17, one car white Kia(SLW6324M) in front of mine, suddenly applied emergency brakes. I had to stop my car and manage to avoid hitting onto SLW6324M. SLW6324M then drove off. Suddenly, I felt a an impact from the rear of my vehicle. I exited my car and discovered that a white Ford(SKL8072X) knock into the rear of my vehicle. I exited my car and cab SHC6463Y that hit on to SKL8072X's rear.

As soon as the accident happened, two Chinese ladies ran from the side of the road across the expressway to render assistance and asked if we needed help. Another car SJS5420A, a black Honda Jazz also stopped and render assistance. We suddenly had people offering help, claiming that they have tow trucks and workshops readily available.

I wish to say that no one was conveyed via the ambulance and we all managed to drive of after exchanging contact details. I have a front and rear CCTV recording of the whole accident. From the

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20180912/2049

3 of 4

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No: T/20180912/2049

CONTINUATION OF REPORT

accident, it did capture that the white ford managed to stop in tie behind me but the taxi was the one who caused the whole accident.

I went to the doctor and was issued three days of MC for neck and body pain.

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999



T/20180912/2049

4 of 4

Report No. T/20180912/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Staff Sgt CHAN WAI HONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN

ABDULLAH

Contact No: 65476367

Authentication Stamp

Signature

Signature

Singapore Police Force

Signature Of Informant:

Date/Time:

12/09/2018 11:43

Classification Of Case:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA9508X

Soh Yee Chow, Benjamin (su Yichao)

Blk 169c Punggol Field
#09-671
Singapore 823169

86111115

Vehicle & Document Information

WIP No 26843
Reg No/Reg Date SLA9508X / 23/03/2016
Date In/Mileage / 0
Chassis No WDD1760422J439185
Engine No 27091030894044
Make/Model MB/MB A 180 (W176) "STYLE"
Colour/Trim 026 650 Calcit Whit/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator
WCV24474	CRDVCH	12/09/2018/ 15:13	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request
M BPNSUN
POLICY NO/ACC DATE : DMPHQ18-001352 // 11/09/2018
DRIVE IN/TP VEHICLE NO. : 12/09/2018 // SKL8072X - CHINA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M REAR BUMPER

M LH/ REAR BUMPER MOUNTING RAIL

M RH/ REAR BUMPER MOUNTING RAIL

M REAR BUMPER LOWER CHROME

M REAR BUMPER LOWER TRIM

M LH/ BASIC MOUNTING FOR BUMPER

M RH/ BASIC MOUNTING FOR BUMPER

M REAR CROSS MEMBER

M CTR/ BASIC MOUNTING FOR BUMPER

M SPACER RING

M REAR DISTANCE SENSOR

1.00	1275.24	00.00
1.00	23.43	00.00
1.00	23.43	00.00
1.00	127.76	00.00
1.00	221.21	00.00
1.00	47.75	00.00
1.00	47.75	00.00
1.00	454.00	00.00
1.00	104.42	00.00
2.00	6.42	00.00
1.00	172.07	00.00

960 1920.00

600 960.00

0.10 380.00

120.00

de 1275.24

? 23.43

? 23.43

aut 127.76

aut 221.21

? 47.75

? 47.75

? 454.00

? 104.42

wh 12.84

? 172.07

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify

Confirmed & accepted by the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Supplementary item(s) must be resurveyed and

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA9508X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

26843

SLA9508X / 23/03/2016

01/10/2018 / 40971

WDD1760422J439185

27091030894044

MB/MB A 180 (W176) "STYLE"

026 650 Calcit Whit/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	04/10/2018/ 17:36	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BRUNSON

POLICY NO/ACC DATE : DMPHQ18-001352 // 11/09/2018

DRIVE IN/TP VEHICLE NO. : 12/09/2018 // SKL8072X - CHINA

DATE IN/DATE SURVEY: 01/10/2018 1515 // LKK - TAUFIKH

DIRECT SETTLEMENT : 19/09/2018 // CHINA - CATHERINE

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

X REAR BUMPER LOWER CHROME

X SPACER RING

X REAR BUMPER LOWER TRIM

A REAR BUMPER TRIM STRIP

960.00

600.00

0.10

380.00

120.00

1.00 1275.24 00.00

1275.24

1.00 127.76 00.00

127.76

2.00 6.42 00.00

12.84

1.00 204.21 00.00

cut 204.21

1.00 140.03 00.00

cut 140.03

Finalization

Confirmed & accepted by

Nett 3,820.08
7% GST on 3820.08 267.41
Total Payable 4,087.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA9508X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 26843
Reg No/Reg Date SLA9508X / 23/03/2016
Date In/Mileage 01/10/2018/ 40971
Chassis No WDD1760422J439185
Engine No 27091030894044
Make/Model MB/MB A 180 (W176) "STYLE"
Colour/Trim 026 650 Calcit Whit/ 044 471 ARTICO/Fabr

SLA9508X

Account No	Terms	Date/Time Printed	CSE	Operator		
WC000668	Credit	04/10/2018/ 17:35	K0	301 / Kerlyn Ong		
		Description of Goods / Services	Qty	Unit Price	Disc%	Amount

X REAR BUMPER LOWER TRIM
A REAR BUMPER TRIM STRIP

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 344.24**
344.24 24.10
Total Payable 368.34

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016826/T1VBN2

Date: 11/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMPCSN3100151801

Claimant Vehicle No: SLA9508X

Insured Vehicle No: SKL8072X

Date of Loss: 11/09/2018

Nature of Claim: TP

Claim No: SNM18D04426C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA9508X

Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A)

Engine No: 27091030894044

Reg. Date: 23/03/2016 (Man. Year: 2015)

Chassis No: WDD1760422J439185

Colour: White

Odometer: 40971 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size: 225/40R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,854.14	1,760.08	1,094.06	38.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,060.00	1,320.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,234.14	3,820.08	2,414.06	38.72
+ GST 7.00/7.00% (S\$)	436.39	267.41	168.98	38.72
Nett Amount (S\$)	6,670.53	4,087.49	2,583.04	38.72

INSPECTION

Date of Assignment: 14/09/2018

Date Inspected: 01/10/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts:	144	MERCEDES-BENZ A180 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA9508X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,275.24 FS	*1,275.24 FS
2	1		*LH/REAR BUMPER MOUNTING RAIL	Not Necessary	23.43 FS	*- FS
3	1		*RH/REAR BUMPER MOUNTING RAIL	Not Necessary	23.43 FS	*- FS
4	1		*REAR BUMPER LOWER CHROME	Cut	127.76 FS	*127.76 FS
5	1		*REAR BUMPER LOWER TRIM	Not Necessary	221.21 FS	*- FS
6	1		*LH/BASIC MOUNTING FOR BUMPER	Not Necessary	47.75 FS	*- FS
7	1		*RH/BASIC MOUNTING FOR BUMPER	Not Necessary	47.75 FS	*- FS
8	1		*REAR CROSS MEMBER	Not Necessary	454.00 FS	*- FS
9	1		*CTR/BASIC MOUNTING FOR BUMPER	Not Necessary	104.42 FS	*- FS
10	2		*SPACER RING	Necessary	12.84 FS	*12.84 FS
11	1		*REAR DISTANCE SENSOR	Not Necessary	172.07 FS	*- FS
12	1		*REAR BUMPER LOWER TRIM	Cut	204.21 FS	*204.21 FS
13	1		*REAR BUMPER TRIM STRIP	Cut	140.03 FS	*140.03 FS
Total Parts (S\$)					2,854.14	1,760.08

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY REAR BUMPER	New	960.00	600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (S\$)			3,380.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >