

22/03/2018

ASS. REC. BY:

REF:

CS/CT118016878 / Rlvbn2

Special Instruction:

Survivor:

Mentor

**ASSIGNMENT (Office)**

From (Person):

Joelyn Tay

of

CT

Date/Time:

14/09/2018 1:39pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 528Y

Insured:

GBH 3843Z

at Workshop m/s

Trans Tunokars

Tel:

9111 7463

of

B Ubi (10SL)

Policy No:

DMCVSN 1818 271800

Claim No:

SNM18DU4301C02.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02092018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

14/09/2018

Person Contacted:

Vin

Vehicle IN / OUT

Date/Time

Action/Instruction ( ☒ ) Estimate

SLT 528Y - X

GBH 3843Z - X

22/11/18


Final fig \$5012.54 confirmed by email (Red 1702.56, 25/10)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SLT 5284  
 at Workshop m/s TRANS EUREKARS  
 of 27A, Panjank Pkwy Juvet  
 Insured: CTI  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLT 5284 Yr Regn: 2017 / OLT  
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: MAZDA SHAGON 2.0AT c.c. 1998  
 Colour: GRY A/C: Insured / Std / NI / NA  
 Sp. Reading: 24056 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: 3M6CW1071H0127507

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
☒ YOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>02/09/18</u>	D.O.I. <u>17/10/18</u>

Survey held at TRANS EUREKARS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 NOV 2018

22/11/2018

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) 23/11 - typist

Report Format : merimen

Lump Sum / I.B.I. (\$) 5012.54

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Ins Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2018		14 Sep 2018 13:39 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	SKYLINK VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201710755G								
Main Claimant:	PENG CHENN HOAU, ID: S7508286Z								
Vehicle Reg. No.:	SLT528Y	Date of Loss:	02/09/2018 10:00 - :59						
Claim Type:	TP / SNM18D04301C02	Policy/Cover Note No.:	DMCVSN1818271800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH3843Z	Policy No. (Claimant):	1700075759						
		Excess:	S\$0.00						
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 25/09/2018]</b>								
Driver/Custodian (Insured):	YIP HAN WEI, VINCENT (29 / Male), NRIC: S8852106D, Tel: +6597304633								
Adj Asg. Remarks:	EST \$6715.10, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** vion.lim@eurokars.com.sg  
**Sent:** Monday, 12 November 2018 2:56 PM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** RE: PENDING FINALISE

Hi Veron,

Vehicle has just completed repairs last week. We will finalise asap once my side has gone thru the file.  
Thank you.

Best Regards.



**Vion Lim**

Insurance Claims Officer

### EUROKARS SERVICES PTE LTD

27A Tanjong Penjuru, Singapore 609042

D: (65) 6331 0684 H: (65) 9111 7463

E: [vion.lim@eurokars.com.sg](mailto:vion.lim@eurokars.com.sg)

Website: [www.eurokars.com.sg](http://www.eurokars.com.sg)

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** 12 November 2018 2:53 PM  
**To:** Vion Lim <vion.lim@eurokars.com.sg>  
**Subject:** PENDING FINALISE

Dear Vion,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

<u>Vehicle</u>	<u>DOA</u>
1) SLT528Y	2/9/18-CHINA TAIPING TP
2) SLW 4589D	21/9/18-CHINA TAIPING TP

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 22 November 2018 1:59 PM  
**To:** Mei Kwan (LKKAuto); catherinechua@eurokars.com.sg  
**Cc:** 'vion.lim@eurokars.com.sg'; SUR  
**Subject:** RE: SLT528Y - FINALISATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm COR: \$5012.54 before GST @4 repair days

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Wednesday, 21 November 2018 7:27 PM  
**To:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** FW: SLT528Y - FINALISATION OF COR

CS/CTI18016828/R1vb

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg) <[catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg)>  
**Sent:** Wednesday, 21 November, 2018 4:29 PM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** [vion.lim@eurokars.com.sg](mailto:vion.lim@eurokars.com.sg); CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** SLT528Y - FINALISATION OF COR

Dear Rasul

Our COR computation and B4 paint photos are attached for your agreement.

COR: \$5012.54 before GST

4 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards  
Catherine Chua  
Insurance Claims Executive  
Trans Eurokars Pte Ltd  
DID: 6603 6121  
FAX: 6476 7417

*This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

**From:** [mazdacanone@mazda.com.sg](mailto:mazdacanone@mazda.com.sg) <[mazdacanone@mazda.com.sg](mailto:mazdacanone@mazda.com.sg)>  
**Sent:** 21 November 2018 2:22 PM  
**To:** Catherine Chua <[catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg)>  
**Subject:** Attached Image

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 09:23
Date Of Accident	02/09/2018 10:45
Exact Location Of Accident	CARPARK @ GHIM MOH MARKET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT528Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PENG CHENN HOAU
NRIC No	S7508286Z
Email Address	HP90667767@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90667767
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 5 DR WAGON (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700075759
Cover Note Number	

### Driver

Name of Driver	PENG CHENN HOAU
NRIC No	S7508286Z
Date Of Birth	12/03/1975
Occupation	INDOOR
Date Of Driving Pass	25/10/1994
Driving Experience	23 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90667767
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	HP90667767@GMAIL.COM

Address	BLK 212 JURONG EAST STREET 21 #25-289
Postcode	600212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3843Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YIP HAN WEI VINCENT
NRIC/Passport Number	S8852106D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO:

ACCIDENT DATE: 02 SEP 2018

CONTACT NUMBER: 90667767

ACCIDENT TIME: 1045 hrs.

EMAIL: hp90667767@gmail.com

LOCATION: Carpark at Ghim Moh Market

The incident happened while I was following a truck, QBH 3843 Z, to go out of the carpark. At a turn just before the exit, the truck suddenly reverse without warning. I horned but it was too late. The truck hit the front right of my car.

The driver, YIP HAN WEI VINCENT 88852106 D, admit his mistake and offered private settlement.


NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ REPORTING ONLY

### DECLARATION


I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:

3/9/18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



TRANS EUROKARS PTE LTD  
NO:5 UBI CLOSE, SINGAPORE 408605  
ESTIMATE COST OF REPAIRS



(TP)

CHINA TAIPING INSURANCE P/L		NAME : Mr Peng Chenn Hoau		WIP : 22609	
3 ANSON ROAD		ADDRESS : 212 Jurong East Street 21		EXCESS :	
#16-00 SPRINGLEAF TOWER		#25-289		DATE: 13-Sep-18	
SINGAPORE 079909		Singapore 600212			
ATTN : MOTOR CLAIMS		TEL : 90667767			
FAX :					
VEH NO :	SLT528Y	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6CW1071H0127507	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	16-Oct-17	POLICY NO. :	

**NATURE OF WORKS**

**Parts Description**

NO	QTY	REVISED	PRICES
1	FRONT BUMPER <i>re-</i>	1	MC513-50-031BBB \$ 1,055.40 ✓
2	RETAINER RHS <i>X</i>	1	MC513-50-0T1B \$ 20.50 ✓
3	BRACKET RHS <i>X</i>	1	MC513-50-151A \$ 40.20 ✓
4	COVER RHS, FOGLAMP <i>cut</i>	1	MC513-50-C11 \$ 74.40 ✓
5	CLIP, FRONT BUMPER <i>re-</i>	10	MC274-50-133 \$ 35.00 ✓
6	RIVET, FRONT BUMPER <i>re-</i>	4	MEA01-50-037 \$ 30.40 ✓
7	RIVET, FRONT BUMPER <i>re-</i>	4	MBN8F-50-355 \$ 21.60 ✓
8	GROMMET, FRONT BUMPER <i>re-</i>	2	MC513-50-0T5A \$ 30.80 ✓
9	FRONT FENDER RHS <i>repair</i>	1	MCG37-52-111 \$ 307.00 ✓
10	STAY RHS, FENDER <i>X</i>	1	MC513-52-140 \$ 30.50 ✓
11	MUDGUARD RHS <i>X</i>	1	MC513-56-130B \$ 200.40 ✓
12	FASTENER, MUDGUARD <i>X</i>	15	MB45A-56-146A \$ 42.00 ✓
13	HEADLAMP RHS <i>CRA</i>	1	MC513-51-0K0F \$ 1,411.40 ✓
14	CLIP, HEADLAMP <i>re-</i>	3	MDR61-50-133 \$ 18.30 ✓
15	RIVET, HEADLAMP <i>re-</i>	1	MB092-51-833 \$ 3.30 ✓
16	WASHER TANK <i>? X</i>	1	MBBN9-67-480A \$ 217.80 ✓
TOTAL PARTS			\$ 3,539.00
LESS 10%			\$ 353.90
TOTAL PARTS COST			\$ 3,185.10

**Labour Description**

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	990 \$ 1,320.00 ✓
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.	\$ 1,260.00 ✓
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X \$ 250.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	20 NETT	\$ 100.00
			net	
TOTAL LABOUR			\$ -	\$ 3,530.00
TOTAL PARTS			\$ -	\$ 3,185.10
TOTAL			\$ -	\$ 6,715.10
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
Authorised Signature

254L  
Hp 90010068  
4 days  
17/10/18 @ 1540  
Resy 54 paint  
18/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIRS**



(TP)

<b>CHINA TAIPING INSURANCE P/L</b>		<b>NAME :</b> Mr Peng Chenn Hoau		<b>WIP :</b> 22609	
3 ANSON ROAD		<b>ADDRESS :</b> 212 Jurong East Street 21		<b>EXCESS :</b>	
#16-00 SPRINGLEAF TOWER		#25-289		<b>DATE:</b> 13-Sep-18	
SINGAPORE 079909		Singapore 600212			
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b> 90667767			
<b>FAX :</b>					
<b>VEH NO :</b>	<b>SLT528Y</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	Vion 63957877
<b>CHASSIS NO :</b>	JM6CW1071H0127507	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MAZDA5	<b>DATE REG.:</b>	16-Oct-17	<b>POLICY NO. :</b>	

**NATURE OF WORKS**

Parts Description			REVISED	PRICES
NO	QTY			
1	FRONT BUMPER	1	MC513-50-031B8B	\$ 1,055.40 \$ 1,055.40
2	RETAINER RHS	1	MC513-50-0T1B	\$ 20.50
3	BRACKET RHS	1	MC513-50-151A	\$ 40.20
4	COVER RHS, FOGLAMP	1	MC513-50-C11	\$ 74.40 \$ 74.40
5	CLIP, FRONT BUMPER	10	MC274-50-133	\$ 35.00 \$ 35.00
6	RIVET, FRONT BUMPER	4	MEA01-50-037	\$ 30.40 \$ 30.40
7	RIVET, FRONT BUMPER	4	MBN8F-50-355	\$ 21.60 \$ 21.60
8	GROMMET, FRONT BUMPER	2	MC513-50-0T5A	\$ 30.80 \$ 30.80
9	FRONT FENDER RHS	1	MCG37-52-111	\$ 307.00
10	STAY RHS, FENDER	1	MC513-52-140	\$ 30.50
11	MUDGUARD RHS	1	MC513-56-130B	\$ 200.40
12	FASTENER, MUDGUARD	15	MB45A-56-146A	\$ 42.00
13	HEADLAMP RHS	1	MC513-51-0K0F	\$ 1,411.40 \$ 1,411.40
14	CLIP, HEADLAMP	3	MDR61-50-133	\$ 18.30 \$ 18.30
15	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30 \$ 3.30
16	WASHER TANK	1	M8BN9-67-480A	\$ 217.80
<b>TOTAL PARTS</b>			<b>\$ 2,680.60</b>	<b>\$ 3,539.00</b>
<b>LESS 10%</b>			<b>\$ 268.06</b>	<b>\$ 353.90</b>
<b>TOTAL PARTS COST</b>			<b>\$ 2,412.54</b>	<b>\$ 3,185.10</b>

**Labour Description**

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 990.00	\$ 1,320.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.	\$ 1,260.00	\$ 1,260.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00

5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 2,600.00	\$ 3,530.00
TOTAL PARTS			\$ 2,412.54	\$ 3,185.10
TOTAL			\$ 5,012.54	\$ 6,715.10
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 5,012.54	
GST 7%			\$ 350.88	\$ -
GRAND TOTAL			\$ 5,363.42	\$ -

**REMARKS:**

**4 REPAIR DAYS** (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016828/R1VBN2

Date: 26/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1818271800
Claimant Vehicle No :	SLT528Y	Insured Vehicle No :	GBH3843Z
Date of Loss:	02/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04301C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLT528Y	Engine No:	PE10541114
Make & Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Chassis No:	JM6CW1071H0127507
Reg. Date:	16/10/2017 (Man. Year: 2017)	Odometer:	24056 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,285.10	2,432.54	852.56	25.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,580.00	850.00	24.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,715.10</b>	<b>5,012.54</b>	<b>1,702.56</b>	<b>25.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>470.06</b>	<b>350.88</b>	<b>119.18</b>	<b>25.35</b>
<b>Nett Amount (S\$)</b>	<b>7,185.16</b>	<b>5,363.42</b>	<b>1,821.74</b>	<b>25.35</b>

## INSPECTION

Date of Assignment:	14/09/2018	
Date Inspected:	17/10/2018	Inspected At:
		Trans Eurokars Pte Ltd (Sungei Kadut)
		12 Sungei Kadut Ave
		Singapore 729648
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 26 Nov 2018)	
<b>Parts:</b>	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT528Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,055.40 FL	*1,055.40 FL
2	1		*RETAINER RHS	Not Necessary	20.50 FL	*- FL
3	1		*BRACKET RHS	Not Necessary	40.20 FL	*- FL
4	1		*COVER RHS,FOGLAMP	Cut	74.40 FL	*74.40 FL
5	10		*CLIP,FRONT BUMPER	Necessary	35.00 FL	*35.00 FL
6	4		*RIVET,FRONT BUMPER	Necessary	30.40 FL	*30.40 FL
7	4		*RIVET,FRONT BUMPER	Necessary	21.60 FL	*21.60 FL
8	2		*GROMMET,FRONT BUMPER	Necessary	30.80 FL	*30.80 FL
9	1		*FRONT FENDER RHS	Repair	307.00 FL	*- FL
10	1		*STAY RHS,FENDER	Not Necessary	30.50 FL	*- FL
11	1		*MUDGUARD RHS	Not Necessary	200.40 FL	*- FL
12	15		*FASTENER MUDGUARD	Not Necessary	42.00 FL	*- FL
13	1		*HEADLAMP RHS	Cracked	1,411.40 FL	*1,411.40 FL
14	3		*CLIP,HEADLAMP	Necessary	18.30 FL	*18.30 FL
15	1		*RIVET,HEADLAMP	Necessary	3.30 FL	*3.30 FL
16	1		*WASHER TANK	Not Necessary	217.80 FL	*- FL
17	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,639.00</b>	<b>2,700.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>353.90</b>	<b>268.06</b>
<b>Total Parts (\$\$)</b>	<b>3,285.10</b>	<b>2,432.54</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER AND FRONT FENDER RH.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,320.00	990.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH	New	1,260.00	1,260.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	-
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			3,430.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >