

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC7226E180909

Estimate

Customer

Name: India International Insurance Pte Ltd

Address: Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building Singapore 049711

Date: 13-09-18

Vehicle No: GBC7226E

Model/Make: Fiat Doblo Cargo

Maxi 1.6 MJ Diesel (Glazed)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear the Bumper 745	\$ 1,245.50	✓
2	Rear Bumper Clips 1 set 102	\$ 65.00	✓
3	Rear Fender 115	\$ 780.00	α
4	Rear Hub-Cab 115	\$ 225.00	SN
5	Rear bumper reinforcement 475	\$ 496.90	✓
6	1 set Rear reverse sensor 700	\$ 400.00	SN 2005. ✓
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 800.00	500
To putty & spray painting & including touch up paint on accident affected areas		\$ 800.00	600
To apply Rust Proofing, reseal tuff-coating treatment on accident area		\$ 60.00	x
To remove, replace and transfer REVERSE SENSOR		80.00	50

Total Parts & Labour of estimate for damaged vehicle

\$ 4,652.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Authorized
LKK
L/s 2000/-
14/9/18
take photo After repair
4 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: