

Confirmed on 25/09/2018



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKK2393P
Date of Accident : 13 September 2018

Messrs Tran-Sports Alliance

Date : 13 September 2018

Estimate To Repair SKC3871L - Hyundai Elantra 1.6GLS
Chassis No : KMHDH41CMCU221693

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	right rear door <i>30150</i>	\$ 1,208.00
02	1 pc	right rear door window frame tape front <i>me</i>	\$ 27.00
03	1 pc	right rear door window frame tape rear <i>me</i>	\$ 27.00
04	1 pc	right rear door window frame tape top <i>me</i>	\$ 27.00
05	1 pc	right rear door window glass outer weatherstrip moulding <i>11</i>	\$ 88.00
06	1 pc	right rear door window glass channel weatherstrip <i>11</i>	\$ 115.00
07	1 pc	right rear door power window motor <i>11</i>	\$ 297.00
08	1 pc	right rear door regulator <i>11</i>	\$ 251.00
09	1 pc	right rear door inner lock <i>11</i>	\$ 191.00
10	1 pc	right rear door inner lock striker <i>11</i>	\$ 25.00
11	1 pc	right rear door weatherstrip <i>me</i>	\$ 112.00
12	1 pc	right rear fender <i>30150</i>	\$ 1,768.00
13	1 pc	right rear fender inner liner <i>De</i>	\$ 114.00
14	6 ps	right rear fender inner liner clips @ \$5.00 <i>me</i>	\$ 30.00
15	1 pc	right rear fender air vent <i>11</i>	\$ 29.00
16	1 pc	rear windscreen glass moulding <i>11</i>	\$ 145.00
17	1 pc	rear bumper <i>Deep cut</i>	\$ 459.00
18	1 pc	right rear bumper side retainers <i>11</i>	\$ 26.00
19	10 ps	rear bumper clips @ \$5.00 <i>me</i>	\$ 50.00
20	1 pc	right rear bumper end splashshield cover <i>11</i>	\$ 38.00
21	1 pc	right rear shock absorber <i>11</i>	\$ 291.00
22	1 pc	right rear wheel bearing with hub <i>11</i>	\$ 155.00
23	1 pc	rear axle beam assy <i>11</i>	\$ 978.00
			\$ 6,451.00
Less 20 %			\$ 1,290.20
			\$ 5,160.80
<u>SPECIAL NETT ITEMS</u>			
24	1 pc	rear windscreen glass sealant <i>11</i>	\$ 120.00
25	1 pc	rear windscreen glass inner sponge seal <i>11</i>	\$ 80.00
26	1 pc	right rear wheel rim <i>cut</i>	\$ 650.00
27	1 pc	right rear wheel tyre <i>Sn</i>	\$ 400.00
			\$ 1,250.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of right rear door fittings and perform water seepage test.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 200.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00

not allowed
nhr
25/9/18
1/5 \$3900/
the photo after repair
4h.

L44 - Marcus

25/09/18 009236h

3822
3057.60

X
X
300
X

60
60
80



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKK2393P
Date of Accident : 13 September 2018

Messrs Tran-Sports Alliance

Date : 13 September 2018

Estimate To Repair SKC3871L - Hyundai Elantra 1.6GLS
Chassis No : KMHDH41CMCU221693

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
04		To check steering geometry and computer wheel alignment.	\$ 150.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		To check electrical lighting concerned.	\$ 60.00
07		To remove and refit rear windscreen glass.	\$ 11 180.00
08		To transfer of tyre, rim and on wheel balancing.	\$ 11 60.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
10		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 3,080.00
		Total	\$ 9,490.80

60
40
20
X
X
600
600
1520
4877.6

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: