



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



MAXUS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Instamart Pte. Ltd.
	Reg No/Reg Date	GBG2849U / 03/07/2017
	Date In/Mileage	12/09/2018/ 0
	Chassis No	LSKG4GL10HA410037
	Engine No	19D4N1PYGB01K052
	Make/Model	MAXCV/G10D19TMT
	Colour/Trim	GRY / BK Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	13/09/2018/ 16:23	DS	218 / MarsLer	64936

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS		60		80.00
S MIPNT88088 DIAGNOSTIC / SCANNING		11	X	250.00
S MIPNT88088 TO REPLACE FRONT BUMPER,RH HEADLAMP.RHF FENDER,ETC STRAIGHTEN REFORM,ALIGN ON RH SIDE ACCIDENT AFFECTED AREAS	600	1200		2400.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL		100		200.00
S MIPNT98088 SPRAY PAINTING ON RH SIDE & FRT ACCIDENT AFFECTED AREAS	420	1470		2100.00
P NC00071562 FASCIA-FRT BPR(W/ LP	1.00	437.00	0.00	437.00
P NC00061663 PLUG-HDLP WASHING ME	1.00	6.00	0.00	6.00
P NC00018087 BRACKET-HDLP WASHING	1.00	11.00	0.00	11.00
P NC00037358 PANEL-FRT FOGLIGHT R	1.00	10.00	0.00	10.00
P NC00018122 ABSORBER-FRT BPR ENG	1.00	42.00	0.00	42.00
P NC00024454 SUPPORT-BUMPER FRT	1.00	6.00	0.00	6.00
P NC00024453 SUPPORT-BUMPER FRT	1.00	6.00	0.00	6.00
P NC00056664 HEADLAMP RH	1.00	1652.00	0.00	1652.00
M NC00036428 LAMP-FRT FOG	1.00	69.00	0.00	69.00
P NC00070693-4100 FENDER-FRT RH	1.00	376.00	0.00	376.00
M NC00028358 PANEL-FDR INSULATOR	1.00	8.00	0.00	8.00
M NC00027161-4100 BRACKET ASM-FDR MOUN	1.00	15.00	0.00	15.00
P NC00073482 RHF WHEEL SHIELD LIN	1.00	70.00	0.00	70.00
Z NOTES ACCIDENT ON 12/09/2018 ALONG TAMPINES BLOCK 838 STREET 82 OPEN CARPARK OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP # GBD6944S TP INS : CHINA TAIPING				

LKK Auto Consultants hence notify
the Repairer of the following:

Confirm & accepted by To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Parts	2,708.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,030.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	7,738.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.