

Insured:

Mappens

DOB:

ASSIGNMENT

1/19/18

Date / Time:

14/9/2018

Registered in Merit:

Pre-assign / CCU / FTE

SJN 47768



Insured Vehicle No.

Name of Insured

PATRICK CHEAH POH JIN

Insured Tel No.

HP:

Excess Sec II : S5

DQA:

12/9/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Quah Lyming.

Driver Tel No.:

91069028

(V/L: YES / NO)

Claim No.

Policy No.

DMPPH218-00849

Make / Model:

T-AXIO.

Place of Accident:

East Coast Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

Sme7094M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah Motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

2/9/18 @ 11.32am Called OI, Mr Quah. Not pick up (x2).

12/12/18

- TV VIDEO IN. V DRIVE / VIO / SMC7094M
 - OI/OI OFFER & BULK TO OI TO NOTIFY
 - IF CLAIM & NOB 169088.

- MINACRED:

- IF LOD IN BY BULK

12/12/18

- OI/OI APPROVE BULK TO IF.
 - NO BU PRODUCE. ALL BOOS IN
 ORDER.

TO CLOSE RECEIVED 14 DEC 2018

PRELIMINARY ADVICE

Date/Time:

24/08/18

Sent By:

23

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$ 5,521.76

5

days

Reduction:

28

%

FINAL SETTLEMENT

Date/Time:

12/12/18

Confirm with:

PHONE

Email:

Call:

Final Liability:

%

100

(A/Red / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/gov)

S\$ 5,908.50

Loss of Rental (LOR):

(w/gov)

S\$ 535.00

5

days

x

\$100.00

Loss of Use (LOU):

S\$

—

(\$

x

days)

Loss of Income (LOI):

S\$

—

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

—

Medical:

S\$

—

Disbursement:

S\$

—

Legal Cost

S\$

—

Total:

S\$

6,443.50

Global Sum S\$:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

6,443.50

Name 1:

KAH MOTOR CO.

Name 2:

Name 3:

Payee 2: (Strike if N.A.)

S\$

—

Payee 3: (Strike if N.A.)

S\$

—

Name 1:

Name 2:

Name 3:

Name 4:

Name 5:

Name 6:

Name 7:

Name 8:

Name 9:

Name 10:

Name 11:

Name 12:

REF: TOL

ASSIGNMENT

From: Date: 17092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 7094M

at Workshop m/s: Kuch motor
of: 15 ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Lim

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

L1A38878

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMC 7094M Yr Regn: 7 18

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda HR-V C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 4484 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU1810GX204309

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 12/9/18 D.O.I. 17/9/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$5,921.78
C/P: \$5,502.10 (38%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS)

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18016834/Uha3

Date: 17.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SMC 7094M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.09.2018 at the premises of M/s Kah Motor Co Sdn Bhd (Ubi) have the following to report:-

Workshop Estimate Amount	: S\$	9,023.88
Revised Estimate Amount	: S\$	5,748.06
"Check" Items Amount	: S\$	852.47
Total (Including Check Items)	: S\$	6,600.53
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly help to arrange
surveyor to survey the
vehicle. Thanks.

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer	EQ INSURANCE COMPANY LTD	Document No.	SQT18003844	Page	1
	5 MAXWELL ROAD	Date	12. Sep 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	WZE011		
	SINGAPORE 069110	Svc Advisor	LIM CHOU SIONG		
Registration No	SMC7094M	Engine No	L15B4534307		
Chassis No	JHMRU1810GX204309	Date Time	12. Sep 2018 6:34:04 PM		
Model	HRV DX-SIN CVT YM 2016	Surveyor Name			
Owner's Name	KELVIN YAP FOOK KEONG	Survey Date			
Ins Policy No.		Authorisation Date			
Date of Accident	12/9/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (JINO)						
	OWNER: KELVIN YAP FOOK KEONG						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 12/9/2018						
	SURVEYED BY						
	DATE						
	REF NO:						
	TP INSURER: EQ INSURANCE COMPANY LTD						
	TP VEH: SJN4776B						
73214-T7J-H01	RUBBER CR WINDSHIELD DAMPER <i>nee</i>	1	19.30	25	14.47	1.01	15.48
73225-SZW-000	DAMPERSTD 5X5 <i>nee</i>	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL WINDSHIELD DAMPER <i>nee</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>nee</i>	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD <i>nee</i>	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B <i>nee</i>	2	4.90	25	7.35	0.51	7.86
91536-S50-J01	FASTENER AW/SHIELD <i>nee</i>	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nee</i>	2	60.00		120.00	8.40	128.40
68100-T7A-J20Z2	TAIL GATE COMP <i>Body D</i>	1	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE <i>11</i>	1	96.80	25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE <i>11</i>	1	76.60	25	57.45	4.02	61.47
74813-T5A-003	STRIKER ASSYTAILGATE <i>11</i>	1	24.70	25	18.52	1.30	19.82
84431-T7A-J01ZA	LINING ASSYTAILGATE <i>11</i>	1	133.40	25	100.05	7.00	107.05
84441-S2K-000ZB	POCKETTAILGATE PULL <i>11</i>	1	14.90	25	11.17	0.78	11.95
75722-T7W-A01	EMBLEMRR <i>nee</i>	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM.RR. I-VTEC <i>nee</i>	1	14.10	25	10.57	0.74	11.31
75701-T5A-000	EMBLEMH <i>nee</i>	1	10.70	25	8.02	0.56	8.58
90301-S70-003	NUTPUSH 3MM <i>11</i>	2	1.90	25	2.85	0.20	3.05
33502-T7A-J01	LAMP UNITR <i>11</i>	1	428.70	25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL <i>11</i>	1	428.70	25	321.52	22.51	344.03

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel +65 6541 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance: Call 98203838

QUOTATION

GST Reg No: M200050223

Company Ref. No: S80FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110
Registration No : SMC7094M
Chassis No : JHMRU1810GX204309
Model : HRV DX-SIN CVT YM 2016
Owner's Name : KELVIN YAP FOOK KEONG
Ins Policy No :
Date of Accident : 12/9/2018

Document No. : SQT18003844
Date : 12 Sep 2018
Customer No. : WZE011
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4534307
Date | Time : 12 Sep 2018 6:34:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
34150-T7A-J01	LIGHT ASSY R LID	1	254.60	25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSY L LID	1	254.60	25	198.45	13.89	212.34
90650-SZT-003	GROMMET RR COMBINATION LIGHT	2	2.50	25	3.75	0.26	4.01
90653-TX6-A01	CLIP RR COMBINATION LIGHT	2	1.90	25	2.85	0.20	3.05
91625-TA0-A01	GROMMET TAIL LIGHT	2	2.80	25	4.20	0.29	4.49
74890-T7A-J12ZS	GARNISH ASSY RR LICENSE	1	186.10	25	139.57	9.77	149.34
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR SENSOR	1	320.00		320.00	22.40	342.40
71501-T7B-000	FACE RR BUMPER	1	762.50	25	571.88	40.04	611.99
33555-T7A-J01	REFLECTOR ASSY RR	1	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSY LR	1	151.80	25	113.85	7.97	121.82
04717-T7A-000ZZ	FACER RR BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL RR BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
71593-T7A-000	SPACER RR BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACER LR BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP BUMPER	8	2.00	25	12.00	0.84	12.84
84840-T7A-J01ZA	LINING ASSY RR PANEL	1	43.00	25	32.25	2.26	34.51
38387-TZ5-A01	ANTENNA ASSY LF	1	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	Buzzer ASSY SMART	1	59.30	25	44.47	3.11	47.58
Sum Item					3743.88	262.07	4,005.95

BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML021	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR WINDSCREEN (N)	1	300.00		300.00	21.00	321.00
BOMISC1	REMOVE & INSTALL & RESET REAR VIEW CAMERA (N)	1	320.00		320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		320.00	22.40	342.40

Printed on 13/9/2018 7:38:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any additional charges.

GST Amount is calculated from individual items.

* Third party survey is on a "Without Prejudice" basis.
* No legal modification(s) is allowed.

* Supplementary item(s) must be authorised and is subject to final approval from Insurer's Liability.

Acknowledged by Repairer

Signature:

Date:

HONDA**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel : +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203638

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SMC7094M

Chassis No : JHMRU1810GX204309

Model : HRV DX-SIN CVT YM 2016

Owner's Name : KELVIN YAP FOOK KEONG

Ins Policy No. :

Date of Accident : 12/9/2018

Document No. : SQT18003844

Date : 12 Sep 2018

Customer No. : WZE011

Svc Advisor : LIM CHOU SIONG

Engine No : L15B4534307

Date | Time : 12 Sep 2018 5:34:04 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		350.00	250	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	1	380.00	✓	380.00	26.50	406.50
BKBU02R	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE	1	1500.00	1120	1500.00	105.00	1605.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1500.00	1350	1500.00	105.00	1605.00
Sum Labor					5280.00	369.50	5649.50

Survey By

Date & Time

Excess

Status

Signature

mercus hah
17/9/18 @ 10am

C. S. Lim
17/9/18

Total Amount 9,023.85 631.67 9,655.55

Total (Inclusive of GST) 9,655.55

not authorized

Take photo before painting
5 day.

p/p \$5521.78 confirmed.

LKK Auto Consultants hence notify the Receiver of the following:

- To resurvey deterioration spray painting
- To replace damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- For legal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Reparer

Signature:

Date:

Printed on 13/9/2018 7:38:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual lines.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480



28/9/2018 Page 1/2

SERVICE PRE-INVOICE

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

5 days

Customer: WZE011 / EQ INSURANCE
Chassis No: JHMRU1810GX204309
License No: SMC7094M
Mileage: 5781
Engine No: L15B4534307

Document No: SVO18056161
Printed By: CSLIM
Order Date: 24. September 2018
Order Time: 10:24:55 AM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71276) OWNER: KELVIN YAP FOOK KEONG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 12/9/2018 SURVEYED BY: MARCUS (L.K.K.) DATE: 17/09/2018 @ 10:00AM REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SJN47768						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73228-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-S50-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-W5-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	638.90	25	629.17	44.04	673.21
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	2	2.50	25	3.75	0.26	4.01
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	2	1.90	25	2.85	0.20	3.05
91626-TA0-A01	GROMMETTAILLIGHT	1	2.80	25	2.10	0.15	2.25
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
04716-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
	SUM PARTS:				1,251.78	87.62	1,339.40
BOSUN	0672	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BOMISC1	EXT-YJ	1	320.00		320.00	22.40	342.40
	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)						
BOMISC1	0626	1	320.00		320.00	22.40	342.40
	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)						
BMI02D	EXT-YJ	1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)						


KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 8022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5480

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE011 / EQ INSURANCE
Chassis No: JHMRU1610GX204309
License No: SMC7094M
Mileage: 5781
Engine No: L15B4534307

Document No: SVO18058181
Printed By: CSLIM
Order Date: 24. September 2018
Order Time: 10:24:55 AM
Service Advisor: LIM CHOU SIONG

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKBU02R	EXT-YJ REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE PARTS.	1	1,120.00	1,120.00	78.40	1,198.40
BP03R	EXT-YBH SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1,350.00	1,350.00	94.50	1,444.50
		SUM LABOUR:		4,270.00	296.80	4,566.80
		TOTAL SGD		5,521.78	366.52	5,908.30
		Total Payable (SGD)				5,908.30

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks.***QUOTATION**GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SMC7094M

Chassis No : JHMRU1810GX204309

Model : HRV DX-SIN CVT YM 2016

Owner's Name : KELVIN YAP FOOK KEONG

Ins Policy No. :

Date of Accident : 12/9/2018

Document No. : SQT18003844

Date : 12. Sep 2018

Customer No. : WZE011

Svc Advisor : LIM CHOU SIONG

Engine No : L15B4534307

Date | Time : 12. Sep 2018 6:34:04 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: KELVIN YAP FOOK KEONG						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 12/9/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: EQ INSURANCE COMPANY LTD						
	TP VEH: SJN4776B						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>nee</i>	1	19.30	/ 25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>nee</i>	1	6.30	/ 25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>nee</i>	1	19.30	/ 25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>nee</i>	1	4.70	/ 25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD <i>nee</i>	4	3.20	/ 25	9.60	0.67	10.27
91502-S70-003	FASTENER B <i>nee</i>	2	4.90	/ 25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD <i>nee</i>	2	3.50	/ 25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nee</i>	2	60.00	/	120.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP. <i>Body.D</i>	1	638.90	/ 25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	? 25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47
74813-T5A-003	STRIKER ASSYTAILGATE <i>11</i>	1	24.70	X 25	18.52	1.30	19.82
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	? 25	100.05	7.00	107.05
84441-S2K-000ZB	POCKETTAILGATE PULL	1	14.90	? 25	11.17	0.78	11.95
75722-T7W-A01	EMBLEMRR. <i>nee</i>	1	12.90	/ 25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR I-VTEC <i>nee</i>	1	14.10	/ 25	10.57	0.74	11.31
75701-T5A-000	EMBLEMH <i>nee</i>	1	10.70	? 25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	? 25	2.85	0.20	3.05
33502-T7A-J01	LAMP UNITR. <i>11</i>	1	428.70	X 25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL. <i>11</i>	1	428.70	X 25	321.52	22.51	344.03



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLK MND BUILDING
 SINGAPORE 069110
 Registration No : SMC7094M
 Chassis No : JHMRU1810GX204309
 Model : HRV DX-SIN CVT YM 2016
 Owner's Name : KELVIN YAP FOOK KEONG
 Ins Policy No. :
 Date of Accident : 12/9/2018

Document No. : SQT18003844 Page 2
 Date : 12 Sep 2018
 Customer No. : WZE011
 Svc Advisor : LIM CHOU SIONG
 Engine No : L15B4534307
 Date | Time : 12 Sep 2018 6:34:04 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
34150-T7A-J01	LIGHT ASSY,R.LID 11	1	264.60	X 25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSYL.LID 11	1	264.60	X 25	198.45	13.89	212.34
90650-SZT-003	GROMMETRR.COMBINATION LIGHT 111	2	2.50	2 25	3.75	0.26	4.01
90650-TX6-A01	CLIPRR.COMBINATION LIGHT 111	2	1.90	2 25	2.85	0.20	3.05
91626-TA0-A01	GROMMETTALLIGJHT 111	2	2.80	2 25	4.20	0.29	4.49
74890-T7A-J12ZS	GARNISH ASSYRR.LICENSE 11	1	186.10	X 25	139.57	9.77	149.34
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) 111	1	45.00	✓	45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00	?	320.00	22.40	342.40
71501-T7B-000	FACE RR.BUMPER 111	1	762.60	2 25	571.95	40.04	611.99
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	151.80	? 25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR. 11	1	151.80	X 25	113.85	7.97	121.82
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER 11	1	92.30	X 25	69.22	4.85	74.07
04718-T7A-000ZZ	FACELRR.BUMPER CORNER	1	92.30	? 25	69.22	4.85	74.07
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	? 25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	? 25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER 111	8	2.00	2 25	12.00	0.84	12.84
84640-T7A-J01ZA	LINING ASSYRR.PANEL 11	1	43.00	X 25	32.25	2.26	34.51
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	? 25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	? 25	44.47	3.11	47.58
Sum Item					3743.88	262.07	4,005.95
BOSUN	SUNDRIES 111	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00	✓	80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	11 X	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00	✓	130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11 X	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00	✓	300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	320.00	✓	320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00	✓	320.00	22.40	342.40

Printed on 13/9/2018 7:38:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLK MND BUILDING
 SINGAPORE 069110
 Registration No : SMC7094M
 Chassis No : JHMRU1810GX204309
 Model : HRV DX-SIN CVT YM 2016
 Owner's Name : KELVIN YAP FOOK KEONG
 Ins Policy No. :
 Date of Accident : 12/9/2018

Document No. : SQT18003844 Page 3
 Date : 12. Sep 2018
 Customer No. : WZE011
 Svc Advisor : LIM CHOU SIONG
 Engine No : L15B4534307
 Date | Time : 12. Sep 2018 6:34:04 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		350.00	250	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE, ADJUST &	1	380.00	✓	380.00	26.60	406.60
BKBU02R	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE	1	1500.00	1120	1500.00	105.00	1605.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1500.00	1350	1500.00	105.00	1605.00
Sum Labor					5280.00	369.60	5,649.60

Survey By : Marcus Hah C Slim
 Date & Time : 17/9/18 @ 10am 81006303 (HAP)
 Excess : —
 Status : Not Authorized
 Signature : Take photo before painting
5 day.

Total Amount 9,023.88 631.67 9,655.55
 Total (Inclusive of GST) 9,655.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Final prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Printed on 13/9/2018 7:38:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 13 December, 2018 7:52 PM
To: Faeaz
Cc: Emillin Liew; Daryle Tan; Admin A; Vic (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: RE: Accident Involving SMC7094M & SJN4776B On 12.09.18 LKK REF CC4/EQ118016834/Uha3

Without Prejudice

Dear Faeaz,

We refer further to your below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we confirm acceptance of your offer of **\$6,443.30** (all in) to settle your client's claim.

Kindly note that no DV is required.

The above amount is to be made payable to **KAH MOTOR CO. SDN. BHD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Faeaz [<mailto:faeaz@honda.com.sg>]
Sent: Thursday, 13 December, 2018 5:35 PM
To: Admin A; Hsiao Tong (LKKAUTO); Vic (LKKAUTO)

Cc: Emillin Liew; Daryle Tan

Subject: FW: Accident Involving SMC7094M & SJN4776B On 12.09.18

Dear Hsiao Tong,

Your Ref : CC4/EQI18016834/Uha3

When can we expect to receive your response on the above claim settlement?

Can you please kindly expedite the process and let us have your settlement offer
Soonest possible.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Faeaz

Sent: Monday, 19 November, 2018 9:58 AM

To: Admin A ; Hsiao Tong (LKKAUTO) ; 'Vic (LKKAUTO)'

Cc: Emillin Liew ; Daryle Tan

Subject: FW: Accident Involving SMC7094M & SJN4776B On 12.09.18

Dear Hsiao Tong,

Your Ref : CC4/EQI18016834/Uha3

Refer to our below email dated 8/11/18.

To date we still have yet to receive your response on the above claim settlement?

We appreciate if you could kindly expedite the process and let us have your settlement
Offer soonest possible.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Faeaz
Sent: Thursday, 8 November, 2018 11:51 AM
To: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Vic (LKKAuto)' <vicalpeh@lkkauto.com>
Cc: Emillin Liew <emillinliew@honda.com.sg>; Daryle Tan <daryletan@honda.com.sg>
Subject: Accident Involving SMC7094M & SJN4776B On 12.09.18

Dear Hsiao Tong,

Your Ref : CC4/EQ18016834/Uha3

We have submitted the attached claim documents to you on 2/10/18.

To date we still have yet to receive your response on the above claim Settlement.

We appreciate if you could kindly expedite the process and let us have your Settlement offer soonest possible.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Printer Service
Sent: Thursday, 8 November, 2018 11:04 AM
To: Faeaz <faeaz@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4

Singapore 408610

Tel : +65 6841 3838

Fax : +65 6748 0770

www.honda.com.sg

M/s EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Date: 02/10/18

Your ref: CC4/EQ18016834/Uha3

Attn: Motor Claims Department

Our ref: SMC7094M

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SMC7094M AND SJN4776B ON 12.09.18

We refer to the items(s) marked (✓) below:

- (✓) We refer to LKK-Hsiao Tong's email dated 19.07.18
- (✓) We enclose herewith the repair invoice / Third Party Direct Settlement Agreement.
- (✓) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to emillinliew@honda.com.sg or faeaz@honda.com.sg
- () We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the followings:-

Repair Cost	S\$5,908.30 payable to Kah Motor Co Sdn Bhd
Loss of Use	NIL
Rental	S\$535.00 payable to Kelvin Yap Fook Keong
Third Party Insurer Search	NIL
LTA Search	NIL
- (✓) Kindly let us have your cheque made in favour of the above mention names(s) for transmission as soon as possible.
- (✓) Letter of Authority, Rental Bill

Thank you.

Yours faithfully,



Lim Chou Siong



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ118016834/Uha3

13 DECEMBER 2018

PATRICK CHEAH POH JIN
66 LENGKONG TIGA
#11-16
SINGAPORE 417471

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SJN 4776B AND SMC 7094M ON 12/09/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh Sanghilan
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)
kpinying@hotmail.com / kelvinfkyap@hotmail.com (email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 13 December, 2018 7:24 PM
To: kelvinfkyap@hotmail.com
Cc: kpinying@hotmail.com; Admin A; Vic (LKKAUTO)
Subject: Your Ref: SJN 4776B_ACCIDENT INVOLVING SJN 4776B AND SMC 7094M ON 12/09/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ118016834/Uha3

13 DECEMBER 2018

PATRICK CHEAH POH JIN
66 LENGKONG TIGA
#11-16
SINGAPORE 417471

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SJN 4776B AND SMC 7094M ON 12/09/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SMC 7094M
& (THIRD PARTY'S VEHICLE NO.) SJN4776B
ON 12/09/2018 ALONG East Coast Road

- I hereby authorize Kah Motor Co Sdn Bhd and its agents or any person authorized by Kah Motor to do all or any of the following.
- To submit, resolve and make any claims(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher / indemnity forms and all necessary documents in connection with and arising out of the above claim

Any payment should be made in favour of my name / Kah Motor Co Sdn Bhd



Owner Signature

(Co stamp & authorized signature if it's Co. registered vehicle)

Name : BELVIN AP
NRIC No : S6967743F
Vehicle No : SMC 7094M
Date : 16/9/2018

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

EQ INSURANCE COMPANY LTD
MOTOR CLAIMS DEPT
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE, 069110

Customer No. : WZE011

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S80FC1380G

Invoice No. : SINV-BS18001742
Invoice Date : 29/09/18
Order No. : SVO18058161
Reference :
Job Card No. : 71276
Date/Time Received : 12/09/18 / 8:34:04 PM
Licence No. : SMC7094M
Model : HRV DX-SIN CVT YM 2016
Car Chassis No. : JHMRU1810GX204309
Car Engine No. : L15B4534307
Mileage : 5781
Service Advisor : LIM CHOU SIONG 0427A
Served By : CSLIM
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	incl GST
	TP DIRECT SETTLEMENT (J/NO: 71276) OWNER: KELVIN YAP FOOK KEONG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 12/9/2018 SURVEYED BY: MARCUS (L.K.K.) DATE: 17/09/2018 @ 10:00AM REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SJN4778B							
BOSUN	0672 SUNDRIES	1	Hours	20.00		20.00	1.40	21.40
BML02I	EXT- INSPECT RR LIGHTING MECHANISMS.	1	Hours	80.00		80.00	5.60	85.60
	YJ PERFORM WATER TEST.(N)							
BA02R	EXT- REMOVE & RENEW REVERSE SENSORS-4	1	Hours	130.00		130.00	9.10	139.10
	YJ PCS (N)							
BG02D	EXT- REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	300.00		300.00	21.00	321.00
	YJ							
BOMISC1	EXT- REMOVE, INSTALL & RESET REAR VIEW	1	Hours	320.00		320.00	22.40	342.40
	YJ CAMERA.(N)							
BOMISC1	0626 RESET SMART ENTRY SYSTEM & REMOVE	1	Hours	320.00		320.00	22.40	342.40
	NECESSARY COMPONENT.(N)							
BMI02D	EXT- REMOVE & INSTALL REAR COMPARTMENT	1	Hours	250.00		250.00	17.50	267.50
	YJ LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)							
BKTG02R	EXT- REMOVE & TRANSFER ITEMS TO NEW	1	Hours	380.00		380.00	26.60	406.60
	YJ TAILGATE. ADJUST & ALIGN TAILGATE.(N)							
BKBU02R	EXT- REPLACE RR BUMPER, REPAIR RR PANEL &	1	Hours	1,120.00		1,120.00	78.40	1,198.40
	YJ OTHER DAMAGE PARTS.							
BP03R	EXT- SPRAY PAINTING ON TAILGATE, RR BUMPER	1	Hours	1,350.00		1,350.00	94.50	1,444.50
	YBH & RR PANEL							
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	Each	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	Each	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	Each	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	Each	838.90	25	629.17	44.04	673.21

Printed by CSLIM on 29 Sep 2018 at 2:08:31 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your
feedback by scanning
the QR Code using
mobile device





Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S80FC1380G

EQ INSURANCE COMPANY LTD
MOTOR CLAIMS DEPT
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE, 069110

Customer No. : WZE011

Invoice No. : SINV-BS18001742
Invoice Date : 29/09/18
Order No. : SVO18058161
Reference :
Job Card No. : 71276
Date/Time Received : 12/09/18 / 6:34:04 PM
Licence No. : SMC7094M
Model : HRV DX-SIN CVT YM 2016
Car Chassis No. : JHMRU1810GX204309
Car Engine No. : L15B4534307
Mileage : 5781
Service Advisor : LIM CHOU SIONG 0427A
Served By : CSLIM
Page : 2

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount Incld	
						Amount	GST
75722-T7W-A01	EMBLEMRR.	1	Each	12.90	25	9.67	0.68
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	Each	14.10	25	10.57	0.74
75701-T5A-000	EMBLEMH	1	Each	10.70	25	8.02	0.56
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	2	Each	2.50	25	3.75	0.26
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	2	Each	1.90	25	2.85	0.20
91626-TA0-A01	GROMMETTAILLIGJHT	1	Each	2.80	25	2.10	0.15
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	Each	45.00		45.00	3.15
04715-T7A-900ZZ	FACE,RR.BUMPER	1	Each	463.70	25	347.77	24.34
91505-TM8-003	CLIPBUMPER	8	Each	2.00	25	12.00	0.84

Sum Labor	4,270.00	298.90	4,568.90
Sum Item	1,251.78	87.62	1,339.40
Total SGD	5,521.78	386.52	5,908.30
Total Payable (SGD)			5,908.30

Printed by CSLIM on 29 Sep 2018 at 2:08:31 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s).

Please give us your
feedback by scanning
the QR Code using
mobile device



KELVIN YAP FOOK KEONG

741 TAMPINES STREET 72
 #12-80
 520741
 SINGAPORE

Customer Information

Customer Name : KELVIN YAP FOOK KEONG
 Customer Ref No. : SMC7094M

Rental Information

Date/Time Out : 24/09/2018 09:48
 Date/Time Return : 28/09/2018 17:28

Billing Detail

#	Description	Amt
1	5 Days @ 100.00	500.00

Tax Invoice

Invoice No. : CRINV/18/01930
 Invoice Date : 29 Sep 2018
 Customer No. : *****743F
 Ref :
 Currency : SGD
 Terms : COD
 RA No. : 05157

Car Information

Registration No. : SJU7232Y
 Car Model : HONDA CIVIC 1.8L
 SAT
 Car Color : RED

Starting Mileage : 91103
 Ending Mileage : 91417
 Mileage Travelled : 314

Remarks:

UBI/BS - SA: C S LIM

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

Printed by ubibdysa02 at 01/10/2018 08:40

Subtotal : S\$ 500.00
 GST 7.0% : S\$ 35.00
Total : S\$ 535.00
 Paid : S\$ 535.00
 Outstanding : S\$ 0.00

RENTAL AGREEMENT

No. 05157

Date: 24 Sep 2018

VEHICLE PARTICULAR

Vehicle No. : SJU7232Y
Make : HONDA
Model : HONDA CIVIC 1.8L 5AT
Out (Date & Time) : 24 Sep 2018 | 0948
In (Date & Time) : 28 Sep 2018 | 1728

HIRER PARTICULAR

Name : KELVIN YAP FOOK KEONG
Address (Res) : 741 TAMPINES STREET 72
#12-80 520741 SINGAPORE
Tel : 65953713
Name on Credit Card : KHOO PIN YING
Credit Card No. : XXXX-XXXX-XXXX-8026
Payment Mode : Visa

MAIN DRIVER PARTICULAR

Name : KELVIN YAP FOOK KEONG
Address (Res) : 10 PARI DEDAP WALK #05-17 S(486062)
Driving License No. : S6967743F
Passing Date : 24/06/2010
Date of Birth : 01/10/1969
NRIC/FIN/Passport No : S6967743F

ADDITIONAL DRIVER PARTICULAR

Name : KHOO PIN YING
Address (Res) : 10 PARI DEDAP WALK #05-17 S(486062)
Driving License No. : S8066099E
Passing Date : 27/04/2010
Date of Birth : 15/09/1980
NRIC/FIN/Passport No : S8066099E

PAYMENT

Day: 5 days x 100.00 500.00
Week 0.00
Month 0.00
Add HRS 0.00
SUB TOTAL 500.00
GST 35.00

NETT AMOUNT

SECURITY DEPOSIT 0.00

REMARKS

SA: CSLIM
T/P D/S EQ INSURANCE



TERMS & CONDITIONS

BY: _____

- Malaysia Drive Surcharge
 - Normal days \$20/day + 7% GST
 - Blackout dates, Eve of PH & PH \$40/day + 7% GST
 - Insurance Excess
 - S'pore Drive Excess - \$1500 + 7% GST
 - Malaysia Drive Excess - \$2500 + 7% GST (Excluding towing & custome fees)
 - Vehicle is rented to hirer upon terms and conditions on the front and back of this agreement.
 - Vehicle is to be driven only by hirer and any additional hirer listed above.
 - Hirer is responsible for all parking, fines and ERP charges.
 - Hirer must report all accidents to Kah Motor within 24 hours of occurrence.
 - Violation of the terms of this agreement makes the hirer responsible for the full loss or damage to the vehicle whether insurance is accepted or not.
 - Vehicle is strictly for Singapore use, unless covered by insurance for Malaysia use.
 - Return of rental car beyond the stated duration will incur the following charges:
 1. Less than or equal to 5 hours, a **0.5 day** charge will apply
 2. More than 5 hours, a **FULL DAY** charge will apply
 - Unpaid rental bookings will not be confirmed, and will subsequently be released after 10 mins.
 - Rental Deposit
 - A rental deposit will be collected upon confirmation of rental booking.
 - Rental deposit & rental fees will be forfeited if cancellation of rental booking is made less than 7 working days from intended start date of rental.
 - Rental deposit will be refunded after the end of the rental period.
 - Refund process will take approx 2-3 weeks via respective payment mode used at point of initial payment.
- **Kindly top up the petrol before you return us the rental car. Otherwise, there will be charges added to your final bill. ****

I have read and agree to the terms and conditions on both sides of this agreement.

I authorize Kah Motor Co. Sdn. Bhd. to process a credit card voucher if any for charges under this agreement including any miscellaneous charges.

All information I have given Kah Motor Co. Sdn. Bhd. in connection with this agreement is true.


Hirer's Signature

Main Driver's Signature
(if not hirer)

Credit Card Holder's
Signature (if not hirer)



Rented out by



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 31/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJN 4776B (Insd Veh)	Your Ref. No. : DMPPHQ18-000849
	SMC 7094M (TP Veh)	Our Ref. No. : CC4/EQI18016834/Uha3q2
Date of Accident	12/9/2018	

Liability	100%	
Final Repair Cost	: \$ 5,908.30	
Loss of Use	: \$	days
Rental (If any)	: \$ 535.00	5 days
Others:	: \$	
	: \$	
	6,443.30	
Final Settlement Sum	: \$ 6,443.30	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	KAH MOTOR CO.SDN.BHD.	: \$ 6,443.30
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18016834/Uha3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 31-12-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 4776B	Veh. Inspected	SMC 7094M	
Policy No.	DMPPHQ18-000849	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JUSTIN	Assign Date	14/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMRU1810GX204309	Colour	GREY	
Odometer	4484	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2018	Inspection Date	17/09/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7094M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RUBBER CR.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.22	6.22
1	RUBBER CL .WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	CAPPVOT (SN)	NECESSARY	3.52	3.52
4	FASTENER BW/SHIELD (SN)	NECESSARY	9.60	9.60
2	FASTENER B (SN)	NECESSARY	7.35	7.35
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.25	5.25
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	TAIL GATE COMP (SN)	BADLY DENTED	629.17	629.17
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	72.60	-
1	LOCK ASSYTAILGATE (SN)	NOT NECESSARY	57.45	-
1	STRIKER ASSYTAILGATE (SN)	NOT NECESSARY	18.52	-
1	LINING ASSYTAILGATE (SN)	NOT NECESSARY	100.05	-
1	POCKETTAILGATE PULL (SN)	NOT NECESSARY	11.17	-
1	EMBLEMRR (SN)	NECESSARY	9.67	9.67
1	EMBLEM,RR.I-VTEC (SN)	NECESSARY	10.57	10.57
1	EMBLEMH (SN)	NECESSARY	8.02	8.02
2	NUTPUSH 3MM (SN)	NOT NECESSARY	2.85	-
1	LAMP UNITR (SN)	NOT NECESSARY	321.52	-
1	LAMP UNITL (SN)	NOT NECESSARY	321.52	-
1	LIGHT ASSY,R.LID (SN)	NOT NECESSARY	198.45	-
1	LIGHT ASSYL,LID (SN)	NOT NECESSARY	198.45	-
2	CROMMETRR.COMBINATION LIGHT (SN)	NECESSARY	3.75	3.75
2	CLIPRR.COMBINATION LIGHT (SN)	NECESSARY	2.85	2.85
2	GROMMETTAILLIGJHT (SN)	NECESSARY (1 PCS ONLY)	4.20	2.10
1	GARNISH ASSYRR.LICENSE (SN)	NOT NECESSARY	139.57	-
1	NUMBER PLATE WITH CASING -S (SN)	BENT	45.00	45.00
4	ACT RR .SENSOR (SN)	SERVICEABLE	320.00	-
1	FACE RR.BUMPER (SN)	DENTED	571.95	347.77
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	113.85	-

Report Ref No. CC4/EQ18016834/Uha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	113.85	-
1	FACER.RR.BUMPER CORNER (SN)	NOT NECESSARY	69.22	-
1	FACEL.RR.BUMPER CORNER (SN)	NOT NECESSARY	69.22	-
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
8	CLIPBUMPER (SN)	NECESSARY	12.00	12.00
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	32.25	-
1	ANTENNA ASSYL.F (SN)	NOT NECESSARY	43.57	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	44.47	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			3,793.88	1,271.78
	LABOUR			
	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER.		80.00	80.00
	BODY UNDERSIDE COATING .	NOT NECESSARY	100.00	-
	REMOVE & RENEW REVERSE SENSORS .		130.00	130.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR WINDSCREEN.		300.00	300.00
	REMOVE,INSTALL & RESET REAR VIEW CAMETA.		320.00	320.00
	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY.		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS ,RR.		350.00	250.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &.		380.00	380.00
	REPLACE RR BUMPER ,REPAIR RR PANEL & OTHER DAMAGE.		1,500.00	1,120.00
	SPRAY PAINTING ON TAILGATE ,RR BUMPER & RR PANEL.		1,500.00	1,350.00
			5,230.00	4,250.00
	GRAND TOTAL		9,023.88	5,521.78
	RECOMMENDED COST OF REPAIRS			5,521.78

Report Ref No. CC4/EQ118016834/Uha3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.