

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 17 Sep 2018

Preliminary Advice

Insured Vehicle No	: FBL9474U	Accident Date	: 03/09/2018
TP Vehicle No	: SLV4859E	Assignment Date	: 14/09/2018
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 4.00
Date of Inspection	: 10/09/2018		
Inspection At	: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	10,260.00 (Labour Only)
Revised Amount	:S\$	2,520.00 (Labour Only)
Check Items (Estimated)	:S\$	600.00
Total	:S\$	3,120.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
- Pending parts prices from repairer.