

ASS. REC. BY:

REF:

CS/CALISD16841/Gigber

Special Instructions:

Surveys

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAC

Date/Time:

14/09/18 2:31pm

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 3372L

Insured:

at Workshop m/s

Hua Hong Sing Ah Tee

Tel:

6661 9688 6763 6183

of

Unpacked at 35D Sungai Kadut St 1

Policy No:

Claim No:

MOMV000007785 - 00 - 000

Sum Insured:

Excess:

TAA 600

Make of Veh:

D.O.A.

08092018

(Client's Record)

CA / REV

REP. / REV 24 HRS

17/09/2018 @ Morning

H.O.D. Endorsement:

Date/Time:

14/09/2018 2:22pm

Person Contacted:

Yvonne

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

YN 3372L - NA / U0614021367/d2

Dtn 13-11-14

07/12/18 @ 9.55am Sharon Ng informed that the vehicle already tow to Sing Ah Tee for repair on 15/10/18.

14/12/18 @ 2.27pm informed Sharon Ng, according to Sing Ah Tee the vehicle still under repair. We will advise repairer to expedite the repair.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: YN3372L
 at Workshop n/s Hua Hong
 of 250 Sungai Kadut St. 1
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: TBA
 (Client's Record)
 Make of Veh: _____

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value: \$~~40K~~ 50K
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 14 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YN3372L Yr Regn: 21 Nov 2012
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hino XZ4710R c.c. 4009
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: - T/Ratio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHHUCP3H 30K 004497
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: S/Rim / STD A/Rim or
 Tyre Size: F: 7.00 R16
 R: "
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Double Happiness
 Front 5 mm R/Bal. 5/5 mm
 Rear 5 mm L/Bal. 5/5 mm
 D.O.A. _____ D.O.I: 17-09-18
 Survey held at W/S 11Am
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
23/1/19 @ 11.44am	Report limit \$26K. check with Janice, she said the vehicle still may under repair. so she will go and double check.
30/4/19	According to Sharon (shg 9th floor), they tender this vehicle at CAR \$14118 as agreed with GAI.

RECEIVED 02 MAY 2019

Date/Time, File Pass to? : Prell. Report
 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 14
 Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	<u>450</u>
Transportation:	_____
Photos:	_____
Other:	_____
TOTAL	<u>450</u>

tender Report Format: OD
COX
 Lump Sum / L.B. / F3: 14118

Catherine Chong (LKK Auto)

From: Yvonne Toh <yvonne@huahong.com.sg>
Sent: Friday, 14 September, 2018 2:50 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'Admin A'; 'assignments'; 'Jerleen Tang'
Subject: FW: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70
Attachments: ESTIMATE.pdf; GIA REPORT - OD GA.pdf; CI.pdf; Driver WP AND DL.pdf

Dear Catherine,

As spoken, please kindly assist to arrange survey.

Thank you.

Regards,

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg



From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, 14 September 2018 2:31 PM
To: Yvonne Toh <yvonne@huahong.com.sg>
Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>
Subject: RE: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Yvonne

Noted on the OD claim request.

We will arrange for LKK to conduct survey.

Dear LKK

Please accept assignment. Attached documents for reference

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Yvonne Toh <yvonne@huahong.com.sg>
Sent: Friday, September 14, 2018 1:20 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Sir/Mdm

Please refer to attached.

Our insured claiming Own Damage.

Vehicle towed in our premise. Kindly arrange for survey.

Should you have any queries, please contact us @ 6661 9688.

Thank you.

Regards,

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg



From: Yvonne Toh <yvonne@huahong.com.sg>

Sent: Wednesday, 12 September 2018 3:21 PM

To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>

Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>

Subject: RE: YN 3372 L (DOA 08/09/2018 08:55)

Dear Rachel,

As requested, please find attached WP & DL.

Yes, we are currently coming up with the estimated cost of repair.

Thank you.

Regards,

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg



From: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent: Wednesday, 12 September 2018 3:03 PM

To: claims@huahong.com.sg

Subject: YN3372L (DOA 08/09/2018 08:55)

Dear Sir

We refer to the attached GIA report made at your reporting centre.

Please provide copy of WP and DL.

Are you assisting them to file OD claim on policy ?

Rachel Tan, Executive | P. +65 6804 7846 | F. +65 6235 3354 | rachel.tan@sg.gaig.com



Motor Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 11, 2017

Moody's
A1 (Good)
Published December 2017

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 14 December 2018 2:27 PM
To: Ng, Sharon
Cc: SUR
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Sharon,

According to the repairer, the vehicle still under repair. We have advise repairer to expedite the repair.

No investigation report as we have informed Rachel that we will conduct interview statement and forward a copy to her without bill.

According to Bryan, there is no mechanical issue with the vehicle.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Friday, 7 December 2018 9:55 AM
To: Shiau Chan (LKKAuto) <sjewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Hi Shiau Chan

YN3372L was been towed to Sng Ah Tee on 15 Oct for repair.

Please make arrangement with repairers on post-repair assessment/photographs.

To give them a nudge as it is taking almost 2 months to repair and insured's road tax has expired and unable to renew due to veh undergoing repair.

Your side investigated the matter. Please give us the final IR and advise OI on the query, actions to be taken.

Regards

Sharon

Great American

From: Shiau Chan (LKKAuto) <sjewsc@lkkauto.com>
Sent: Wednesday, September 19, 2018 4:04 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

Please find the attached of YN 3372L photo.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent: Wednesday, 19 September 2018 3:27 PM

To: Shiau Chan (LKKAuto) <sjewsc@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Hi

Can I have the survey photos

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Shiau Chan (LKKAuto) <sjewsc@lkkauto.com>

Sent: Tuesday, September 18, 2018 4:03 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

Enclosed herewith preliminary advice of YN 3372L.

Pending repair cost from repairer.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Tuesday, 18 September, 2018 3:33 PM

To: 'Shiau Chan (LKKAuto)' <sjewsc@lkkauto.com>

Subject: FW: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Toh [<mailto:yvonne@huahong.com.sg>]
Sent: Friday, 14 September, 2018 2:50 PM
To: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>; 'assignments' <assignments@lkkauto.com>; 'Jerleen Tang' <jerleen@huahong.com.sg>
Subject: FW: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Catherine,

As spoken, please kindly assist to arrange survey.

Thank you.

Regards,
Yvonne Toh
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg
   

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, 14 September 2018 2:31 PM
To: Yvonne Toh <yvonne@huahong.com.sg>
Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>
Subject: RE: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Yvonne
Noted on the OD claim request.
We will arrange for LKK to conduct survey.

Dear LKK
Please accept assignment. Attached documents for reference

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Yvonne Toh <yvonne@huahong.com.sg>
Sent: Friday, September 14, 2018 1:20 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Sir/Mdm

Please refer to attached.

Our insured claiming Own Damage.
Vehicle towed in our premise. Kindly arrange for survey.

Should you have any queries, please contact us @ 6661 9688.

Thank you.

Regards,
Yvonne Toh
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGAI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg



From: Yvonne Toh <yvonne@huahong.com.sg>
Sent: Wednesday, 12 September 2018 3:21 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: 'Jerleen Tang' <jerleen@huahong.com.sg>
Subject: RE: YN 3372 L (DOA 08/09/2018 08:55)

Dear Rachel,

As requested, please find attached WP & DL.

Yes, we are currently coming up with the estimated cost of repair.

Thank you.

Regards,
Yvonne Toh
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGAI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | huahong.com.sg



From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 12 September 2018 3:03 PM
To: claims@huahong.com.sg
Subject: YN3372L (DOA 08/09/2018 08:55)

Dear Sir

We refer to the attached GIA report made at your reporting centre.

Please provide copy of WP and DL.

Are you assisting them to file OD claim on policy ?

Rachel Tan, Executive | P. +65 6804 7846 | F. +65 6235 3354 | rachel.tan@sg.gaig.com



Motor Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 11, 2017

Moody's
A1 (Good)
Published December 2017

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Friday, 7 December 2018 9:55 AM
To: Shiau Chan (LKKAuto)
Cc: SUR
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Hi Shiau Chan

YN3372L was been towed to Sng Ah Tee on 15 Oct for repair.

Please make arrangement with repairers on post-repair assessment/photographs.

To give them a nudge as it is taking almost 2 months to repair and insured's road tax has expired and unable to renew due to veh undergoing repair.

Vehicle still under repair

- we have advise repairer to expedite the

Your side investigated the matter. Please give us the final IR and advise OI on the query, actions to be taken.

the

Regards
Sharon
Great American

✓ No investigation report as we informed Rachel that we will

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, September 19, 2018 4:04 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

conduct ~~interview~~ interview statement and forward a

copy to

her without bill.

According to a Bryan,

there is no mechanical

issue with the

vehicle -

Dear Rachel,

Please find the attached of YN 3372L photo.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 19 September 2018 3:27 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Hi

Can I have the survey photos

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

Shiau Chan (LKKAuto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 2 October 2018 4:43 PM
To: Denise Tay (LKKAuto); Shiau Chan (LKKAuto)
Cc: SUR; Tan, Rachel
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Denise

Please advise

- a) what is the repair cost proposal from the repairer;
 - i) based on lump sum (combined for front and rear)
 - ii) split by front and rear portion
- b) check with the repairer whether OI video is available;
- c) The market value recommended at \$50k appear high. The rest of our surveyors advised in the range of \$45-\$46k. Please provide source of your checks

Regards
Sharon
GAIC

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, October 01, 2018 11:23 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

According to our surveyor, the condition of the tyres were also in serviceable condition with a remaining tread depth of approximately front 5mm and rear 5/5mm each.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 September 2018 4:04 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

- Woon Meng - woonmeng@singnet.com.sg Tel: 63161131 Ms Heng
- Sing Ah Tee - sharon@singahtee.com, admin@singahtee.com Tel: 62686183 Sharon Sing
- Wah Hong - michael@wahhong.sg Tel: 97880700 | 67737377 Michael Tee
- Sin Sheng - sinsheng1981@gmail.com Tel: 68639595 Susan
- Lee Kuan Hwa - kuanhwa@singnet.com.sg Tel: 9028 8798 Adeline Lee
- Mah Lian - sihui.g@gmail.com Tel: 91070026 Si Hui
- Goldbell - williamgasc@goldbell.com.sg Tel: 97397127 William Go.

Denise Tay (LKKAuto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 2 October 2018 4:43 PM
To: Denise Tay (LKKAuto); Shiau Chan (LKKAuto)
Cc: SUR; Tan, Rachel
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Denise

Please advise

- a) what is the repair cost proposal from the repairer;
 - i) based on lump sum (combined for front and rear)
 - ii) split by front and rear portion *labour?*
- b) check with the repairer whether OI video is available;
- c) The market value recommended at \$50k appear high. The rest of our surveyors advised in the range of \$45-\$46k. Please provide source of your checks

Regards
Sharon
GAIC

Based on SG car met, March 2012 vehicle is cdt 41K. Apply the

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, October 01, 2018 11:23 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

According to our surveyor, the condition of the tyres were also in serviceable condition with a remaining tread depth of approximately front 5mm and rear 5/5mm each.

of cdt 41K per year, the insured MV is cdt 49-50K. Add cdt 8 mths of depreciation from the March 2012 registered vehicle.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Reverse MV to 46K

From: Shiau Chan (LKKAuto)

Sent: Wednesday, 19 September 2018 4:04 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 1 October 2018 11:23 AM
To: Shiau Chan (LKKAuto); Tan, Rachel
Cc: SUR
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

According to our surveyor, the condition of the tyres were also in serviceable condition with a remaining tread depth of approximately front 5mm and rear 5/5mm each.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 September 2018 4:04 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Dear Rachel,

Please find the attached of YN 3372L photo.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 19 September 2018 3:27 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70 / CLMOMVC000003457

Hi

Can I have the survey photos

Regards
Rachel Tan

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 18 September 2018 4:02 PM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70
Attachments: YN3372 EST.pdf, CSGAI18016841Gqb.pdf

Dear Rachel,

Enclosed herewith preliminary advice of YN 3372L.
Pending repair cost from repairer.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Tuesday, 18 September, 2018 3:33 PM
To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: FW: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Toh [<mailto:yvonne@huahong.com.sg>]
Sent: Friday, 14 September, 2018 2:50 PM
To: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>; 'assignments' <assignments@lkkauto.com>; 'Jerleen Tang' <jerleen@huahong.com.sg>
Subject: FW: MOMVC000007785-00-000 / YN3372L / 08.09.208 / EST AMT: \$41,176.70

Dear Catherine,

As spoken, please kindly assist to arrange survey.

Thank you.

Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Claim No. : MOMVC000007785-00-000

Date: 18th September 2018

Our Ref: CS/GAI18016841/Gqb

The Motor Claims Department
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. YN 3372L


We thank you for the instruction on 14/09/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/09/2018 at the premises of M/s HUA HONG and have the following to report:-

Workshop Estimate Amount	: S\$ <u>38,482.90</u>	
	<u>Front Portion</u>	<u>Rear Portion</u>
Revised Estimate Amount	: S\$ <u>22,888.85</u>	S\$ <u>-</u>
"Check" Items Amount	: S\$ <u>7,500.30</u>	S\$ <u>5,800.00</u>
Market Value	: S\$ <u>50,000.00</u>	
Salvage Value	: S\$ <u>23,364.00</u>	
Nett Value	: S\$ <u>26,636.00</u>	

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages consistent.

Pending repair cost from repairer.

Recommend repair days: 16 days

We have NOT authorise repair.

Yours faithfully

Guo Qiang
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5030W
Vehicle Details	
Vehicle No.:	YN3372L
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2018
Vehicle Make:	HINO
Vehicle Model:	XZU710R 4.0 MANUAL ABS TURBO
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	N04CUV13111
Chassis No.:	JHHUCP3H30K004497
Maximum Power Output:	-
Open Market Value:	\$33,680.00
Original Registration Date:	21 Nov 2012 ✓
First Registration Date:	21 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$1,684.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$23,364.00
Total Rebate Amount:	\$23,364.00

The information contained herein is correct as at 18 Sep 2018

OK

► Hino XZU710R Used Vehicle List (14 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Hino XZU710R (Diesel)	\$41,800	\$11,860 /yr	28-Mar-2012	4,009 cc	-	Bell Auto Pte Ltd	Availat
Branded Freezer Fitted On Durable 14 Ft Truck. Class 3 & Freezer Tested To Deliver -10°C Office No. - 67457076 Kk Ong - 97111066 Raymond - 96792154							
Hino XZU710R (Diesel)	\$62,800	\$9,260 /yr	29-Jun-2015	4,009 cc	77,887 km	Think One Automobile & Trading	Availat
Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome! Office No. - 64673300 Kelvin - 96720298 Sophia - 90707950 Yow Tat - 91561581							
Hino XZU710R (Diesel)	\$59,800	\$8,370 /yr	09-Nov-2015	4,009 cc	67,463 km	ABWIN (1994) Pte Ltd	Availat
Still Under Warranty. Under Utilized Vehicle. In Good Condition. Box At 5.5ft (Extendable). Interior Comes With Free Checkered Plate. Able To Fetch 4.5 T Class 3 License Plus VPC Needed. In House L... Office No. - - Joey Lim - 85186788 Alex - 98539992 Elton - 88767169							
Hino XZU710R (Diesel)	\$66,500	\$8,850 /yr	23-Mar-2016	4,009 cc	-		Availat
Regularly Servicing At Agent. Office No. - - Jeff - 90680330							
Hino XZU710R (Diesel)	\$69,800	\$8,550 /yr	16-Nov-2016	4,009 cc	20,000 km		Availat
No Agents Please, 1 Careful Owner, New Road Tax, Used 1 Year, 4 Years Agent Warranty, 20k Km Mileage, Free Servicing, Free Warranty, Serving At Ag Need VPC. Office No. - - Freddie Woo - 97305040							
Hino XZU710R (Diesel)	\$85,888	\$9,030 /yr	23-Mar-2018	4,009 cc	-	Net Link Partners Pte Ltd	Availat
Cheapest In The Market! No Need VPC, Class 3 Licence Can Drive! Best 14ft In Its Class. Low On Diesel And Repair Costs! 2+1 Front Seating, 5 Years Or 200,000km Free Servicing! Optional Canopy And Rear... Office No. - 67531661 Sitoh - 96648460 Soon - 83228009 Yi Long - 83338517							
Hino XZU710R (Diesel)	\$86,800	\$9,040 /yr	23-Apr-2018	4,009 cc	18 km	Valley Trading	Availat
Latest Euro 6 Hino XZU710R 14ft From Borneo Motors. 3 Years Or 100,000Km Warranty. Free 20 Times Servicing Packages. Call Us Now For More Enquir Office No. - 63445088 Richard Teo - 90251988 Thomas - 96302490 Patrick Teo - 96681822							
Hino XZU710R (Diesel)	\$80,800	\$8,410 /yr	25-Apr-2018	4,009 cc	-	Ding Feng Pte Ltd	Availat
Agent Unit, 3 Years Warranty, 20 Free Servicing! 100% Loan Available. Please Call Our Friendly Sale Executive Now For More Information. Office No. - 67499699 Nikki - 83146959 Alvin - 97914451							
Hino XZU710R (Diesel)	\$79,800	\$8,290 /yr	02-May-2018	4,009 cc	-	Ding Feng Pte Ltd	Availat
Cheapest In The Market! No Need VPC, Class 3 Licence Can Drive. Agent Unit, 3 Years Warranty, 20 Free Servicing! 100% Loan Available. Please Call Ou Friendly Sale Executive Now For More Information. Office No. - 67499699 Nikki - 83146959 Alvin - 97914451							
Hino XZU710R (Diesel)	\$86,800	\$8,990 /yr	14-May-2018	4,009 cc	18 km	Valley Trading	Availat

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 17:17
Date Of Accident	08/09/2018 08:55
Exact Location Of Accident	ALONG SUNGEI KADUT DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3372L
Insured/Policyholder	
Name Of Registered Owner	POH WAH SCAFFOLDING & ENGINEERING PTE. LTD.
Co Reg No	200615030W
Email Address	STORE@POHWAHGROUP.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68507276

Vehicle Particulars

Manufacturer	HINO
Model	XZU710R 4.0 MANUAL ABS TURBO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVC000007785-00-000
Cover Note Number	

Driver

Name of Driver	PAZHANI SAKTHIVEL
Passport No/FIN	G2368034W
Date Of Birth	16/01/1993
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2014
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86732892
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured -
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions DRIZZLING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN & POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD8551T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver WANG PENG
 NRIC/Passport Number G5126746Q
 Contact Number 81629952
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XB7410J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver CHUA TECK SIONG
NRIC/Passport Number S1161152D
Contact Number 91147238
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PAZHANI SAKTHIVEL
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN3372L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


P. Chong

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Yvonne Toh

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 8 Sep 2018, 0855 hrs
 Accident Location: Along Sungai Kadit Drive

As per police report

To add on: I would like to state that my vehicle's front cabin was damaged after the collision with veh B. Veh C who was overtaking my parked vehicle, accidented onto my vehicle and the impact of the moving veh C damaged my vehicle's canopy causing it to fall. I was on the road side and witnessed the accident. I moved veh C to side but to no avail.

Reporting Only Own Damage Third Party Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

***IMPORTANT NOTE:**
 This form is subject to the conditions that in the event that you wish to claim against your own policy (Own Damage Claim), there is a FOURTEEN (14) days time whereby the claim must be made within the stipulated timeframe from the day of occurrence.



Policyholder's Signature
 Date & Time:

P. S. Koh
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Y. Toh
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180908/2138

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 788827
Tel No: 1800-8529999

2 of 4

Report No. T/20180908/2138

CONTINUATION OF REPORT

Name	CHUA TECK SIONG		ID No.	S1161152D
Related Vehicle	XB7410J (Lorry)		Contact No.	91147238
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Name	WANG PENG		ID No.	G5126746Q
Related Vehicle	XD8551T (Lorry)		Contact No.	81629952
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	PAZHANI SAKTHIVEL		ID No.	G2368034W
Related Vehicle	YN3372L (Lorry)		Contact No.	86732892
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	08/09/2018		Date Discharge	08/09/2018
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight

Brief Details.

On 8/9/2018 at about 0855hrs, I was driving in my company's lorry (A) bearing Reg No.: YN3372L along the first lane of Sungai Kadut Drive toward Kranji Way. At about 170 metres before Kranji Way, the lorry (B) in front of me bearing Reg No.: XD8551T stopped suddenly. I braked immediately but as the road was slippery due to the rain, my vehicle could not stop in time. As such, the front of my lorry hit the rear of the said lorry. The front of my lorry was bent inwards due to the impact. My right knee had a 4-cm cut which still hurts till now. My lower back is also aching due to the impact.

Shortly after, another lorry (C) Reg No.: XB7410J from behind my lane tried to overtake as my vehicle (A) was stationary at that point of time. However, the front of the said lorry (C) somehow hit my lorry's (A) canopy left side.



**SINGAPORE
POLICE FORCE**



T/20180908/2138

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 4

Report No. T/20180908/2138

CONTINUATION OF REPORT

All parties exchanged particulars. Traffic Police and Ambulance were there to attend to the incident. I was conveyed by the Ambulance to Khoo Teck Puat Hospital where I was treated and given medication for my pain.

I have an in-car camera inside my Lorry (A) but am not sure if it was recording during the incident.



**SINGAPORE
POLICE FORCE**



T/20180908/2138

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

4 of 4


Report No. T/20180908/2138

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F1 Sgt 2 KEITH GARRETT ILETO LIM WSP Jolene Ng	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 08/09/2018 18:52
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case: 
Authentication Stamp NP168	

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **G 2868034 W**
Name:

PAZHANI SAKTHIVEL

Birth Date: 16 Jan 1993
Issue Date: 26 Jul 2014
Valid Till 25 Jul 2019



WORK PERMIT

Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
POH WAH CONSTRUCTION PTE. LTD.

C085



Name:
PAZHANI SAKTHIVEL
Work Permit No. Director:
0 36201363 CONSTRUCTION



K0063240

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	26 Jul 2014
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	26 Jul 2014



NP 429A

VISIT PASS

Immigration Regulations

05-10-2017

Name:
PAZHANI SAKTHIVEL



Passport No:
G2368034W
Date of Birth: 16-01-1993 Sex: M
Nationality: **INDIAN**

Download SGWork Pass App to check status



MULTIPLE JOURNEY VISA ISSUED
YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



CERTIFICATE OF INSURANCE

· Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) · Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
· Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia)

Policy Details

Certificate Number : MOMVC000007785-00-000 Cover : Commercial Vehicle (Comprehensive)
Policyholder Name : Poh Wah Scaffolding & Engineering Pte Ltd Chassis Number : JHHUCP3H30K004497
NCD Entitlement : 10% No Claim Discount Engine Number : N04CUV13111
Hire Purchase : N/A Registration Number : YN3372L
Period of Insurance : From 21/11/2017 (00:00) To 20/11/2018 (23:59) (Both Dates Inclusive)

Persons or Classes of Persons entitled to Drive

a) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor or so has been Vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to Use

- a) Use in connection with Policyholder's business
b) Use for carriage of passengers (other than for hire and reward) in connection with the Policyholder's business

This Policy does not cover:

- a) Use for Hire and Reward
b) Use for racing, pace making, reliability trial or speed testing

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987(Malaysia), are not to be included under these headings

Excess (Section 1) : SGD 600.00
Excess (Section 2) : N/A
Windscreen Excess : SGD 100.00
ADDITIONAL EXCESS : Please refer overleaf

Driver Details


Named Driver 01 : Any driver driving on the policyholder's order or permission

Name of Intermediary : Capstone Insurance Agency Pte Ltd

Date of Issue : 22/03/2018

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of
Great American Insurance Company



Authorised Signatory

m1ow



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

14 September 2018

Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Attn: Motor Claims Department

LJK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display HHC Claims 18-10
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCIDENT INVOLVING YN 3372 L, XD 8551 T & XB 7410 J ON 08/09/2018 ALONG SUNGEI KADUT DRIVE AT ABOUT 0855 HOURS

Insured : POH WAH SCAFFOLDING & ENGINEERING PTE. LTD.
 Vehicle Registration No : YN 3372 L
 Vehicle Make : HINO
 Vehicle Model : XZU710R 4.0 MANUAL ABS TURBO
 Vehicle Chassis No : JHHUCP3H30K004497
 Policy No : MOMVC000007785-00-000
 Date of Accident : 08/09/2018

Type of Claim: Own Damage

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper / BT		\$ 980.00
2	2	Front Bumper Bracket (LH/RH) X NN	\$ 295.00	\$ 590.00
3	2	Front Head Lamp (LH/RH) X NN, LH X NN	\$ 1,020.00	\$ 2,040.00
4	1	Front Grille / Mis		\$ 680.00
5	10	Front Grille Clip / MC	\$ 2.00	\$ 20.00
6	1	Emblem / MC		\$ 75.00
7	1	Sticker (Hino) / MC		\$ 38.00
8	1	Sticker (300) / MC		\$ 36.00
9	1	Front Panel (Outer) / BUC		\$ 480.00
10	2	Front Corner Panel (LH/RH) RH - Re, LH X NN	\$ 450.00	\$ 900.00
11	2	Front Corner Panel Pad (LH/RH) X NN	\$ 6.00	\$ 12.00
12	2	Front Corner Panel Seal Plate (LH/RH) X NN	\$ 28.00	\$ 56.00
13	12	Front Corner Panel Clip (LH/RH) / MC	\$ 2.00	\$ 24.00
14	1	Front Windscreen Moulding / MC		\$ 35.00
15	1	Front Windscreen / SM		\$ 1,580.00
16	1	Front Wiper Arm (LH) / SBT		\$ 105.00
17	1	Front Wiper Arm (RH) / SBT		\$ 99.00
18	1	Front Wiper Blade (LH/RH - 1 Set) - Curt		\$ 60.00
19	1	Front Wiper Linkage X NN		\$ 340.00
20	1	Side Mirror Round (RH) / Lt		\$ 135.00
21	1	Side Mirror Stand (LH) / BR		\$ 395.00
22	2	Door (LH/RH) LH - BT, RH - BUC	\$ 1,328.00	\$ 2,656.00
23	2	Door Weather Strip (LH/RH) / TV	\$ 85.00	\$ 170.00
24	4	Door Hinge (LH/RH) Upper/Lower RH - BT, LH X NN	\$ 75.00	\$ 300.00
25	1	Door Checker (LH/RH) RH - BT, LH X NN		\$ 135.00
				\$ 11,941.00



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

ACCIDENT INVOLVING YN 3372 L, XD 8551 T & XB 7410 J ON 08/09/2018 ALONG SUNGAI KADUT DRIVE AT ABOUT 0855 HOURS

Estimate Repair List for Vehicle : YN 3372 L - Hino XZU710R

		Balance B/F	\$ 11,941.00
26	2	Door Lower Protector (LH/RH) / acc acc	\$ 95.00 \$ 190.00
27	1	Door Glass (RH) / SM	\$ 490.00 \$ 490.00
28	1	Door P/Window Motor (RH) X NN	\$ 520.00 \$ 520.00
29	1	Door P/Window Regulator (RH) X NN	\$ 295.00 \$ 295.00
30	2	Door Lock (LH/RH) RH - BT, LH X NN	\$ 255.00 \$ 510.00
31	1	Front Door Trim (RH) - re	\$ 465.00
32	10	Front Door Trim Clip - acc	\$ 2.50 \$ 25.00
33	1	Front Window Glass U-Channel (RH) - re	\$ 185.00
34	1	Front Window Glass Moulding (RH) - re	\$ 175.00
35	2	Front Door Sticker (LH/RH) (616) RH X NN, LH - acc	\$ 45.00 \$ 90.00
36	2	Front Door Sticker (LH/RH) (EURO 4) RH X NN, LH - acc	\$ 45.00 \$ 90.00
37	2	Front Cabin Pillar (LH/RH)(Outer) - 1/2 acc	\$ 340.00 \$ 680.00
38	2	Front Cabin Pillar (LH/RH)(Inner) - 1/2 acc	\$ 280.00 \$ 560.00
39	2	Front Cabin Pillar Upper (LH/RH)(Inner) X NN	\$ 220.00 \$ 440.00
40	2	Rear Cabin Pillar (LH/RH) (Outer) - 1/2 acc	\$ 520.00 \$ 1,040.00
41	2	Rear Cabin Pillar (LH/RH) Inner - 1/2 acc	\$ 250.00 \$ 500.00
42	2	Rear Cabin Pillar Upper (LH/RH) Inner X NN	\$ 235.00 \$ 470.00
43	2	Front Pillar Inner Garnish (LH/RH) - re	\$ 135.00 \$ 270.00
44	2	Front Door Pillar Moulding (LH/RH) - re	\$ 85.00 \$ 170.00
45	1	Roof Panel X repair	\$ 950.00
46	1	Roof Lining - clamp	\$ 650.00
47	1	Rear Cabin Panel - glue	\$ 1,150.00
48	1	Dashboard - CRA	\$ 380.00
49	1	Dashboard Meter Panel X NN	\$ 160.00
50	1	Dashboard Reinforcement X NN	\$ 285.00
51	1	Steering Shaft Cover (Bottom) X NN	\$ 95.00
52	1	Heater Assy X NN	\$ 950.00
53	1	Heater Water Pipe (Inlet) - 1/2 BT	\$ 85.00
54	1	Heater Water Pipe (Outlet) - 1/2 BT	\$ 85.00
55	1	Blower Assy X NN	\$ 890.00
56	1	Front Aircon Suction Pipe - 1/2 BT	\$ 158.00
57	1	Front Aircon Liquid Pipe - 1/2 BT	\$ 145.00
			\$ 25,089.00
			Cost +10%
			\$ 2,508.90
			\$ 27,597.90
58	1	Sealant - 1/2 acc	NETT \$ 40.00
59	1	IU Bracket - 1/2 acc	NETT \$ 15.00
60	1	Towing Fee X NN	NETT \$ 120.00
			\$ 27,772.90



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

ACCIDENT INVOLVING YN 3372 L, XD 8551 T & XB 7410 J ON 08/09/2018 ALONG SUNGAI KADUT DRIVE AT ABOUT 0855 HOURS

Estimate Repair List for Vehicle : YN 3372 L - Hino XZU710R

	Balance B/F	\$ 27,772.90
To dismantle, cut & weld front panel, front LH/RH cabin pillar, rear LH/RH cabin pillar, rear panel, roof panel, dismantle & change front LH/RH head lamp, front LH/RH door, front LH/RH corner panel, front bumper, front grille, knocking & pull straight front inner panel, front cabin bracket, re-align front cabin and all area affected by accident.	\$ 2,400.00	2000
To perform wire checking.	\$ 20.00	✓
To dismantle & refit new front windscreen.	\$ 120.00	✓
To transfer LH/RH door fitting and mechanism to new door.	\$ 120.00	✓
To dismantle & refit roof lining, seats, inner trim and garnish to facilitate repair.	\$ 150.00	120
To dismantle & refit dashboard.	\$ 150.00	✓
To dismantle & refit heater assy and blower assy.	\$ 150.00	X
To dismantle & refit rear wooden carrier, replace wooden rack & wooden drop grille. (1100)	\$ 2,000.00	X
To supply & install canopy. (1600)	\$ 3,800.00	X
To spray front bumper, front panel, front inner panel, front LH/RH corner panel, front LH/RH door, roof panel, rear panel and LH/RH cabin pillar.	\$ 1,800.00	1600

Excess : TBA
 Not Authorised.
 Quo Riang - 8288 0282
 17/9/18
 Lumpsum repair.
 After repair.
 14-16 Days

	\$ 38,482.90
7% GST	\$ 2,693.80
Total	\$ 41,176.70



 Authorised by Claims Dept
 Mrs Tan @ 9639 9195



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

STATEMENT

PARTICULARS

Name : Pazhani Sakthivel
 NRIC / Passport No. : FIN G 2368034W
 Address : 42 Sungai Kadut Loop (dormitory)
 Telephone : (R) _____ (O) _____
 (HP) 86732892
 Sex / Age : Male 25 yrs old
 Occupation / Name of Company : Construction / Driver
 Nationality : India National

Recorded By : P. Dryan Date : 26/09/18 Time: 1200hrs
 Place Recorded: LKK office
 Language Spoken: English Interpreted By: _____

FACTS OF CASE:

I am the above mentioned person and driver of vehicle YH 3372L when it was involved in an accident on 08/09/2018 at about 0855hrs along Sungai Kadut Drive.
 I am currently under the employment of Pan Wan Construction Pte Ltd, which is located at 33 Senoko Way.
 I am employed as a general driver since 25 November 2017. My job scope ~~include~~ include sending workers to job site and back to their dormitory as well as daily delivery of goods to various job sites. I am in possession of a valid class 2B and class 3 driving licence (Singapore) for the period July 2014 to July 2019. The vehicle YH 3372L is normally driven by my other colleague however as he is on home leave, I had drive it for about 10 days on the instruction of my company. The lorry I used to drive was sold hence I was instructed to drive this lorry YH 3372L. The previous lorry that I had driven was also same size as this lorry YH 3372L. I am therefore familiar with the handling of YH 3372L on 08/09/2018 at about 0730hrs, I had ~~drove~~ drive the vehicle YH 3372L with workers to a job site at Madras Street (Little India). After that, I drive the lorry to the company's warehouse at 42 Sungai Kadut Loop to check if there is

Signed:

Recorded by:

P. Sakthivel

G12368034W

STATEMENT

any delivery. As there was no scheduled delivery, I informed by supervisor that I will send the lorry to a workshop at Kranji Crescent to fix a leaking issue to the roof of the lorry's front cabin. It was during this journey that I was involved in the accident.

I was travelling on the right lane of the 2-lane roadway of Sungai Kadut Drive. I was alone, the lorry bed was empty. It was raining slightly at that time. As I was travelling along at an estimated speed of about 45kmph, the front vehicle XD8551T (a tipper truck) braked. I immediately also braked. But due to the wet road surface, I was not able to stop in time and the front of my lorry rounded into the rear portion of this tipper truck. I then switched off my engine and jumped out from the driver's door window as my door was stuck due to the accident. After alighting, I also noticed that the tipper truck driver had alighted. At this time, I estimate to be about less than 5 mins, a metal bin truck XB7410J rounded into the left rear side of my lorry causing the canopy to shift forward. The right side of the metal (centre) bin had hit the canopy of my lorry. ~~It~~ The metal bin lorry stopped about 10 metres away, ~~next to a bus~~ at a bus stop. Ambulance was activated by me after the accident. A passing Police Patrol car stopped behind my lorry. I exchanged particulars with the other 2 drivers and I was subsequently conveyed to hospital as my right knee was injured. My lorry was subsequently towed from the scene by towing service that was arranged by my company.

I wish to add that there is no issue with this lorry YN3372L. The brakes and tyre condition was fine. I believe that the wet road surface had caused my lorry to move forward and cannot stop in time.

I have read the above statement and confirm it to be true to the best of my recollection.

That's all

Signed:

P. Subramaniam

G 2368 034W

Recorded by:

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

TAX INVOICE

GREAT AMERICAN INSURANCE COMPANY

3 Temasek Avenue #16-01

Centennial Tower (S) 039190

TEL/HP : 68046053

FAX : 62353354

REMARK :

NO : 1308834

DATE : 29/04/2019

VEHICLE NO : YN3372L

VEH MODEL : HINO XZU71

CHASSIS NO. :

MILEAGE :

PAGE 1 OF 1

TERM : DAYS

W/O REF.

FROM : SO003734

1 TENDER REPAIR	1	14,118.00	14,118.00
2 LESS EXCESS	1 LOT	-600.00	-600.00
			<u>SS 13,518.00</u>

FORTEEN THOUSAND FOUR HUNDRED AND SIXTY FOUR AND CENTS
TWENTY SIX ONLY

SUB-TOTAL : S\$ 13,518.00

ADD.GST 7% : S\$ 946.26


TOTAL : S\$ 14,464.26

ADV.PYMT : S\$ (0.00)

BALANCE : S\$ 14464.26

Customer's Signature/Co. Stamp

for SNG AH TEE MOTOR & PANEL SERVICE PTE LTD


SHARON

CASH/CHEQUE UPON COLLECTION OF CAR
ALL CHEQUES MUST BE MADE PAYABLE TO 'SNG AH TEE MOTOR & PANEL SERVICE PTE LTD'
OCBC BANK ACCOUNT NO. 514-734425-001
PLEASE WRITE THE INVOICE AND/OR VEHICLE NO. ON THE BACK OF THE CHEQUE

E & O E

CLAIM NO. CLMOMVC 0000037457

DATE: 29/11/2019

TO: MOTOR CLAIMS DEPT

Great American Insurance Company

Satisfaction & Discharge Voucher

I/ We hereby declare that the repair to my/our Hino 300
vehicle No. YN 3372L have been completed to my/our satisfaction
and I/We agree that the payment of the account of \$ 14464.76 (Dollars
Fourteen thousand Four hundred Sixty - Four & Cents Twenty Six) paid to SNG AH
TEE MOTOR & PANEL SERVICE PTE. LTD. AT BLK 3 PIONEER ROAD NORTH #01-18
SINGAPORE 628457 for such repairs are in full discharge of my/our claim under Policy no.
MOMVC 00000795-00-000 in respect of the damages caused in
the accident which occurred on the 8th day of Sept
20 18. I/ We authorized the workshop appointed by me/us to bill to
Great America Insurance Company


Signature of Assured





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18016841/Gqbe2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 02-05-2019	
		Code : GAI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	YN 3372L
Policy No.		Coverage (\$)	0.00
Claim No.	MOMVC000007785-00-000	Excess (\$)	600.00
Assign From	RACHEL TAN	Assign Date	14/09/2018
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JHHUCP3H30K004497	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16	DOUBLE HAPPINESS	5 mm
L/H Front Tyre	7.00 R16	DOUBLE HAPPINESS	5 mm
R/H Rear Tyre	7.00 R16 (D)	DOUBLE HAPPINESS	5/5 mm
L/H Rear Tyre	7.00 R16 (D)	DOUBLE HAPPINESS	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/09/2018	Inspection Date	17/09/2018
Survey held at	25D SUNGEI KADUT STREET 1 S(729332)		
Repairer	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$50,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 3372L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP)	BENT	980.00	980.00
2	FRONT BUMPER BRACKET (LH/RH) @\$295.00 (WCP)	NOT NECESSARY	590.00	-
2	FRONT HEAD LAMP (LH/RH) @\$1020.00 (WCP)	O/S CUT / N/S NOT NECESSARY	2,040.00	1,020.00
1	FRONT GRILLE (WCP)	MISSING	680.00	680.00
10	FRONT GRILLE CLIP @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	EMBLEM (WCP)	NECESSARY	75.00	75.00
1	STICKER (HINO) (WCP)	NECESSARY	38.00	38.00
1	STICKER (300) (WCP)	NECESSARY	36.00	36.00
1	FRONT PANEL (OUTER) (WCP)	BUCKLED	480.00	480.00
2	FRONT CORNER PANEL (LH/RH) @\$450.00 (WCP)	O/S DEFORMED / N/S NOT NECESSARY	900.00	450.00
2	FRONT CORNER PANEL PAD (LH/RH) @\$6.00 (WCP)	NOT NECESSARY	12.00	-
2	FRONT CORNER PANEL SEAL PLATE (LH/RH) @\$28.00 (WCP)	NOT NECESSARY	56.00	-
12	FRONT CORNER PANEL CLIP (LH/RH) @\$2.00 (WCP)	NECESSARY	24.00	24.00
1	FRONT WINDSCREEN MOULDING (WCP)	NECESSARY	35.00	35.00
1	FRONT WINDSCREEN (WCP)	SMASHED	1,580.00	1,580.00
1	FRONT WIPER ARM (LH) (WCP)	BENT	105.00	105.00
1	FRONT WIPER ARM (RH) (WCP)	BENT	99.00	99.00
1	FRONT WIPER BLADE (LH/RH - 1 SET) (WCP)	CUT	60.00	60.00
1	FRONT WIPER LINKAGE (WCP)	NOT NECESSARY	340.00	-
1	SIDE MIRROR ROUND (RH) (WCP)	CUT	135.00	135.00
1	SIDE MIRROR STAND (LH) (WCP)	BROKEN	395.00	395.00
2	DOOR (LH/RH) @\$1328.00 (WCP)	N/S BENT / O/S BUCKLED	2,656.00	2,656.00
2	DOOR WEATHER STRIP (LH/RH) @\$85.00 (WCP)	TORN	170.00	170.00
4	DOOR HINGE (LH/RH) UPPER / LOWER @\$75.00 (WCP)	O/S BENT / N/S NOT NECESSARY	300.00	150.00
2	DOOR CHECKER (LH/RH) (WCP)	O/S BENT / N/S NOT NECESSARY	135.00	67.50
2	DOOR LOWER PROTECTOR (LH/RH) @\$95.00 (WCP)	NECESSARY	190.00	190.00

Report Ref No. CS/GAI18016841/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR GLASS (RH) (WCP)	SMASHED	490.00	490.00
1	DOOR P/WINDOW MOTOR (RH) (WCP)	NOT NECESSARY	520.00	-
1	DOOR P/WINDOW REGULATOR (RH) (WCP)	NOT NECESSARY	295.00	-
2	DOOR LOCK (LH/RH) @\$255.00 (WCP)	O/S BENT / N/S NOT NECESSARY	510.00	255.00
1	FRONT DOOR TRIM (RH) (WCP)	DEFORMED	465.00	465.00
10	FRONT DOOR TRIM CLIP @\$2.50 (WCP)	NECESSARY	25.00	25.00
1	FRONT WINDOW GLASS U-CHANNEL (RH) (WCP)	DEFORMED	185.00	185.00
1	FRONT WINDOW GLASS MOULDING (RH) (WCP)	DEFORMED	175.00	175.00
2	FRONT DOOR STICKER (LH/RH) (616) @\$45.00 (WCP)	O/S NOT NECESSARY / N/S NECESSARY	90.00	45.00
2	FRONT DOOR STICKER (LH/RH) (EURO 4) @\$45.00 (WCP)	O/S NOT NECESSARY / N/S NECESSARY	90.00	45.00
2	FRONT CABIN PILLAR (LH/RH) (OUTER) @\$340.00 (WCP)	BUCKLED	680.00	680.00
2	FRONT CABIN PILLAR (LH/RH) (INNER) @\$280.00 (WCP)	BUCKLED	560.00	560.00
2	FRONT CABIN PILLAR UPPER (LH/RH) (INNER) @\$220.00 (WCP)	NOT NECESSARY	440.00	-
2	REAR CABIN PILLAR (LH/RH) (OUTER) @\$520.00 (WCP)	BUCKLED	1,040.00	1,040.00
2	REAR CABIN PILLAR (LH/RH) INNER @\$250.00 (WCP)	BUCKLED	500.00	500.00
2	REAR CABIN PILLAR UPPER (LH/RH) INNER @\$235.00 (WCP)	NOT NECESSARY	470.00	-
2	FRONT PILLAR INNER GARNISH (LH/RH) @\$135.00 (WCP)	DEFORMED	270.00	270.00
2	FRONT DOOR PILLAR MOULDING (LH/RH) @\$85.00 (WCP)	DEFORMED	170.00	170.00
1	ROOF PANEL (WCP)	TO REPAIR SEE LABOUR	950.00	-
1	ROOF LINING (WCP)	CRUMPLED	650.00	650.00
1	REAR CABIN PANEL (WCP)	BUCKLED	1,150.00	1,150.00
1	DASHBOARD (WCP)	CRACKED	380.00	380.00
1	DASHBOARD METER PANEL (WCP)	NOT NECESSARY	160.00	-
1	DASHBOARD REINFORCEMENT (WCP)	NOT NECESSARY	285.00	-
1	STEERING SHAFT COVER (BOTTOM) (WCP)	NOT NECESSARY	95.00	-
1	HEATER ASSY (WCP)	NOT NECESSARY	950.00	-
1	HEATER WATER PIPE (INLET) (WCP)	BENT	85.00	85.00

Report Ref No. CS/GAI18016841/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEATER WATER PIPE (OUTLET) (WCP)	BENT	85.00	85.00
1	BLOWER ASSY (WCP)	NOT NECESSARY	890.00	-
1	FRONT AIRCON SUCTION PIPE (WCP)	BENT	158.00	158.00
1	FRONT AIRCON LIQUID PIPE (WCP)	BENT	145.00	145.00
	COST PLUS 10%		2,508.90	1,700.35
			27,597.90	18,703.85
	SPECIAL NETT ITEMS			
1	SEALANT (SN)	NECESSARY	40.00	40.00
1	IU BRACKET (SN)	NECESSARY	15.00	15.00
			55.00	55.00
	LABOUR			
	TOWING FEE.	NOT NECESSARY	120.00	-
	TO DISMANTLE, CUT & WELD FRONT PANEL, FRONT LH / RH CABIN PILLAR, REAR LH / RH CABIN PILLAR, REAR PANEL, ROOF PANEL, DISMANTLE & CHANGE FRONT LH / RH HEAD LAMP FRONT LH / RH DOOR, FRONT LH / RH CORNER PANEL, FRONT BUMPER, FRONT GRILLE, KNOCKING & PULL STRAIGHT FRONT INNER PANEL, FRONT CABIN BRACKET, RE-ALIGN FRONT CABIN AND ALL AREA AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF ROOF PANEL.		2,400.00	2,000.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT NEW FRONT WINDSCREEN.		120.00	120.00
	TO TRANSFER LH / RH DOOR FITTING AND MECHANISM TO NEW DOOR.		120.00	120.00
	TO DISMANTLE & REFIT ROOF LINING, SEATS, INNER TRIM AND GARNISH TO FACILITATE REPAIR.		150.00	120.00
	TO DISMANTLE & REFIT DASHBOARD.		150.00	150.00
	TO DISMANTLE & REFIT HEATER ASSY AND BLOWER ASSY.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIT REAR WOODEN CARRIER, REPLACE WOODEN RACK & WOODEN DROP GRILLE.	NOT NECESSARY	2,000.00	-
	TO SUPPLY & INSTALL CANOPY.	NOT NECESSARY	3,800.00	-

Report Ref No. CS/GAI18016841/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY FRONT BUMPER, FRONT PANEL, FRONT INNER PANEL, FRONT LH / RH CORNER PANEL, FRONT LH / RH DOOR, ROOF PANEL, REAR PANEL AND LH / RH CABIN PILLAR.		1,800.00	1,600.00
			10,830.00	4,130.00
GRAND TOTAL			38,482.90	22,888.85
RECOMMENDED COST OF REPAIRS (AS PER AGREEMENT BETWEEN INSURANCE AND REPAIRER AT REPAIR COST \$14,118.00)				14,118.00
LESS EXCESS				-600.00
NETT LIABILITY				13,518.00

Report Ref No. CS/GAI18016841/Gqbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.