

ASS. REC. BY:

REF:

CS/SMD18016846/Klsbⁿ²

Special Instruction:

SURVEYOR:

meimen

ASSIGNMENT (Office)

From (Person):

Agnes Chun

of

SMD

Date/Time:

14092018 4:25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1003U

Insured:

XD 1346R

at Workshop m/s

Premier

Tel:

65446671

of

33 Chung South Ave 2 #01-02

Policy No:

Claim No:

CM1803992

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A

14092018

CA / REV / REP. / REV 24 HRS w/p

17092018

H.O.D. Endorsement:

Date/Time:

14092018 4:27pm

Person Contacted:

Gany

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 1003U - CS/msh17014388 / KlgbXX DA: 250717
	XD 1346R - CS/SMD17015449 / Mlgbej DA: 050817
18/09/18	@ 14:32 p.m. revised IA to Agnes Chun via meimen.

Customer: Kalvin

REF: SMD

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 10034

at Workshop m/s: Premier

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 10034 Yr Regn: 11 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685

Colour: Silver A/C: Ins / Ed / Std / NI / NA

Sp. Reading: — T/Radio: Ins / Ed / Std / NI / NA

Eng/No: _____

C/No: KNA6M414MFS 657888

Gen. Cond: Good / Fa / Poor / Burnt

Steering: Inorder / U / Jammed / Leaked / Burnt or

Brake: Inorder / U / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / U / STA/Rim or

Tyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Max x.3

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 14/9/18 D.O.I. 17/9/18

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front nds

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/11/18	Veh cannot start Checked PIP \$21,178.10 / 10 days.
03/12/18	Confirmed PIP \$21,178.10 @ 10 days with Kalvin. (\$ 3,457.50 - Red - 14%)

RECEIVED 04 DEC 2018

[Signature]
4/12/2018

Date/Time, File Pass to? 04/12/18
1) Typist
Date/Time, File Return to? _____

: Preli. Report
 : Final Report

Days Of Repair: 10
Resurvey No. of Trip: 1

Report Format : _____
Lump Sum / I.B.I: (\$ 21,178.10 AP)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	450
Transportation:	10
TOTAL	460

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 18 Sep 2018

Preliminary Advice

Insured Vehicle No	: XD1346R	Accident Date	: 14/09/2018
TP Vehicle No	: SHD1003U	Assignment Date	: 14/09/2018
Make	: KIA OPTIMA	Est. Duration of Repair	: 7-8 days
Date of Inspection	: 17/09/2018		
Inspection At	: Premier Automotive Services Pte Ltd (Changi) 23 Changi South Ave 2 #01-02 Singapore 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,254.10
Revised Amount	:S\$	11,142.20
Check Items (Estimated)	:S\$	9,648.00
Total	:S\$	20,790.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2018		14 Sep 2018 16:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CA TRANSPORTATION & WAREHOUSING PTE LTD, Co. Reg. No.: 199200740D		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHD1003U	Date of Loss:	14/09/2018 06:00 - :59
Claim Type:	TP / CMTD1803992	Policy/Cover Note No.:	D18MTHCVE001686 (Third Party Only)
Vehicle Reg. No. (Insured):	XD1346R	Policy No. (Claimant):	
		Excess:	
Repairer:	Premier Automotive Services Pte Ltd (Changi) 23 Changi South Ave 2 #01-02, 486443 Changi - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 14 September, 2018 4:26 PM
To: Gary Shi; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Goh Wee Dek; Vincent Chua; Chan, Shu Hui Agnes; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1803992/AGC - SUV(LKK)/ XD1346R & SHD1003U ACC ON 14.09.18

Without Prejudice

Our Claim Reference: CMTD1803992/AGC
Your Reference: SHD1003U

Hi Gary,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

As spoken, we shall appoint **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SHD1003U on a without Prejudice Basis and without any admission of liability basis.

Please submit with your report via Merimen upon completion of survey to my colleague, Ms. Agnes Chan.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Gary Shi [mailto:gary.shi@premiertaxi.com]
Sent: Friday, September 14, 2018 12:41 PM
To: Claims - Motor Survey
Cc: Goh Wee Dek; Vincent Chua
Subject: Pre-inspection / Accident involving SHD1003U & XD1346R on 14.09.18

Dear all,

We refer to the above mentioned.

Kindly arrange for survey.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/09/2018 09:56
Date Of Accident	14/09/2018 06:20
Exact Location Of Accident	WEST COAST ROAD // PANDAN GARDENS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD1003U
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	TAY KIM SIA
NRIC No	S1639034H
Date Of Birth	29/10/1963
Occupation	OUTDOOR
Date Of Driving Pass	05/01/1984
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97467512
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 336A #10-28 ANCHORVALE CRESCENT
Postcode	541336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

BOTH VEH. - NO PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1346R
Vehicle Make/Model/Colour	PRIME MOVER + CONTAINER = TRD3373U
Details Of Properties	VEH. B
Vehicle Category	GOODS VEHICLE
Name of Driver	AGILAN A/L JAYABALAN
NRIC/Passport Number	G7496989K
Contact Number	98906515/96530759 - COMPANY
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT PORTION
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten signature]

14 SEP 2018

[Handwritten signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/RC SketchPlanForm_v3

25-1639034-H
49747512
SHD10034

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHD-10030

B: XD 1346R.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

X AB

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14 SEP 2018

GIARMC Sketch Plan Form v3

XS-1639034-H

Describe Circumstance of the Accident.

ON 14/09/2018 @ 0620HRS, I WAS DRIVING MY TAXI (SHD 1003 U), TRAVELLING ALONG THE TRAFFIC LIGHT JUNCTION OF WEST COAST ROAD & PANDAN GARDENS - IN THE RIGHT LANE.


TRAFFIC LIGHT AHEAD WAS SHOWING GREEN ARROW (BLINKING) - ON MY ROUTE FAVOUR & I PROCEED AHEAD WITH MY RIGHT INDICATOR - TO MAKE A RIGHT TURN INTO PANDAN GARDENS.

IN THE MIDST OF TURNING RIGHT INTO PANDAN GARDENS, SUDDENLY VEHICLE B (XD 1346 R - PRIME MOVER WITH CONTAINER TRD 3373 U) WHICH WAS APPROACHING FROM THE OPPOSITE DIRECTIONS, FAILED TO STOP - THUS BEAT THE RED TRAFFIC LIGHT & CONTINUED MOVING FORWARD. UPON SEEING IT, I WAS UNABLE TO STOP IN TIME & WAS FORCED TO COLLIDE ONTO THE FRONT PORTION OF VEHICLE B.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE FRONT PORTION AND FRONT WINDSCREEN. VEHICLE B HAD DAMAGES ON THE FRONT PORTION AS WELL.

NO INJURY.
NO PASSENGERS ONBOARD BOTH VEHICLES.

*VIDEO FOOTAGE CAPTURED



Driver's Signature & NRIC Number
Friday, September 14, 2018 @ 10:11:23 AM

(attended by



S1639034-H



Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	11 Dec 2015 / 08:57:51	Receipt No.:	AACCK001-AX239-151211-000009
Asset Type:	Vehicle	Transaction Amount:	\$68,285.00
Asset ID:	SHD1003U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151211085751160306		

Vehicle No.:	SHD1003U
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	11 Dec 2015
Original Registration Date:	11 Dec 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5657858
Engine No.:	D4FDFH314565
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,913.00
Minimum PARF Benefit:	\$13,607.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	11 Dec 2015 08:57:51
COE No.:	2015121101003452C
COE Expiry Date:	10 Dec 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,466.00
Lifespan Expiry Date:	10 Dec 2023

CASH SALE/WORK ORDER No:Y 9008



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL : 6743 1987 (3 LINES) FAX : 6743 0013
Reg No: 200415052W

Messrs: Premier Date: 14/9/18

車號 Vehicle No: SHP 1003 U 車型 Model No: Optima

由 From: West Coast Rd

到 To: Changi South

其他 Remark: Omega-L1 ERP BLE #1-50 MCE #3-00

時間 Time:

0	8	0	7	0	8	:	8	5	-	0	9	0
---	---	---	---	---	---	---	---	---	---	---	---	---

 AMOUNT: \$

注意: 本公司所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人 Authorised by: 4363 收貨人 Received by: [Signature]

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1003 U

1 pc	Bonnet	— Bent	\$	979.00	*
1 pc	Bonnet insulator	X sus	\$	219.00	
1 pc	Bonnet lock	— Bent	\$	36.00	*
1 pc	Bonnet lifter	— Bent	\$	70.00	*
2 pc	Bonnet hinge o/s & n/s @ \$23.00	— Bent	\$	46.00	*
1 pc	Bonnet weatherstrip	X sus	\$	58.00	
1 pc	Bonnet cable long	— tm	\$	25.00	*
1 pc	Bonnet cable short	— tm	\$	15.00	*
1 pc	Bonnet strip seal centre	X sus	\$	23.00	
2 pcs	Bonnet strip seal n/s & o/s @ \$25.00	X sus	\$	50.00	
1 pc	Bonnet grille	— em	\$	385.00	*
1 pc	Wiper top garnish	— em	\$	368.00	*
1 pc	Front windscreen	— em	\$	801.00	*
1 pc	Front windscreen moulding	— em	\$	87.00	*
1 pc	Support panel	— Bent	\$	645.00	*
1 pc	Support panel top cover	— em	\$	40.00	*
1 pc	Front bumper strip	X sus	\$	28.00	
1 pc	Front bumper	— Rebound	\$	531.00	*
1 pc	Front bumper emblem	— em	\$	44.00	*
1 pc	Front bumper centre grille	— em	\$	174.00	*
1 pc	Front bumper lower stiffer	X repair	\$	134.00	
1 pc	Front bumper tow hook cover	X repair	\$	14.00	
1 pc	Front bumper lip	— em	\$	52.00	*
1 pc	Front bumper inner sponge	— tm	\$	110.00	*
1 pc	Front bumper reinforcement	— Bent	\$	328.00	*
1 pc	Front bumper upper reinforcement	X repair	\$	40.00	
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	n/s — em o/s X sus	\$	32.00	16
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	n/s — em o/s X sus	\$	32.00	16
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	n/s — em o/s X sus	\$	32.00	16
2 pcs	n/s & o/s headlamp @ \$1028.00	— em	\$	2,056.00	*
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00	n/s missing o/s X sus	\$	132.00	66
2 pcs	Front bumper o/s & n/s protector @ \$51.00	n/s missing o/s X sus	\$	102.00	51
1 pc	Front n/s fender	— Bent	\$	384.00	*

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1003 U

1 pc	Front n/s fender inner shield	— torn	\$	120.00
1 pc	Front n/s wheel house	— Buckled	\$	484.00
1 pc	Air con condenser	✓ Bent	\$	805.00
1 pc	Air con discharge hose	X sue	\$	129.00
1 pc	Air con liquid pipe	X sue	\$	215.00
1 pc	Suction and liquid tube	X sue	\$	619.00
1 pc	Radiator	✓ Bent	\$	669.00
2 pc	Radiator top mounting @ \$18.00	X sue	\$	36.00
1 pc	Intercooler	✓ Bent	\$	800.00
1 pc	Blower assy	✓ cr	\$	596.00
1 pc	Washer tank motor	X sue	\$	48.00
1 pc	Washer tank	X sue	\$	47.00
1 pc	Radiator upp hose	— torn	\$	78.00
1 pc	Radiator Lower hose	— torn	\$	64.00
1 pc	Engine under cover- Front	✓ torn	\$	44.00
1 pc	Engine under cover- n/s	✓ torn	\$	144.00
1 pc	Engine under cover- o/s	✓ torn	\$	173.00
1 pc	Air cleaner box	— cr	\$	483.00
1 pc	Air duct	— cr	\$	210.00
1 pc	ECU	✓ cr	\$	2,281.00
1 pc	Wiring Assy	✓ torn	\$	3,672.00
			\$	19,789.00
			Less 10%	\$ 1,978.90
				<u>\$ 17,810.10</u>

16162-60

S/NETT

1 pc	Front no. plate with casing	— cr	\$	50.00
1 pc	Front bumper clips	— ne	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	n/s — cr o/s X sue	\$	12.00 6
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	n/s — cr o/s X sue	\$	6.00 3
1 set	Bonnet insulator clips	X in	\$	52.00
1 set	Wiper garnish clips	— nec	\$	48.00
1 pc	Battery	— cr 50%	\$	180.00 90
1 pc	Coolant 6L	— nec	\$	80.00
2 pcs	Front n/s & o/s fender inner shield clips @ \$24.00	n/s — cr o/s X sue	\$	48.00 24
1 pc	Front n/s fender stickers	— nec	\$	30.00
1 pc	Sealant	— nec	\$	50.00
1 set	n/s door stickers	— nec	\$	100.00

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1003 U

Towing Fee	\$	50.00	/
Sundry	net \$	50.00	20
To check for wiring and to focus head lamps	\$	40.00	20
To dismantle and replace the front windscreen	\$	120.00	100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
To dismantle and refit the dashboard to facilitate repair on front n/s wheel house	\$	450.00	150
To lift engine to facilitate repair on the front n/s wheel house	\$	450.00	150
To labour charge for dismantle and renew the accident damaged parts. To cut/heat and weld on the front n/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front n/s chassis member, front n/s door etc	\$	1,800.00	1200
To putty and spray painting on bonnet, bonnet grille, front bumper, front n/s fender, front o/s fender, front n/s door, front n/s chassis member	\$	1,400.00	1260
To apply rustproofing on the repaired and replaced panels.	\$	200.00	100
	\$	<u>23,254.10</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

24635.60

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Loh (1000)

17/9/18 1340hr

10 Days

PIP

Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are fixed to market level
- Third party survey is on a "no dispute" basis
- No illegal modifications allowed
- Supplemental charges are not surveyed and is subject to line approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

30-Nov-18

SUPPLEMENTARY REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1003 U

1 pc	Battery Tray	✓ <i>Buy</i>	\$	21.00
1 pc	Battery Bracket	✓ <i>ca</i>	\$	5.00
1 pc	Wiring- Control	✓ <i>turn</i>	\$	1,509.00
			\$	<u>1,535.00</u>
			Less 10%	\$ 153.50
				<u>\$ 1,381.50</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.



1770460

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18016846/K1SBN2

Date: 11/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE001686
Claimant Vehicle No :	SHD1003U	Insured Vehicle No :	XD1346R
Date of Loss:	14/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1803992

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1003U	Engine No:	D4DFDH314565
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5657858
Reg. Date:	11/12/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65R16	Rear Tyre Size:	205/65R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,945.60	18,098.10	1,847.50	9.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	3,080.00	1,610.00	34.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,635.60	21,178.10	3,457.50	14.03
+ GST 7.00/7.00% (S\$)	1,724.49	1,482.47	242.02	14.03
Nett Amount (S\$)	26,360.09	22,660.57	3,699.52	14.03

INSPECTION

Date of Assignment:	14/09/2018	
Date Inspected:	17/09/2018 Inspected At:	Premier Automotive Services Pte Ltd (Changi) 23 Changi South Ave 2 #01-02 Singapore 486443
Estimated Period of Repair:	10.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1003U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	979.00 FL	*979.00 FL
2	1		*BONNET INSULATOR	Serviceable	219.00 FL	*- FL
3	1		*BONNET LOCK	Bent	36.00 FL	*36.00 FL
4	1		*BONNET LIFTER	Bent	70.00 FL	*70.00 FL
5	2		*BONNET HINGE O/S & N/S	Bent	46.00 FL	*46.00 FL
6	1		*BONNET WEATHERSTRIP	Serviceable	58.00 FL	*- FL
7	1		*BONNET CABLE LONG	Torn	25.00 FL	*25.00 FL
8	1		*BONNET CABLE SHORT	Torn	15.00 FL	*15.00 FL
9	1		*BONNET STRIP SEAL CENTRE	Serviceable	23.00 FL	*- FL
10	2		*BONNET STRIP SEAL N/S & O/S	Serviceable	50.00 FL	*- FL
11	1		*BONNET GRILLE	Cracked	385.00 FL	*385.00 FL
12	1		*WIPER TOP GARNISH	Cracked	368.00 FL	*368.00 FL
13	1		*FRONT WINDSCREEN	Cracked	801.00 FL	*801.00 FL
14	1		*FRONT WINDSCREEN MOULDING	Necessary	87.00 FL	*87.00 FL
15	1		*SUPPORT PANEL	Bent	645.00 FL	*645.00 FL
16	1		*SUPPORT PANEL TOP COVER	Cracked	40.00 FL	*40.00 FL
17	1		*FRONT BUMPER STRIP	Serviceable	28.00 FL	*- FL
18	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
19	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
20	1		*FRONT BUMPER CENTRE GRILLE	Cracked	174.00 FL	*174.00 FL
21	1		*FRONT BUMPER LOWER STIFFER	Repair	134.00 FL	*- FL
22	1		*FRONT BUMPER TOW HOOK COVER	Repair	14.00 FL	*- FL
23	1		*FRONT BUMPER LIP	Cracked	52.00 FL	*52.00 FL
24	1		*FRONT BUMPER INNER SPONGE	Torn	110.00 FL	*110.00 FL
25	1		*FRONT BUMPER REINFORCEMENT	Bent	328.00 FL	*328.00 FL
26	1		*FRONT BUMPER UPPER REINFORCEMENT	Repair	40.00 FL	*- FL
27	1		*FRONT BUMPER O/S & N/S SIDE RETAINER	N/s Cracked/O/s Serviceable	32.00 FL	*16.00 FL
28	1		*FRONT BUMPER O/S & N/S UPPER BRACKET	N/s Cracked/O/s Serviceable	32.00 FL	*16.00 FL
29	1		*FRONT BUMPER O/S & N/S SUPPORT BRACKET	N/s Cracked/O/s Serviceable	32.00 FL	*16.00 FL
30	2		*N/S & O/S HEADLAMP	Cracked	2,056.00 FL	*2,056.00 FL
31	1		*FRONT BUMPER O/S & N/S FOG LAMP COVER	N/s Missing/O/s Serviceable	132.00 FL	*66.00 FL
32	1		*FRONT BUMPER O/S & N/S PROTECTOR	N/s Missing/O/s Serviceable	102.00 FL	*51.00 FL
33	1		*FRONT N/S FENDER	Dented	384.00 FL	*384.00 FL
34	1		*FRONT N/S FENDER INNER SHIELD	Torn	120.00 FL	*120.00 FL
35	1		*FRONT N/S WHEEL HOUSE	Buckled	484.00 FL	*484.00 FL
36	1		*AIR CON CONDENSER	Bent	805.00 FL	*805.00 FL
37	1		*AIR CON DISCHARGE HOSE	Serviceable	129.00 FL	*- FL
38	1		*AIR CON LIQUID PIPE	Serviceable	215.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*SUCTION AND LIQUID TUBE	Serviceable	619.00 FL	*- FL
40	1		*RADIATOR	Bent	669.00 FL	*669.00 FL
41	2		*RADIATOR TOP MOUNTING	Serviceable	36.00 FL	*- FL
42	1		*INTERCOOLER	Bent	800.00 FL	*800.00 FL
43	1		*BLOWER ASSY	Cracked	596.00 FL	*596.00 FL
44	1		*WASHER TANK MOTOR	Serviceable	48.00 FL	*- FL
45	1		*WASHER TANK	Serviceable	47.00 FL	*- FL
46	1		*RADIATOR UPP HOSE	Torn	78.00 FL	*78.00 FL
47	1		*RADIATOR LOWER HOSE	Torn	64.00 FL	*64.00 FL
48	1		*ENGINE UNDER COVER-FRONT	Torn	44.00 FL	*44.00 FL
49	1		*ENGINE UNDER COVER-N/S	Torn	144.00 FL	*144.00 FL
50	1		*ENGINE UNDER COVER-O/S	Torn	173.00 FL	*173.00 FL
51	1		*AIR CLEANER BOX	Cracked	483.00 FL	*483.00 FL
52	1		*AIR DUCT	Cracked	210.00 FL	*210.00 FL
53	1		*ECU	Cracked	2,281.00 FL	*2,281.00 FL
54	1		*WIRING ASSY	Torn	3,672.00 FL	*3,672.00 FL
55	1		*BATTARY TRAY	Bent	21.00 FL	*21.00 FL
56	1		*BATTARY BRACKET	Cracked	5.00 FL	*5.00 FL
57	1		*WIRING-CONTROL	Torn	1,509.00 FL	*1,509.00 FL
58	1		*FRONT NO PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
59	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
60	1		*FRONT O/S & N/S HEAD LAMP LOWER CLIP	N/s Cracked/O/s Serviceable	12.00 FS	*6.00 FS
61	1		*FRONT O/S & N/S HEAD LAMP SIDE CLIP	N/s Cracked/O/s Serviceable	6.00 FS	*3.00 FS
62	1		*SET BONNET INSULATOR CLIPS	Not Necessary	52.00 FS	*- FS
63	1		*SET WIPER GARNISH CLIPS	Necessary	48.00 FS	*48.00 FS
64	1		*BATTERY (50%)	Cracked	180.00 FS	*90.00 FS
65	1		*COOLANT 6L	Necessary	80.00 FS	*80.00 FS
66	1		*FRONT N/S & O/S FENDER INNER SHIELD CLIPS	Ns Necessary/Os Not Necessary	48.00 FS	*24.00 FS
67	1		*FRONT N/S FENDER STICKERS	Necessary	30.00 FS	*30.00 FS
68	1		*SEALANT	Necessary	50.00 FS	*50.00 FS
69	1		*SET N/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
70	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,078.00	20,048.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,132.40	1,949.90
Total Parts (\$\$)	19,945.60	18,098.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS	New	40.00	20.00
3	TO DISMANTLE AND REPLACE THE FRONT WINDSCREEN	New	120.00	100.00
4	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS	New	180.00	50.00
5	TO DISMANTLE AND REFIT THE DASHBOARD TO FACILITATE REPAIR ON FRONT N/S WHEEL HOUSE	New	450.00	150.00
6	TO LIFT ENGINE TO FACILITATE REPAIR ON THE FRONT N/S WHEEL HOUSE	New	450.00	150.00
7	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO CUT/HEAT AND WELD ON THE FRONT N/S WHEEL HOUSE INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE FRONT N/S CHASSIS MEMBER,FRONT N/S DOOR ETC	New	1,800.00	1,200.00
8	TO PUTTY AND SPRAY PAINTING ON BONNET,BONNET GRILLE,FRONT BUMPER,FRONT N/S FENDER,FRONT O/S FENDER,FRONT N/S DOOR,FRONT N/S CHASSIS MEMBER	New	1,400.00	1,260.00
9	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	100.00
Gross Labour Cost (S\$)			4,690.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >