

INS. CASE OWNER:

C 06 / AXA140

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time :

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner? (YES / NO)

If NO, Driver Name / Age :

Driver Tel No. :

Nature of Accident :

(V/L: YES / NO Insured Liability :

% Final ? Yes / No

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

XB 9368 K



INSRS:

WSP: K Kim Han

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age :

Driver's Own Vehicle Number:

Insurance Company:

XB 9368 K - x; XD 3809 J - x

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA :

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

4/12/15

called OI. Mohammed Sallah.

Inform about the claim. confirm the accident. He was a head of TP vehicle and TP collided into his vehicle from the rear left. no witness no video.

Letter out to OI to inform about the liability and no issue. KLV.

COPY SENT
12/11/15

FINAL SETTLEMENT

Date :

Confirm with

Repair Cost:

S\$

Final Liability:

%(Agreed / Assessed)

BOLA S/N No. : ML

Loss of Rental:

S\$

(days)

If NO or B 28, Ass. Lia :

Loss of Use:

S\$

(\$ x days)

1) Claim status: Normal/Reject/Private Settle

Disbursement:

2) Report Format: WP

Legal Cost :

S\$

3) Survey fee: 250

Total:

S\$

Global Sum: S\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC6/AXA14016899/Kza3	
8 SHENTON WAY #27-01SINGAPORE 068811		Date : 04-09-2014	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 3809J	Veh. Inspected	XB 9368K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/09/2014
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/09/2014	Inspection Date	03/09/2014
Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

No. : 26316

Vehicle Insured : XD 3809 J
Accident Date : 02-Sep-2014

Date : 10-Sep-2014

Our Ref : 140606 (AXA) / XW

PAGE : 1

HUP HOE TRANSPORT
Singapore

ESTIMATED COST OF REPAIR FOR NISSAN CKB45ABTN2 (2004) XB9368K
=====

1 pc	front bumper			By 1,750.00 ✓
1 pc	o/s front bumper side garnish			Di 225.00 ✓
1 pc	o/s front bumper foglamp			Si 330.00 X
1 pc	o/s front bumper top rubber pad			Di 180.00 ✓
1 pc	o/s front bumper lower side grille			Si 190.00 X
1 pc	o/s front bumper bracket			By 275.00 ✓
1 pc	o/s headlamp assy			Si 660.00 X
1 pc	o/s front signal lamp			Si 190.00 X
1 pc	o/s headlamp lower apron garnish			By 375.00 ✓
1 pc	o/s front corner garnish - outer & inner			CM 720.00 ✓
1 pc	o/s front door			By 3,600.00 ✓
1 pc	o/s front door "UD" logo			Di 120.00 ✓
1 pc	o/s front door signal lamp			Di 240.00 ✓
1 pc	o/s front door lower hinge			By 145.00 ✓
1 pc	o/s front door weatherstrip			Si 370.00 X
1 pc	o/s front door step panel-TOP			Si 165.00 X
1 pc	o/s front door step garnish			CM 495.00 ✓
1 pc	o/s front door step panel - lower			Di 165.00 ✓
1 pc	o/s front door step panel bracket			By 675.00 ✓
1 pc	o/s front splash shield			Di 240.00 ✓
2 pcs	o/s front splash shield bracket	@ S\$ 85.00		By 170.00 ✓
1 pc	o/s front door outer arch garnish			CM 580.00 ✓

Con't Page 2 ...

Vehicle Insured : XD 3809 J
Our Ref : 140606

Page : 2
No. : 26316

1 pc o/s front door regulator & motor
1 pc o/s wingmirror -stay
1 pc o/s wingmirror- big

]

Dis/In 350.00 ✓

R 150.00 X

Dis 90.00 ✓

12,450.00

Less 30% : -3,735.00

8,715.00

1 pc o/s front door signal bulb

Dis 15.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

600.00 *500*

To remove door's fittings

80.00 ✓

To putty and respray on affected
portions.

800.00 *700*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *20*

Total : S\$10,260.00

=====

Singapore Dollars Ten Thousand Two Hundred and
Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

DATE IN:

DOA: Mong

Machinery

REG. NUMBER:

XB 9368 K

MAKE/MODEL:

Nissan CKB45ABTN2

CHASSIS NUMBER:

CKB45ABT00405

QUANTITY	SPARE PARTS	COST PRICE
PC	Front Bumper ✓	
PC	o/s " " side garnish ✓	
PC	o/s " " Fog Lamp ?	
PC	o/s " " Top Rubber Pad ✓	
PC	o/s " " Lower Side Grille ?	
PC	o/s " " Bracket ✓	
PC		
PC	o/s Headlamp Assy X	
PC	o/s Front Signal Lamp X	
PC	o/s Headlamp Lower Apron Garnish ✓	
PC		
PC	o/s Front Corner Garnish - Outer ✓	
PC	" " " " - Inner ✓	
PC		
PC	o/s Front Door ✓	
PC	" " " " UD' log ✓	
PC	" " " " Signal Lamp ✓	
PC	" " " " Bulb ?	
PC	" " " " Lower Hinge ✓	
PC	" " " " weatherstrip ?	
PC	" " " " Step Panel - top X	
PC	" " " " Garnish ✓	
PC	" " " " Panel - Lower ✓	
PC	" " " " Bracket ✓	

LIST

* Currently all prices are not available.

* (If) Any supplementary will be forward accordingly.

金興(興)汽車私人有限公司

KIM HIN AUTO PTE.

新加坡新民道 (大牌34) 101-114

Blk 34 Sin Ming Drive #01-114

Singapore 575708

Tel: 6452 7018 (5 Lines)

Fax: 6458 3895

Admin-A (LKK Auto)

From: Jas Tan Siok Thiew [jas.tan@axa.com.sg]
Sent: Wednesday, 12 November, 2014 11:18 AM
To: Admin-A (LKK Auto)
Cc: KKLau; Zayyer; Winnie Ho Ping Ping
Subject: DS / K. KIM HIN / P1079117 / OD- XD3809J / TP- XB9368K / DOA: 02.09.2014 / EST: TBA / XS- 1000 / JT

Categories: HMK

Hi,
Please proceed with DS.

Thanks & regards

Jas Tan
Executive - Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Customer Care : 1800 8804741 press 3
Website: www.axa.com.sg



We are all born to protect, but for me it's a calling.
Discover our stories on www.borntoprotect.sg

redefining / insurance



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Admin-A (LKK Auto) [mailto:admin-a@lkkauto.com]
Sent: Tuesday, November 11, 2014 1:45 PM
To: Jas Tan Siok Thiew
Cc: KKLau; Zayyer; Winnie Ho Ping Ping
Subject: RE: WP / K. KIM HIN / P1079117 / OD- XD3809J / TP- XB9368K / DOA: 02.09.2014 / EST: TBA / XS- 1000 / JT

WITHOUT PREJUDICE

Dear Jas,

We refer to our below email.

Kindly advise whether we can proceed direct settlement for this case.

Thank You.

Best Regards,
Mei Kwan
LKK Auto Consultants Pte Ltd
DID: 6366 0055

FAX: 6741 4108
EMAIL: admin-a@lkkauto.com

From: Winnie Ho Ping Ping [<mailto:winnie.ho@axa.com.sg>]
Sent: Monday, 10 November, 2014 3:31 PM
To: Admin-A (LKK Auto); Jas Tan Siok Thiew
Cc: KKLau; Zayyer
Subject: RE: WP / K. KIM HIN / P1079117 / OD- XD3809J / TP- XB9368K / DOA: 02.09.2014 / EST: TBA / XS- 1000 / JT

Hi Jas,

OSP cleared.

Thanks & Regards

Winnie Ho
Claims Assistant – Claims Services
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
winnie.ho@axa.com.sg
Customer Care No. 1800 8804741 press 3
Website: www.axa.com.sg



We are all born to protect, but for me it's a calling.
Discover our stories on www.borntoprotect.sg

redefining / insurance



Please consider the environment before printing this message

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately

From: Admin-A (LKK Auto) [<mailto:admin-a@lkkauto.com>]
Sent: 10 November, 2014 11:32 AM
To: Winnie Ho Ping Ping; Jas Tan Siok Thiew
Cc: KKLau; Zayyer
Subject: RE: WP / K. KIM HIN / P1079117 / OD- XD3809J / TP- XB9368K / DOA: 02.09.2014 / EST: TBA / XS- 1000 / JT

WITHOUT PREJUDICE

Dear Winnie / Jas,

Kindly advise whether OI had reporting.

Thank You.

Best Regards,
Mei Kwan
LKK Auto Consultants Pte Ltd
DID: 6366 0055
FAX: 6741 4108
EMAIL: admin-a@lkkauto.com

From: Winnie Ho Ping Ping [mailto:winnie.ho@axa.com.sg]

Sent: Monday, 8 September, 2014 12:23 PM

To: assignments; Admin-A (LKK Auto); SUR

Cc: Jas Tan Siok Thiew; Tan Chia Ling (PSC); Ong Eng Hong (PSC); pinglin.chang@axa.com.my; siyu.lim@axa.com.my

Subject: WP / K. KIM HIN / P1079117 / OD- XD3809J / TP- XB9368K / DOA: 02.09.2014 / EST: TBA / XS- 1000 / JT

RISK 1 – P1079117

CLAIM RECEIVE : 05.09.2014

XD3809J (INSD) C/W XB9368K

IMP HOV

VTP

LKK : 08.09.2014

NCD : Y

CH : JT

Thanks & Regards

Winnie Ho

Claims Assistant – Claims Services

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

winnie.ho@axa.com.sg

DID: (65) 6880 4833

Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Admin-A (LKK Auto) [mailto:admin-a@lkkauto.com]

Sent: 05 September, 2014 9:38 AM

To: Winnie Ho Ping Ping; Tan Tiong Beng; Kitty Teo Poh Guek

Cc: KKLau; Zayyer

Subject: Direct Settlement - Accident Involving XD3809J (OI : AXA - TBA) & XB9368K (TP : LKK REF - CC6/AXA14016899/Kza3) on 02.09.2014

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle XB9368K at M/s K Kim Hin Auto Pte Ltd - Sin Ming on 03.09.2014.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair for your perusal.

Please be informed that our Preliminary Advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thank You.

Best Regards,

Mei Kwan

LKK Auto Consultants Pte Ltd

DID: 6366 0055

FAX: 6741 4108

EMAIL: admin-a@lkkauto.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AXA14016899/Kza3
AXA Policy No: P1079117

4 February 2015

UBTS PTE LTD
12 Tanjong Penjuru Crescent
Singapore 608975

Dear Sir/Madam,

ACCIDENT INVOLVING XD 3809J & XB 9368K ON 02/09/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 14/02/2015, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. As your policy carries an excess of \$ 1,000.00 under third party claim and the third party vehicle has lodged a claim against your policy, you are advised to issue a cheque of \$1,000.00 in favour of our principal AXA Insurance Singapore Pte Ltd to enable us to handle third party claim.

Please call us if you have further queries.

Yours faithfully,

Zayer
Case Handler
DID: 6749 9635
FAX: 6741 4108
Email: zayyer@lkkauto.com
c.c. *AXA Insurance Singapore Pte Ltd*
(Motor Claims Dept)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE SINGAPORE PTE LTD

Ref : CC6/AXA14016899/Kza3s2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 13-11-2015



ATTN: VALE OH

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 3809J	Veh. Inspected	XB 9368K
Policy No.	P1079117	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/09/2014

2. Vehicle Particulars & Condition

Make & Model	NISSAN	c.c	12503
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	CKB45ABT00405	Colour	YELLOW / RED
Odometer	569378	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	10.00X20X16	CEAT	6 mm
L/H Front Tyre	10.00X20X16	CEAT	6 mm
R/H Rear Tyre	10.00X20X16 (D)	CEAT	8/8 mm
L/H Rear Tyre	10.00X20X16 (D)	CEAT	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2014	Inspection Date	03/09/2014
Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 9368K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BENT	1,750.00	1,750.00
1	O/S FRONT BUMPER SIDE GARNISH (CONSISTENT)	DISTORTED	225.00	225.00
1	O/S FRONT BUMPER FOGLAMP (CONSISTENT)	SERVICEABLE	330.00	-
1	O/S FRONT BUMPER TOP RUBBER PAD (CONSISTENT)	DENTED	180.00	180.00
1	O/S FRONT BUMPER LOWER SIDE GRILLE (CONSISTENT)	SERVICEABLE	190.00	-
1	O/S FRONT BUMPER BRACKET (CONSISTENT)	BENT	275.00	275.00
1	O/S HEADLAMP ASSY (CONSISTENT)	SERVICEABLE	660.00	-
1	O/S FRONT SIGNAL LAMP (CONSISTENT)	SERVICEABLE	190.00	-
1	O/S HEADLAMP LOWER APRON GARNISH (CONSISTENT)	BENT	375.00	375.00
1	O/S FRONT CORNER GARNISH - OUTER & INNER (CONSISTENT)	CRACKED	720.00	720.00
1	O/S FRONT DOOR (CONSISTENT)	BENT	3,600.00	3,600.00
1	O/S FRONT DOOR "UD" LOGO (CONSISTENT)	NECESSARY	120.00	120.00
1	O/S FRONT DOOR SIGNAL LAMP (CONSISTENT)	NECESSARY	240.00	240.00
1	O/S FRONT DOOR LOWER HINGE (CONSISTENT)	BENT	145.00	145.00
1	O/S FRONT DOOR WEATHERSTRIP (CONSISTENT)	SERVICEABLE	370.00	-
1	O/S FRONT DOOR STEP PANEL - TOP (CONSISTENT)	SERVICEABLE	165.00	-
1	O/S FRONT DOOR STEP GARNISH (CONSISTENT)	CRACKED	495.00	495.00
1	O/S FRONT DOOR STEP PANEL - LOWER (CONSISTENT)	DISTORTED	165.00	165.00
1	O/S FRONT DOOR STEP PANEL - BRACKET (CONSISTENT)	BENT	675.00	675.00
1	O/S FRONT SPLASH SHIELD (CONSISTENT)	DISTORTED	240.00	240.00
2	O/S FRONT SPLASH SHIELD BRACKET @ \$ 85.00 (CONSISTENT)	BENT	170.00	170.00
1	O/S FRONT DOOR OUTER ARCH GARNISH (CONSISTENT)	CRACKED	580.00	580.00
1	O/S FRONT DOOR REGULATOR & MOTOR (CONSISTENT)	DISTORTED / JAMMED	350.00	350.00
1	O/S WINGMIRROR - STAY (CONSISTENT)	TO REPAIR SEE LABOUR	150.00	-
1	O/S WINGMIRROR - BIG (CONSISTENT)	MISSING	90.00	90.00

Report Ref No. CC6/AXA14016899/Kza3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 30% DISCCOUNT		-3,735.00	-3,118.50
			8,715.00	7,276.50
	<u>SPECIAL NETT ITEMS</u>			
1	O/S FRONT DOOR SIGNAL BULB (CONSISTENT) (SN)	SERVICEABLE	15.00	-
			15.00	-
	<u>LABOUR</u>			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF O/S WINGMIRROR - STAY .		600.00	500.00
	TO REMOVE DOOR'S FITTINGS.		80.00	80.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		800.00	700.00
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	20.00
			1,530.00	1,300.00
	GRAND TOTAL		10,260.00	8,576.50
	RECOMMENDED COST OF LUMP SUM REPAIRS. (TO ITS PRE-ACCIDENT CONDITION)			6,850.00

Report Ref No. CC6/AXA14016899/Kza3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.