

REF:

CC3/ALH18016867/Acb

ASS. REC. BY Adrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SLP7242X-

Yr Regn:

2017 / June

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

Make:

Audi Q2

cc 999

at Workshop mis

Colour:

Grey.

A/C: Insured / Std / NI / NA

of

Sp. Reading

8048

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WAU222GAG6HA022118

Claims No.

183147119959

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

1200 19/1/18

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Tyre Size:

F: 215/55R17.

R: 215/55R17.

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

115K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res: Yes or No

Lum Sum:

%

3 Val.: Yes or No

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

13/09/18.

Survey held at

Premium.

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SLP 7242X - (3/18/2018) 11:57 / 11:58

DUT: 03057018

17/1/18 @ 3.49pm request to Victor via Messenger.

18/1/18 @ 2.04pm Victor informed C/A via Messenger.

19/1/18 @ 9.19am Informed Jeffrey C/A to ex: \$1200 by email.

20/1/18 @ 5.10pm 2nd request to Victor via Messenger. (Supplementary)

04/12/18 @ 11.42am Victor informed C/A at 617213 via Messenger.

04/12/18 @ 1.33pm Informed Jeffrey approve on Supplementary Items (\$4087).

24/12/18 @ 11.43am confirmed with Currie for a fig of 14866.60, 5 days (Red \$9945.40, 40%.)

Date/Time, File Path to?

☐

: Preli. Report

Days Of Repair:

11/20/2 11:57am

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Path to?

D

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Ins (\$

☐

: Weekend (\$

Report Format

MER-00

Lump Sum / L.B.I. (\$

14866.60

Survey Fee:

Transportation

S + RS. \$

Photo

Other

TOTAL

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 24 December 2018 11:43 AM
To: 'Boo seng yak'; SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SLP7242X - OD AIG - SURVEYED 13 SEP 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$14,866.60 before excess \$1,200.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 10 December 2018 5:56 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLP7242X - OD AIG - SURVEYED 13 SEP 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$14,866.60 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 4 December 2018 1:33 PM
To: Claims Dept; Admin-D (LKKAUTO)
Subject: RE: Request Certificate Insurance for vehicle no. SLP 7242X

Dear Jeffrey,

Insurance just approve on supplementary items.

For your below email, we also don't have any idea why the officer take so long for approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Tuesday, 4 December 2018 12:16 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: Request Certificate Insurance for vehicle no. SLP 7242X

Dear Shiau Chan,

May we know what is taking AIG so long for the confirmation?

Kindly revert back.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Sep 2018 15:12	Cim Veh Model Changed		[] Merimen Administrator
2	01 Sep 2018 15:12	Cim Created	Reg No: SLP7242X, Acct Date: 2018/08/31, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd, (SG). Ins.Status => Notification, Created from SAS:MPA118113481	[I] Merimen Administrator
3	17 Sep 2018 11:38	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	17 Sep 2018 11:38	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	17 Sep 2018 11:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	17 Sep 2018 11:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] CATHERINE CHONG KAI LING
7	17 Sep 2018 11:38	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	17 Sep 2018 11:38	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	17 Sep 2018 11:38	Cim Veh Model Changed	(205236) AUDI Q2 999cc TFSI S-TRONIC (A).	[A] CATHERINE CHONG KAI LING
10	17 Sep 2018 11:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	17 Sep 2018 15:21	Cim Registration Modified	Init.Est.:->3,000 - 4,000, Excess: -> 1200.00, 2F Remarks: -> Not Applicable. GS T: -> 7.00.	[I] Dally Amri, Mimi Zarina
12	17 Sep 2018 15:21	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
13	17 Sep 2018 15:22	Adj Rpt Initiated		[A] SHIAU CHAN
14	17 Sep 2018 15:22	Cim Dtl Modified	JPJ Reg. Date: -> 2017/06/15.	[A] SHIAU CHAN
15	17 Sep 2018 15:22	Cim Details Notified		[A] SHIAU CHAN
16	17 Sep 2018 15:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
17	17 Sep 2018 15:49	Adj Mandate Request	Cur.Reg:15244.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	18 Sep 2018 14:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	18 Sep 2018 14:04	Adj Mandate Set	Approved:13976.00:Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.	[I] Koh, Victor-CK
20	20 Nov 2018 17:10	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
21	20 Nov 2018 17:10	Adj Mandate Request	Cur.Reg:18481.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	04 Dec 2018 11:42	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2018/09/26, Mandate Remarks: Submit survey report in merimen. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
23	04 Dec 2018 11:42	Adj Mandate Set	Approved:17213.00:Submit survey report in merimen. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1918403	17/09/2018 15:22	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP7242X		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 20 Nov 2018

Preliminary Advice

Vehicle No	: SLP7242X	Accident Date	: 31/08/2018
Make	: AUDI Q2	Policy No.	:
Assignment Date	: 17/09/2018	Excess	: S\$1,200.00
Date of Inspection	: 13/09/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,815.00	(ESTIMATE \$20,728.00 + SUPPLEMENTARY \$4,087.00)
Revised Amount	:S\$	17,213.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,268.00	
Total	:S\$	18,481.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	58,311.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,689.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 19 September 2018 9:19 AM
To: Claims Dept
Cc: SUR
Subject: RE: Request Certificate Insurance for vehicle no. SLP 7242X

Dear Jeffrey,

As instructed by our client, please proceed to repair the insured vehicle **SLP 7242X (Excess \$1,200/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Tuesday, 18 September 2018 5:59 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: Request Certificate Insurance for vehicle no. SLP 7242X

Dear Shiau Chan,

Kindly assist on the approval from AIG for this case.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 198902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Sep 2018 15:12	Cim Veh Model Changed		[] Merimen Administrator
2	01 Sep 2018 15:12	Cim Created	Reg No: SLP7242X, Acct Date: 2018/08/31. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification, Created from SAS:MPA118113481	[T] Merimen Administrator
3	17 Sep 2018 11:38	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	17 Sep 2018 11:38	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	17 Sep 2018 11:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	17 Sep 2018 11:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] CATHERINE CHONG KAI LING
7	17 Sep 2018 11:38	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	17 Sep 2018 11:38	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	17 Sep 2018 11:38	Cim Veh Model Changed	(205236) AUDI Q2 999cc TFSI S-TRONIC (A).	[A] CATHERINE CHONG KAI LING
10	17 Sep 2018 11:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	17 Sep 2018 15:21	Cim Registration Modified	Init.Est.->3,000 - 4,000. Excess: -> 1200.00. 2F Remarks: -> Not Applicable. GS T: -> 7.00.	[I] Dally Amri, Mimi Zarina
12	17 Sep 2018 15:21	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
13	17 Sep 2018 15:22	Adj Rpt Initiated		[A] SHIAU CHAN
14	17 Sep 2018 15:22	Cim Dtl Modified	JPJ Reg. Date: -> 2017/06/15.	[A] SHIAU CHAN
15	17 Sep 2018 15:22	Cim Details Notified		[A] SHIAU CHAN
16	17 Sep 2018 15:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
17	17 Sep 2018 15:49	Adj Mandate Request	Cur.Req:15244.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	18 Sep 2018 14:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26. Mandate Remarks: Re-Inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	18 Sep 2018 14:04	Adj Mandate Set	Approved:13976.00:Re-Inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1918403	17/09/2018 15:22	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP7242X		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 17 Sep 2018

Preliminary Advice

Vehicle No	: SLP7242X	Accident Date	: 31/08/2018
Make	: AUDI Q2	Policy No.	:
Assignment Date	: 17/09/2018	Excess	: S\$1,200.00
Date of Inspection	: 13/09/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,728.00
Revised Amount	:S\$	13,976.00
Check Items (Estimated)	:S\$	1,268.00
Total	:S\$	15,244.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	58,311.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,689.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9676M
Vehicle Details	
Vehicle No.:	SLP7242X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	Q2 SPORT 1.0 TFSI S TRONIC (NAV)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CHZ300978
Chassis No.:	WAUZZZGA6HA022118
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$30,753.00
Original Registration Date:	15 Jun 2017
First Registration Date:	15 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$25,055.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2027
PARF Rebate Amount:	\$18,791.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$39,520.00
Total Rebate Amount:	\$58,311.00

The information contained herein is correct as at 17 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/09/2018 14:38
Date Of Accident	31/08/2018 15:00
Exact Location Of Accident	22 LOCK ROAD OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP7242X
Insured/Policyholder	
Name Of Registered Owner	PREMIUM LEASING PTE LTD
Co Reg No	201009676M
Email Address	JACQUELYN.TAN@PREMIUMLEASING.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64712123
Vehicle Particulars	
Manufacturer	AUDI
Model	Q2 1.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	1
Driver	
Name of Driver	ANIELA MAWAR RAHARDJA
NRIC No	S8563875J
Date Of Birth	04/04/1985
Occupation	INDOOR
Date Of Driving Pass	12/05/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93699238
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

31/8/18

Driver's Signature
(If driver is not the policyholder)

Date & Time:

31/8/18



Reporting Centre Personnel's Signature

Name: LIM KEE SENG

NRIC/Fin No: G1855239M

Accident Photo




Accident Photo



Accident Photo







HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.400

COMPREHENSIVE COMMERCIAL MOTOR

CERTIFICATE NO. 999994451/100827963-00000

OWN DAMAGE EXCESS S\$1,200.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED S\$1.00
INSURING WITH COE/PAF YES

1) VEHICLE REGISTRATION NO.

SLP7242X

2) NAME OF INSURED

Premium Leasing Pte Ltd

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

21 Jul 2018

4) DATE OF EXPIRY OF INSURANCE

20 Jul 2019

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

Any person who is driving on the Insured's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use for the carriage of passengers or goods in connection with the insured's business.

Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.

The Policy does not cover

1) Use for racing, pace-making, reliability trial or speed-testing.

2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

LOSS OF USE NOT INCLUDED

* NAMED DRIVER N/A

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 14 Sep 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

504106-222
PREMIUM AUTOMOBILES PTE LTD
55 UBI ROAD 1
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 468699

Authorised Representative

ORIGINAL

SSCOSK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1038/2018/PH
Date	:	6-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Leasing Pte Ltd
Address	:	9 Leng Kee Rd, Singapore 159090
Telephone	:	HP +65 64712123
Type of Claim	:	Own Damage Claim
Policy No.	:	
Vehicle No	:	SLP 7242 X
Model Code	:	Audi Q2 Sedan 1.0 TFSI
Model / Year	:	Jun-17
Engine No	:	CHZ 300978
Chassis No	:	WAUZZZGA6HA022118
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Aug-18
Place of Accident	:	22 Lock Road open space carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X.

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00 1250 ✓
3	To respray front bumper, front lower spoiler, bonnet, both front wheel arc cover and bonnet hinges.	\$ 2,900.00 1600 + 1100 500 1600 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		\$ <u>5,902.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	\$ 1,620.00 ✓	1295.20
2	FIXING PARTS FOR FRONT BUMPER <i>Not nec</i>	\$ 297.00 X	
3	GRILLE - CENTRE <i>Cracked. Not nec</i>	\$ 269.00 X	
4	AIR GUIDE GRILLE - RH <i>Not nec</i>	\$ 319.00 X	
5	END CAP - RH <i>Not nec</i>	\$ 232.00 X	
6	FRONT SPOILER	\$ 292.00 X	
7	UNDERRUN BAR	\$ 410.00 X	
8	CLOSING ELEMENT	\$ 134.00 X	
9	WHEEL SPOILER - RH	\$ 30.00 X	
10	TRIM WHEEL HOUSING LINER LH/RH <i>Not nec</i>	2 \$ 58.00 ? X	
11	RADIATOR GRILLE <i>Cracked</i>	\$ 1,215.00 ✓	972
12	STRIKER PLATE <i>Not nec</i>	\$ 108.00 X	
14	FOAM FILLER PIECE <i>Not nec</i>	\$ 66.00 ? X	
15	FRONT BUMPER CARRIER <i>Not nec</i>	\$ 600.00 ? X	
16	BUMPER COVER <i>Not nec</i>	\$ 86.00 ✓	68.32
17	CAUTION' SIGN STICKER <i>Not nec</i>	\$ 12.00 ✓	9.78
18	BONNET <i>Dented</i>	\$ 2,378.00 ✓	1903.40
19	ATTACHMENT PARTS FOR BONNET <i>Not nec</i>	\$ 141.00 ? X	
20	LID HINGE - LH/RH <i>Not nec</i>	2 \$ 106.00 X	
SUB-TOTAL SPARE PARTS		\$ 8,373.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description		Damage Pa S/NETT	
21	LID HINGE - LH/RH } <i>new</i>	2 S	106.00 ✓	
22	STRIKER - LH/RH	2 S	192.00 ✓	
23	IMPACT PROTECTOR - CENTER <i>new</i>	S	26.00 ✓	20.32
24	IMPACT PROTECTOR - LH <i>new</i>	S	27.00 ✓	20.96
25	IMPACT PROTECTOR - RH <i>new</i>	S	26.00 ✓	20.32
26	LID LOCK WITH BONNET SWITCH <i>new</i>	2 S	353.00 ✓	
27	BOWDEN CABLE - CENTER } <i>new</i>	S	50.00 ✓	
28	BOWDEN CABLE	S	50.00 ✓	
29	BUNGS <i>new</i>	2 S	36.00 ✓	
30	WHEEL COVER - LH/RH FRONT <i>new</i>	2 S	736.00 ✓	598
31	CLIP <i>new</i>	S	45.00 ✓	X
32	MOUNTING FOR MAIN HEADLIGHT - RH <i>new</i>	S	103.00 ?	82.40 ✓
33	LED HEADLIGHT - RH <i>new</i>	S	4,378.00 ✓	3502.40
34	CAR PLATE - FRONT <i>new</i>	S/N S	25.00 ✓	
35	SUNDRIES <i>new</i>	S	300.00 ?	24.80 ✓
TOTAL SPARE PARTS		:	\$ 14,826.00	
TOTAL LABOUR CHARGES		:	\$ 5,902.00	
GRAND TOTAL		:	\$ 20,728.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 13/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/1038/2018/PH

14-Sep-18

Jeffery Tan

1

SLP 7242 X

Audi Q2 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>cracked</i>	\$ 854.00	✓ 693.70
2	Coolant <i>new</i>	\$ 133.00	✓ x
		\$ 987.00	
LABORS			
1	To remove and transfer air cond condenser, radiator, additional radiator, electrical fans, and contol unit. To carry out vacuum/regas to pressurise cooling system. (Special Nett)	\$ 1,000.00	✓
2	To renew front lock carrier and align to position. Reinstall all parts removed.	\$ 2,100.00	1250.00
TOTAL		\$ 4,087.00	

For Premium Automobiles Pte Ltd

Adrian Ling
88/8

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1038/2018/PH
Date : 6-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 10 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Rd
:
Singapore 159090
Telephone : HP +65 64712123
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SLP 7242 X**
Model Code : Audi Q2 Sedan 1.0 TFSI
Model / Year : Jun-17
Engine No : CHZ 300978
Chassis No : WAUZZZGA6HA022118
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Aug-18
Place of Accident : 22 Lock Road open space carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$ 360.00
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$	2,450.00	\$ 1,250.00
3	To respray front bumper, front lower spoiler, bonnet, both front wheel arc cover and bonnet hinges.		\$	2,900.00	\$ 1,600.00
4	Added labour charges		\$	3,100.00	\$ 2,250.00
5	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES			\$	9,002.00	\$ 5,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,620.00	\$ 1,295.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 297.00	
3	GRILLE - CENTRE	\$ 269.00	
4	AIR GUIDE GRILLE - RH	\$ 319.00	
5	END CAP - RH	\$ 232.00	
6	FRONT SPOILER	\$ 292.00	
7	UNDERRUN BAR	\$ 410.00	
8	CLOSING ELEMENT	\$ 134.00	
9	WHEEL SPOILER - RH	\$ 30.00	
10	TRIM WHEEL HOUSING LINER LH/RH	2 \$ 58.00	
11	RADIATOR GRILLE	\$ 1,215.00	\$ 972.00
12	STRIKER PLATE	\$ 108.00	
14	FOAM FILLER PIECE	\$ 66.00	
15	FRONT BUMPER CARRIER	\$ 600.00	
16	BUMPER COVER	\$ 86.00	\$ 68.32
17	CAUTION' SIGN STICKER	\$ 12.00	\$ 9.28
18	BONNET	\$ 2,378.00	\$ 1,902.40
19	ATTACHMENT PARTS FOR BONNET	\$ 141.00	
20	LID HINGE - LH/RH	2 \$ 106.00	
SUB-TOTAL SPARE PARTS		\$ 8,373.00	\$ 4,247.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X .

S/N	Parts Description	Damage Parts & Prices		
		S/NETT		REMARK:
		<i>c/f</i>	\$	4,247.20
21	LID HINGE - LH/RH	2 \$	106.00	
22	STRIKER - LH/RH	2 \$	192.00	
23	IMPACT PROTECTOR - CENTER	\$	26.00	\$ 20.32
24	IMPACT PROTECTOR - LH	\$	27.00	\$ 20.96
25	IMPACT PROTECTOR - RH	\$	26.00	\$ 20.32
26	LID LOCK WITH BONNET SWITCH	2 \$	353.00	
27	BOWDEN CABLE - CENTER	\$	50.00	
28	BOWDEN CABLE	\$	50.00	
29	BUNGS	2 \$	36.00	
30	WHEEL COVER - LH/RH FRONT	2 \$	736.00	\$ 588.00
31	CLIP	\$	45.00	
32	MOUNTING FOR MAIN HEADLIGHT - RH	\$	103.00	\$ 82.40
33	LED HEADLIGHT - RH	\$	4,378.00	\$ 3,502.40
34	CAR PLATE - FRONT	S/N \$	25.00	\$ 25.00
35	Added parts	\$	987.00	\$ 683.20
36	SUNDRIES	\$	300.00	\$ 24.80
	TOTAL SPARE PARTS	:	\$ 15,813.00	\$ 9,214.60
	TOTAL LABOUR CHARGES	:	\$ 5,902.00	\$ 5,652.00
	GRAND TOTAL	:	\$ 21,715.00	\$ 14,866.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1038/2018/PH 14-Sep-18 Jeffery Tan 1 SLP 7242 X Audi Q2 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Lock carrier	\$ 854.00	\$ 683.20
2	Coolant	\$ 133.00	
		\$ 987.00	\$ 683.20
<u>LABORS</u>			
1	Tp remove and transfer air cond condenser, radiator, additional radiator, electrical fans, and contol unit. To carry out vacuum/regas to pressurise cooling system. (Special Nett)	\$ 1,000.00	\$ 1,000.00
2	To renew front lock carrier and align to position. Reinstall all parts removed.	\$ 2,100.00	\$ 1,250.00
			\$ 2,250.00
TOTAL		\$ 4,087.00	\$ 2,933.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLP 7242 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1038/2018/MAS

15 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLP 7242 X, Audi Q2 1.0 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLP 7242 X**, claimant, **Premium Leasing Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013404 – S\$14,623.26
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLP 7242 X

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8563875J**

ANIELA MAWAR RAHARDJA

Birth Date **04 Apr 1985**
Issue Date **06 Apr 2018**

002790478G




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8563875J



Name
ANIELA MAWAR RAHARDJA

Race
CHINESE

Date of birth
04-04-1985

Country/Place of birth
INDONESIA

Sex
F

S8563875J



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 3	Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	12 May 2010

NP 428A



9477724



SPNC No. **S8563875J**



Nationality
INDONESIAN

Date of issue
09-03-2018

Address
**8 SCOTTS ROAD
#13-02
SINGAPORE 228238**



HOTLINE TEL: (65) 8419-3000
FAX: (65) 8415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MA 2 420

COMPREHENSIVE COMMERCIAL MOTOR

CERTIFICATE NO. 999994451/100827963-00000

OWN DAMAGE EXCESS S\$1,200.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED S\$1.00

INSURING WITH COE/PARF YES

1) VEHICLE REGISTRATION NO.

SLP7242X

2) NAME OF INSURED

Premium Leasing Pte Ltd

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

21 Jul 2018

4) DATE OF EXPIRY OF INSURANCE

20 Jul 2019

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

Any person who is driving on the Insured's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use for the carriage of passengers or goods in connection with the Insured's business.

Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.

The Policy does not cover

1) Use for racing, pace-making, reliability trial or speed-testing.

2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

LOSS OF USE NOT INCLUDED

* NAMED DRIVER N/A

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 14 Sep 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

504106-222
PREMIUM AUTOMOBILES PTE LTD
55 UBI ROAD 1
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 408695

Authorized Representative

ORIGINAL

SSCOSK



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119958
Main Telephone: 6386 2221
Main Telefax: 6471 3733
Page 1 18:01

Alexandra Service Centre
281 Alexandra Road
Singapore 119958
Telephone: 6386 2221
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408714
Telephone: 6386 1211
Telefax: 6471 3733

Customer Service
Service Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2221
6386 1211

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013404 Date : 21/01/2019 Order : SLP7242X Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP7242X IV 329521 Regn Date: 15/06/2017 Mileage: 8405 WIP No.: 39462
Model: Q2 1.0 TFSI S tronic (SPORT) G Chassis: WAUZZZ6A6H022118 Engine: CHZ 300978 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (50)

	Details	Qty	Unit Price	Amount
S	BODYWORK M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK M: TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK M: TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT WHEEL ARC COVER	1600.00	1.00	1,600.00
S	BODYWORK M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK M: TO REMOVE AND TRANSFER AIRCON CONDENSOR, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY PIT VACUUM/RESAS TO	1000.00	1.00	1,000.00
Sub-Total				
7% GST				
Grand Total				



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 2 18:01

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6388 2223
Telefax: 6475 1035

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2223
Telefax: 6475 1035

Customer Service
Service Appointment
4386 2223
6878 1233
Email: customers.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013404 Date : 21/01/2019 Order : SLP7242X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP7242X (V 32952) Regn Date: 15/06/2017 Mileage: 8405 WIP No.: 39462
Model: Q2 1.0 TFSI S tronic (SPORT) G Chassis: WAUZZZ6A6HA022118 Engine: CHZ 300978 Dept: U
VSB No.:
You have been assisted by :- (B-Jiayee (50)

		Details	Qty	Unit Price	Amount
S	BODYWORK	PRESSURISE COOLING SYSTEM N:	1250.00	1.00	1,250.00
		TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.			
D	EXC	N: 8888 Insurance Excess/Liability	-1200.00	1.00	-1,200.00
S	SUBLET	N: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
X	A81A853651 1RR	GRILLE Less 020%	1.00	1215.00	972.00
X	A81A941774A	HEADLIGHT Less 020%	1.00	4378.00	3,582.40
X	A81A807107 GRU	COVER Less 020%	1.00	746.50	597.20
X	A81A807108 GRU	COVER Less 020%	1.00	746.50	597.20
X	A81A853717A GRU	COVER Less 020%	1.00	367.50	294.00
X	A81A853718A GRU	COVER Less 020%	1.00	367.50	294.00
X	A81A805594A	CARRIER Less 020%	1.00	854.00	683.20
X	A81A823029	HOOD Less 020%	1.00	2378.00	1,902.40
X	A81A807563 GRU	CONN PIECE Less 020%	1.00	125.00	100.00
X	A81A823126	PROTECTION Less 020%	1.00	25.40	20.32
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6336 2223
Fax: 6331 2133

Alexandra Service Centre
181 Alexandra Road
Singapore 159538
Telephone: 6388 2223
Telefax: 6475 1033

Ubi Service Centre
52 Ubi Road 1
Singapore 408621
Telephone: 6888 2145

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2525
6838 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013404
Date : 21/01/2019
Order : SLP7242X
Term : 30

Accounts: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLP7242X (V 32952) Regn Date: 15/06/2017 Mileage: 8405 WIP No.: 39462
Model: Q2 1.0 TFSI S tronic (SPORT) 6 Chassis: WAUJZZGAGH022118 Engine: CHZ 300978 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (50)

		Details		Qty	Unit Price	Amount
X	A81A823125	PROTECTION	Less 020%	1.00	26.20	26.96
X	A81A805608	MOUNTING	Less 020%	1.00	103.00	82.40
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A8V0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	A81A121284K	AIR DUCT	Less 020%	1.00	24.90	19.92
X	A81A807081	COVER	Less 020%	1.00	85.40	68.32
X	A81A823124	PROTECTION	Less 020%	1.00	25.40	20.32

Parts 3,189.60
Labour 0.00
Sublet 5,677.00
Menus 0.00
Lubricant 0.00

Sub-Total 13,666.60
7% GST 956.66
Grand Total 14,623.26



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLP7242X

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1038/2018/TF
17 Oct 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q2 1.0 TFSI S tronic
Vehicle Chassis No. : WAUZZZGA6HA022118
Vehicle Regn No. : SLP7242X
Vehicle Mileage : 8405KM
Vehicle Owner : M/S Premium Leasing Pte Ltd
Certificate No : 999994451/100827963-00000
Policy Excess : S\$1,284.00 (Inclusive GST)
Accident Date : 31 August 2018
Place : 22 Lock Rd Open space carpark
Repair Cost : S 14,623.26
WIP No. : 39462
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



17/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		17 Sep 2018 11:38 Edit Adj Rpt	\$14,866.60 Edit Estimates	\$14,866.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	PREMIUM LEASING PTE LTD, Co. Reg. No.: 201009676M								
Vehicle Reg. No.:	SLP7242X	Date of Loss:	31/08/2018 15:00 - :59 [14 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1831471199SG	Policy/Cover Note No.:	(Comprehensive)						
		Excess:	\$1,200.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2018]								
Driver/Custodian:	ANIELA MAWAR RAHARDJA (33 / Female), NRIC: S8563875J, Tel: +6593699238 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/12/2018): Alert - Adj Mandate Approved (\$17213.00) - SLP7242X - Claim Handler: Dally Amri... - AIG_SG (18/09/2018): Alert - Adj Mandate Approved (\$13976.00) - SLP7242X - Claim Handler: Dally Amri... - AIG_SG (17/09/2018): SLP7242X / OD / 31/08/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7242X (1831471199SG)
OD

Aug 31 2018 3:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	17/09/18 15:48	Adjuster Immediate Advice														Load HTM				
2	20/11/18 17:10	Adjuster Immediate Advice														Load HTM				
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	17/09/18 15:27	General View														Load JPG		☒		
2	17/09/18 15:27	Chassis Number														Load JPG		☒		
3	17/09/18 15:27	General View														Load JPG		☒		
4	17/09/18 15:27	General View														Load JPG		☒		
5	17/09/18 15:27	General View														Load JPG		☒		
6	17/09/18 15:27	General View														Load JPG		☒		
7	17/09/18 15:27	General View														Load JPG		☒		
8	17/09/18 15:27	General View														Load JPG		☒		
9	17/09/18 15:27	General View														Load JPG		☒		
10	17/09/18 15:27	General View														Load JPG		☒		
11	17/09/18 15:27	General View														Load JPG		☒		
12	17/09/18 15:27	General View														Load JPG		☒		
13	17/09/18 15:27	General View														Load JPG		☒		
14	17/09/18 15:27	General View														Load JPG		☒		
15	17/09/18 15:27	General View														Load JPG		☒		
16	17/09/18 15:27	General View														Load JPG		☒		
17	17/09/18 15:27	General View														Load JPG		☒		
18	17/09/18 15:27	General View														Load JPG		☒		
19	17/09/18 15:27	General View														Load JPG		☒		
20	17/09/18 15:27	General View														Load JPG		☒		
21	17/09/18 15:27	General View														Load JPG		☒		
22	17/09/18 15:27	General View														Load JPG		☒		
23	17/09/18 15:27	General View														Load JPG		☒		
24	17/09/18 15:27	General View														Load JPG		☒		
25	17/09/18 15:27	General View														Load JPG		☒		
26	17/09/18 15:27	General View														Load JPG		☒		
27	17/09/18 15:27	General View														Load JPG		☒		
28	17/09/18 15:27	General View														Load JPG		☒		
29	20/11/18 17:11	Reinspection Photo														Load JPG		☒		
30	20/11/18 17:11	Reinspection Photo														Load JPG		☒		
31	20/11/18 17:11	Reinspection Photo														Load JPG		☒		
32	20/11/18 17:11	Reinspection Photo														Load JPG		☒		
33	20/11/18 17:11	Reinspection Photo														Load JPG		☒		
34	20/11/18 17:11	Reinspection Photo														Load JPG		☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	20/11/18 17:11	Reinspection Photo		☒
36	20/11/18 17:11	Reinspection Photo		☒
37	20/11/18 17:11	Reinspection Photo		☒
38	20/11/18 17:11	Reinspection Photo		☒
39	20/11/18 17:11	Reinspection Photo		☒
40	20/11/18 17:11	Reinspection Photo		☒
41	20/11/18 17:11	Reinspection Photo		☒
42	20/11/18 17:11	Reinspection Photo		☒
43	20/11/18 17:12	Reinspection Photo		☒
44	20/11/18 17:12	Reinspection Photo		☒
45	20/11/18 17:12	Reinspection Photo		☒
46	20/11/18 17:12	Reinspection Photo		☒
47	20/11/18 17:12	Reinspection Photo		☒
48	20/11/18 17:12	Reinspection Photo		☒
49	20/11/18 17:12	Reinspection Photo		☒
50	20/11/18 17:12	Reinspection Photo		☒
51	20/11/18 17:12	Reinspection Photo		☒
52	20/11/18 17:12	Reinspection Photo		☒
53	20/11/18 17:12	Reinspection Photo		☒
54	20/11/18 17:12	Reinspection Photo		☒
55	20/11/18 17:12	Reinspection Photo		☒
56	20/11/18 17:12	Reinspection Photo		☒
57	18/12/18 19:16	Reinspection Photo		☒
58	18/12/18 19:16	Reinspection Photo		☒
59	18/12/18 19:16	Reinspection Photo		☒
60	18/12/18 19:16	Reinspection Photo		☒
61	18/12/18 19:16	Reinspection Photo		☒
62	18/12/18 19:16	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:25	Singapore Accident Statement		
2	17/09/18 15:25	Certificate of Insurance		
3	17/09/18 15:26	ESTIMATE		
4	17/09/18 17:17	Driver's Driving License		
5	22/02/19 11:32	WORKSHOP INVOICE		
6	22/02/19 11:32	DISCHARGE VOUCHER		
7	22/02/19 11:32	SUPPLEMENTARY PART		

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/09/18 15:12	Accident Statement		
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/09/18 15:11	Accident Photo		☒
2	01/09/18 15:11	Accident Photo		☒
3	01/09/18 15:11	Accident Photo		☒
4	01/09/18 15:11	Accident Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
5	01/09/18 15:11	Accident Photo	 Load JPG	☒
6	01/09/18 15:11	Accident Photo	 Load JPG	☒
7	01/09/18 15:11	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/09/18 15:10	Sketch Plan	 Load JPG	☒
2	01/09/18 15:10	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016867/AQBQ2

Date: 22/02/2019

REFERENCE

Insured/Claimant: PREMIUM LEASING PTE LTD
Date of Loss: 31/08/2018

Policy No:
Nature of Claim: OD **Claim No:** 1831471199SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7242X	Engine No:	CHZ300978
Make & Model:	AUDI Q2, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZGA6HA022118
Reg. Date:	15/06/2017 (Man. Year: 2017)	Odometer:	8048 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,642.20	9,214.60	6,427.60	41.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,002.00	5,652.00	3,350.00	37.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,644.20	14,866.60	9,777.60	39.68
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
Nett Amount (S\$)	23,444.20	13,666.60	9,777.60	41.71

INSPECTION

Date of Assignment:	17/09/2018		
Date Inspected:	13/09/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,620.00 FS	*1,295.20 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	297.00 FS	*- FS
3	1		*GRILLE -CENTRE	Not Necessary	269.00 FS	*- FS
4	1		*AIR GUIDE GRILLE-RH	Not Necessary	319.00 FS	*- FS
5	1		*END CAP -RH	Not Necessary	232.00 FS	*- FS
6	1		*FRONT SPOILER	Not Necessary	292.00 FS	*- FS
7	1		*UNDERRUN BAR	Not Necessary	410.00 FS	*- FS
8	1		*CLOSING ELEMENT	Not Necessary	134.00 FS	*- FS
9	1		*WHEEL SPOILER -RH	Not Necessary	30.00 FS	*- FS
10	2		*TRIM WHEEL HOUSING LINER LH/RH	Not Necessary	58.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	1,215.00 FS	*972.00 FS
12	1		*STRIKER PLATE	Not Necessary	108.00 FS	*- FS
13	1		*FOAM FILLER PIECE	Not Necessary	66.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	600.00 FS	*- FS
15	1		*BUMPER COVER	Cut	86.00 FS	*68.32 FS
16	1		*CAUTION SIGN STICKER	Necessary	12.00 FS	*9.28 FS
17	1		*BONNET	Dented	2,378.00 FS	*1,902.40 FS
18	1		*ATTACHMENT PARTS FOR BONNET	Not Necessary	141.00 FS	*- FS
19	2		*LID HINGE -LH/RH	Not Necessary	106.00 FS	*- FS
20	2		*LID HINGE -LH/RH	Not Necessary	106.00 FS	*- FS
21	2		*STRIKER -LH/RH	Not Necessary	192.00 FS	*- FS
22	1		*IMPACT PROTECTOR -CENTER	Necessary	26.00 FS	*20.32 FS
23	1		*IMPACT PROTECTOR -LH	Necessary	27.00 FS	*20.96 FS
24	1		*IMPACT PROTECTOR -RH	Necessary	26.00 FS	*20.32 FS
25	2		*LID LOCK WITH BONNET SWITCH	Not Necessary	353.00 FS	*- FS
26	1		*BOWDEN CABLE-CENTER	Not Necessary	50.00 FS	*- FS
27	1		*BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
28	2		*BUNGS	Not Necessary	36.00 FS	*- FS
29	2		*WHEEL COVER -LH/RH FRONT	Necessary	736.00 FS	*588.00 FS
30	1		*CLIP	Not Necessary	45.00 FS	*- FS
31	1		*MOUNTING FOR MAIN HEADLIGHT -RH	Cracked	103.00 FS	*82.40 FS
32	1		*LED HEADLIGHT-RH	Cracked	4,378.00 FS	*3,502.40 FS
33	1		*CAR PLATE -FRONT	Necessary	25.00 FS	*25.00 FS
34	1		*SUNDRIES	Necessary	300.00 FS	*24.80 FS
35	1		*LOCK CARRIER	Cracked	683.20 FS	*683.20 FS
36	1		*COOLANT	Not Necessary	133.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	15,642.20	9,214.60
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIPE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND RHS HEADLIGHT .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER ,FRONT LOWER SPOILER ,BONNET ,BOTH FRONT WHEEL ARC COVER AND BONNET HINGES	New	2,900.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND TRANSFER AIR COND CONDENSER,RADIATOR,ADDITIONAL RADIATOR ,ELECTRICAL FANS , AND CONTOL UNIT.TO CARRY OUT VACUUM /REGAS TO PRESSURIES COOLING SYSTEM	New	1,000.00	1,000.00
6	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
Gross Labour Cost (S\$)			9,002.00	5,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >