

order 21/9/2018

Document Flow

 Status overview  Display document  Service documents 

Business partner 0000000771 Premium Automobiles Pte. Ltd.
Material 8X4833405D HINGE



Document		Quantity	Unit	On	Status
▼  Special Order 0004997182 / 130	▼  Delivery 0314787322 / 10	1 PC		21.09.2018	Completed
	•  Picking request 0142146335 / 10	1 PC		21.09.2018	Completed
	▼  Inv. ZSO2/ZSOA 0076721114 / 8	1 PC		21.09.2018	Completed
	•  Accounting document 0106270651	1 PC		18.12.2013	Not cleared
	•  Accounting document 0108019078	1 PC		21.09.2018	Not cleared
•  GD goods issue: delvy 5608796648 / 1		1 PC		21.09.2018	complete

Received 2709.2013

Display Stock Card

Part number: A

A8X4833405D

▲ Packed:

A8334058X4D

▼ Description:

HINGE

Exit

Help

Description | Other | Quantities | Prices And Costs | Demand | Movement | Lost Sales | Kit | Assembly | P.Orders | B.Orders | Imprest | Text

Decarded	Customer	Op	P/O Rqn	Invoice	WTP no	Qty	L	Result	Cost	Audit	I
01/10/2018	C0018	106	439056	0	24434	-1	2	0	12.18	3	S
27/09/2018	A0094	109	6456	76721114	76721114	1	2	1	12.18	2	P

Alternatives...

Quickmail...

Other stock...

Filter...

Legend

Sales

Purchases

Outside margin

Financial

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1068/2018/PH
Date	:	13-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Lim Lay See
Address	:	Blk 304A Anchorvale Link
	:	#07-146
	:	Singapore 541304
Telephone	:	HP +65 97846682
Type of Claim	:	OWN DAMAGE CLAIMS
Policy No.	:	2100510925-01
Vehicle No	:	SKS 701 E
Model Code	:	Audi Q5 2.0 TFSI
Model / Year	:	Jul-17
Engine No	:	DAX 005393
Chassis No	:	WAUZZZFY7H2023030
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Sep-18
Place of Accident	:	TPE exit to Loyang

Hi Adrian

You recommended 6 days

We took 12 days exclude 12 Sundays

Add parts with order fm Germany

jb 27 Oct 18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 701 E

S/N	Nature of Jobs	Estimated Charges	Surveyors's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00	\$ 280.00
3	To dismantle front bumper, lhs front fender and lhs front door. To renew lhs front fender, lhs front door and lhs wing mirror assy. Re-organise lhs crash management components.	\$ 3,150.00	\$ 1,500.00
4	To respray lhs front fender, lhs front door, lhs wing mirror cover and both front wheel arc covers.	\$ 2,500.00	\$ 1,700.00
4a	Added labour charges - see attached (\$200 for door cover \$50 for door hinge)	\$ 400.00	\$ 250.00
5	To carry out diagnostic check	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 7,002.00	\$ 4,402.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 701 E .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH	\$ 1,202.00	\$ 961.60
2	BRACKET - LH	\$ 15.00	
3	FRONT FENDER BRACE - LH	\$ 198.00	
4	COVER - LH	\$ 27.00	\$ 21.04
5	COVER - LH	\$ 35.00	\$ 27.28
6	COVER - LH OUTER	\$ 68.00	
7	FRONT DOOR - LH	\$ 2,692.00	\$ 2,153.60
8	OUTER DOOR SEAL	\$ 176.00	\$ 140.40
9	BONDING AGENT	\$ 43.00	
10	CLEANING SOLUTION	\$ 64.00	
11	ATTACHMENT PARTS FOR DOOR - FRONT LH	\$ 108.00	
12	DOOR SEAL, INNER	\$ 176.00	
13	DOOR CATCH	\$ 127.00	\$ 101.60
14	DOOR CATCH COVER	\$ 15.00	
15	DOUBLE SIDE-SIDED TAPE ADHESIVE TAPE	\$ 53.00	
16	WING MIRROR ASSEMBLY - LH	\$ 1,543.00	\$ 1,234.40
17	WING MIRROR CAP	\$ 418.00	
18	TURN SIGNAL FOR WING MIRROR CAP	\$ 111.00	
19	WING MIRROR LENS	\$ 1,483.00	
20	WHEEL COVER - FRONT LH/RH	2 \$ 1,090.00	\$ 872.00
21	SUPPLEMENTARY	\$ 674.00	\$ 538.88
22	SUNDRIES	\$ 300.00	\$ 39.76
	TOTAL SPARE PARTS	\$ 10,618.00	\$ 6,090.56
	TOTAL LABOUR CHARGES	\$ 7,002.00	\$ 4,402.00
	GRAND TOTAL	\$ 17,620.00	\$ 10,492.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1068/2018/PH
43363
jb
one
SKS701E
Q5 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Door hinge <i>Best</i>	\$ 40.00	\$ 31.68
	Door cover <i>new</i>	\$ 634.00	\$ 507.20
		\$674.00	\$ 538.88
<u>LABORS</u>			
1	To respray paint on LHS front door cover, hinges	\$ 400.00	\$ 250.00
TOTAL		\$ 1,074.00	\$ 788.88

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKS 701 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1068/2018/MAS

19 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKS 701 E, Audi Q5 Sport 2.0 TFSI Qu S-Tro

With reference to the above-mentioned vehicle, no. **SKS 701 E**, claimant, **Ms, Lim Lay See**, please find the related document per attached.

1. A copy of the Original invoice no. 85013345 – S\$10,157.04
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKS 701 E

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6399 1111

Customer Service
Service Appointment 6366 2223
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:24

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013345
Date : 02/01/2019
Order : SKS0701E
Term : 30

Account: 0000 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SKS0701E (V 34640) Regn Date: 20/07/2017 Mileage: 11156 WIP No.: 24434
Model: G5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF7H2023030 Engine: DAX 005393 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER, LHS FRONT DOOR. REPAIR LHS WING MIRROR ASSY. REORGANISE LHS CRASH MANAGEMENT COMPONENTS.	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER AND BOTH FRONT WHEEL	1700.00	1.00	1,700.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
981 Alexandra Road
Singapore 159938
Main Telephone: 6386 1223
Main Telefax: 6471 3733
Page 2 17:24

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408621
Telephone: 6388 3423
Telefax: 6471 1477

Customer Service
Service Appointment
hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013345
Date: 02/01/2019
Order: SKS0701E
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SKS0701E (V 34640) Regn Date: 20/07/2017 Mileage: 11156 WIP No.: 24434
Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF7H2023030 Engine: DAX 005393 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ARC COVER M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	250.00	1.00	250.00
		TO RESPRAY PAINT ON LHS FRONT DOOR COVER, HINGES			
X	A80A820581B	006471/(V) (GER) COVER	Less 020%	1.00	26.30
X	A8X4033405D	(V) (G) HINGE (BENDI)	Less 020%	1.00	39.60
X	A80C857409C 989	MOUNTING	Less 020%	1.00	1543.00
X	A80A821105A STL	FENDER	Less 020%	1.00	1202.00
X	A80A853718E GRU	COVER	Less 020%	1.00	545.00
X	A80A853717E GRU	COVER	Less 020%	1.00	545.00
X	A80A831051H STL	DOOR	Less 020%	1.00	2692.00
X	AD 007000A2	SILICSPRAY (DG)	Less 020%	1.00	29.30
X	A80A805285A 989	COVER	Less 020%	1.00	34.10
X	A80A837911D	006453/(V) (SK) SEAL	Less 020%	1.00	175.50
X	A8H0831701	BOLT	Less 020%	2.00	3.20
X	A3C0853506	GROMMET	Less 020%	5.00	2.40
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408600
Telephone: 6388 2223

Customer Service
Service Appointment
24 hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013345
Date: 02/01/2019
Order: SKS0701E
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SKS0701E (V 34640) Regn Date: 20/07/2017 Mileage: 11156 WIP No.: 24434
Model: GS SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF7H2023030 Engine: DAX 005393 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A00A837249	(GER)CHECK ROD			
X	AMHT003237	BOLT	1.00	127.00	101.60
X	A00A853959A GRU	(A)(SK)COVER 01/10/2	2.00	1.00	1.60
			1.00	634.00	507.20
Sub-Total					9,492.56
7% GST					664.48
Grand Total					10,157.04

Parts 6,090.56
Labour 0.00
Sublet 4,402.00
Menus 0.00
Lubricant 0.00

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SKS 701 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1068/2018/GW
26 Sept 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 Sport 2.0 TFSI Quattro
Vehicle Chassis No. : WAUZZZF7H2023030
Vehicle Regn No. : SKS 701 E
Vehicle Mileage : 11156 km
Vehicle Owner : Ms. Lim Lay See
Certificate No : 2100510925-01
Policy Excess : S\$1070.00(Inclusive of GST)
Accident Date : 11 September 2018
Place : TPE Exit To Loyang
Repair Cost : S 10,157.04
WIP No. : 04434
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 09/10/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2018		17 Sep 2018 11:41 Edit Adj Rpt	\$S\$10,492.56 Edit Estimates	\$S\$10,492.56 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM LAY SEE, ID: S7406457D, Tel: +6597846682, Email: GECKOLLS@SINGNET.COM.SG		
Vehicle Reg. No.:	SKS701E	Date of Loss:	11/09/2018 07:00 - :59 [13 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 5843383108SG	Policy/Cover Note No.:	2100510925-01 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2018]		
Driver/Custodian:	LIM LAY SEE (44 / Female), NRIC: S7406457D, Tel: +6597846682		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (18/09/2018): Alert - Adj Mandate Approved (\$S\$10966.00) - SKS701E - Claim Handler: Loo, Tong S...
- AIG_SG (17/09/2018): SKS701E / OD / 11/09/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS701E (5843383108SG)**
OD
Sep 11 2018 7:30AM
[LIM LAY SEE]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

1 per page
☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 14:52	Adjuster Immediate Advice	Load HTM	

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 14:53	General View	Load JPG	☒
2	17/09/18 14:53	Chassis Number	Load JPG	☒
3	17/09/18 14:53	General View	Load JPG	☒
4	17/09/18 14:53	General View	Load JPG	☒
5	17/09/18 14:53	General View	Load JPG	☒
6	17/09/18 14:53	General View	Load JPG	☒
7	17/09/18 14:53	General View	Load JPG	☒
8	17/09/18 14:53	General View	Load JPG	☒
9	17/09/18 14:53	General View	Load JPG	☒
10	17/09/18 14:53	General View	Load JPG	☒
11	17/09/18 14:53	General View	Load JPG	☒
12	17/09/18 14:53	General View	Load JPG	☒
13	17/09/18 14:53	General View	Load JPG	☒
14	17/09/18 14:53	General View	Load JPG	☒
15	17/09/18 14:53	General View	Load JPG	☒
16	17/09/18 14:53	General View	Load JPG	☒
17	17/09/18 14:53	General View	Load JPG	☒
18	17/09/18 14:53	General View	Load JPG	☒
19	13/11/18 09:02	Reinspection Photo	Load JPG	☒
20	13/11/18 09:02	Reinspection Photo	Load JPG	☒
21	13/11/18 09:02	Reinspection Photo	Load JPG	☒
22	13/11/18 09:02	Reinspection Photo	Load JPG	☒
23	13/11/18 09:02	Reinspection Photo	Load JPG	☒
24	13/11/18 09:02	Reinspection Photo	Load JPG	☒
25	13/11/18 09:02	Reinspection Photo	Load JPG	☒
26	13/11/18 09:02	Reinspection Photo	Load JPG	☒

1 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 14:52	Singapore Accident Statement	Load PDF	
2	17/09/18 14:52	Certificate of Insurance	Load PDF	
3	17/09/18 14:52	Driver's Driving License	Load PDF	
4	17/09/18 14:52	ESTIMATE	Load PDF	
5	25/01/19 15:41	SUPPLEMENTARY	Load PDF	
6	25/01/19 15:41	DISCHARGE VOUCHER	Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	25/01/19 15:41	WORKSHOP INVOICE	1 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	11/09/18 11:37	Accident Statement	1 Load HTM			
Photos/Images			3 per page	☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
2	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
3	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
4	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
5	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
6	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
7	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
8	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
9	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
10	11/09/18 11:33	Accident Photo	1 Load JPG	☒		
Documentation			1 per page	☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	11/09/18 11:26	Sketch Plan	1 Load JPG	☒		
2	11/09/18 11:26	Sketch Plan #2	1 Load JPG	☒		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☒ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016868/ATBS2
Date: 25/01/2019

REFERENCE

Insured/Claimant:	LIM LAY SEE	Policy No:	2100510925-01	Claim No:	5843383108SG
Date of Loss:	11/09/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS701E	Engine No:	DAX005393
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF7H2023030
Reg. Date:	20/07/2017 (Man. Year: 2017)	Odometer:	10983 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,482.88	6,090.56	4,392.32	41.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,002.00	4,402.00	2,600.00	37.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,484.88	10,492.56	6,992.32	39.99
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	16,484.88	9,492.56	6,992.32	42.42
+ GST 7.00/7.00% (S\$)	1,153.94	664.48	489.46	42.42
Nett Amount (S\$)	17,638.82	10,157.04	7,481.78	42.42

INSPECTION

Date of Assignment:	17/09/2018		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	14/09/2018	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Dented	1,202.00 FS	*961.60 FS
2	1		*BRACKET - LH	Not Necessary	15.00 FS	*- FS
3	1		*FRONT FENDER BRACE - LH	Not Necessary	198.00 FS	*- FS
4	1		*COVER - LH	Necessary	27.00 FS	*21.04 FS
5	1		*COVER - LH	Necessary	35.00 FS	*27.28 FS
6	1		*COVER - LH OUTER	Not Necessary	68.00 FS	*- FS
7	1		*FRONT DOOR - LH	Dented	2,692.00 FS	*2,153.60 FS
8	1		*OUTER DOOR SEAL	Necessary	176.00 FS	*140.40 FS
9	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
10	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
11	1		*ATTACHMENT PARTS FOR DOOR - FRONT LH	Not Necessary	108.00 FS	*- FS
12	1		*DOOR SEAL, INNER	Not Necessary	176.00 FS	*- FS
13	1		*DOOR CATCH	Damaged	127.00 FS	*101.60 FS
14	1		*DOOR CATCH COVER	Not Necessary	15.00 FS	*- FS
15	1		*DOUBLE SIDE - SIDED TAPE ADHESIVE TAPE	Not Necessary	53.00 FS	*- FS
16	1		*WING MIRROR ASSEMBLY - LH	Cut	1,543.00 FS	*1,234.40 FS
17	1		*WING MIRROR CAP	Repair	418.00 FS	*- FS
18	1		*TURN SIGNAL FOR WING MIRROR CAP	Repair	111.00 FS	*- FS
19	1		*WING MIRROR LENS	Not Necessary	1,483.00 FS	*- FS
20	2		*WHEEL COVER - FRONT LH/RH	Necessary	1,090.00 FS	*872.00 FS
21	1		*SUNDRIES	Necessary	300.00 FS	*39.76 FS
22	1		*DOOR HINGE	Bent	31.68 FS	*31.68 FS
23	1		*DOOR COVER	Necessary	507.20 FS	*507.20 FS
Total Parts (S\$)					10,482.88	6,090.56

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FENDER, LHS FRONT DOOR AND LHS WING MIRROR ASSY. RE-ORGANISE LHS CRASH MANAGEMENT COMPONENTS.	New	3,150.00	1,500.00
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER AND BOTH FRONT WHEEL ARC COVERS.	New	2,500.00	1,700.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
6	TO RESPRAY PAINT ON LHS FRONT DOOR COVER, HINGES.	New	400.00	250.00
Gross Labour Cost (S\$)			7,002.00	4,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >