

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 3646 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - RH <i>Distorted</i>	\$ 860.00	✓ <i>688</i>
2	ATTACHMENT PARTS FOR FENDER <i>Not nec</i>	\$ 49.00	? X
3	BRACKET FOR FENDER - FRONT RH <i>Not nec</i>	\$ 46.00	? X
4	BRACKET FOR DEFORMATION <i>Not nec</i>	\$ 43.00	? X
5	FENDER BRACE - RH LOWER <i>Not nec</i>	\$ 103.00	? X
6	CLOSING ELEMENT - RH <i>Not nec</i>	\$ 112.00	X
7	SEAL <i>Not nec</i>	\$ 26.00	X
8	STONE CHIP GUARD <i>Not nec</i>	\$ 39.00	✓ <i>31.20</i>
9	WHEEL HOUSING LINER - RH <i>Not nec</i>	\$ 215.00	X
10	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not nec</i>	\$ 38.00	X
11	FRONT DOOR - RH <i>Dented</i>	\$ 2,509.00	✓ <i>2007.20</i>
12	OUTER DOOR SEAL - RH <i>Not nec</i>	\$ 184.00	✓ <i>146.80</i>
13	BONDING AGENT <i>Not nec</i>	\$ 43.00	? X
14	CLEANING SOLUTION <i>Not nec</i>	\$ 64.00	? X
15	ATTACHMENT PARTS FOR DOOR <i>Not nec</i>	\$ 77.00	? X
16	DOOR SEAL, INNER <i>Not nec</i>	\$ 192.00	X
17	DOOR CATCH <i>Not nec</i>	\$ 1,054.00	X
18	DOOR CATCH COVER <i>Not nec</i>	\$ 14.00	X. <i>13.44</i> ✓
19	DATA PLATE FOR TYRE PRESSURE <i>Not nec</i>	\$ 17.00	X
20	FRONT ALUMINIUM RIM - RH <i>Not</i>	\$ 659.00	✓ <i>527.20</i>
SUB TOTAL SPARE PARTS		\$ 6,344.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

4268

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 3646 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT RH MICHELIN TYRE <i>Not on car.</i>	\$ 906.00	<i>x 320 ✓</i>
22	SUNDRIES ?	\$ 300.00	<i>x, nn</i>
TOTAL SPARE PARTS		:	\$ 7,550.00
TOTAL LABOUR CHARGES		:	\$ 5,152.00
GRAND TOTAL		:	\$ 12,702.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/1069/2018/GW
Date	05-Oct-18
Service Advisor	GW
Pages	1
Regn No	SFZ 3646 J
Model No	Audi A4 1.8 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT TYRE MICHELIN-RH	\$ 906.00	
		<u>\$ 906.00</u>	
	TOTAL	<u>\$ 906.00</u>	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1069/2018/PH
Date	:	13-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

you recommended 5 days -

We took 7 days - jb - 17 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tang Kok Thye
Address	:	26 Taman Mas Merah Singapore 128155
Telephone	:	HP +65 96675360
Type of Claim	:	OWN DAMAGE CLAIMS
Policy No.	:	
Vehicle No	:	SFZ 3646 J
Model Code	:	Audi A4 1.8 TFSI
Model / Year	:	Jun-14
Engine No	:	CJE 076544
Chassis No	:	WAUZZZ8K9EA115170
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Sep-18
Place of Accident	:	Along South Bridge Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFZ 3646 J

S/N	Nature of Jobs		Estimated Charges	Surveyors's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N	\$ 280.00	\$ 280.00
3	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender, rhs front door. Re-organise rhs crash management components. Reinstall all aprts removed.	\$	2,400.00	\$ 1,500.00
4	To respray rhs front fender, rhs front door.	\$	1,600.00	\$ 1,100.00
5	To renew rhs front rim and tyre. To carry out wheel alignment. To inspect for damages.	S/N	\$ 320.00	\$ 320.00
6	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,152.00</u>	<u>\$ 3,752.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 3646 J .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - RH	\$ 860.00	\$ 688.00
2	ATTACHMENT PARTS FOR FENDER	\$ 49.00	
3	BRACKET FOR FENDER - FRONT RH	\$ 46.00	
4	BRACKET FOR DEFORMATION	\$ 43.00	
5	FENDER BRACE - RH LOWER	\$ 103.00	
6	CLOSING ELEMENT - RH	\$ 112.00	
7	SEAL	\$ 26.00	
8	STONE CHIP GUARD	\$ 39.00	\$ 31.20
9	WHEEL HOUSING LINER - RH	\$ 215.00	
10	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 38.00	
11	FRONT DOOR - RH	\$ 2,509.00	\$ 2,007.20
12	OUTER DOOR SEAL - RH	\$ 184.00	\$ 146.80
13	BONDING AGENT	\$ 43.00	
14	CLEANING SOLUTION	\$ 64.00	
15	ATTACHMENT PARTS FOR DOOR	\$ 77.00	
16	DOOR SEAL, INNER	\$ 192.00	
17	DOOR CATCH	\$ 1,054.00	
18	DOOR CATCH COVER	\$ 14.00	\$ 13.44
19	DATA PLATE FOR TYRE PRESSURE	\$ 17.00	\$ 527.20
20	FRONT ALUMINIUM RIM - RH	\$ 659.00	
SUB TOTAL SPARE PARTS		\$ 6,344.00	\$ 3,413.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 3646 J .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 3,413.84
21	FRONT RH MICHELIN TYRE	\$ 906.00	\$ 320.00
23	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS	\$ 7,550.00	\$ 3,733.84
	TOTAL LABOUR CHARGES	\$ 5,152.00	\$ 3,752.00
	GRAND TOTAL	\$ 12,702.00	\$ 7,485.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1069/2018/GW
5-Oct-18
GW
1
SFZ 3646 J
Audi A4 1.8 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT TYRE MICHELIN-RH <i>Left Reported</i>	\$ 906.00	X.
		\$ 906.00	
TOTAL		\$ 906.00	ITEM 21

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFZ 3646 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1069/2018/MAS

19 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SFZ 3646 J, Audi A4 1.8T FSI Mu

With reference to the above-mentioned vehicle, no. **SFZ 3646 J** claimant, **Mr. Tang Kok Thye**, please find the related document per attached.

1. A copy of the Original invoice no. 85013346 – S\$7,153.85
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFZ 3646 J

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2223
Main Telefax: 6471 3733
Page 1 09:45

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone: 6388 2323

Customer Service
Service Appointment: 6366 2223
24 hour Breakdown Service: 9826 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013346 Date : 03/01/2019 Order : SFZ3646J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SFZ3646J (V 23304) Regn Date: 26/06/2014 Mileage: 76638 WIP No.: 24633
Model: A4 1.8T FSI MU 8K203H NEW LIM Chassis: WAUZZZ8K9EA115170 Engine: CJE 076544 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. REORGANISE RHS CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR	1100.00	1.00	1,100.00
S	BODYWORK	M: TO RENEW RHS RIM AND TYRE. TO CARRY OUT WHEEL	320.00	1.00	320.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6386 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408608
Telephone 6386 2323

Customer Service
Service Appointment
Hour Breakdown Service:
Email customer.care@premiumauto.com.sg

6386 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 09:45

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013346 Date : 03/01/2019 Order : SFZ3646J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SFZ3646J (V 23304) Regn Date: 26/06/2014 Mileage: 76638 WIP No.: 24633
Model: A4 1.8T FSI MU 8K203H NEW LIM Chassis: WAUZZZ8K9EA115170 Engine: CJE 076544 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ALIGNMENT TO INSPECT FOR DAMAGES M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ZM225/55R16MP4	MICHELIN PRIMACY 4	1.00	320.00	320.00
X	ABK0821106J	FENDER	1.00	860.00	860.00
X	ABK0831052J	DOOR	1.00	2509.00	2,007.20
X	ABK0601025CL	(A) (SK) RIM 16" C9P(0	1.00	659.00	527.20
X	ABK0853824	STONEGUARD	1.00	39.00	31.20
X	ABK0010502KL	LABEL	1.00	16.80	13.44
X	ABK08379120	SEAL	1.00	183.50	146.80

Parts	3,733.84	Sub-Total	6,685.84
Labour	0.00	7% GST	468.01
Sublet	3,752.00	Grand Total	7,153.85
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SFZ 3646 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1069/2018/GW
10 October 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8 TFSI
Vehicle Chassis No. : WAUZZZ8K9EA115170
Vehicle Regn No. : SFZ 3646 J
Vehicle Mileage : 76641 KM
Vehicle Owner : Mr. Tang Kok Thye
Certificate No : 2100377178-04
Policy Excess : S\$856.00(inclusive of 7% GST)
Accident Date : 08th September 2018
Place : Along South Bridge Road
Repair Cost : \$ 7,135.85
WIP No. : 24633
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Sep 2018		17 Sep 2018 11:45 Edit Adj Rpt	S\$7,485.84 Edit Estimates	S\$7,485.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TANG KOK THYE, ID: S6876873Z, Tel: +6596675360, Email: kotthye@addp.sg		
Vehicle Reg. No.:	SFZ3646J	Date of Loss:	08/09/2018 20:00 - :59 [50 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3001604042SG	Policy/Cover Note No.:	(Comprehensive)
		Excess:	S\$800.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2018]		
Driver/Custodian:	TANG KOK THYE (58 / Male), NRIC: S6876873Z, Tel: +6596675360		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (18/09/2018): Alert - Adj Mandate Approved (S\$8020.00) - SFZ3646J - Claim Handler: Dally Amri,...
- AIG_SG (17/09/2018): SFZ3646J / OD / 08/09/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS ▾

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFZ3646J (3001604042SG)

OD

Sep 8 2018 8:05PM

[TANG KOK THYE]

Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

Assessment Reports			1 per page ▼	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:05	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page ▼	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:05	General View	Load JPG	☒
2	17/09/18 15:05	Chassis Number	Load JPG	☒
3	17/09/18 15:05	General View	Load JPG	☒
4	17/09/18 15:05	General View	Load JPG	☒
5	17/09/18 15:05	General View	Load JPG	☒
6	17/09/18 15:05	General View	Load JPG	☒
7	17/09/18 15:05	General View	Load JPG	☒
8	17/09/18 15:05	General View	Load JPG	☒
9	17/09/18 15:05	General View	Load JPG	☒
10	17/09/18 15:05	General View	Load JPG	☒
11	17/09/18 15:05	General View	Load JPG	☒
12	17/09/18 15:05	General View	Load JPG	☒
13	17/09/18 15:05	General View	Load JPG	☒
14	17/09/18 15:05	General View	Load JPG	☒
15	17/09/18 15:05	General View	Load JPG	☒
16	17/09/18 15:05	General View	Load JPG	☒
17	17/09/18 15:05	General View	Load JPG	☒
18	17/09/18 15:05	General View	Load JPG	☒
19	17/09/18 15:05	General View	Load JPG	☒
20	17/09/18 15:05	General View	Load JPG	☒
21	17/09/18 15:05	General View	Load JPG	☒
22	17/09/18 15:05	General View	Load JPG	☒
23	19/12/18 09:25	Reinspection Photo	Load JPG	☒
24	19/12/18 09:25	Reinspection Photo	Load JPG	☒
25	19/12/18 09:25	Reinspection Photo	Load JPG	☒
26	19/12/18 09:25	Reinspection Photo	Load JPG	☒

Documentation			1 per page ▼	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:07	Singapore Accident Statement	Load PDF	
2	17/09/18 15:07	Police Photos	Load PDF	
3	17/09/18 15:07	ESTIMATE	Load PDF	
4	17/09/18 16:28	Driver's Driving License	Load PDF	
5	17/09/18 16:28	Certificate of Insurance	Load PDF	
6	24/01/19 13:04	DISCHARGE VOUCHER	Load PDF	

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	24/01/19 13:04	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/09/18 19:20	Accident Statement	 Load HTM	

Photos/Images			3 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/09/18 18:37	Police Report	 Load JPG	☒
2	10/09/18 18:37	Police Report	 Load JPG	☒
3	10/09/18 18:37	Police Report	 Load JPG	☒
4	10/09/18 18:37	Police Report	 Load JPG	☒
5	10/09/18 18:37	Accident Photo	 Load JPG	☒
6	10/09/18 18:37	Accident Photo	 Load JPG	☒
7	10/09/18 18:37	Accident Photo	 Load JPG	☒
8	10/09/18 18:37	Accident Photo	 Load JPG	☒
9	10/09/18 18:37	Accident Photo	 Load JPG	☒
10	10/09/18 18:37	Accident Photo	 Load JPG	☒
11	10/09/18 18:37	Accident Photo	 Load JPG	☒
12	10/09/18 18:37	Accident Photo	 Load JPG	☒
13	10/09/18 18:37	Accident Photo	 Load JPG	☒
14	10/09/18 18:37	Accident Photo	 Load JPG	☒
15	10/09/18 18:37	Accident Photo	 Load JPG	☒
16	10/09/18 18:37	Accident Photo	 Load JPG	☒
17	10/09/18 18:37	Accident Photo	 Load JPG	☒
18	10/09/18 18:37	Accident Photo	 Load JPG	☒
19	10/09/18 18:38	Accident Photo	 Load JPG	☒
20	10/09/18 18:38	Accident Photo	 Load JPG	☒

Documentation			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/09/18 18:31	Sketch Plan	 Load JPG	☒
2	10/09/18 18:31	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016869/AQBS2
Date: 24/01/2019

REFERENCE

Insured/Claimant: TANG KOK THYE Policy No:
Date of Loss: 08/09/2018 Nature of Claim: OD Claim No: 3001604042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFZ3646J
Make & Model: AUDI A4, 1.8 TFSI (A) Engine No: CJE076544
Reg. Date: 26/06/2014 (Man. Year: 2014) Chassis No: WAUZZZ8K9EA115170
Colour: Black Odometer: 75690 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,550.00	3,733.84	3,816.16	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,152.00	3,752.00	1,400.00	27.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,702.00	7,485.84	5,216.16	41.07
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	11,902.00	6,685.84	5,216.16	43.83
+ GST 7.00/7.00% (S\$)	833.14	468.01	365.13	43.83
Nett Amount (S\$)	12,735.14	7,153.85	5,581.29	43.83

INSPECTION

Date of Assignment: 17/09/2018
Date Inspected: 14/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Distorted	860.00 FS	*688.00 FS
2	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	49.00 FS	*- FS
3	1		*BRACKET FOR FENDER - FRONT RH	Not Necessary	46.00 FS	*- FS
4	1		*BRACKET DEFORMATION	Not Necessary	43.00 FS	*- FS
5	1		*FENDER BRACE - RH LOWER	Not Necessary	103.00 FS	*- FS
6	1		*CLOSING ELEMENT - RH	Not Necessary	112.00 FS	*- FS
7	1		*SEAL	Not Necessary	26.00 FS	*- FS
8	1		*STONE CHIP GUARD	Necessary	39.00 FS	*31.20 FS
9	1		*WHEEL HOUSING LINER - RH	Not Necessary	215.00 FS	*- FS
10	1		*ATTACHMENTS PARTS FOR WHEEL HOUSING LINER	Not Necessary	38.00 FS	*- FS
11	1		*FRONT DOOR - RH	Dented	2,509.00 FS	*2,007.20 FS
12	1		*OUTER DOOR SEAL - RH	Necessary	184.00 FS	*146.80 FS
13	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
15	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	77.00 FS	*- FS
16	1		*DOOR SEAL, INNER	Not Necessary	192.00 FS	*- FS
17	1		*DOOR CATCH	Not Necessary	1,054.00 FS	*- FS
18	1		*DOOR CATCH COVER	Necessary	14.00 FS	*13.44 FS
19	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	17.00 FS	*- FS
20	1		*FRONT ALUMINIUM RIM - RH	Cut	659.00 FS	*527.20 FS
21	1		*FRONT RH MICHELIN TYRE	Cut	906.00 FS	*320.00 FS
22	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
				Total Parts (\$\$)	7,550.00	3,733.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR. RE-ORGANISE RHS CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,400.00	1,500.00
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR.	New	1,600.00	1,100.00
5	TO RENEW RHS FRONT RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT. TO INSPECT FOR DAMAGES.	New	320.00	320.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			5,152.00	3,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >