LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. To:

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Dally Amri, Mimi Zarina

Date:

13 Nov 2018

Preliminary Advice

Vehicle No

: SKV9834E

Accident Date

: 05/09/2018

Make

: AUDI A3

Policy No.

: 2100433003

Assignment Date

: 17/09/2018

Excess

: \$\$600.00

Date of Inspection

: 14/09/2018

Est. Duration of Repair

: 6.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,636.00
Revised Amount	:S\$	14,148.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,148.92

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	55,049.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,951.00

Remarks

()	<))	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
0	8)	Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

17 Sep 2018

Preliminary Advice

Vehicle No

: SKV9834E

Accident Date

: 05/09/2018

Make

: AUDI A3

Policy No.

: 2100433003

Assignment Date

: 17/09/2018

Excess

: \$\$0.00

Date of Inspection

: 14/09/2018

Est, Duration of Repair

: 6.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

SINGAPORE 408699

55 UBI ROAD 1

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,636.00
Revised Amount	:S\$	11,903.00
Check Items (Estimated)	:S\$	3,596.00
Total	:S\$	15,499.00

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	55,049.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,951.00

Remarks

	The vehicle is repairable at our adjusted amount let us have your authorisation.	t. We have also confi	irmed excess and policy	y coverage.	Kindly
--	--	-----------------------	-------------------------	-------------	--------

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Friday, November 16, 2018 12:14 PM

To:

'Boo seng yak'; Adrian Ling (LKKAuto); SUR; Carrine Leong;

jiayee.yap@premiumauto.com.sg; Chang Chee Sing

Subject:

RE: FINAL REVISION - SKV9834E - OD AIG - SURVEYED 14 SEP 18

Dear Mr. Boo,

Confirm repair cost of \$14,148.92 @ 6 days of repairs.

Kindly send us DV and Invoice for our early closure

Thank you.

est Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Saturday, November 10, 2018 5:13 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKV9834E - OD AIG - SURVEYED 14 SEP 18

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$14,148.92 @ 6 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAuto)

From:

Boo seng yak <boojohnny@gmail.com>

Sent:

Saturday, November 10, 2018 5:13 PM Adrian Ling (LKKAuto); Janice Lee (LKKAuto); SUR; Carrine Leong;

To:

jiayee.yap@premiumauto.com.sg; Chang Chee Sing

Subject:

FINAL REVISION - SKV9834E - OD AIG - SURVEYED 14 SEP 18

Attachments:

PA10432018- SKV 9834 E - A3 sedan 1.4 TFSI - FRONT (NTUC).xls; WhatsApp Image 2018-09-21 at 5.35.54 PM (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.54 PM (2) (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.55 PM (1) (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.56 PM (1) (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.56 PM (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.57 PM (2) (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.57 PM (2) (resize).jpeg; WhatsApp Image

2018-09-21 at 5.35.57 PM.jpeg; WhatsApp Image 2018-09-21 at 5.35.58 PM (1) (resize).jpeg; WhatsApp Image 2018-09-21 at 5.35.58 PM (2) (resize).jpeg

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$14,148.92 @ 6 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Wednesday, September 19, 2018 5:45 PM

To:

'Claims'; 'Nora Khai'; SUR

Subject:

RE: Request for OD approval SKV 9834 E -

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKV 9834E (excess \$600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-

25 | S(408933) ----- Original Message-----

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Wednesday, September 19, 2018 5:34 PM

To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: Request for OD approval SKV 9834 E -

Dear all,

Please update us on repair approval.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183 e. claims@premiumauto.com.sg w. www.audi.com.sg Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotion

Print Received Message

This mail is associated with:

*SKV9834E (1522723834SG)

OD

Sep 5 2018 10:00PM [CORDELIA TAN SIEW AIK] Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 16/11/2018 11:46 AM.

To Subject LKK_HQ

Alert - Adj Mandate Approved (S\$14148.92) - SKV9834E - Claim Handler: Dally Amri, Mimi Zarina

Approved:14148.92:		

Print Received Message

This mail is associated with:

*SKV9834E (1522723834SG)

OD

Sep 5 2018 10:00PM [CORDELIA TAN SIEW AIK] Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/09/2018 11:44 AM.

To

LKK_HQ

Alert - Adj Mandate Approved (S\$11903.00) - SKV9834E - Claim Handler: Dally Amri, Mimi Zarina Subject

Approved:11903.00:Re-inspection to be done for damage check and supplementary items / labour.

Print Received Message

This mail is associated with:

*SKV9834E (1522723834SG)

OD

Sep 5 2018 10:00PM [CORDELIA TAN SIEW AIK] Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/09/2018 11:00 AM.

To Subject LKK_HQ

SKV9834E / OD / 05/09/2018 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$600.00

Thank you

Dally Amri, Mimi Zarina

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	4604J	
Vehicle Details		
Vehicle No.:	SKV9834E	
Vehicle to be Exported:	No	
Intended Deregistration Date:	17 Sep 2018	
Vehicle Make:	AUDI	
Vehicle Model:	A3 SEDAN 1.4 TFSI (AMBIENTE)	
Primary Colour:	Grey	
Manufacturing Year:	2015	
	CZC276061	
Engine No.: Chassis No.:	WAUZZZ8V7G1014951	
Maximum Power Output:	92.0 kW (123 bhp)	
Open Market Value:	\$27,587.00	
Original Registration Date:	13 Oct 2015	
First Registration Date:	13 Oct 2015	
Transfer Count:	0	
Actual ARF Paid:	\$20,622.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	12 Oct 2025	
PARF Rebate Amount:	\$15,466.00	
Intended COE Rebate Details		
COE Expiry Date:	12 Oct 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$56,001.00	
COE Rebate Amount:	\$39,583.00	
Total Rebate Amount:	\$55,049.00	

The information contained herein is correct as at 17 Sep 2018

MPA118115659-01 / Premium Automobiles Pte Ltd - UBI ENTRY DATE & TIME: 06/09/2018 15:17 SUBMITTED BY: Tony Foong Chin Fong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI	DENIT	CTA	TEN	нымп
ACCI	JEN	314	-	

Date Of Report

06/09/2018 15:17

Date Of Accident

05/09/2018 22:15

Exact Location Of Accident

CTE (SLE) AFTER MOULMEIN EXIT

Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKV9834E

SINGAPORE

Insured/Policyholder

Name Of Registered Owner

CORDELIA TAN SIEW AIK

NRIC No

S6824604J

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-96863882

Alternative Phone No

OTHERS-96863882

Vehicle Particulars

Manufacturer

AUDI

Model

A3 SEDAN 1.4 TFSI

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

2100433003-02

Cover Note Number

Driver

Name of Driver

CORDELIA TAN SIEW AIK

NRIC No Date Of Birth S6824604J

01/07/1968

Occupation

INDOOR

Date Of Driving Pass

25/02/2000

Driving Experience

18 YEARS AND 6 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-96863882

Fax Number

Contact Number

OTHERS-96863882

EMail Address

NOEMAIL

Address

513 YIO CHUA KANG ROAD

#03-29

Postcode

787067

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: CLARESTA YEO

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

THE ACCIDENT HAPPENED ALONG CTE (SLE), AFTER MOULMEIN EXIT, THE CAR INFRONT (SKS1904E) TRY TO FILTER AND JAM BRAKE CAME TO A FULL STOP. I COULD NOT STOP IN TIME AND HIT THE CAR INFRONT. THE DRIVER GOT OUT AND KEEP APOLOGIZING AND ADMITTED WAS HER FAULT. SHE SAID SHE HAS BEEN TRYING TO FILTER BUT COULDN'T, THAT IS WHY SHE CAME TO A FULL STOP. SHE CLAIMED WAS HER FAULT AND WILLING TO TAKE FULL RESPONSIBILITY AND COMPENSATE THE DAMAGES, SUPPORTED HER COMMITMENT WITH HER STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SKS1904E

Details Of Properties

PRIVATE CAR

Vehicle Category

V. NITHIYA

Name of Driver

NRIC/Passport Number

S8917127Z

Contact Number

97851621

Address

Postcode

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

3

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: Tony Foo No NRIC/FIN No. (57) NO. 1477

6-0411471

Sketch Plan #2

LIFERIA DI ANI		
KETCH PLAN	Cont sup	A - 5k v 9 83
141411.7		
DESCRIBE CIRCUMSTANCES O	THE ACCIDENT	
	PENED ALUNG CTECSLE) A	FTER MULLMEIN GALT.
THE WAR TOTOGOT (SKS 1904E) TRY TO FILTER	AND JAM BRAKE CAME TO A
Kun Graft . L con	MA SMIT MY POTS TON GAN	DHIT THE CAR INTROVE
THE DRIVER GOT OUT	AND KEEP APVLUGIZING BEEN TRYING TO FILTER B	AND ADMITTED WAS HER FAULT. THAT'S WHY SHE
CAME TO A FULL STO	OF. SHE CLAIMED WAS HE	ER FAULT AND WILLING TO TAKE
FULL RESPONSIBILLT	Y AND COMPENSAGE THE DAM	MCES, SUPPORTED HER
COMMITMENT WITH		
DECLARATION		
I/We declare the foregoing particu	lars are true in every respect.	(()) »)
×t		Reporting Centre Personnel's Signature
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Name: To At Formy NRIC/FIN No.: 43-04-0147 X 7

THIRD PARTY STATEMENT

V. Nithuga / Str. V. Poorani 97851621/91769952 S9200426A 88917127Z We are at fault for this collistor & we will bettle any payments/damyon. Scs. 1904E 10-15pm Nissan Almana. CHE (SCE) after Moulmein Exit



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder Period of Insurance

: CORDELIA TAN SIEW AIK : 13 Oct 2017 To 12 Oct 2018

Engine No.

: CZC276061

Chassis No.

: WAUZZZ8V7G1014951

Vehicle No.

: SKV9834E

Policy No.

: 2100433003-02

Endorsement No.

Issued Date

: 19 Sep 2017

ABOUT THE COVER

Make/Model

: AUDI A3 SEDAN 1.4 TFSI (AMBIENTE)

Engine Capacity/Tonnage : 1,395.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexpenenced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 40 years old and above

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Maleysia), are not to be included under these headings

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

TAN SIEW AIK - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125251

PREMIUM LEASING -LES

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

Motor Cars and Motor Tractors the weight of 25 Feb 2000 which unladen does not exceed 2500 kilograms

NP 428A

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Accident Repairs Ubi Road 1 Workshop Contact No 6366 2323

6841 1183 Fax No

: PA/TP/1043/2018/GW Reference 7-Sep-18 Date

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle is: SKV 9834 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Tel: Fax 6338 1504

Owner's Name Ms Cordelia Tan Siew Aik Address Blk 513 Yio Chu Kang Rd

#03-29

Singapore 787067

HP +65 96863882 Telephone

Third Party Claims OD Alouin Type of Claim

2100433003-02 Policy No. SKV 9834 E Vehicle No

: Audi A3 Sedan 1.4 TFSI **Model Code**

Model / Year Oct-15 CZC 276061 **Engine No**

WAUZZZ8V7G1014951 Chassis No

Mileage Date In

Liability **Excess Cost**

: Allan Wu **Estimated By Accident Date** 5-Sep-18

Place of Accident CTE(SLE) after Moulmein exit

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 9834 E.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	Z 360
2	To remove and renew air con condenser. To transfer radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,000.00	? (000
3	To dismantle front bumper, lhs fender, bonnet and both frontheadlight. Renew front lock carrier and align to position.		\$ 5,400.00	1500- 2750
4	To respray front bumper,bonnet,bonnet hinges and lhs front fender. $\ensuremath{\boldsymbol{\chi}}$		\$ 2,300.00	1100 1100
5	To carry out diagnostic check	5/N	\$ 192.00	192.00
	TOTAL LABOUR CHARGES	:	\$ 9,252.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 9834 E.

S/N	Parts Description		Damaged Parts S/Nett	& Prices Remark
	Λ .			72
1	FRONT BUMPER Rehand		\$ 1,739.00	1391.20
2	FIXING PARTS FOR FRONT BUMPER		\$ 161.00 K	
3	COVER TRIM - LH/RH	2	\$ 280.00 🛠	4×
4	CLOSING ELEMENT - LOWER CENTRE ME		\$ 140.00 +	
5	PULL STAP HE M	4	\$ 175.00 +	
6	GUIDE SECTION - LH/RH	2	\$ 66.00 F	
7	AIR GUIDE GRILLE - LH/RH Lit Missing	2	\$ 190.00 9	5. 75.84
8	RADIATOR GRILLE Creeks		\$ 573.00	458 00
9	COVER FOR RADIATOR GRILLE		\$ 86.00	68.16
10	FOAM FILLER PIECE Deformed.		\$ 117.00	93.60
11	SIDE REINFORCEMENT but		\$ 633.00	506.00
12	COVER Phyd.		\$ 48.00	37.92
13	CAUTION' STICKER MAL		\$ 12.00	9.28
14	BONNET Buckled		\$ 2,755.00	12204.00
15	ATTACHMENT PARTS FOR BONNET THE NEC	(8)	\$ 141.00	7
16	LID HINGE - LH/RH Nen	2	\$ 106.00 ×	7×
17	BONNET HOOK Men		\$ 78.00 ⁺	
18	STRIKER - LH/RH	2	\$ 192.00 🖟	9
19	EDGE PROTECTION ALL		\$ 24.00	18.88
20	LID LOCK WITH MICRO-SWITCH No Me	2	\$ 353.00	X
	SUB TOTAL SPARE PARTS CHARGES	:	\$ 7,869.00	
	All charges are not inclusive of GST			

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 9834 E.

			Damaged Parts	& Prices
S/N	Parts Description		S/Nett	Remark
21	BOWDEN CABLE Hole NA	s	50.00 🗶	1
22	BUNGS WHE ME	2 \$	36.00 🚜	
23	FRONT FENDER - LH Repris	\$	746.00 <	
24	ASTTACHMENT PARTS FOR FENDER	s	62.00 🗡	
25	BRACKET FOR FENDER - LH	s	24.00 4	1 /
26	BRACKET No No	\$	34.00 *	
27	FRONT FENDER BRACE WING - LH	\$	84.00 🐣	
28	HEADLIGHT - LH/RH Crubed	2 \$	3,528.00	/ 2822,40
29	LIFT CYLINDER FOR HEADLIGHT - LH/RH AND A	1m2 5	348.00 <	. ×
30	LOCK CARRIER FOR COOLANT RADIATOR	lud. s	638.00	
31	COOLANT THE.	4 \$	133.00	65.28
32	A/C CONDENSER Best	\$	500.00	399.60
33	AIR CON COMPRESSOR SEAL RING ?	\$	3.00 *	7
34	AIR CON COMPRESSOR SEAL RING	\$	4.00 4	J
35	CAR PLATE - FRONT Beck	S/N \$	25.00	25,00
36	SUNDRIES Nec.	\$	300.00 7	61.76
	TOTAL SPARE PARTS CHARGES	\$	14,384.00	
	TOTAL LABOUR CHARGES	: \$	9,252.00	
	GRAND TOTAL	\$	23,636.00	
	All charges are not inclusive of GST.	200		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Adrian hing 14/09/18

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Not Anothorised, 06 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following: To resurvey before latter spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

: Accident Repairs

Workshop

: Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/TP/1043/2018/GW

Date

: 07-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle is : SKV 9834 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Ms Cordelia Tan Siew Alk

Address

Blk 513 Yio Chu Kang Rd

#03-29

Singapore 787067

Telephone

HP +65 96863882

Type of Claim

Third Party Claims

2100433003-02

Policy No. Vehicle No

SKV 9834 E

Model Code

Audi A3 Sedan 1.4 TFSI

Model / Year

Oct-15

Engine No

CZC 276061

Chassis No

WAUZZZ8V7G1014951

Mileage

Date In

.

Liability

Excess Cost

Estimated By

: Allan Wu

Accident Date Place of Accident : 05-Sep-18 CTE(SLE) after Moulmein exit

Hi Adrian

6 days exclude 1 Sunday

jb 10 Nov 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 9834 E.

S/n	Nature of Jobs		Estimated Charges		rveyor's nmendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	s	360.00
2	To remove and renew air con condenser. To transfer radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,000.00	\$	1,000.00
3	To dismantle front bumper, lhs fender, bonnet and both frontheadlight. Renew front lock carrier and align to position.		\$ 5,400.00	\$	2,750.00
4	To respray front bumper, bonnet, bonnet hinges and lhs front fender.		\$ 2,300.00	\$	1,100.00
5	To carry out diagnostic check	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 9,252.00	\$	5,402.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 9834 E.

			Damaged Pa		
S/N	Parts Description		S/Nett	R	emark
1	FRONT BUMPER	\$	1,739.00	\$	1,391.20
2	FIXING PARTS FOR FRONT BUMPER	\$	161.00		
3	COVER TRIM - LH/RH	2 \$	280.00		
4	CLOSING ELEMENT - LOWER CENTRE	\$	140.00		
5	PULL STAP	4 \$	175.00		
6	GUIDE SECTION - LH/RH	2 \$	66.00		
7	AIR GUIDE GRILLE - LH/RH	2 \$	190.00	\$	75.84
8	RADIATOR GRILLE	s	573.00	\$	458.00
9	COVER FOR RADIATOR GRILLE	\$	86.00	\$	68.16
10	FOAM FILLER PIECE	\$	117.00	\$	93.60
11	SIDE REINFORCEMENT	\$	633.00	\$	506.00
12	COVER	9	48.00	\$	37.92
13	CAUTION' STICKER		12.00	\$	9.28
14	BONNET		\$ 2,755.00	\$	2,204.00
15	ATTACHMENT PARTS FOR BONNET		\$ 141.00		
16	LID HINGE - LH/RH	2	\$ 106.00		
17	BONNET HOOK		\$ 78.00		
18	200220	2	\$ 192.00		
19			\$ 24.00	\$	18.88
20		2	\$ 353.00		
20	SUB TOTAL SPARE PARTS CHARGES		\$ 7,869.00	\$	4,862.88
	JOD TOTAL OF THE STATE OF THE S				

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 9834 E.

		Damaged Par	ts & P	rices		
S/N	Parts Description			S/Nett		Remark
3/N	c/f				\$	4,862.88
21	BOWDEN CABLE		\$	50.00		
22	BUNGS	2	\$	36.00		
23	FRONT FENDER - LH		\$	746.00		
24	ASTTACHMENT PARTS FOR FENDER		\$	62.00		
25	BRACKET FOR FENDER - LH		\$	24.00		
26	BRACKET		\$	34.00		
27	FRONT FENDER BRACE WING - LH		\$	84.00		
28	HEADLIGHT - LH/RH	2	\$	3,528.00	\$	2,822.40
29	LIFT CYLINDER FOR HEADLIGHT - LH/RH	2	\$	348.00		
30	LOCK CARRIER FOR COOLANT RADIATOR		\$	638.00	\$	510.00
31	COOLANT	4	\$	133.00	\$	65.28
32	A/C CONDENSER		\$	500.00	\$	399.60
33	AIR CON COMPRESSOR SEAL RING		\$	3.00		
34	AIR CON COMPRESSOR SEAL RING		\$	4.00		
35	CAR PLATE - FRONT	S/N	\$	25.00	\$	25.00
37	SUNDRIES		\$	300.00	\$	61.76
	TOTAL SPARE PARTS CHARGES	:	\$	14,384.00	\$	8,746.92
	TOTAL LABOUR CHARGES	:	\$	9,252.00	\$	5,402.00
	GRAND TOTAL	1	\$	23,636.00	\$	14,148.92
			-			

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SKV 9834 E Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg

Body & Paint Dept PA/OD/1043/2018/MAS

29 Nov 2018

from

Telephone +65-Telefax +65-

EMail

Date

Our department

Our Ref Your Ref

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SKV 9834 E, Audi A3 Sedan 1.4 TFSI

With reference to the above-mentioned vehicle, no. SKV 9834 E, claimant, Ms Tan Siew Aik, please find the related document per attached.

- 1. A copy of the Original invoice no. 85013183 S\$14,497.34
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SKV 9834 E

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case Main	Notified 10 Sep 2018	Est Su	bmitted	Adj Assigned 17 Sep 2018 11:56 Edit Adj Rpt	Adj R S\$14,14 Edit Estir	18.92	Adj Submitted S\$14,148.92 View Rpt	100000	uth'ed	Pending for Report Cancel Case	y 8
	Main	7	Re	ference	J d	Claim De	etails	Do	cuments		Show All
	SUBFOLDER DE	TAILS	CORDE	LIA TAN SIEW /	NK. ID: S	6824604), Tel: +65968	63882, Er	[Create	d by insurer]	
insured: Vehicle R	eg. No.:		SKV9	555 200.20	,	Date of			[34 Mon	018 22:00 - :59 ths and 23 Date (Man Yr)]	
Claim Ty	pe:		OD /	152272383450	;	Policy/C	over Note No.:		a company of places been	003 (Comprehensive)	
			***********	Excess: S\$600.00 Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911							
Repairer: Handling	Insurer:		AIG A	um Automobiles sia Pacific Insuri rina.DallyAmri@a	ance Pte. L	td. (SG)	- Tel: 65-6419-	3000 [H	indled by	Dally Amri, M	imi Zarina
Adjuster:	1		LKK A	uto Consultants 6/09/2018]	Pte Ltd (H	Q) - Tel:	6256-3561 [1				al Rpt
Driver/C	ustodian:		CORDE	LIA TAN SIEW AI	K (50 / Fem	ale), N	RIC: S6824604J	, Tel: +65	9686388	2	
ASSOCI	ATED MAIL RE	CEIVED						,	/iew All	Compose (Case Mail
• AIG_9	SG (16/11/2018):	Alert -	Adj Mano	date Approved (date Approved (/ 05/09/2018	5\$11903.0	U) - 5K1	79834E - Claim	Handler: [Handler: [ally Amr	i	
ALL AS	SOCIATED TAS	KS				V	iew All Searc	h Tasks	Create	New Task	Complete
Due D	oate Priority	Туре	Task	Group Subje	ct Hand	ler /	Assigned By	Complet	ed On	Created Or	Done?

Claim Documents

*SKV9834E (15227238345G) OD Sep 5 2018 10:00PM [CORDELIA TAN SIEW AIK] Premium Automobiles Pte Ltd

L	ipload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	20000	Use Viewer	1000
Asse	essment Reports					1 per p	Thumbnail	Pelet
	Finalized On	LKK Auto Consult				0	Load HTM	Pilli
	17/09/18 18:10	Adjuster Immedia				0	Load HTM	
2	13/11/18 11:12	Adjuster Immedia	ate Advice				l. consequences	
ho	tos/Images					3 per p		V
No	Relabel/Reorder	LKK Auto Consult	ants Pte Ltd (HQ)				Thumbnail	
1	17/09/18 18:18	General View				0	Load JPG	V
2	17/09/18 18:18	General View				0	Load JPG	V
3	17/09/18 18:18	General View				0	Load JPG	V
4	17/09/18 18:18	General View				0	Load JPG	V
5	17/09/18 18:18	General View				0	Load JPG	V
6	17/09/18 18:18	General View				0	Load JPG	1
7	17/09/18 18:18	General View				0	Load JPG	V
8	17/09/18 18:18	General View				0	Load JPG	7
9	17/09/18 18:18	General View				0	Load JPG	1
	17/09/18 18:18	General View				0	Load JPG	1
10		General View				0	Load JPG	V
11	17/09/18 18:18	General View				0	Load JPG	V
12	17/09/18 18:18	A CONTROL OF THE CONT				0	Load JPG	V
13	17/09/18 18:18	General View				0	Load JPG	V
14	17/09/18 18:18	General View				0	Load JPG	V
15	17/09/18 18:18	General View				0	Load JPG	V
16	17/09/18 18:18	General View				0	Load JPG	V
17	17/09/18 18:18	General View				0	Load JPG	V
18	17/09/18 18:18	General View				0	100000000000000000000000000000000000000	V
19	17/09/18 18:18	General View					Load JPG	_
20	17/09/18 18:18	General View				0	Load JPG	[V
21	17/09/18 18:18	General View				0	Load JPG	
22	17/09/18 18:18	General View				0	Load JPG	-
23	17/09/18 18:18	General View				0	Load JPG	
24	17/09/18 18:18	General View				0	Load JPG	-
25	17/09/18 18:18	General View				0	Load JPG	
26	17/09/18 18:18	General View				0	Load JPG	
27	17/09/18 18:18	General View				0	Load JPG	Į.
28	17/09/18 18:18	General View				0	Load JPG	U
29	17/09/18 18:18	General View				0	Load JPG	19
30	The second reservoir	General View				0	Load JPG	1
31		Reinspection Ph	noto			0	Load JPG	1
32		Reinspection Ph				0	Load JPG	B
	100000000000000000000000000000000000000	Reinspection Ph				0	Load JPG	6
33		Reinspection Ph	Senatory			0	Load JPG	B
34	C 1541 10.00 10.	Reinspection Ph				0		
35						0		-
36		Reinspection Ph				0		
37		Reinspection Ph				0		
38	8 13/11/18 09:55	Reinspection Pl	1010			0		

40	13/11/18 09:55	Reinspection Photo	1 Load JPG	V
Doc	umentation		1 per page	V
550	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	-
No	17/09/18 18:17	SKV 9834E EST	Load PDF	
2	17/09/18 18:17	Certificate of Insurance	1 Load PDF	
3	17/09/18 18:17	Driver's Driving License	1 Load PDF	-
4	17/09/18 18:17	Singapore Accident Statement	0 Load PDF	-
5	13/11/18 11:14	SKV 9834E FINALIZE ADJUSTMENT	1 Load PDF	_
6	05/12/18 11:28	WORKSHOP INVOICE	Load PDF	8
7	05/12/18 11:28	DISCHARGE VOUCHER	1 Load PDF	š .

Linked Accident Report Documents

			View	Use Viewer	•
A c c c	essment Reports		1 per p	age •	V
	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
No 1	06/09/18 16:08	Accident Statement	0	Load HTM	
2	14/09/18 09:34	Addendum Sheet	Ð	Load JPG	V
3	14/09/18 09:35	Accident Statement Addm. #1	0	Load HTM	
Pho	tos/Images		3 per	page 🔻	V
No		Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	06/09/18 15:38	THIRD PARTY STATEMENT	0	Load JPG	7
2	06/09/18 16:05	Accident Photo	0	Load JPG	V
3	06/09/18 16:05	Accident Photo	0	Load JPG	V
4	06/09/18 16:05	Accident Photo	0	Load JPG	7
5	06/09/18 16:05	Accident Photo	0	Load JPG	V
6	06/09/18 16:05	Accident Photo	0	Load JPG	7
7	06/09/18 16:05	Accident Photo	0	Load JPG	V
8	06/09/18 16:05	Accident Photo	0	Load JPG	V
9	06/09/18 16:05	Accident Photo	0	Load JPG	J
10	06/09/18 16:05	Accident Photo	0	Load JPG	V
11	06/09/18 16:05	Accident Photo	0	Load JPG	V
12	06/09/18 16:05	Driving License	0	Load JPG	7
13	06/09/18 16:05	Accident Photo	0	Load JPG	V
14	06/09/18 16:05	Accident Photo	0	Load JPG	V
15	06/09/18 16:05	Accident Photo	0	Load JPG	V
16	To depart Contanua	Accident Photo	0	Load JPG	V
17	06/09/18 16:05	Accident Photo	0	Load JPG	V
	To serve and the serve	100000000000000000000000000000000000000	1 000	page 🔻	7
Do	cumentation		1 per	Thumbnai	Andrew Control
No	7 (1200) (100) (100)	Premium Automobiles Pte Ltd (UBI)	0		V
1	06/09/18 15:37	Sketch Plan	0		V
2	06/09/18 15:37	Sketch Plan #2	-		100.3

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	*
	-
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG18016870/ACBN2

Date:

OD

05/12/2018

REFERENCE

Insured/Claimant: Date of Loss:

CORDELIA TAN SIEW AIK

Policy No: Nature of Claim: 05/09/2018

2100433003

Claim No: 1522723834SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKV9834E

Make & Model:

AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)

Engine No: Chassis No: CZC276061

43471 km

Reg. Date:

Bronze

13/10/2015 (Man. Year: 2015)

Odometer:

WAUZZZ8V7G1014951

Colour: **Engine Capacity:**

1395 cc

Market Value/New Car Price:

\$\$85,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

41.18

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Front Right Side: Pirelli 6 mm Pirelli 6 mm Rear Left Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 14,384.00 0.00	Adjuster's 8,746.92 0.00	5,637.08 0.00	Diff % 39.19
Labour	9,252.00	5,402.00	3,850.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) - Excess (S\$)	23,636.00 600.00	14,148.92 600.00	9,487.08 0.00	40.14 0.00
+ GST 7.00/7.00% (S\$)	23,036.00	13,548.92	9,487.08	41.18
	1,612.52	948.42	664.10	41.18

24,648.52

INSPECTION

Date of Assignment:

17/09/2018

Nett Amount (S\$)

Date Inspected:

14/09/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

10,151.18

55 Ubi Road 1

14,497.34

Singapore 408699

Estimated Period of Repair:

6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

No.	Qty	Part No.	ed Parts Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,739.00 FS	
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	161.00 FS	*-FS
	1.5		*COVER TRIM-LH/RH	Not Necessary	280.00 FS	*-FS
3	2		*CLOSING ELEMENT-LOWER CENTRE	Not Necessary	140.00 FS	*-FS
	4		*PULL STRAP	Not Necessary	175.00 FS	*-FS
5 6	2		*GUIDE SECTION-LH/RH	Not Necessary	66.00 FS	*-FS
7	1		*AIR GUIDE GRILLE-LH/RH	N/s Missing	190.00 FS	*75.84 FS
8	1		*RADIATOR GRILLE	Cracked	573.00 FS	*458.00 FS
9	1		*COVER FOR RADIATOR GRILLE	Damaged	86.00 FS	*68.16 FS
10	1		*FOAM FILLER PIECE	Deformed	117.00 FS	*93.60 FS
11	1		*SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
12	1		*COVER	Damaged	48.00 FS	*37.92 FS
13	1		*CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
14	1		*BONNET	Buckled	2,755.00 FS	*2,204.00 FS
15	1		*ATTACHMENT PARTS FOR BONNET	Not Necessary	141.00 FS	*- FS
16	2		*LID HINGE-LH/RH	Not Necessary	106.00 FS	*- FS
17	1		*BONNET HOOK	Not Necessary	78.00 FS	*-FS
18	2		*STRIKER-LH/RH	Not Necessary	192.00 FS	*-FS
19	1		*EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
20	2		*LID LOCK WITH MICRO-SWITCH	Not Necessary	353.00 FS	*-FS
21	1		*BOWDEN CABLE	Not Necessary	50.00 FS	
22	2		*BUNGS	Not Necessary	36.00 FS	
23	1		*FRONT FENDER-LH	Repair	746.00 FS	
24	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	62.00 FS	
25	1		*BRACKET FOR FENDER-LH	Not Necessary	24.00 FS	
26	1		*BRACKET	Not Necessary	34.00 FS	
27	1		*FRONT FENDER BRACE WING-LH	Not Necessary	84.00 FS	
28	2		*HEADLIGHT-LH/RH	Cracked	3,528.00 FS	*2,822.40 FS
29	2		*LIFT CYLINDER FOR HEADLIGHT-LH/RH	Not Necessary	348.00 FS	
30	1		*LOCK CARRIER FOR COOLANT RADIATOR	Cracked	638.00 FS	*510.00 FS
31	4		*COOLANT	Necessary	133.00 FS	
32	1		*A/C CONDENSER	Bent	500.00 FS	*399.60 FS
33	1		*AIR CON COMPRESSOR SEAL RING	Not Necessary	3.00 FS	
34	1		*AIR CON COMPRESSOR SEAL RING	Not Necessary	4.00 FS	
35	1		*CAR PLATE-FRONT	Bent	25.00 FS	
36	1		*SUNDRIES	Necessary	300.00 FS	*61.76 FS
	ranchis	e part. S=Sp		ALTO LEVEL MONTH TO THE PARTY OF THE PARTY O	W. X21111 SCC00120 C	
	- 201101110	(A)		Total Parts (S\$	14,384.00	8,746.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended	Labour		
No	Particulars			

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		VENDO INVENDO	
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIR CON CONDENSER.TO TRANSFER RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE FRONT BUMPER, LHS FENDER, BONNET AND BOTH FRONT HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION	New	5,400.00	2,750.00
4	TO RESPRAY FRONT BUMPER, BONNET, BONNET HINGES AND LHS FRONT FENDER	New	2,300.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labo	ur Cost (S\$)	9,252.00	5,402.00
	Report was unsubmitted dur	ng this print-out.		

< END OF ESTIMATES >



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale	Des Experts En Automobile	
--------------------------	----------------	---------------------------	--

ERGO INSURANCE PTE LTD

Ref : CS/EGI18020488/T1sd3e2

5 TEMASEK BOULEVARD



TEMASEK BOULEV		Date: 05-12-2018					
SINGAPORE 038985		Code: EGI					
	Policy Particula	ars :- THIRD PARTY CLA	M				
Insured Veh.	YM 6929S	Veh. Inspected	SKH 8393R				
Policy No.		Coverage (\$)	0.00				
Claim No.	YM6929S/SA/pl	Excess (\$)	0.00				
Assign From	YEE PEI LI	Assign Date	13/11/2018				
2.	Vehicle Pa	articulars & Condition					
Make & Model	HONDA HRV	c.c	1496				
Engine No.	HIDDEN	Year of Reg.	2017				
Chassis No.	JHMRU1830GX201908	Colour	BLACK				
Odometer	19237	Steering	IN ORDER				
Brakes	IN ORDER	Modification	SPORTS RIM				
General	GOOD						
3.	Con	ditions of Tyres					
	Size	Make	Balance				
R/H Front Tyre	215/60 R16	DUNLOP	6 mm				
L/H Front Tyre	215/60 R16	DUNLOP	6 mm				
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm				
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm				
4.	Descr	ription of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.							
DAMAGES SEE I	DETAILS.						
5.	Ger	neral Information					
Accident Date	02/11/2018	Inspection Date	14/11/2018				
Survey held at	rvey held at KAH MOTOR CO SDN BERHAD						
	NO. 255 ALEXANDRA ROAD SINGAPORE 159937						
5a.	Remarks						
A)THE INSPECT B)IN ACCORDAN	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days							