

Tajira

REF:

WLG

CC3/Ath 18016873 / Tlaper

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop m/s

of

Insured:

Policy No.

2100479660-02

Claims No.

431340166654

Sum Insured

Excess:

3600 20/9/18

(Client's Record)

for

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

P111K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

40

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLF6656U

Yr Regn:

20/6

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 station

cc 1395

Colour:

white

A/C Insured / Std / NI / NA

Sp. Reading

14063

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAM 222 F 40H 022515

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50 R17

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/9/18

Survey held at

Premium Bemo

Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rebate: \$65,089

Repair limit \$45K.

17/9/18 @ 4.04 pm visit to Victor via messenger.

20/9/18 @ 11.29 am 2nd visit to Victor via messenger. (Indicate New for Old Value)

20/9/18 @ 2.24 pm Andy informed c/a at \$83593. via messenger. (Based on New for Old)

20/9/18 @ 5.58 pm Inform Tony c/a not more than \$832 part by put basis ex. \$360

Tony asking for double confirm the authorise amount based on New for old.

22/9/18 @ 11.10 am 3rd visit to Victor via messenger. (supplementary).

27/9/18 @ 11.44 am Victor informed to withdraw mandate requested of supplementary as not yet

confirm the supplementary terms have damage.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

40

RECEIVED 04 DEC 2019

Date/Time, File Return to?

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation

S + RS: 3

Phone

Others

TOTAL

11

211

Add Fee:

☐

Site Insp IS

☐

Interview IS

☐

Tech. Invs IS

☐

Week end IS

Report Format:

MER-09

Lump Sum / L.B.I. IS

\$0000

Repair

Vehicle: SLK 66564 DOB: 31/08/18 AGE: 0D

18/10/18 @ 4.15pm 3rd request to Victor via Meinen. (supplementary of engine)

08/11/18 @ 3.40pm 4th request to Victor via Meinen. (2nd supplementary)

05/12/18 @ 6.38am Andy Fong informed CIA at £90K via Meinen.

05/12/18 @ 10.29am informed Tony CIA not more than £90K on part by part basic by email.

31/10/19 @ 5.47pm confirmed with Carvine repair sum £5000, 40 days.
(Red £ 68620.60, 46%)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 31 October 2019 5:47 PM
To: Carrine Leong
Cc: 'Boo seng yak'; jiajee.yap@premiumauto.com.sg; SUR; 'Claims Dept'; 'Nora Khai'
Subject: RE: FINAL REVISION - SLF6656U - OD AIG - SURVEYED 14 SEP 18 TAUFIKH

Dear Carrine,

WITHOUT PREJUDICE

Confirm repair sum \$80,000.00 before excess \$3,600.00 & GST and 40 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 17 October 2019 4:45 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; jiajee.yap@premiumauto.com.sg; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>; 'Nora Khai' <nora.khai@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLF6656U - OD AIG - SURVEYED 14 SEP 18 TAUFIKH

Hi Taufikh,

Ok, please confirm repair cost of \$80,000.00 (Original 91,669.44), thanks.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Sep 2018 16:54	Cim Veh Model Changed		[] Merimen Administrator
2	03 Sep 2018 16:54	Cim Created	Reg No: SLF6656U. Policy No: 2100479660-02. Acct Date: 2018/08/31. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118114176	[I] Merimen Administrator
3	11 Sep 2018 11:05	Cim Registration Modified	Init.Est.: -> 5,000 - 6,000.	[I] Hor, Yinrul
4	17 Sep 2018 12:01	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
5	17 Sep 2018 12:01	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
6	17 Sep 2018 12:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
7	17 Sep 2018 12:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] CATHERINE CHONG KAI LING
8	17 Sep 2018 12:01	Adj Mandate Set	Approved:6000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
9	17 Sep 2018 12:01	Cim Registration Modified	Rep:1137->204491.	[A] CATHERINE CHONG KAI LING
10	17 Sep 2018 12:01	Cim Veh Model Changed	[204616] AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
11	17 Sep 2018 12:02	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
12	17 Sep 2018 15:54	Adj Rpt Initiated		[A] SHIAU CHAN
13	17 Sep 2018 15:54	Cim Dtl Modified	JPJ Reg. Date: -> 2016/08/22.	[A] SHIAU CHAN
14	17 Sep 2018 15:54	Cim Details Notified		[A] SHIAU CHAN
15	17 Sep 2018 16:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
16	17 Sep 2018 16:09	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
17	18 Sep 2018 11:41	Cim Registration Modified	Excess: -> 3600.00. ZF Remarks: -> Young Driver. GST: -> 7.00.	[I] Loo, Tong Shing
18	18 Sep 2018 11:41	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	18 Sep 2018 15:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26. Mandate Remarks: Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
20	18 Sep 2018 15:57	Adj Mandate Set	Maintained:Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
21	20 Sep 2018 10:31	Label Added	(26):Total Loss.	[A] SHIAU CHAN
22	20 Sep 2018 10:31	Claim Offer Type Changed	Offer Type: Cost of Repairs->Total Loss, Total Loss Type: N/A->BER	[A] SHIAU CHAN
23	20 Sep 2018 11:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
24	20 Sep 2018 11:27	Label Removed	(26):Total Loss.	[A] SHIAU CHAN
25	20 Sep 2018 11:29	Adj Mandate Request	Cur.Reg:83593.00:DAMAGES CONSISTENT. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
26	20 Sep 2018 14:24	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/09/26. Mandate Remarks: To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY
27	20 Sep 2018 14:24	Adj Mandate Set	Approved:83593.00:To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY
28	27 Sep 2018 11:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN

AUDIT TRAIL

No.	On	Audit	Remarks	By
29	27 Sep 2018 11:10	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
30	27 Sep 2018 11:46	Adj Mandate Request Cancelled	AS REQUESTED BY VICTOR DUE TO THE SUPPLEMENTARY ITEMS NOT YET BE CONFIRM HAVE DAMAGE.	[A] SHIAU CHAN
31	18 Oct 2018 16:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
32	18 Oct 2018 16:15	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
33	08 Nov 2018 15:35	Adj Mandate Request Cancelled		[A] SHIAU CHAN
34	08 Nov 2018 15:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
35	08 Nov 2018 15:40	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
36	05 Dec 2018 06:38	Adj Mandate Set	Approved:90000.00.	[I] Fong, Andy-SY
37	18 Oct 2019 17:07	Adj Mandate Request	Cur.Req:80000.00:KINDLY APPROVE REPAIR COST OF \$80,000.00.	[A] SHIAU CHAN
38	31 Oct 2019 16:21	Adj Mandate Set	Approved:80000.00.	[I] Fong, Andy-SY

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1918472	17 Sep 2018 15:54:12	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLF6656U		10.70
1949936	18 Oct 2018 16:09:53	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SLF6656U	SHIAU CHAN	xx.xx

Shiau Chan (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 20 April 2019 4:58 PM
To: Adrian Ling (LKKAUTO); Shiau Chan (LKKAUTO); SUR; Carrine Leong; jiyee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLF6656U - OD AIG - SURVEYED 14 SEP 18 TAUFIKH
Attachments: PA10662018 -SLF 6656 U - Audi A4 SEDAN 1.4 TFSI FRONT OD (AIG) + SUPP.xls

Hi Adrian, Taufikh and all,

Revised estimate is attached.

Please confirm repair cost of \$80,000.00 (Original 91,669.44)

Please discuss with our Miss Nora for days of repairs.

Photographs is obtainable from our office folders.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 5 December 2018 10:29 AM
To: 'Claims'; assignments
Cc: SUR
Subject: RE: RE : OD claim for SLF 6656 U - Resurvey engine

Dear Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLF 6656U** at repair cost not more than **\$90,000.00 on part by part basis. (Excess \$3,600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 18 October 2018 3:06 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: RE : OD claim for SLF 6656 U - Resurvey engine

Dear Shiau Chan,

We confirm on part by part repair basic.

Kindly expedite confirm the limit repair and engine replacement.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Sep 2018 16:54	Cim Veh Model Changed		[] Merimen Administrator
2	03 Sep 2018 16:54	Cim Created	Reg No: SLF6656U, Policy No: 2100479660-02, Acct Date: 2018/08/31, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118114176	[I] Merimen Administrator
3	11 Sep 2018 11:05	Cim Registration Modified	Init.Est.: -> 5,000 - 6,000.	[I] Hor, Yinrul
4	17 Sep 2018 12:01	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD,	[] CATHERINE CHONG KAI LING
5	17 Sep 2018 12:01	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
6	17 Sep 2018 12:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
7	17 Sep 2018 12:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] CATHERINE CHONG KAI LING
8	17 Sep 2018 12:01	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
9	17 Sep 2018 12:01	Cim Registration Modified	Rep:1137->204491.	[A] CATHERINE CHONG KAI LING
10	17 Sep 2018 12:01	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
11	17 Sep 2018 12:02	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
12	17 Sep 2018 15:54	Adj Rpt Initiated		[A] SHIAU CHAN
13	17 Sep 2018 15:54	Cim Dtl Modified	JPJ Reg. Date: -> 2016/08/22.	[A] SHIAU CHAN
14	17 Sep 2018 15:54	Cim Details Notified		[A] SHIAU CHAN
15	17 Sep 2018 16:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
16	17 Sep 2018 16:09	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT, PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
17	18 Sep 2018 11:41	Cim Registration Modified	Excess: -> 3600.00, 2F Remarks: -> Young Driver, GST: -> 7.00.	[I] Loo, Tong Shing
18	18 Sep 2018 11:41	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	18 Sep 2018 15:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26, Mandate Remarks: Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
20	18 Sep 2018 15:57	Adj Mandate Set	Maintained:Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
21	20 Sep 2018 10:31	Label Added	(26):Total Loss.	[A] SHIAU CHAN
22	20 Sep 2018 10:31	Claim Offer Type Changed	Offer Type: Cost of Repairs->Total Loss, Total Loss Type: N/A->BER	[A] SHIAU CHAN
23	20 Sep 2018 11:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
24	20 Sep 2018 11:27	Label Removed	(26):Total Loss.	[A] SHIAU CHAN
25	20 Sep 2018 11:29	Adj Mandate Request	Cur.Reg:83593.00:DAMAGES CONSISTENT. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
26	20 Sep 2018 14:24	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/09/26, Mandate Remarks: To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY
27	20 Sep 2018 14:24	Adj Mandate Set	Approved:83593.00:To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY
28	27 Sep 2018 11:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
29	27 Sep 2018 11:10	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
30	27 Sep 2018 11:46	Adj Mandate Request Cancelled	AS REQUESTED BY VICTOR DUE TO THE SUPPLEMENTARY ITEMS NOT YET BE CONFIRM HAVE DAMAGE.	[A] SHIAU CHAN
31	18 Oct 2018 16:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
32	18 Oct 2018 16:15	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
33	08 Nov 2018 15:35	Adj Mandate Request Cancelled		[A] SHIAU CHAN
34	08 Nov 2018 15:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
35	08 Nov 2018 15:40	Adj Mandate Request	Cur.Req:90000.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON	[A] SHIAU CHAN
36	05 Dec 2018 06:38	Adj Mandate Set	Approved:90000.00.	[I] Fong, Andy-SY

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1918472	17/09/2018 15:54	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLF6656U		10.70
1949936	18/10/2018 16:09	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SLF6656U	SHIAU CHAN	xx.xx

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 08 Nov 2018

Preliminary Advice

Vehicle No	: SLF6656U	Accident Date	: 31/08/2018
Make	: AUDI A4	Policy No.	: 2100479660-02
Assignment Date	: 17/09/2018	Excess	: S\$3,600.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	148,107.00	(ESTIMATE \$91,307.00 + SUPPLEMENTARY 1 \$51,513.00 + SUPPLEMENTARY 2 \$5,287.00)
Revised Amount	:S\$	94,913.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	45,480.00	
Total	:S\$	140,393.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	169,200.00
Pre-Accident Value	:S\$	111,000.00
COE / PARF Rebate	:S\$	65,058.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	104,142.00
Margin for Repair	:S\$	45,942.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE.
REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON PART BY PART BASIS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 18 Oct 2018

Preliminary Advice

Vehicle No	: SLF6656U	Accident Date	: 31/08/2018
Make	: AUDI A4	Policy No.	: 2100479660-02
Assignment Date	: 17/09/2018	Excess	: S\$3,600.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	142,820.00	(ESTIMATE \$91,307.00 + SUPPLEMENTARY \$51,513.00)
Revised Amount	:S\$	89,626.00	
Check Items (Estimated)	:S\$	45,480.00	
Total	:S\$	135,106.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	169,200.00
Pre-Accident Value	:S\$	111,000.00
COE / PARF Rebate	:S\$	65,058.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	104,142.00
Margin for Repair	:S\$	45,942.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE.
REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON PART BY PART BASIS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 27 Sep 2018

Preliminary Advice

Vehicle No	: SLF6656U	Accident Date	: 31/08/2018
Make	: AUDI A4	Policy No.	: 2100479660-02
Assignment Date	: 17/09/2018	Excess	: S\$3,600.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	142,820.00	(ESTIMATE \$91,307.00 + SUPPLEMENTARY \$51,513.00)
Revised Amount	:S\$	65,134.00	
Check Items (Estimated)	:S\$	69,972.00	
Total	:S\$	135,106.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	169,200.00
Pre-Accident Value	:S\$	111,000.00
COE / PARF Rebate	:S\$	65,058.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value as at 08/12/2017)	:S\$	104,142.00
Margin for Repair	:S\$	45,942.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :
PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE.
REPAIRER AGREED REPAIR COST NOT MORE THAN \$90,000.00 ON PART BY PART BASIS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 20 September 2018 5:58 PM
To: 'Claims'; SUR; Admin A
Subject: RE: RE : OD claim for SLF 6656 U

Dear Tony and Phua,

As instructed by our client, please proceed to repair the insured vehicle **SLF 6656U** at repair cost not more than **\$80,000.00 on part by part basis. (Excess \$3,600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

67689828

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 13 September 2018 4:37 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE : OD claim for SLF 6656 U

Good afternoon all ,

Here are the estimate and GIA report for your kind reference .

Thank you.

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902771W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Sep 2018 16:54	Cim Veh Model Changed		[] Merimen Administrator
2	03 Sep 2018 16:54	Cim Created	Reg No: SLF6556U. Policy No: 2100479660-02. Acct Date: 2018/08/31. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118114176	[I] Merimen Administrator
3	11 Sep 2018 11:05	Cim Registration Modified	Init.Est.->5,000 - 6,000.	[I] Hor, Yinrul
4	17 Sep 2018 12:01	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
5	17 Sep 2018 12:01	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
6	17 Sep 2018 12:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
7	17 Sep 2018 12:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] CATHERINE CHONG KAI LING
8	17 Sep 2018 12:01	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
9	17 Sep 2018 12:01	Cim Registration Modified	Rep:1137->204491.	[A] CATHERINE CHONG KAI LING
10	17 Sep 2018 12:01	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
11	17 Sep 2018 12:02	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
12	17 Sep 2018 15:54	Adj Rpt Initiated		[A] SHIAU CHAN
13	17 Sep 2018 15:54	Cim Dtl Modified	JPJ Reg. Date: -> 2016/08/22.	[A] SHIAU CHAN
14	17 Sep 2018 15:54	Cim Details Notified		[A] SHIAU CHAN
15	17 Sep 2018 16:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
16	17 Sep 2018 16:09	Adj Mandate Request	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
17	18 Sep 2018 11:41	Cim Registration Modified	Excess: -> 3600.00. 2F Remarks: -> Young Driver. GST: -> 7.00.	[I] Loo, Tong Shing
18	18 Sep 2018 11:41	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	18 Sep 2018 15:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/26. Mandate Remarks: Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
20	18 Sep 2018 15:57	Adj Mandate Set	Maintained:Please confirm if repairer is able to undertake repairs at repair limit before seeking mandate to proceed	[I] Fong, Andy-SY
21	20 Sep 2018 10:31	Label Added	(26):Total Loss.	[A] SHIAU CHAN
22	20 Sep 2018 10:31	Claim Offer Type Changed	Offer Type: Cost of Repairs->Total Loss, Total Loss Type: N/A->BER	[A] SHIAU CHAN
23	20 Sep 2018 11:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/26	[A] SHIAU CHAN
24	20 Sep 2018 11:27	Label Removed	(26):Total Loss.	[A] SHIAU CHAN
25	20 Sep 2018 11:29	Adj Mandate Request	Cur.Req:83593.00:DAMAGES CONSISTENT, PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
26	20 Sep 2018 14:24	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/09/26. Mandate Remarks: To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY
27	20 Sep 2018 14:24	Adj Mandate Set	Approved:83593.00:To commence repair within repair limit. Clear photos to be available for all damaged, check item and supplementary items.	[I] Fong, Andy-SY

Date From



Date To



Audit Type None

Go

ACTIVITY

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 20 Sep 2018

Preliminary Advice

Vehicle No	: SLF6656U	Accident Date	: 31/08/2018
Make	: AUDI A4	Policy No.	: 2100479660-02
Assignment Date	: 17/09/2018	Excess	: S\$3,600.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	91,307.00
Revised Amount	:S\$	65,134.00
Check Items (Estimated)	:S\$	18,459.00
Total	:S\$	83,593.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value (as at 08/12/2017)	:S\$	169,200.00
Pre-Accident Value	:S\$	111,000.00
COE / PARF Rebate	:S\$	65,058.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value as at 08/12/2017)	:S\$	104,142.00
Margin for Repair	:S\$	45,942.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE TAKE NOTE THAT THE NEW FOR OLD VALUE IS AS AT 08/12/2017 DUE TO CURRENTLY AUDI A4 1.4 MODEL'S NEW CAR PRICES NOT AVAILABLE.

RETAIL PRICE LIST

Effective as of 8 December 2017



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	Retail Price	CEVS/VES (relate / surcharge)	Nett Price after CEVS / VES
AUDI A3 Sportback						
A3 1.0 TFSI S tronic	116	200	4.8	\$144,100	\$0	\$144,100
S3 2.0 TFSI qu S tronic	290	380	6.6	\$234,500	\$20,000	\$254,500
RS 3 2.5 TFSI qu S tronic	400	480	8.4	\$293,600	\$20,000	\$313,600
AUDI A3 Sedan						
A3 1.0 TFSI S tronic	116	200	4.7	\$146,300	\$0	\$146,300
S3 2.0 TFSI qu S tronic	290	380	6.5	\$236,700	\$20,000	\$256,700
RS 3 2.5 TFSI qu S tronic	400	480	8.4	\$301,300	\$5,000	\$306,300
AUDI A3 Cabriolet						
A3 1.4 TFSI S tronic	116	200	5.3	\$182,839	\$10,000	\$192,839
AUDI A4 Sedan						
A4 1.4 TFSI S tronic	150	250	5.2	\$179,200	(\$10,000)	\$189,200
A4 2.0 TFSI S tronic	190	320	5.2	\$181,900	\$0	\$181,900
A4 2.0 TFSI qu S tronic (Design)	252	370	6.2	\$238,900	\$20,000	\$258,900
S4 3.0 TFSI qu tiptronic	354	500	7.7	\$299,600	\$10,000	\$309,600
AUDI A4 Avant						
A4 2.0 TFSI S tronic	190	320	5.4	\$191,400	\$0	\$191,400
A4 2.0 TFSI qu S tronic (Design)	252	370	6.5	\$247,600	\$20,000	\$267,600
S4 3.0 TFSI qu tiptronic	354	500	7.8	\$309,100	\$10,000	\$319,100
AUDI A5 Sportback						
A5 2.0 TFSI S tronic (Design)	190	320	5.6	\$206,900	\$0	\$206,900
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	\$251,850	\$20,000	\$271,850
S5 3.0 TFSI qu tiptronic	354	500	7.9	\$304,500	\$10,000	\$314,500
AUDI A5 Coupe						
A5 2.0 TFSI S tronic (Design)	190	320	5.5	\$211,500	\$0	\$211,500
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	\$256,950	\$20,000	\$276,950
S5 3.0 TFSI qu tiptronic	354	500	7.8	\$311,800	\$10,000	\$321,800
RS 5 2.9 TFSI qu tiptronic	400	600	8.8	\$374,000	\$20,000	\$394,000
AUDI A5 Cabriolet						
A5 2.0 TFSI S tronic (Design)	190	320	5.9	\$250,621	\$0	\$250,621
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.7	\$289,200	\$0	\$289,200
AUDI A6 Sedan						
A6 1.8 TFSI S tronic	180	320	5.7	\$227,238	\$0	\$227,238
A6 1.8 TFSI S tronic (Assistance package)	190	320	5.7	\$235,286	\$0	\$235,286
A6 2.0 TFSI S tronic (Assistance package)	252	370	5.9	\$253,386	\$10,000	\$263,386
A6 2.0 TFSI qu S tronic	252	370	7.0	\$264,800	\$0	\$264,800
A6 3.0 TFSI qu S tronic	333	440	7.6	\$355,900	\$10,000	\$365,900
AUDI A6 Avant						
A6 1.8 TFSI S tronic (Assistance package)	190	320	5.9	\$245,586	\$0	\$245,586
RS 6 4.0 TFSI qu tip	540	700	9.6	\$529,200	\$20,000	\$549,200
AUDI A7 Sportback						
A7 2.0 TFSI S tronic	252	370	5.9	\$305,000	\$10,000	\$315,000
A7 3.0 TFSI qu S tronic	333	440	7.6	\$376,500	\$10,000	\$386,500
AUDI A8						
A8L 3.0 TFSI qu tip	310	440	7.9	\$417,500	\$10,000	\$427,500
AUDI Q2						
Q2 1.0 TFSI S tronic	116	200	5.2	\$152,391	\$0	\$152,391
Q2 1.0 TFSI S tronic (Sport)	116	200	5.2	\$163,300	\$0	\$163,300
Q2 1.4 TFSI COD S tronic (Sport)	150	250	5.3	\$175,300	\$0	\$175,300
AUDI Q3						
Q3 1.4 TFSI S tronic	150	250	6.0	\$171,315	\$10,000	\$181,315
Q3 2.0 TFSI qu S tronic (Design)	180	320	6.1	\$187,000	\$10,000	\$197,000
AUDI Q5						
Q5 2.0 TFSI qu S tronic (Sport)	252	370	7.4	\$234,000	\$10,000	\$244,000
Q5 3.0 TFSI qu tiptronic	354	500	8.7	\$301,000	\$20,000	\$321,000
AUDI Q7						
Q7 2.0 TFSI qu tip	252	370	7.4	\$301,526	\$10,000	\$311,526
Q7 3.0 TFSI qu tip	333	440	7.9	\$358,322	\$20,000	\$378,322
AUDI TT Coupe						
TT 1.8 TFSI S tronic	180	250	5.9	\$219,700	\$0	\$219,700
TT 2.0 TFSI qu S tronic	230	370	6.4	\$254,200	\$0	\$254,200
AUDI TT Roadster						
TT 1.8 TFSI S tronic	180	250	6.1	\$224,900	\$0	\$224,900
TT 2.0 TFSI qu S tronic	230	370	6.7	\$259,400	\$0	\$259,400
AUDI R8 Coupe						
R8 5.2 FSI qu S tronic	540	540	11.4	\$778,300	\$20,000	\$798,300
AUDI R8 Spyder						
R8 5.2 FSI qu S tronic	540	540	11.7	\$852,000	\$20,000	\$872,000

Terms and Conditions :

- ✓ Retail price is subject to in-house Financial and Insurance. Price includes 12-months road tax, registration fee and GST but without insurance.
 - ✓ CDE is non guaranteed and subject to b-bids, failing which new terms and conditions shall apply.
 - ✓ Booking deposit for all models is \$520,000/-. Minimum booking deposit for indent order is \$525,000/-, with the exception of RS/RB is \$75,000/-.
 - ✓ All deposits are non-refundable upon cancellation.
 - ✓ In-house utilization of PARF/CDE Relates for new car registration is within Premium Automobile's Discretion.
- All prices and promotions are subject to change without any prior notice.

Premium Automobiles

Audi Centre Singapore
281 Alexandra Road Singapore 159938

RETAIL PRICE LIST

Effective as of 11 Sep 2018



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	VES (Band)	Retail Price	VES (rebate / surcharge)	Nett Price after VES
AUDI A3 Sportback							
A3 1.0 TFSI S tronic	116	200	4.8	C1	\$124,240	\$10,000	\$134,240
A3 1.4 TFSI S tronic	150	250	5.0	B	\$140,280	\$0	\$140,280
S3 2.0 TFSI qu S tronic	290	380	6.6	C2	\$219,580	\$20,000	\$239,580
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$278,680	\$20,000	\$298,680
AUDI A3 Sedan							
A3 1.0 TFSI S tronic	116	200	4.7	C1	\$126,440	\$10,000	\$136,440
A3 1.4 TFSI S tronic	150	250	4.9	B	\$142,480	\$0	\$142,480
S3 2.0 TFSI qu S tronic	290	380	6.5	C2	\$221,780	\$20,000	\$241,780
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$286,380	\$20,000	\$306,380
AUDI A3 Cabriolet							
A3 1.4 TFSI S tronic	116	200	5.3	C1	\$172,919	\$10,000	\$182,919
AUDI A4 Sedan							
A4 2.0 TFSI S tronic	190	320	5.2	B	\$166,980	\$0	\$166,980
A4 2.0 TFSI qu S tronic (Design)	252	370	6.2	C2	\$223,080	\$20,000	\$243,080
S4 3.0 TFSI qu tiptronic	354	500	7.7	C1	\$284,680	\$10,000	\$294,680
AUDI A4 Avant							
A4 2.0 TFSI S tronic	190	320	5.4	B	\$176,480	\$0	\$176,480
A4 2.0 TFSI qu S tronic (Design)	252	370	6.5	C2	\$232,680	\$20,000	\$252,680
S4 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$294,180	\$10,000	\$304,180
RS 4 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$362,280	\$20,000	\$382,280
AUDI A5 Sportback							
A5 2.0 TFSI S tronic (Design)	190	320	5.6	B	\$191,980	\$0	\$191,980
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$236,930	\$20,000	\$256,930
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$289,580	\$10,000	\$299,580
AUDI A5 Coupe							
A5 2.0 TFSI S tronic (Design)	190	320	5.5	B	\$196,580	\$0	\$196,580
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$242,030	\$20,000	\$262,030
S5 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$296,880	\$10,000	\$306,880
RS 5 2.9 TFSI qu tiptronic	450	600	8.8	C2	\$359,080	\$20,000	\$379,080
AUDI A5 Cabriolet							
A5 2.0 TFSI S tronic (Design)	190	320	5.9	B	\$235,701	\$0	\$235,701
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.7	B	\$274,280	\$0	\$274,280
S5 3.0 TFSI qu tiptronic	354	500	8.1	C1	\$334,780	\$10,000	\$344,780
AUDI A6 Sedan							
A6 1.8 TFSI S tronic (Assistance package)	190	320	5.7	B	\$220,366	\$0	\$220,366
AUDI A7 Sportback							
A7 2.0 TFSI S tronic	252	370	5.9	C1	\$290,080	\$10,000	\$300,080
AUDI A8							
A8 L 3.0 TFSI qu tip	310	440	7.9	C1	\$402,580	\$10,000	\$412,580
A8 L 3.0 TFSI qu tip (New)	340	500	8.2	C2	\$417,479	\$20,000	\$437,479
AUDI Q2							
Q2 1.0 TFSI S tronic	116	200	5.2	C1	\$130,906	\$10,000	\$140,906
Q2 1.4 TFSI CDD S tronic	150	250	5.3	B	\$150,406	\$0	\$150,406
Q2 1.4 TFSI CDD S tronic (Sport)	150	250	5.3	B	\$160,380	\$0	\$160,380
AUDI Q3							
Q3 1.4 TFSI S tronic	150	250	6.0	C1	\$158,395	\$10,000	\$168,395
Q3 2.0 TFSI qu S tronic (Design)	180	320	6.7	C1	\$182,080	\$10,000	\$192,080
AUDI Q5							
Q5 2.0 TFSI qu S tronic (Sport)	252	370	7.4	C1	\$219,080	\$10,000	\$229,080
SQ5 3.0 TFSI qu tiptronic	354	500	8.7	C2	\$286,080	\$20,000	\$306,080
AUDI Q7							
Q7 2.0 TFSI qu tip	252	370	7.4	C1	\$283,780	\$10,000	\$293,780
Q7 3.0 TFSI qu tip	333	440	7.9	C2	\$343,402	\$20,000	\$363,402
AUDI TT Roadster							
TT 1.8 TFSI S tronic	180	250	6.1	B	\$209,980	\$0	\$209,980
AUDI R8 Coupe							
R8 5.2 FSI qu S tronic	540	540	11.4	C2	\$763,380	\$20,000	\$783,380
AUDI R8 Spyder							
R8 5.2 FSI qu S tronic	540	540	11.7	C2	\$837,080	\$20,000	\$857,080

Terms and Conditions :

- ✓ Retail price is subject to in-house Financier and Insurance. Price includes 12-months road tax, registration fee and GST but without insurance.
 - ✓ CDE is non guaranteed and subject to B-bids, failing which new terms and conditions shall apply.
 - ✓ Booking deposit for all models is S\$20,000/-. Minimum booking deposit for indent order is S\$25,000/-. with the exception of RS/R8 is S\$75,000/-.
 - ✓ All deposits are non-refundable upon cancellation.
 - ✓ In-House utilization of PARF/CDE Rebates for new car registration is within Premium Automobile's discretion.
- All prices and promotions are subject to change without any prior notice.

Shiau Chan (LKKAUTO)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 20 September 2018 9:45 AM
To: Shiau Chan (LKKAUTO); SUR
Cc: claims@premiumauto.com.sg
Subject: RE: RE : OD claim for SLF 6656 U

Dear Shiau Chan,

We propose total loss this vehicle as we are unable repair within \$45k.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 19 September, 2018 4:41 PM
To: 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: RE : OD claim for SLF 6656 U

Dear Shiau Chan,

Can check again on the repair margin?

Thank you.

Best Regards,
Tony Foong

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 17 Sep 2018

Preliminary Advice

Vehicle No	: SLF6656U	Accident Date	: 31/08/2018
Make	: AUDI A4	Policy No.	: 2100479660-02
Assignment Date	: 17/09/2018	Excess	: S\$0.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	91,307.00
Revised Amount	:S\$	65,134.00
Check Items (Estimated)	:S\$	18,459.00
Total	:S\$	83,593.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	111,000.00
COE / PARF Rebate	:S\$	65,058.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,942.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0154I
Vehicle Details	
Vehicle No.:	SLF6656U
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CVN017236
Chassis No.:	WAUZZZF40HA022515
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,161.00
Original Registration Date:	22 Aug 2016
First Registration Date:	22 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$27,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Aug 2026
PARF Rebate Amount:	\$20,269.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$44,789.00
Total Rebate Amount:	\$65,058.00

The information contained herein is correct as at 17 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 16:30
Date Of Accident	31/08/2018 15:00
Exact Location Of Accident	ALONG ROAD 1 WOODLANDS AVE 9 JUNCTION BEF RP
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF6656U
Insured/Policyholder	
Name Of Registered Owner	TENG CHENG HAI
NRIC No	S1580154I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85338647
Alternative Phone No	OTHERS-85338647

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.4 TFSI S-TRO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100479660-02
Cover Note Number	

Driver

Name of Driver	ELSTON TENG JIA KUAN
NRIC No	S9629969I
Date Of Birth	08/08/1996
Occupation	INDOOR
Date Of Driving Pass	05/08/2016
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85338647
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	52 CHOA CHU KANG NORTH 6 #21-17
Postcode	689575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO. - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20180901/2092

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE3068K
Vehicle Make/Model/Colour	TOYOTA DYNA 150 / VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GLENN LOH
NRIC/Passport Number	S9707521B
Contact Number	93369805
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLF6656U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or provided by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal runs of correspondence/packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in respect and of future claims;
- (e) the information so collected under (b) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

2/1/18

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name: Yong Jia Jia

DATE/TIME REC: 20180102

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no: T/20180401/2042

DECLARATION

(Date and time the following participants are listed on every record)

Reporting Officer's Signature
Date & Time

2/1/18

Driver's Signature
(If driver is not the police officer)
Date & Time

Reporting Officer's Signature
Name: [Signature]
SABOTAGE NO: 0-20180401



Police Report



SINGAPORE
POLICE FORCE



T201805010502

1 of 3

Report No. T201805010502

Police Station Of Origin:
Choa Chu Kang N.P.C.
20 Choa Chu Kang Street 52 801-02
SINGAPORE 689285
Tel No. 1800-7859999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 01/09/2018 14:22	Vide Report No.:	Station Diary No. 104
---	------------------	--------------------------

Informant's Particulars

Name of Informant: ELSTON TENG JIA KUAN	Address 52 CHOA CHU KANG NORTH 5 #21-17 SINGAPORE 689575		
ID Type / ID No. NRIC NO / S9629989I	Contact No.: Home/Office: Mobile: 85338647		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 22	Date of Birth: 08/08/1996	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name: University College Dublin
Occupation: Student	Driving Licence Information Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 31/08/2018 15:00	Type of Location: X-Junction
Location: Along Road 1 WOODLANDS AVENUE 5				
Junction before RP				
Weather: Drozzling		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBE3059K	Van	TOYOTA	TOYOTA DYNA 150 MAHJUB	White	Slightly Damaged	0
SLF6856U	Car	AUDI	A4 1.4 TFSI S TRONIC	White		0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: Nil	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



1/201809012092

Police Station Of Origin
Choa Chu Kang N.P.C
70 Choa Chu Kang Street 62 #01-02
SINGAPORE 689286
Tel No: 1800-7652999

2 of 3

Report No: 1/201809012092

CONTINUATION OF REPORT

Driver			
Name	GLENN LOH	ID No.	S07075218
Related Vehicle	GBE3068K (Van)	Contact No.	93369805
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ELSTON TENG JIA KUAN	ID No.	S90299091
Related Vehicle	SLF6556U (Car)	Contact No.	85338547
Hospital/Clinic	KHOO TECK FUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	31/08/2018	Date Discharge	31/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Serious

Brief Details.

On 31/8/2018 I was driving a car, SLF6556U along Woodlands Ave 8 near to Republic Poly, when I met with an accident with GBE3068K. I was at a traffic junction, I slowed down when I was reaching the junction as I was not sure when the traffic light was going to turn amber. When I reach the traffic light, it was still in my favour, so I continued to move forward. There was a van, GBE3068K that was at the opposite direction waiting to turn right. When I just started to drive past the junction, I saw the van as he was also trying to turn right from the opposite lane, hence I stepped on the brake. Unfortunately, the front of my car hit the left side of the van. The airbag was deployed, I am unsure what damages my car suffered as I was in pain. There was Traffic Police and ambulance at scene. Due to my injury, I was conveyed to the hospital, where the doctors informed that there was injury on my left forearm, wrist and elbow.

Police Report



SINGAPORE
POLICE FORCE



1/0010000100002

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 680286
Tel No. 1800 7652999

3 of 3

Report No. 1/0010000100002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474585 stating the report number as reference.

Signature Of Officer Recording The Report:

Sgt 2 EDWINA CHEW HUI LING

Signature Of Interpreter:
Not applicable

Singapore Police Force

Officer In Charge Of Case

TP / GIT /

SING CHWEE THENG

Contact No.: 65475297 / 65475246

Signature Of Informant

Date/Time:

01/09/2016 14:22

Classification Of Case

Authentication Stamp:
SP128



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TENG CHENG HAI
 Period of Insurance : 22 Aug 2018 To 21 Aug 2019
 Engine No. : CVN017236
 Chassis No. : WAUZZZF40HA022515

Vehicle No. : SLF6656U
 Policy No. : 2100479660-02
 Endorsement No. :
 Issued Date : 31 Jul 2018

ABOUT THE COVER

Make/Model : AUDI
 Engine Capacity/Tonnage : 1,395.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2016
 Insuring with COE/PAFF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and Inexperienced Driver Excess" ("YIDE") if you are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

TENG CHENG HAI - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Centre Add: 55 Ubi Road 1 Singapore 408696 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 50 Mobile App. Simply search and download "AIG 50" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia)

0504125217

PREMIUM LEASING - EF
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159935

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SGP118

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428886

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1066/2018/PH
Date	:	12-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Teng Cheng Hai
Address	:	52 Choa Chu Kang North 6 #21-17 Singapore 689575
Telephone	:	HP +65 85338647
Type of Claim	:	Own Damage Claims
Policy No.	:	2100479660-02
Vehicle No	:	SLF 6656 U
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	28/011/2016
Engine No	:	CYN 017236
Chassis No	:	WAUZZZF40HA022515
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Aug-18
Place of Accident	:	Along Road 1 Woodlands Ave 9 junction before RP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle, SLF 6656 U.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement test on car o-liner.	S/N \$ 800.00	? photo ✓
2	To remove,check and reinstall front wire harness for headlights,horns,fog lamps,outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
3	To remove and renew aircon condenser,additional radiator,radiator,electrical fans and control unit.Pressurise cooling system.To carry out vacuum and regas.	S/N \$ 1,200.00	✓
4	To dismantle lhs front door panel trim.To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00	✓
5	To remove center console,instrument panels and clusters.Renew dashboard,both frontal airbags,slip ring.Transfer old fittings.Renew seat belts and control unit,pillar trims,roof lining,both curtain air bags and central protection.	S/N \$ 3,600.00	✓
TOTAL LABOUR CHARGES		: \$ 6,260.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 6656 U.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To suspend engine. To remove and reinstall front suspension assy with subframe to facilitate car o-line repairs. Inspect for damages and renew if necessary.	S/N \$ 2,800.00	? photo. ✓
7	To setup vehicle on car-o-liner for repair	S/N \$ 1,800.00	? photo. ✓
8	To dismantle and renew front bumper, both front fenders, both headlights, bonnet, lhs front door. Repair and straighten front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash mangement components. Reinstall all parts removed.	\$ 8,600.00	5000 3500 ✓
9	To respray front bumper, both front fenders, bonnet, bonnet hinges, lhs front door and engine compartment. b.m. - A' pillar.	\$ 5,300.00	3300 ✓
10	To carry out wheel alignment	S/N \$ 240.00	? ✓
11	To carry out diagnostic check	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 25,384.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6656 U.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER	S	1,849.00	de / 1479.20
2	RADIATOR GRILLE	S	1,524.00	car / 1219.20 nm
3	AIR GUIDE GRILLE - LH/RH	1 X S	638.00	RH-090, LH-?X 255
4	FOAM FILLER PIECE	S	107.00	de / 85.20
5	BUMPER CARRIER	S	702.00	bb / 561.60
6	HEXAGON HEAD BOLT	4 S	47.00	nc / 40.32
7	BRACKET - LH/RH	2 S	390.00	? de / 312 ✓
8	HEXAGON HEAD BOLT	4 S	47.00	? ne / 33.92 ✓
9	SUPPORT - LH/RH	2 S	48.00	ne / 40.64
10	BRACKET LOCK CARRIER	S	118.00	car / 94
11	BUMPER COVER	S	109.00	car / 87.20
12	RELEASE LEVER	S	12.00	car / 9.60
13	BOWDEN CABLE	S	50.00	dis / 41.68
14	CAUTION' STICKER	S	12.00	ne / 9.76
15	BRACKET	S	16.00	? ne / 13.44 ✓
16	EXTERNAL TEMPERATURE SENSOR	S	52.00	? ne / 42.96 ✓
17	SECURING STRIP	2 S	60.00	ne / 50.88
18	GRILLE - CENTER	S	171.00	? de / 136.80 ✓
19	AIR GUIDE - LH/RH	2 S	146.00	? X nn
20	CLOSING ELEMENT - LOWER CENTRE	S	180.00	? de / 143.60 ✓
SUB TOTAL SPARE PARTS CHARGES			\$ 6,278.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	FRONT FENDER - LH/RH	2 S	1,330.00	bt- 1064
22	ATTACHMENT PARTS FOR FENDER	2 S	90.00	rel ✓ x m
23	CLOSING ELEMENT - LH	2 S	88.00	rel ✓ 72
24	BRACKET FOR FENDER - LH/RH	2 S	62.00	rel ✓ 50.40
25	BRACKET FOR DEFORMATION	2 S	86.00	rel ✓ 71.70
26	BRACE - LH/RH	2 S	206.00	? x m
27	COVER - LH/RH	2 S	40.00	rel ✓ 72.32
28	COVER - LH/RH	2 S	54.00	rel ✓ 44.48
29	WHEEL HOUSING LINER - LH	S	215.00	? de 178.40 ✓
30	WHEEL HOUSING LINER - RH	S	209.00	? de 167.20 ✓
31	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	2 S	155.00	? x m
32	WHEEL SPOILER - LH/RH	2 S	126.00	? de 104.64 ✓
33	STONE CHIP GUARD	2 S	88.00	? x m
34	LED HEADLIGHT - LH/RH	2 S	13,946.00	CNC ✓ 11156.80
35	POWER MODULE FOR MAIN LIGHT ELECTRONICS	2 S	1,389.00	? de 1111.70 ✓
36	CONTROL UNIT FOR LIGHT CONTROL SYSTEM	2 S	1,314.00	? de 1051.70 ✓
37	HOSE	2 S	60.00	? de 50.72 ✓
38	COMPENSATING PIECE	2 S	75.00	rel ✓ 61.12
39	COMPENSATING PIECE	4 S	140.00	rel ✓ 115.20
40	COMPENSATING PIECE	2 S	70.00	rel ✓ x m
SUB TOTAL SPARE PARTS CHARGES			\$ 19,743.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
41	LIFT CYLINDER - LH/RH	2 S	368.00	? ^{us} 294.40 ✓
42	CORRUGATED PIPE	S	79.00	? x un
43	BONNET	S	2,163.00	bt ✓ 1730.40
44	ATTACHMENT PARTS FOR BONNET	S	105.00	ad ✓ 88.80
45	LID HINGE - LH/RH	2 S	532.00	bt ✓ 443.20
46	IMPACT PROTECTION - LH/RH/CENTRE	3 S	72.00	ad ✓ 59.40
47	FRONT BONNET STRUT	2 S	209.00	? x un
48	STRIKER - LH/RH	2 S	88.00	bt ✓ 72.48
49	LID LOCK	2 S	376.00	bt ✓ 300.80
50	BOWDEN CABLE -CENTER	S	50.00	dis ✓ 41.68
51	FRONT LOCK CARRIER FOR COOLANT RAIDATOR	S	891.00	cm ✓ 712.80
52	AIR GUIDE - LH/RH	2 S	46.00	de ✓ 39.68
53	AIR GUIDE - UPPER	S	14.00	ma ✓ 11.28
54	A/C CONDENSER WITH FLUID RESERVIOR	S	540.00	bt ✓ 432
55	SEAL RING	2 S	8.00	ad ✓ 6.40
56	SEAL RING	2 S	7.00	ad ✓ 5.76
57	A/C PRESSURE SENSOR SWITCH	S	170.00	bt ✓ 135.60
58	A/C PRESSURE SENSOR SWITCH SAFETY SWITCH	S	46.00	dis ✓ 37.76
59	O RING	S	3.00	ad ✓ 2.40
60	COOLER FOR COOLANT	S	585.00	bt ✓ 468
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,352.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RUBBER BUSH	2 \$ 22.00	na / 18.56
62	ADDITIONAL COOLER FOR COOLANT	\$ 455.00	bt / 364
63	COOLANT	4 \$ 82.00	nei / 67.70
64	FAN RING	\$ 230.00	re / - photo - 184
65	RADIATOR FAN WITH CONTROL UNIT	\$ 2,055.00	one / photo - 1644
66	INTAKE AIR DUCT - RH	\$ 18.00	de / 15.70
67	AIR GUIDE	\$ 31.00	de / 26.68
68	SEAL	\$ 13.00	nei / 10.32
69	AIR FILTER	\$ 338.00	unt / 270
70	INTAKE HOSE	\$ 80.00	de / 67.84
71	TOOTHED BELT GUARD - UPPER	\$ 64.00	ana / 52.66
72	COVER	\$ 102.00	? x un
73	TOOTHED BELT GUARD - LOWER	\$ 64.00	? ds 28.37 ✓
74	RETAINER FOR CONTROL UNIT	\$ 50.00	de / 42
75	ALTERNATOR	\$ 2,561.00	? x
76	A/C COMPRESSOR	\$ 2,327.00	? x
77	HEXAGON BOLT (M8X95)	3 \$ 23.00	? x
78	POLY V-BELT	\$ 42.00	? x
79	BELT TENSIONER DAMPER	\$ 165.00	? x
80	BRACKET	\$ 45.00	? x
SUB TOTAL SPARE PARTS CHARGES		\$ 8,767.00	

All charges are not inclusive of GST

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
81	WINDOW SLOT SEAL WITH TRIM STRIP - LH	S	265.00	act - 712
82	WINDOW GUIDE - LH	S	392.00	X
83	TRIM STRIP FOR WINDOW GUIDE - LH	S	222.00	X } int
84	COVER FOR PNEUM CHAMBER	S	85.00	? X }
85	SOUND ABS. FOR BONNET	S	296.00	de - 736.80
86	CAR PLATE - FRONT	S/N S	25.00	bt -
87	SUNDRIES	S	1,000.00	? , ue 496.32
88	AIRBAG UNIT FOR STEERING WHEEL	S	3,111.00	act - 2499.80
89	FRONT AIRBAG UNIT - LH	S	3,981.00	act - 3184.80
90	HEAD AIRBAG UNIT - LH	S	1,692.00	act - 1353.60
91	HEAD AIRBAG UNIT - RH	S	1,692.00	act - 1353.60
92	CONTROL UNIT FOR AIRBAG	S	1,870.00	act - 1496.
93	CRASH SENSOR FOR AIRBAG - FRONT	S	818.00	act - 415.60
94	CENTRAL PROTECTION	S	470.00	act - 388.
95	FRONT SEAT BELT WITH TENSIONER - LH	S	956.00	act - 764.80
96	FRONT SEAT BELT WITH TENSIONER - RH	S	956.00	act - 764.80
97	SEAT BELT HEIGHT ADJUSTER	2 S	306.00	? act - 253.60 ✓
98	DASHBOARD WITH AIR DUCT	S	4,604.00	de ✓ 3683.20
99	MOULDED HEADLINING (CLOTH)	S	1,682.00	de - 1345.60
100	A-PILLAR TRIM	2 S	360.00	? photo. 287.20 ✓ de
TOTAL SPARE PARTS CHARGES		:	\$ 65,923.00	
TOTAL LABOUR CHARGES		:	\$ 25,384.00	
GRAND TOTAL		:	\$ 91,307.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

167222.68

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Taufik. 97495749.
Surveyed Date : 14/9/18 @ 1115.
Authorised Date : Not Authorised
Excess Cost : to be advise
Liability :
Remarks : Resuming before paint.
sur @ Hellen.com.
18 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1066/2018/PH

27-Sep-18

Tony

1

SLF 6656 U

Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	BASE ENGINE	\$ 24,492.00	
2	GEARBOX	\$ 27,021.00	
		\$ 51,513.00	
TOTAL		\$ 51,513.00	

19597.60 mg

Jim ✓
R - No compression ✓
X N

For Premium Automobiles Pte Ltd



Authorised Signature

9

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1066/2018/PH 29-Oct-18 CHANG 1 of 1 SLF 6656 U Audi A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To renew engine assy and damaged attachment. S/N	\$ 3,200.00	
2	To carry out engine number stamping. LTA inspection and procedures. S/N	\$ 400.00	
TOTAL LABOURS :		\$ 3,600.00	
Parts			
1	ENGINE OIL	\$ 264.00	215.60
2	ENGINE ATTACHMENT SEALS, BOLTS AND NUTS	\$ 510.00	408.00
3	ENGINE MOUNTING - LH/RH 2	\$ 545.00	435.60
4	ENGINE MOUNTING SUPPORT - LH/RH 2	\$ 215.00	174.00
5	ENGINE MOUNTING COVER PLATE - RH	\$ 32.00	26.24
6	ATF FLUID	\$ 121.00	97.60
TOTAL PARTS :		\$ 1,687.00	
GRAND TOTAL :		\$ 5,287.00	

For Premium Automobiles Pte Ltd

Signature
24/10/18



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1066/2018/PH
Date : 12-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Teng Cheng Hai
Address : 52 Choa Chu Kang North 6
#21-17
Singapore 689575
Telephone : HP +65 85338647
Type of Claim : Own Damage Claims
Policy No. : 2100479660-02
Vehicle No : **SLF 6656 U**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : 28/011/2016
Engine No : CVN 017236
Chassis No : WAUZZZF40HA022515
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Aug-18
Place of Accident : Along Road 1 Woodlands Ave 9 junction before RP

Hi Adrian

Vehicle in workshop for 81 days
exclude Sundays - Please discuss
with Miss Nora for closure - jb -

20-Apr-19

35 days
40 days

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 6656 U.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement test on car o-liner.	S/N \$	800.00	\$ 800.00
2	To remove,check and reinstall front wire harness for headlights,horns,fog lamps,outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
3	To remove and renew aircon condenser,additional radiator,radiator,electrical fans and control unit.Pressurise cooling system.To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
4	To dismantle lhs front door panel trim.To remove and reinstall lhs wing mirror assy.	S/N \$	300.00	\$ 300.00
5	To remove center console,instrument panels and clusters.Renew dashboard,both frontal airbags,slip ring.Transfer old fittings.Renew seat belts and control unit,pillar trims,roof lining,both curtain air bags and central protection.	S/N \$	3,600.00	\$ 3,600.00
TOTAL LABOUR CHARGES		:	<u>\$ 6,260.00</u>	<u>\$ 6,260.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 6656 U.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 6,260.00
6	To suspend engine. To remove and reinstall front suspension assy with subframe to facilitate car o-line repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,800.00	\$ 2,800.00
7	To setup vehicle on car-o-liner for repair	S/N	\$ 1,800.00	\$ 1,800.00
8	To dismantle and renew front bumper, both front fenders, both headlights, bonnet, lhs front door. Repair and straighten front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed. (Added 3 days for chassis repair \$1500.00)		\$ 8,600.00	\$ 5,000.00
9	To respray front bumper, both front fenders, bonnet, bonnet hinges, lhs front door and engine compartment.		\$ 5,300.00	\$ 3,300.00
10	To carry out wheel alignment	S/N	\$ 240.00	\$ 240.00
11	Added labour charges - see attached		\$ 3,600.00	\$ 3,600.00
12	To carry out diagnostic check	S/N	\$ 384.00	\$ 384.00
	TOTAL LABOUR CHARGES	:	\$ 28,984.00	\$ 23,384.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6656 U.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	RADIATOR GRILLE	\$ 1,524.00	\$ 1,219.20
3	AIR GUIDE GRILLE - LH/RH	2 \$ 638.00	\$ 255.20
4	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
5	BUMPER CARRIER	\$ 702.00	\$ 561.60
6	HEXAGON HEAD BOLT	4 \$ 47.00	\$ 40.32
7	BRACKET - LH/RH	2 \$ 390.00	\$ 312.00
8	HEXAGON HEAD BOLT	4 \$ 47.00	\$ 33.92
9	SUPPORT - LH/RH	2 \$ 48.00	\$ 40.64
10	BRACKET LOCK CARRIER	\$ 118.00	\$ 94.00
11	BUMPER COVER	\$ 109.00	\$ 87.20
12	RELEASE LEVER	\$ 12.00	\$ 9.60
13	BOWDEN CABLE	\$ 50.00	\$ 41.68
14	CAUTION' STICKER	\$ 12.00	\$ 9.76
15	BRACKET	\$ 16.00	\$ 13.04
16	EXTERNAL TEMPERATURE SENSOR	\$ 52.00	\$ 42.96
17	SECURING STRIP	2 \$ 60.00	\$ 50.88
18	GRILLE - CENTER	\$ 171.00	\$ 136.80
19	AIR GUIDE - LH/RH	2 \$ 146.00	
20	CLOSING ELEMENT - LOWER CENTRE	\$ 180.00	\$ 143.60
SUB TOTAL SPARE PARTS CHARGES		\$ 6,278.00	\$ 4,656.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 4,656.80
21	FRONT FENDER - LH/RH	2 \$	1,330.00	\$ 1,064.00
22	ATTACHMENT PARTS FOR FENDER	2 \$	90.00	
23	CLOSING ELEMENT - LH	2 \$	88.00	\$ 72.00
24	BRACKET FOR FENDER - LH/RH	2 \$	62.00	\$ 50.40
25	BRACKET FOR DEFORMATION	2 \$	86.00	\$ 71.20
26	BRACE - LH/RH	2 \$	206.00	
27	COVER - LH/RH	2 \$	40.00	\$ 32.32
28	COVER - LH/RH	2 \$	54.00	\$ 44.48
29	WHEEL HOUSING LINER - LH	\$	215.00	\$ 178.40
30	WHEEL HOUSING LINER - RH	\$	209.00	\$ 167.20
31	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	2 \$	155.00	
32	WHEEL SPOILER - LH/RH	2 \$	126.00	\$ 104.64
33	STONE CHIP GUARD	2 \$	88.00	
34	LED HEADLIGHT - LH/RH	2 \$	13,946.00	\$ 11,156.80
35	POWER MODULE FOR MAIN LIGHT ELECTRONICS	2 \$	1,389.00	\$ 1,111.20
36	CONTROL UNIT FOR LIGHT CONTROL SYSTEM	2 \$	1,314.00	\$ 1,051.20
37	HOSE	2 \$	60.00	\$ 50.72
38	COMPENSATING PIECE	2 \$	75.00	\$ 61.12
39	COMPENSATING PIECE	4 \$	140.00	\$ 115.20
40	COMPENSATING PIECE	2 \$	70.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 19,743.00	\$ 19,987.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 19,987.68
41	LIFT CYLINDER - LH/RH	2 \$	368.00	\$ 294.40
42	CORRUGATED PIPE	\$	79.00	
43	BONNET	\$	2,163.00	\$ 1,730.40
44	ATTACHMENT PARTS FOR BONNET	\$	105.00	\$ 88.80
45	LID HINGE - LH/RH	2 \$	532.00	\$ 443.20
46	IMPACT PROTECTION - LH/RH/CENTRE	3 \$	72.00	\$ 59.44
47	FRONT BONNET STRUT	2 \$	209.00	
48	STRIKER - LH/RH	2 \$	88.00	\$ 72.48
49	LID LOCK	2 \$	376.00	\$ 300.80
50	BOWDEN CABLE -CENTER	\$	50.00	\$ 41.68
51	FRONT LOCK CARRIER FOR COOLANT RAIDATOR	\$	891.00	\$ 712.80
52	AIR GUIDE - LH/RH	2 \$	46.00	\$ 39.68
53	AIR GUIDE - UPPER	\$	14.00	\$ 11.28
54	A/C CONDENSER WITH FLUID RESERVIOR	\$	540.00	\$ 432.00
55	SEAL RING	2 \$	8.00	\$ 6.40
56	SEAL RING	2 \$	7.00	\$ 5.76
57	A/C PRESSURE SENSOR SWITCH	\$	170.00	\$ 135.60
58	A/C PRESSURE SENSOR SWITCH SAFETY SWITCH	\$	46.00	\$ 37.76
59	O RING	\$	3.00	\$ 2.00
60	COOLER FOR COOLANT	\$	585.00	\$ 468.00
SUB TOTAL SPARE PARTS CHARGES			\$ 6,352.00	\$ 24,870.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 8841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 24,870.16
61	RUBBER BUSH	2 \$	22.00	\$ 18.56
62	ADDITIONAL COOLER FOR COOLANT	\$	455.00	\$ 364.00
63	COOLANT	4 \$	82.00	\$ 67.20
64	FAN RING	\$	230.00	\$ 184.00
65	RADIATOR FAN WITH CONTROL UNIT	\$	2,055.00	\$ 1,644.00
66	INTAKE AIR DUCT - RH	\$	18.00	\$ 15.20
67	AIR GUIDE	\$	31.00	\$ 26.08
68	SEAL	\$	13.00	\$ 10.32
69	AIR FILTER	\$	338.00	\$ 270.00
70	INTAKE HOSE	\$	80.00	\$ 67.84
71	TOOTHED BELT GUARD - UPPER	\$	64.00	\$ 52.16
72	COVER	\$	102.00	
73	TOOTHED BELT GUARD -LOWER	\$	64.00	\$ 28.32
74	RETAINER FOR CONTROL UNIT	\$	50.00	\$ 42.00
75	ALTERNATOR	\$	2,561.00	
76	A/C COMPRESSOR	\$	2,327.00	
77	HEXAGON BOLT (M8X95)	3 \$	23.00	
78	POLY V-BELT	\$	42.00	
79	BELT TENSIONER DAMPER	\$	165.00	
80	BRACKET	\$	45.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 8,767.00	\$ 27,659.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF6656 U.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 27,659.84
81	WINDOW SLOT SEAL WITH TRIM STRIP - LH		\$ 265.00	\$ 212.00
82	WINDOW GUIDE - LH		\$ 392.00	
83	TRIM STRIP FOR WINDOW GUIDE - LH		\$ 222.00	
84	COVER FOR PHEUM CHAMBER		\$ 85.00	
85	SOUND ABS. FOR BONNET		\$ 296.00	\$ 236.80
86	CAR PLATE - FRONT	S/N	\$ 25.00	\$ 25.00
87	SUNDRIES		\$ 1,000.00	\$ 496.32
88	AIRBAG UNIT FOR STEERING WHEEL		\$ 3,111.00	\$ 2,488.80
89	FRONT AIRBAG UNIT - LH		\$ 3,981.00	\$ 3,184.80
90	HEAD AIRBAG UNIT - LH		\$ 1,692.00	\$ 1,353.60
91	HEAD AIRBAG UNIT - RH		\$ 1,692.00	\$ 1,353.60
92	CONTROL UNIT FOR AIRBAG		\$ 1,870.00	\$ 1,496.00
93	CRASH SENSOR FOR AIRBAG - FRONT		\$ 818.00	\$ 915.60
94	CENTRAL PROTECTION		\$ 470.00	\$ 388.00
95	FRONT SEAT BELT WITH TENSIONER - LH		\$ 956.00	\$ 764.80
96	FRONT SEAT BELT WITH TENSIONER - RH		\$ 956.00	\$ 764.80
97	SEAT BELT HEIGHT ADJUSTER	2	\$ 306.00	\$ 257.60
98	DASHBOARD WITH AIR DUCT		\$ 4,604.00	\$ 3,683.20
99	MOULDED HEADLINING (CLOTH)		\$ 1,682.00	\$ 1,345.60
100	SUPPLEMENTARY		\$ 1,687.00	\$ 1,362.28
101	SUPPLEMENTARY		\$ 520.00	\$ 416.00
102	SUPPLEMENTARY		\$ 51,513.00	\$ 19,593.60
104	A-PILLAR TRIM	2	\$ 360.00	\$ 287.20
	TOTAL SPARE PARTS CHARGES	:	\$ 119,643.00	\$ 68,285.44
	TOTAL LABOUR CHARGES	:	\$ 28,984.00	\$ 23,384.00
	GRAND TOTAL	:	\$ 148,627.00	\$ 91,669.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6386 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1066/2018/PH 27-Sep-18 Tony 1 SLF 6658 U Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BASE ENGINE	\$ 24,492.00	\$ 19,593.60
2	GEARBOX	\$ 27,021.00	
		\$ 51,513.00	\$ 19,593.60
	TOTAL:	\$ 51,513.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1066/2018/PH 29-Oct-18 CHANG 1 of 1 SLF 6656 U Audi A4 SEDAN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
Labours				
1	To renew engine assy and damaged attachment.	S/N	\$ 3,200.00	\$ 3,200.00
2	To carry out engine number stamping, LTA inspection and procedures.	S/N	\$ 400.00	\$ 400.00
TOTAL LABOURS :			\$ 3,600.00	\$ 3,600.00
Parts				
1	ENGINE OIL		\$ 264.00	\$ 215.60
2	ENGINE ATTACHMENT SEALS, BOLTS AND NUTS		\$ 510.00	\$ 408.04
3	ENGINE MOUNTING - LH/RH	2	\$ 545.00	\$ 435.60
4	ENGINE MOUNTING SUPPORT - LH/RH	2	\$ 215.00	\$ 179.20
5	ENGINE MOUNTING COVER PLATE - RH		\$ 32.00	\$ 26.24
6	ATF FLUID		\$ 121.00	\$ 97.60
TOTAL PARTS :			\$ 1,687.00	\$ 1,362.28
GRAND TOTAL :			\$ 5,287.00	\$ 4,962.28

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 3

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1066/2018/PH 6-Jan-19 CHANG 1 of 1 SLF 6656 U Audi A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	ENGINE UNDERCOVER	\$ 520.00	\$ 416.00
	TOTAL PARTS :	\$ 520.00	\$ 416.00
	GRAND TOTAL :	\$ 520.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 6656 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1066/2019/NH

2 DEC 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLF 6656 U, Audi A4 SEDAN 1.4 TFSL.

With reference to the above-mentioned vehicle, no. **SLF 6656 U**, claimant, **Mr. Teng Cheng Hai**, please find the related document per attached.

1. A copy of the Original invoice no. 85014450 – S\$ 81,748.00
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept


Encl
AIG – SLF 6656 U

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service

Service Appointment 6368 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:13

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014450 Date : 12/11/2019 Order : SLF6656U Term : 30	Account A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No: SLF6656U (V 31068)

Regn Date: 22/08/2016

Mileage: 16928

WIP No : 23856

Model : A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF40HA022515

Engine CVN 017236

Dept : U

You have been assisted by:- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
5	SUBLET	To carry out contractual LUMP SUM repair basis as agreed	80,000.00	1.00	80,000.00
Q	EXC	Insurance Excess/Liability	-3600.00	1.00	-3600.00

Parts 0.00
Labour 0.00
Sublet 80,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 76,400.00
7% GST 5,348.00
Grand Total 81,748.00



13/11

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLF6656U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1066/2018/TF
15 January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF40HA022515
Vehicle Regn No. : **SLF6656U**
Vehicle Mileage : 14075KM
Vehicle Owner : Mr. Teng Cheng Hai
Certificate No : 2100479660-02
Own Damage Excess : S\$ 3,852.00 (inclusive of 7% GST)
Accident Date : 31 August 2018
Place : Along Road 1 Woodlands Ave 9
Repair Cost : \$ 81,748.00
WIP No. : 23856
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 17/1/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Sep 2018		17 Sep 2018 12:01 Edit Adj Rpt	S\$80,000.00 Edit Estimates	S\$80,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	TENG CHENG HAI, ID: S1580154		
Vehicle Reg. No.:	SLF6656U	Date of Loss:	31/08/2018 15:00 - :59 [24 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 4313401665SG	Policy/Cover Note No.:	2100479660-02 (Comprehensive)
		Excess:	S\$3,600.00
Repairer:	Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/09/2018]		
Driver/Custodian:	ELSTON TENG JIA KUAN (22 / Male) , NRIC: S9629969I, Tel: +6585338647 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (31/10/2019): Alert - Adj Mandate Approved (S\$80000.00) - SLF6656U - Claim Handler: Loo, Tong ...
- AIG_SG (05/12/2018): Alert - Adj Mandate Approved (S\$90000.00) - SLF6656U - Claim Handler: Loo, Tong ...
- AIG_SG (20/09/2018): Alert - Adj Mandate Approved (S\$83593.00) - SLF6656U - Claim Handler: Loo, Tong ...
- AIG_SG (18/09/2018): Alert - Adj Mandate Maintained - SLF6656U - Claim Handler: Loo, Tong Shing

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF6656U (4313401666SG)
OD

Aug 31 2018 3:00PM
[TENG CHENG HAI]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 16:09	Video - Other	Load AVI	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 16:09	Adjuster Immediate Advice	Load HTM	
2	20/09/18 11:25	Adjuster Immediate Advice	Load HTM	
3	27/09/18 11:08	Adjuster Immediate Advice	Load HTM	
4	18/10/18 16:15	Adjuster Immediate Advice	Load HTM	
5	08/11/18 15:40	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:57	Odometer Reading	Load JPG	
2	17/09/18 15:57	General View	Load JPG	
3	17/09/18 15:57	General View	Load JPG	
4	17/09/18 15:57	General View	Load JPG	
5	17/09/18 15:57	General View	Load JPG	
6	17/09/18 15:57	General View	Load JPG	
7	17/09/18 15:57	General View	Load JPG	
8	17/09/18 15:57	General View	Load JPG	
9	17/09/18 15:57	General View	Load JPG	
10	17/09/18 15:57	General View	Load JPG	
11	17/09/18 15:57	General View	Load JPG	
12	17/09/18 15:57	General View	Load JPG	
13	17/09/18 15:57	General View	Load JPG	
14	17/09/18 15:57	General View	Load JPG	
15	17/09/18 15:57	General View	Load JPG	
16	17/09/18 15:57	General View	Load JPG	
17	17/09/18 15:57	General View	Load JPG	
18	17/09/18 15:57	General View	Load JPG	
19	17/09/18 15:57	General View	Load JPG	
20	17/09/18 15:57	General View	Load JPG	
21	17/09/18 15:57	General View	Load JPG	
22	17/09/18 15:57	General View	Load JPG	
23	17/09/18 15:57	General View	Load JPG	
24	17/09/18 15:57	General View	Load JPG	
25	17/09/18 15:57	General View	Load JPG	
26	17/09/18 15:57	General View	Load JPG	
27	17/09/18 15:57	General View	Load JPG	
28	17/09/18 15:57	General View	Load JPG	
29	17/09/18 15:57	General View	Load JPG	
30	17/09/18 15:57	General View	Load JPG	
31	17/09/18 15:57	General View	Load JPG	
32	17/09/18 15:57	General View	Load JPG	
33	17/09/18 15:57	General View	Load JPG	
34	17/09/18 15:57	General View	Load JPG	

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	17/09/18 15:57	General View		☒
36	17/09/18 15:57	General View		☒
37	17/09/18 15:57	General View		☒
38	17/09/18 15:57	General View		☒
39	17/09/18 15:57	General View		☒
40	17/09/18 15:57	General View		☒
41	17/09/18 15:57	General View		☒
42	17/09/18 15:57	General View		☒
43	17/09/18 15:57	General View		☒
44	17/09/18 15:57	General View		☒
45	17/09/18 15:57	General View		☒
46	17/09/18 15:57	General View		☒
47	17/09/18 15:57	General View		☒
48	17/09/18 15:57	General View		☒
49	17/09/18 15:57	General View		☒
50	17/09/18 15:57	General View		☒
51	17/09/18 15:57	General View		☒
52	17/09/18 15:57	General View		☒
53	17/09/18 15:57	General View		☒
54	17/09/18 15:57	General View		☒
55	17/09/18 15:57	General View		☒
56	17/09/18 15:57	General View		☒
57	17/09/18 15:57	General View		☒
58	17/09/18 15:57	General View		☒
59	17/09/18 15:57	General View		☒
60	17/09/18 15:57	General View		☒
61	17/09/18 15:57	General View		☒
62	17/09/18 15:57	General View		☒
63	17/09/18 15:57	General View		☒
64	17/09/18 15:57	General View		☒
65	17/09/18 15:57	General View		☒
66	17/09/18 15:57	General View		☒
67	17/09/18 15:57	General View		☒
68	17/09/18 15:57	General View		☒
69	17/09/18 15:57	General View		☒
70	17/09/18 15:57	General View		☒
71	17/09/18 15:57	General View		☒
72	17/09/18 15:57	General View		☒
73	17/09/18 15:57	General View		☒
74	17/09/18 15:57	General View		☒
75	17/09/18 15:57	General View		☒
76	17/09/18 15:57	General View		☒
77	17/09/18 15:57	General View		☒
78	17/09/18 15:57	General View		☒
79	17/09/18 15:57	General View		☒
80	17/09/18 15:57	General View		☒
81	17/09/18 15:57	General View		☒
82	17/09/18 15:57	General View		☒
83	17/09/18 15:57	General View		☒
84	17/09/18 15:57	General View		☒
85	17/09/18 15:57	General View		☒
86	17/09/18 15:57	General View		☒
87	17/09/18 15:57	General View		☒
88	17/09/18 15:57	General View		☒
89	17/09/18 15:57	General View		☒
90	17/09/18 15:57	General View		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	17/09/18 15:57	General View		☒
92	17/09/18 15:57	General View		☒
93	17/09/18 15:57	General View		☒
94	17/09/18 15:57	General View		☒
95	17/09/18 15:57	General View		☒
96	17/09/18 15:57	General View		☒
97	17/09/18 15:57	General View		☒
98	17/09/18 15:57	General View		☒
99	17/09/18 15:57	General View		☒
100	17/09/18 15:57	General View		☒
101	17/09/18 15:57	General View		☒
102	17/09/18 15:57	General View		☒
103	17/09/18 15:57	General View		☒
104	17/09/18 15:57	General View		☒
105	17/09/18 15:57	General View		☒
106	17/09/18 15:57	General View		☒
107	17/09/18 15:57	General View		☒
108	17/09/18 15:57	General View		☒
109	17/09/18 15:57	General View		☒
110	17/09/18 15:57	General View		☒
111	17/09/18 15:57	General View		☒
112	17/09/18 15:57	General View		☒
113	17/09/18 15:57	General View		☒
114	17/09/18 15:57	General View		☒
115	17/09/18 15:57	General View		☒
116	17/09/18 15:57	General View		☒
117	17/09/18 15:57	General View		☒
118	17/09/18 15:57	General View		☒
119	17/09/18 15:57	General View		☒
120	17/09/18 15:57	General View		☒
121	17/09/18 15:57	General View		☒
122	17/09/18 15:57	General View		☒
123	17/09/18 15:57	General View		☒
124	17/09/18 15:57	General View		☒
125	17/09/18 15:57	General View		☒
126	17/09/18 15:57	General View		☒
127	17/09/18 15:57	General View		☒
128	17/09/18 15:57	General View		☒
129	17/09/18 15:57	Chassis Number		☒
130	17/09/18 15:57	General View		☒
131	17/09/18 15:57	General View		☒
132	17/09/18 15:57	General View		☒
133	17/09/18 15:57	General View		☒
134	17/09/18 15:57	General View		☒
135	17/09/18 15:57	General View		☒
136	17/09/18 15:57	General View		☒
137	17/09/18 15:57	General View		☒
138	17/09/18 15:57	General View		☒
139	17/09/18 15:57	General View		☒
140	17/09/18 15:57	General View		☒
141	17/09/18 15:57	General View		☒
142	17/09/18 15:57	General View		☒
143	17/09/18 15:57	General View		☒
144	17/09/18 15:57	General View		☒
145	17/09/18 15:57	General View		☒
146	17/09/18 15:57	General View		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
147	17/09/18 15:57	General View		☒
148	17/09/18 15:57	General View		☒
149	17/09/18 15:57	General View		☒
150	17/09/18 15:57	General View		☒
151	17/09/18 15:57	General View		☒
152	17/09/18 15:57	General View		☒
153	17/09/18 15:57	General View		☒
154	17/09/18 15:57	General View		☒
155	17/09/18 15:57	General View		☒
156	17/09/18 15:57	General View		☒
157	17/09/18 15:57	General View		☒
158	17/09/18 15:57	General View		☒
159	17/09/18 15:57	General View		☒
160	17/09/18 15:57	General View		☒
161	17/09/18 15:57	General View		☒
162	18/10/18 16:09	Reinspection Photo		☒
163	18/10/18 16:09	Reinspection Photo		☒
164	18/10/18 16:09	Reinspection Photo		☒
165	18/10/18 16:09	Reinspection Photo		☒
166	18/10/18 16:09	Reinspection Photo		☒
167	18/10/18 16:09	Reinspection Photo		☒
168	18/10/18 16:09	Reinspection Photo		☒
169	18/10/18 16:09	Reinspection Photo		☒
170	18/10/18 16:09	Reinspection Photo		☒
171	18/10/18 16:09	Reinspection Photo		☒
172	18/10/18 16:09	Reinspection Photo		☒
173	18/10/18 16:09	Reinspection Photo		☒
174	18/10/18 16:09	Reinspection Photo		☒
175	18/10/18 16:09	Reinspection Photo		☒
176	18/10/18 16:09	Reinspection Photo		☒
177	18/10/18 16:09	Reinspection Photo		☒
178	18/10/18 16:09	Reinspection Photo		☒
179	18/10/18 16:09	Reinspection Photo		☒
180	18/10/18 16:09	Reinspection Photo		☒
181	18/10/18 16:09	Reinspection Photo		☒
182	18/10/18 16:09	Reinspection Photo		☒
183	18/10/18 16:09	Reinspection Photo		☒
184	18/10/18 16:09	Reinspection Photo		☒
185	18/10/18 16:09	Reinspection Photo		☒
186	18/10/18 16:09	Reinspection Photo		☒
187	18/10/18 16:09	Reinspection Photo		☒
188	18/10/18 16:09	Reinspection Photo		☒
189	18/10/18 16:09	Reinspection Photo		☒
190	18/10/18 16:09	Reinspection Photo		☒
191	18/10/18 16:09	Reinspection Photo		☒
192	18/10/18 16:09	Reinspection Photo		☒
193	18/10/18 16:09	Reinspection Photo		☒
194	27/09/19 15:10	Reinspection Photo		☒
195	27/09/19 15:10	Reinspection Photo		☒
196	27/09/19 15:10	Reinspection Photo		☒
197	27/09/19 15:10	Reinspection Photo		☒
198	27/09/19 15:10	Reinspection Photo		☒
199	27/09/19 15:10	Reinspection Photo		☒
200	27/09/19 15:10	Reinspection Photo		☒
201	27/09/19 15:10	Reinspection Photo		☒
202	27/09/19 15:10	Reinspection Photo		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
203	27/09/19 15:10	Reinspection Photo		☒
204	27/09/19 15:10	Reinspection Photo		☒
205	27/09/19 15:10	Reinspection Photo		☒
206	27/09/19 15:10	Reinspection Photo		☒
207	27/09/19 15:10	Reinspection Photo		☒
208	27/09/19 15:10	Reinspection Photo		☒
209	27/09/19 15:10	Reinspection Photo		☒
210	27/09/19 15:10	Reinspection Photo		☒
211	27/09/19 15:10	Reinspection Photo		☒
212	27/09/19 15:10	Reinspection Photo		☒
213	27/09/19 15:10	Reinspection Photo		☒
214	27/09/19 15:10	Reinspection Photo		☒
215	27/09/19 15:10	Reinspection Photo		☒
216	27/09/19 15:10	Reinspection Photo		☒
217	27/09/19 15:10	Reinspection Photo		☒
218	27/09/19 15:15	Reinspection Photo		☒
219	27/09/19 15:15	Reinspection Photo		☒
220	27/09/19 15:15	Reinspection Photo		☒
221	27/09/19 15:15	Reinspection Photo		☒
222	27/09/19 15:15	Reinspection Photo		☒
223	27/09/19 15:15	Reinspection Photo		☒
224	27/09/19 15:15	Reinspection Photo		☒
225	27/09/19 15:15	Reinspection Photo		☒
226	27/09/19 15:15	Reinspection Photo		☒
227	27/09/19 15:15	Reinspection Photo		☒
228	27/09/19 15:15	Reinspection Photo		☒
229	27/09/19 15:15	Reinspection Photo		☒
230	27/09/19 15:15	Reinspection Photo		☒
231	27/09/19 15:15	Reinspection Photo		☒
232	27/09/19 15:15	Reinspection Photo		☒
233	27/09/19 15:15	Reinspection Photo		☒
234	27/09/19 15:15	Reinspection Photo		☒
235	27/09/19 15:15	Reinspection Photo		☒
236	27/09/19 15:15	Reinspection Photo		☒
237	27/09/19 15:15	Reinspection Photo		☒
238	27/09/19 15:15	Reinspection Photo		☒
239	27/09/19 15:15	Reinspection Photo		☒
240	27/09/19 15:15	Reinspection Photo		☒
241	27/09/19 15:17	Replacement Part Photo		☒
242	27/09/19 15:17	Replacement Part Photo		☒
243	27/09/19 15:17	Replacement Part Photo		☒
244	27/09/19 15:17	Replacement Part Photo		☒
245	27/09/19 15:17	Replacement Part Photo		☒
246	27/09/19 15:17	Replacement Part Photo		☒
247	27/09/19 15:17	Replacement Part Photo		☒
248	27/09/19 15:17	Replacement Part Photo		☒
249	27/09/19 15:17	Replacement Part Photo		☒
250	04/11/19 11:11	Reinspection Photo		☒
251	04/11/19 11:11	Reinspection Photo		☒
252	04/11/19 11:11	Reinspection Photo		☒
253	04/11/19 11:11	Reinspection Photo		☒
254	04/11/19 11:11	Reinspection Photo		☒
255	04/11/19 11:11	Reinspection Photo		☒
256	04/11/19 11:11	Reinspection Photo		☒
257	04/11/19 11:11	Reinspection Photo		☒
258	04/11/19 11:11	Reinspection Photo		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
259	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
260	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
261	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
262	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
263	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
264	04/11/19 11:11	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:58	Original invoice/receipt for charges incurred in amending or purchasing additional air ticket/accommodation	 Load PDF	
2	17/09/18 15:58	Police Report	 Load PDF	
3	17/09/18 15:58	Certificate of Insurance	 Load PDF	
4	17/09/18 15:58	Driver's Driving License	 Load PDF	
5	17/09/18 15:58	ESTIMATE	 Load PDF	
6	20/09/18 11:27	AUDI PRICE LIST AS AT 08/12/2017	 Load PDF	
7	20/09/18 11:27	AUDI PRICE LIST AS AT 11/09/2018	 Load PDF	
8	20/09/18 11:27	Log card (if available)	 Load PDF	
9	27/09/18 11:09	SUPPLEMENTARY LIST	 Load PDF	
10	18/10/18 16:06	SUPPLEMENTARY LIST	 Load PDF	
11	08/11/18 15:28	SUPPLEMENTARY LIST 2	 Load PDF	
12	06/12/19 09:59	Workshop Invoice	 Load PDF	
13	06/12/19 09:59	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/18 16:54	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/18 16:51	Police Report	 Load JPG	☒
2	03/09/18 16:51	Police Report	 Load JPG	☒
3	03/09/18 16:51	Police Report	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/18 16:50	Sketch Plan	 Load JPG	☒
2	03/09/18 16:50	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016873/T1QB

Date: 06/12/2019

REFERENCE

Insured/Claimant: TENG CHENG HAI Policy No: 2100479660-02
Date of Loss: 31/08/2018 Nature of Claim: OD Claim No: 4313401666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF6656U**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN017236
Reg. Date: 22/08/2016 (Man. Year: 2016) Chassis No: WAUZZZF40HA022515
Colour: White Odometer: 14063 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$111,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	114,413.48	68,285.44	46,128.04	40.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,984.00	23,384.00	5,600.00	19.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	143,397.48	91,669.44	51,728.04	36.07
Approved Total (Overridden) (S\$)		80,000.00		
- Excess (S\$)	3,600.00	3,600.00	0.00	0.00
(S\$)	139,797.48	76,400.00	63,397.48	45.35
+ GST 7.00/7.00% (S\$)	9,785.82	5,348.00	4,437.82	45.35
Nett Amount (S\$)	149,583.30	81,748.00	67,835.30	45.35

INSPECTION

Date of Assignment: 17/09/2018
Date Inspected: 14/09/2018 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 40.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*RADIATOR GRILLE	Cracked	1,524.00 FS	*1,219.20 FS
3	1		*AIR GUIDE GRILLE - LH/RH	O/S Cracked/ N/S Not Necessary	638.00 FS	*255.20 FS
4	1		*FOAM FILLER PIECE	Deformed	107.00 FS	*85.20 FS
5	1		*BUMPER CARRIER	Bent	702.00 FS	*561.60 FS
6	4		*HEXAGON HEAD BOLT	Necessary	47.00 FS	*40.32 FS
7	2		*BRACKET - LH/RH	Deformed	390.00 FS	*312.00 FS
8	4		*HEXAGON HEAD BOLT	Necessary	47.00 FS	*33.92 FS
9	2		*SUPPORT - LH/RH	Necessary	48.00 FS	*40.64 FS
10	1		*BRACKET LOCK CARRIER	Cracked	118.00 FS	*94.00 FS
11	1		*BUMPER COVER	Cracked	109.00 FS	*87.20 FS
12	1		*RELEASE LEVER	Cracked	12.00 FS	*9.60 FS
13	1		*BOWDEN CABLE	Distorted	50.00 FS	*41.68 FS
14	1		*CAUTION STICKER	Necessary	12.00 FS	*9.76 FS
15	1		*BRACKET	Necessary	16.00 FS	*13.04 FS
16	1		*EXTERNAL TEMPERATURE SENSOR	Necessary	52.00 FS	*42.96 FS
17	2		*SECURING STRIP	Necessary	60.00 FS	*50.88 FS
18	1		*GRILLE - CENTER	Deformed	171.00 FS	*136.80 FS
19	2		*AIR GUIDE - LH/RH	Not Necessary	146.00 FS	*- FS
20	1		*CLOSING ELEMENT - LOWER CENTRE	Deformed	180.00 FS	*143.60 FS
21	2		*FRONT FENDER - LH/RH	Bent	1,330.00 FS	*1,064.00 FS
22	2		*ATTACHMENT PARTS FOR FENDER	Not Necessary	90.00 FS	*- FS
23	2		*CLOSING ELEMENT - LH	Necessary	88.00 FS	*72.00 FS
24	2		*BRACKET FOR FENDER - LH/RH	Necessary	62.00 FS	*50.40 FS
25	2		*BRACKET FOR DEFORMATION	Necessary	86.00 FS	*71.20 FS
26	2		*BRACE - LH/RH	Not Necessary	206.00 FS	*- FS
27	2		*COVER - LH/RH	Necessary	40.00 FS	*32.32 FS
28	2		*COVER - LH/RH	Necessary	54.00 FS	*44.48 FS
29	1		*WHEEL HOUSING LINER - LH	Deformed	215.00 FS	*178.40 FS
30	1		*WHEEL HOUSING LINER - RH	Deformed	209.00 FS	*167.20 FS
31	2		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	155.00 FS	*- FS
32	2		*WHEEL SPOILER - LH/RH	Deformed	126.00 FS	*104.64 FS
33	2		*STONE CHIP GUARD	Not Necessary	88.00 FS	*- FS
34	2		*LED HEADLIGHT - LH/RH	Cracked	13,946.00 FS	*11,156.80 FS
35	2		*POWER MODULE FOR MAIN LIGHT ELECTRONICS	Distorted	1,389.00 FS	*1,111.20 FS
36	2		*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Distorted	1,314.00 FS	*1,051.20 FS
37	2		*HOSE	Distorted	60.00 FS	*50.72 FS
38	2		*COMPENSATING PIECE	Necessary	75.00 FS	*61.12 FS
39	4		*COMPENSATING PIECE	Necessary	140.00 FS	*115.20 FS
40	2		*COMPENSATING PIECE	Not Necessary	70.00 FS	*- FS
41	2		*LIFT CYLINDER - LH/RH	Distorted	368.00 FS	*294.40 FS
42	1		*CORRUGATED PIPE	Not Necessary	79.00 FS	*- FS
43	1		*BONNET	Bent	2,163.00 FS	*1,730.40 FS
44	1		*ATTACHMENT PARTS FOR BONNET	Necessary	105.00 FS	*88.80 FS
45	2		*LID HINGE - LH/RH	Bent	532.00 FS	*443.20 FS
46	1		*IMPACT PROTECTION - LH/RH/CENTRE (3 pcs)	Necessary	72.00 FS	*59.44 FS
47	2		*FRONT BONNET STRUT	Not Necessary	209.00 FS	*- FS
48	2		*STRIKER - LH/RH	Bent	88.00 FS	*72.48 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	2		*LID LOCK	Bent	376.00 FS	*300.80 FS
50	1		*BOWDEN CABLE - CENTER	Distorted	50.00 FS	*41.68 FS
51	1		*FRONT LOCK CARRIER FOR COOLANT RADIATOR	Cracked	891.00 FS	*712.80 FS
52	2		*AIR GUIDE - LH/RH	Deformed	46.00 FS	*39.68 FS
53	1		*AIR GUIDE - UPPER	Cracked	14.00 FS	*11.28 FS
54	1		*A/C CONDENSER WITH FLUID RESERVIOR	Bent	540.00 FS	*432.00 FS
55	2		*SEAL RING	Necessary	8.00 FS	*6.40 FS
56	2		*SEAL RING	Necessary	7.00 FS	*5.76 FS
57	1		*A/C PRESSURE SENSOR SWITCH	Bent	170.00 FS	*135.60 FS
58	1		*A/C PRESSURE SENSOR SWITCH SAFETY SWITCH	Distorted	46.00 FS	*37.76 FS
59	1		*O RING	Necessary	3.00 FS	*2.00 FS
60	1		*COOLER FOR COOLANT	Bent	585.00 FS	*468.00 FS
61	2		*RUBBER BUSH	Necessary	22.00 FS	*18.56 FS
62	1		*ADDITIONAL COOLER FOR COOLANT	Bent	455.00 FS	*364.00 FS
63	4		*COOLANT	Necessary	82.00 FS	*67.20 FS
64	1		*FAN RING	Cracked	230.00 FS	*184.00 FS
65	1		*RADIATOR FAN WITH CONTROL UNIT	Cracked	2,055.00 FS	*1,644.00 FS
66	1		*INTAKE AIR DUCT - RH	Deformed	18.00 FS	*15.20 FS
67	1		*AIR GUIDE	Deformed	31.00 FS	*26.08 FS
68	1		*SEAL	Necessary	13.00 FS	*10.32 FS
69	1		*AIR FILTER	Cut	338.00 FS	*270.00 FS
70	1		*INTAKE HOSE	Deformed	80.00 FS	*67.84 FS
71	1		*TOOTHED BELT GUARD - UPPER	Cracked	64.00 FS	*52.16 FS
72	1		*COVER	Not Necessary	102.00 FS	*- FS
73	1		*TOOTHED BELT GUARD - LOWER	Distorted	64.00 FS	*28.32 FS
74	1		*RETAINER FOR CONTROL UNIT	Deformed	50.00 FS	*42.00 FS
75	1		*ALTERNATOR	Not Necessary	2,561.00 FS	*- FS
76	1		*A/C COMPRESSOR	Not Necessary	2,327.00 FS	*- FS
77	3		*HEXAGON BOLT (M8X95)	Not Necessary	23.00 FS	*- FS
78	1		*POLY V-BELT	Not Necessary	42.00 FS	*- FS
79	1		*BELT TENSIONER DAMPER	Not Necessary	165.00 FS	*- FS
80	1		*BRACKET	Not Necessary	45.00 FS	*- FS
81	1		*WINDOW SLOT SEAL WITH TRIM STRIP - LH	Cut	265.00 FS	*212.00 FS
82	1		*WINDOW GUIDE - LH	Not Necessary	392.00 FS	*- FS
83	1		*TRIM STRIP FOR WINDOW GUIDE - LH	Not Necessary	222.00 FS	*- FS
84	1		*COVER FOR PHEUM CHAMBER	Not Necessary	85.00 FS	*- FS
85	1		*SOUND ABS. FOR BONNET	Deformed	296.00 FS	*236.80 FS
86	1		*CAR PLATE - FRONT	Bent	25.00 FS	*25.00 FS
87	1		*SUNDRIES	Necessary	1,000.00 FS	*496.32 FS
88	1		*AIRBAG UNIT FOR STEERING WHEEL	Activated	3,111.00 FS	*2,488.80 FS
89	1		*FRONT AIRBAG UNIT - LH	Activated	3,981.00 FS	*3,184.80 FS
90	1		*HEAD AIRBAG UNIT - LH	Activated	1,692.00 FS	*1,353.60 FS
91	1		*HEAD AIRBAG UNIT - RH	Activated	1,692.00 FS	*1,353.60 FS
92	1		*CONTROL UNIT FOR AIRBAG	Activated	1,870.00 FS	*1,496.00 FS
93	1		*CRASH SENSOR FOR AIRBAG - FRONT	Activated	915.60 FS	*915.60 FS
94	1		*CENTRAL PROTECTION	Activated	470.00 FS	*388.00 FS
95	1		*FRONT SEAT BELT WITH TENSIONER - LH	Activated	956.00 FS	*764.80 FS
96	1		*FRONT SEAT BELT WITH TENSIONER - RH	Activated	956.00 FS	*764.80 FS
97	2		*SEAT BELT HEIGHT ADJUSTER	Activated	306.00 FS	*257.60 FS
98	1		*DASHBOARD WITH AIR DUCT	Deformed	4,604.00 FS	*3,683.20 FS
99	1		*MOULDED HEADLINING (CLOTH)	Deformed	1,682.00 FS	*1,345.60 FS
100	2		*A-PILLAR TRIM	Deformed	360.00 FS	*287.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*BASE ENGINE	Jammed	19,593.60 FS	*19,593.60 FS
102	1		*GEARBOX	Not Necessary	27,021.00 FS	*- FS
103	1		*ENGINE OIL	Necessary	215.60 FS	*215.60 FS
104	1		*ENGINE ATTACHMENT SEALS, BOLTS AND NUTS	Necessary	408.04 FS	*408.04 FS
105	2		*ENGINE MOUNTING - LH/RH	Bent	435.60 FS	*435.60 FS
106	2		*ENGINE MOUNTING SUPPORT - LH/RH	Bent	179.20 FS	*179.20 FS
107	1		*ENGINE MOUNTING COVER PLATE - RH	Bent	26.24 FS	*26.24 FS
108	1		*ATF FLUID	Necessary	97.60 FS	*97.60 FS
109	1		*ENGINE UNDERCOVER	Cracked	416.00 FS	*416.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 114,413.48 68,285.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	New	800.00	800.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	1,200.00
4	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	New	300.00	300.00
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND CENTRAL PROTECTION.	New	3,600.00	3,600.00
6	TO SUSPEND ENGINE. TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	New	2,800.00	2,800.00
7	TO SETUP VEHICLE ON CAR O-LINER REPAIR.	New	1,800.00	1,800.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BOTH HEADLIGHTS, BONNET, LHS FRONT DOOR. REPAIR AND STRAIGHTEN FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	8,600.00	5,000.00
9	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BONNET HINGES, LHS FRONT DOOR AND ENGINE COMPARTMENT	New	5,300.00	3,300.00
10	TO CARRY OUT WHEEL ALIGNMENT.	New	240.00	240.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	New	384.00	384.00
12	TO RENEW ENGINE ASSY AND DAMAGED ATTACHMENT.	New	3,200.00	3,200.00
13	TO CARRY OUT ENGINE NUMBER STAMPING. LTA INSPECTION AND PROCEDURES.	New	400.00	400.00
Gross Labour Cost (S\$)			28,984.00	23,384.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >