

ASS. REC. BY:

REF:

CG / 1E71218016880 / Uvbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGL

Date/Time: 18092018 1055am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 2259R

Insured:

PC 4763A

at Workshop m/s

Fastedh Auto

Tel:

6746 5405.

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

PC4763A / SL/pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15092018

(Client's Record)

CA / REV / REP. / REV 24 HRS / Wpl

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Nancy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 2259R - X

PC 4763A - X

18/9/18

Email Pei Li informed pending est from repairer

4/10/18

Email preli revised to Pei Li

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ER1/

J
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SL52259Rat Workshop m/s Lf.

of _____

Insured: PC 4763A

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL52259R Yr Regn: 9.17Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or (A)Make: Audi A3 C.C. 999Colour: Blue A/C: ☐ Insured / ☐ Std / ☐ M / ☐ NASp. Reading: 18957 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WAUZZZ8V7J1008630Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil ☒ (S/Rim) / ☐ STD A/Rim or

Tyre Size: F: _____

R: 205/55R16BS / DUN / EXNOVA / ☒ GYDFS / LIZA / MIC / OHTSU / PIR / SUMIT

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/9/18 D.O.I. 18/9/18

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop orRear n/c

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

exhaust repair28/9/18 4/5 #6600 contact with other. (Red 8849-40, 5710)

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

4/10 - typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

Report Format: TPLump Sum / I.B.I: (\$ 6600/2)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: PC4763A/SL/pl
Our Ref: CS/EGH18016880/Uvb

Date: 4/10/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLS 2259R


We thank you for your instruction on 18/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/9/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,449.40
Revised Estimate Amount	: S\$6,600.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 4 October 2018 3:23 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018
Attachments: SLS 2259R PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLS 2259R
Date of survey: 17/9/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 18 September 2018 1:47 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLS 2259R on 17/9/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 18 September 2018 10:59 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Tuesday, 18 September, 2018 10:55 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>

Subject: OI : PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 18 September 2018 1:47 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLS 2259R on 17/9/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 18 September 2018 10:59 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 18 September, 2018 10:55 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 18 September, 2018 10:55 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : PC4763A / TP : SLS2259R/LKK / DOA : 15/09/2018
Attachments: SLS2259R - PRS FORM.pdf; SLS2259R - sas.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 18.09.2018
Our Reference: PC 4763A/SL/pl
Your Reference: SLS 2259R

To: FASTECH AUTO PTE LTD

Sent via Fax
or
Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLS 2259R
Insured's Vehicle: PC 4763A
Date Of Accident: 15.09.2018


We acknowledge receipt of your request for PRS on: 17.09.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO CONSULTANTS PTE LTD

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8339C

Vehicle Details

Vehicle No.:	SLS2259R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CHZ522197
Chassis No.:	WAUZZZ8V7J1009630
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,475.00
Original Registration Date:	14 Sep 2017
First Registration Date:	14 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$16,265.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2027
PARF Rebate Amount:	\$12,198.00

Intended COE Rebate Details

COE Expiry Date:	13 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$32,366.00
Total Rebate Amount:	\$44,564.00

The information contained herein is correct as at 17 Sep 2018

OK

FASTECH AUTO PTE LTD
1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO: SLS 2259R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

not Admitted
 17/9/18
 4/5 @ 6600
 427.

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID 'A3' EMBLEM
1 PCS	BOOTLID 'TFSI' EMBLEM
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID WEATHERSTRIP
1 PCS	REAR BUMPER
1 PCS	REAR BUMPER LOWER GARNISH
1 PCS	REAR BUMPER REINFORCEMENT
2 PCS	REAR BUMPER SIDE HOLDERS @ \$115.00
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER REFLECTORS @ \$112.00
2 PCS	REAR BUMPER PDC SENSORS @ \$225.00
2 PCS	TAILLAMPS @ \$1015.00
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR EXHAUST
1 PCS	REAR EXHAUST MOUNTING

R	\$1,888.30	X
ru	\$108.00	—
ru	\$88.20	—
ru	\$85.50	—
11	\$322.30	X
11	\$299.50	—
Torn	\$1,688.20	—
De/maged	\$820.00	—
skp	\$625.10	—
ru	\$230.00	—
ru	\$50.00	—
ru	\$224.00	100
skd	\$450.00	—
com	\$2,030.00	—
3.5/100	\$1,018.00	—
11	\$392.30	—
R	\$1,650.00	X
11	\$60.00	X
	\$12,029.40	

LABOUR CHARGES:

TO CHECK WIRING
TO DISMENTLE & REPLACING PDC SENSOR
TO DISMENTLE & REFIX BOOTLID MECHANISM
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY
TO DISMENTLE & REFIX REAR EXHAUST
TO SPRAY RUSF PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00	20
\$120.00	50
11	\$120.00 X
\$150.00	80
\$150.00	60
\$100.00	50
\$1,200.00	800
\$1,500.00	900
	\$15,449.40

TOTAL

6657.31
 6324.44
 8288.44




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18016880/Uvbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-10-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4763A	Veh. Inspected	SLS 2259R	
Policy No.		Coverage (\$)	0.00	
Claim No.	PC4763A/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	18/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A3 (A)	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WAUZZZ8V7J1009630	Colour	BLUE	
Odometer	18951	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2018	Inspection Date	18/09/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2259R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	TO REPAIR SEE LABOUR	1,888.30	-
1	BOOTLID REAR LOGO	NECESSARY	108.00	108.00
1	BOOTLID "A3" EMBLEM	NECESSARY	88.20	88.20
1	BOOTLID "TFSI" EMBLEM	NECESSARY	85.50	85.50
1	BOOTLID INNER LOCK	NOT NECESSARY	322.30	-
1	BOOTLID WEATHERSTRIP	TWISTED	299.50	299.50
1	REAR BUMPER	TORN	1,688.20	1,688.20
1	REAR BUMPER LOWER GARNISH	DEFORMED / WARPED	820.00	285.00
1	REAR BUMPER REINFORCEMENT	BENT	625.10	501.00
2	REAR BUMPER SIDE HOLDERS @\$115.00	NECESSARY	230.00	120.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS @\$112.00	N/S CRACKED	224.00	82.00
2	REAR BUMPER PDC SENSORS @\$225.00	SHORTED	450.00	450.00
2	TAILLAMPS @\$1015.00	CRACKED	2,030.00	1,732.00
1	REAR END PANEL	BADLY DENTED	1,018.00	922.76
1	REAR END PANEL TOP GARNISH	TWISTED	392.30	245.15
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,650.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	60.00	-
	LESS 5% DISCOUNT		-	-332.87
			12,029.40	6,324.44
LABOUR				
	TO CHECK WIRING.		80.00	20.00
	TO DISMENTLE & REPLACING PDC SENSOR.		120.00	50.00
	TO DISMENTLE & REFIX BOOTLID MECHANISM.	NOT NECESSARY	120.00	-
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMENTLE & REFIX REAR EXHAUST.		150.00	60.00
	TO SPRAY RUST PROOFING.		100.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR EXHAUST.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,420.00	1,960.00
GRAND TOTAL			15,449.40	8,284.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CS/EG18016880/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.