



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 8384 R

Parts	(a) Cost / List Price Items	\$	1,927.12
	Plus/Less 25%	\$	481.78
	Total of Cost / List	\$	1,445.34
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	1,450.00
Total		\$	2,895.34

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/9/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le

Date: 19/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 8384 R**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU103555973**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender Bu	1	\$868.70		✓
2	LH front fender undershield Di	1	\$195.60		✓
3	LH front fender undershield clip m	10	\$25.00		✓
4	LHF fender wording "HYBRID" m	1	\$44.17		✓
5	Front bumper Bu	1	\$450.80		✓
6	Front bumper clip m	10	\$40.00		✓
7	Front bumper side retainer LH Di	1	\$107.20		✓
8	LH front hub cab L	1	\$195.65		X
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829

Company Reg No. 200005485N / GST No. 20-0005485-N

