

REPAIR ESTIMATE*

DATE 17/9/2018 10:14

MODEL : HYUNDAI i40

Like

FWD

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid X Repair			\$ 2,174.90
	Boot Lid 'H' Emblem /			\$ 28.70
	Boot Lid CRDI Plate X			\$ 27.90
	Rear Bumper X Repair			\$ 553.00
	Rear Bumper Clip 10 pcs X			\$ 22.00
	Tail Lamp (RH) /			\$ 697.80
	Rear Fender (RH) X Repair			\$ 2,171.40
	Rear Fender Inner Lining (RH) X			\$ 169.30
	Rear Windscreen Moulding X			\$ 28.30
	SUB TOTAL			\$ 5,873.30
	LESS 20%			\$ 1,174.66
	DISCOUNTED TOTAL			\$ 4,698.64
	Rear Windscreen Sealant X			\$ 46.00
	Nett			
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,090.00
	ESTIMATE TOTAL			\$ 6,834.64

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kaluh (LKK)

17/9/18 1220hrs

3 Days

U/S

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.