



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2018 HYUNDAI ELANTRA AD 1.6 GLS AT (SLW3312S)
Date of Loss	7 September 2018
Time of Loss	12.30
Loss Description	WA4114N (TP) HIT IN THE REAR OF SLW3312S (INSD)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="43316"/>
Nett Loss Amount	\$24,684.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="170"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLW3312S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

07/02/2018



Mileage

13783

Age of Vehicle

0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2018	2018
Make	HYUNDAI	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT	ELANTRA AD 1.6

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	PEH HOE KIAT (BAI HEJIE)	
Date of Birth	10 October 1977	dd/mm/yyyy
Age	41	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	KMHD841CMJU629548	<input type="text" value="KMHD841CMJU"/>
Engine No	G4FGJU135866	<input type="text" value="G4FGJU135866"/>
Engine Capacity		<input type="text" value="1591"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="68000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	7	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yy"/>
License Expiration Date		<input type="text" value="dd/mm/yy"/>
Address	BLK 17 BEACH ROAD, #13-4709, 190017, Singapore	<input type="text" value=""/>
Address type	Residential	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text" value=""/>
Marital status	Married	<input type="text" value=""/>
Identification #	S7728218A	<input type="text" value=""/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/09/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40ZR18

Rear Tyre Size

225/40ZR18

Front left side

WESTLAKE6mm

Rear left side

WESTLAKE6mm

Front right side

WESTLAKE6mm

Rear right side

WESTLAKE6mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BOOTLID			Buckled	1250.92		20		1000.74	Reviewing	
		2	1			BOOTLID LOCK			Bent	116.2		20		92.96	Reviewing	
		3	1			BOOTLID LOCK CATCH			Serviceable	0	0	0	0	0	Deny	
		4	2			BOOTLID HINGE			Repair	0	0	0	0	0	Deny	
		5	1			BOOTLID WEATHERSTRIP			Twisted	80.6		20		64.48	Reviewing	
		6	2			BOOTLID RUBBER STOPPER			Serviceable	0	0	0	0	0	Deny	
		7	1			BOOTLID INNER TRIM			Serviceable	0	0	0	0	0	Deny	
		8	1			N/S BOOTLID LAMP			Serviceable	0	0	0	0	0	Deny	
		9	1			O/S BOOTLID LAMP			Cracked	168.8		20		135.04	Reviewing	
		10	1			BOOTLID EMBLEM LOGO			Necessary	28.8		20		23.04	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	11	1			BOOTLID EMBLEM ELANTRA			Necessary	38.5		20		30.8	Reviewing	
	12	2			BOOTLID LICENCE PLATE LAMP			Serviceable	0	0	0	0	0	Deny	
	13	1			BOOTLID OPENING SWITCH WITH CAMERA			Serviceable	0	0	0	0	0	Deny	
	14	2			TAILLAMP			Cracked	382		20		611.2	Reviewing	
	15	2			TAILLAMP PANEL			Repair	0	0	0	0	0	Deny	
	16	1			REAR BUMPER			Deformed	489		20		391.2	Reviewing	
	17	1			N/S REAR BUMPER REFLECTOR			Cracked	38		20		30.4	Reviewing	
	18	1			O/S REAR BUMPER REFLECTOR			Serviceable	0	0	0	0	0	Deny	
	19	1			REAR BUMPER DIFFESER			Missing	243.87		20		195.1	Reviewing	
	20	2			REAR BUMPER RETAINER			Necessary	40		20		64	Reviewing	
	21	1			REAR BUMPER REINFORCEMENT			Bent	328		20		262.4	Reviewing	
	22	2			REAR BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny	
	23	2			REAR BUMPER SIDE DUST COVER			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		24	1			REAR END PANEL			Buckled	379		20		303.2	Reviewing	
<input type="checkbox"/>		25	1			REAR END PANEL GARNISH			Deformed	105		20		84	Reviewing	
<input type="checkbox"/>		26	1			REAR COMPARTMENT COVER			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		27	1			REAR COMPARTMENT PANEL			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		28	2			REAR FENDER INNER TRIM			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		29	1			REAR SMART SENSOR			Damaged	250		20		200	Reviewing	
<input type="checkbox"/>		30	1			REAR UNDER COVER LH			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		31	1			REAR EXHAUST PIPE			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		32	2			REAR EXHAUST PIPE MOUNTING			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		33	1			REAR EXHAUST PIPE HEAT SHIELD			Bent	115		20		92	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		1		REPAIR & REPLACE DAMAGED PARTS	800	0	0	Reviewing		
<input type="checkbox"/>		2		SPRAY PAINT AFFECTED AREA	900	0	0	Reviewing		
<input type="checkbox"/>		3		REMOVE & REFIX REAR TRIM BOARD & GARNISH	60	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		4		REMOVE & REFIX EXHAUST PIPE	0	0	0	Deny		
		5		CHECK REAR WIRING SYSTEM	30	0	0	Reviewing		
		6		REMOVE & RENEW REVERSE SENSOR	40	0	0	Reviewing		
		7		SPRAY ANTI RUST ON AFFECTED AREA	60	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
<input type="checkbox"/>		2	SET BOOTLID INNER TRIM CLIP	Reviewing	20	NECESSARY	
<input type="checkbox"/>		3	SET REAR BUMPER CLIP	Reviewing	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	4	SET REAR END PANEL GARNISH CLIP	Reviewing	24	NECESSARY	
 	5	2SETS REAR FENDER INNER TRIM CLIP	Reviewing	40	NECESSARY	
 	6	SET REAR UNDER COVER CLIP LH	Reviewing	22	NECESSARY	
 	7	REVERSE SENSOR	Reviewing	200	DAMAGED	
 	8	REAR LICENCE PLATE	Deny	0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$5,806.56

Claim Amount

\$5,806.56

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$3,580.56

\$3,580.56

Labour

\$1,890.00

\$1,890.00

Miscellaneous

\$336.00

\$336.00

[Submit for Review](#)