

22/03/2002

SS. REC. BY:

REF: CS/CT18016888 / T18bs2

Special Instruction:

Survivor

From (Person):

Taufik

Chong Boon Sen

ASSIGNMENT (Office)

CT1

Date/Time: 13/09/2018 1:30pm

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

OBA 1624P.

To Inspect Vehicle No:

SMC 2763Z

Tel:

at Workshop m/s

Tan Chong

of

911 Bukit Timah Rd

Policy No:

DMCVGN 3005261800

Claim No:

SM18D 04342C02

Excess:

Sum Insured:

D.O.A.

03/09/2018

Make of Veh:
(Client's Record)

19-09-2018 @ 11am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS wpi

Lawrence

Vehicle IN / OUT

Date/Time: 17/09/2018 10:37am

Person Contacted:

Date/Time

Action/Instruction (✓) Estimate

SMC 2763Z - X

OBA 1624P - X

Taylor

REF:

CT1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

WP

Veh No:

SMC 27632

Yr Regn:

2018 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Ashgari

C.C

1197

Colour:

Brown

Insured / Std / NI / NA

Sp. Reading

8769

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SNFEA J1192310490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19/9/18

Survey held at

TC Bht finch

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/04/19 Confirmed P/P \$ 7,808.40 @ 6 days with Tumble (\$ 3,366.20 Ret - 30%)

RECEIVED 30 APR 2019

30/4/2019

Date/Time, File Pass to?

30/04/19

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

(\$ + RS. \$)

Photos:

Others:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I (\$ 7,808.40 p/p)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18016888/T1sb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 17-09-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 1624P	Veh. Inspected	SMC 2763Z
Policy No.	DMCVSN3005261800	Coverage (\$)	0.00
Claim No.	SNM18D04342C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	15/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/09/2018	Inspection Date	19/09/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2018		15 Sep 2018 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAILS					
Insured:				[Created by insurer]	
Main Claimant:		LEONG HOON SENG			
Vehicle Reg. No.:		SMC2763Z	Date of Loss:	03/09/2018 00:00 - :59	
Claim Type:		TP / SNM18D04342C02	Policy/Cover Note No.:	DMCVSN3005261800	
Vehicle Reg. No. (Insured):		GBA1624P	Policy No. (Claimant):		
		Excess:	S\$0.00		
Repairer:		Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road, 589622 Bukit Timah - Tel:			
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]			
Adj Asp. Remarks:		EST \$11,174.60, ASSIGN XING QUO QIANG AS SJE.			
ASSOCIATED MAIL RECEIVED					
				View All Compose Case Mail	
There are no mail for this case.					
ALL ASSOCIATED TASKS					
		View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On	Done?
No results.					

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 30 April 2019 3:34 PM
To: 'Lawrence Teo'
Cc: SUR; 'Norsipah'; Taufikh (LKKAuto)
Subject: RE: SMC2763Z ; DOA:03.09.2018

Dear Lawrence,

Confirmed final fig \$7,808.40 @ 6 day of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lawrence Teo [mailto:lawrenceteo@tanchong.com]
Sent: Tuesday, 30 April 2019 10:01 AM
To: SUR <sur@lkkauto.com>; Norsipah <norsipah@tanchong.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SMC2763Z ; DOA:03.09.2018

Dear Taufik,

See attached.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Lawrence Teo
Sent: 23 April 2019 09:52
To: 'sur@lkkauto.com' <sur@lkkauto.com>; Norsipah (norsipah@tanchong.com) <norsipah@tanchong.com>
Subject: FW: SMC2763Z ; DOA:03.09.2018

Dear Sipah,

Fyna..

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: 22 April 2019 12:19
To: Lawrence Teo <lawrenceteo@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: SMC2763Z ; DOA:03.09.2018

Dear Lawrence,

Please confirm final fig \$ 7,621.84 (part by part) @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

S/C
DS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 10:20
Date Of Accident	03/09/2018 09:55
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD (OUTSIDE ST JOSEPH CHURCH)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC2763Z
Insured/Policyholder	
Name Of Registered Owner	LEONG HOON SENG
NRIC No	S1750878D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90702500
Alternative Phone No	OFFICE-90702500

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102386144 (C;ASSIC)
Cover Note Number	

Driver

Name of Driver	LEONG HOON SENG
NRIC No	S1750878D
Date Of Birth	25/01/1966
Occupation	INDOOR
Date Of Driving Pass	05/09/1995
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90702500
Fax Number	
Contact Number	OFFICE-90702500
Email Address	NOEMAIL

Address	6 PETIR ROAD #14-07 MAYSPRING
Postcode	S678267
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SENT TO INSURANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA1624P
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GINSIN
NRIC/Passport Number	
Contact Number	97969164
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

4/9/18
10:30am



Driver's Signature

(If driver is not the policyholder)

Date & Time:

4/9/18
10:30am

- 4 SEP 2018


IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle SMC 2763Z was knocked from back along upper Bukit Timah Rd, near St Joseph church waiting to go up the via duct. The van GBA 1624P crashed into my vehicle back. Damages Done to the rear Bumper, rear Panel, and rear door and rear left signal holder. It all happened about 9.55am 3/9/18. The weather was clear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 4/9/18
10.30am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 4/9/18
10.30am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S1750878D**

Name

LEONG HOON SENG

Birth Date 25 Jan 1966

Issue Date 30 Mar 2004



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1750878D**



Name

LEONG HOON SENG

Race

CHINESE

Date of Birth

25-01-1966

Country of Birth

SINGAPORE

Sex

M


S1750878D



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 05 Sep 1995



NP 428A



0875689

NRIC No. **S1750878D**



Blood Group
AB+

Date of issue
05-04-1993

BLK 6 PETIR ROAD #14-07
SINGAPORE 678267
NRIC No: S1750878D

Date: 25-08-1998

No: 2601943

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: S102386144 Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SMC2763Z**
Chassis Number : SJNFEAJ11U2310490
2. Name of Policyholder : LEONG HOON SENG
3. Effective Date of Insurance : 17 Jul 2018
4. Expiry Date of Insurance : 27 Jun 2019
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
 - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: LEONG HOON SENG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALL INS AGENCY PTE. LTD. (00000571908)

Date of Issue : 17 Jul 2018 12:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0376/2018
DATE : 06-SEP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR LEONG HOON SENG
ADDRESS : BLK 6 PETIR ROAD
#14-07
S(678267)
TELEPHONE NO : 68935866/90702500

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBA1624P
VEHICLE NO : SMC2763Z
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2640945A
CHASSIS NO : SJNFEAJ11U2310490
MILEAGE : 1 KM
DATE IN : 06/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 03/09/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1512
06/09/18
LKK
APR 7
11/11/18
Tan Kah 9 749 5749
WP
17/9/18 @ 1130
06 days
Resurvey before paint
See @ lkkauto.com

25/9/18

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC2763Z

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X-03	360.00	240. ✓
3 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓ nee
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X-03	300.00	100. ✓
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	nee ✓
6 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	✓
7 ZZ/001	CHECK LIGHTING	48.00	✓
8 ZZ/002	R/I DVR TO ASSIST REPAIR	120.00	✓
9 ZZ/003	TRANSFER TAILGATE MECHANICAL PARTS	80.00	✓
10 ZZ/004	SUPPLY AND RENEW PRIVATE HIRER DECAL	20.00	nee ✓
11 ZZ/005	REPAIR END PANEL, LH REAR FENDER AND RENEW TAILGATE, REAR BUMPER	1400.00	280. 840. ✓
12 ZZ/006	S/PAINT REAR BUMPER(2 TONE), END PANEL, TAILGATE, LH REAR FENDER	1500.00	250. 1100. ✓
TOTAL LABOUR CHARGES		4448.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC2763Z

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 CLIP ANTENNA \$3.80 EA X 02	01553-89900		7.60	? X un
2 ANTENNA-SMART KEYLESS	285E5-JK60A	53.50	? X un	
3 EMBLEM-REAR	90890-4EA0A	59.70	re	
4 EMBLEM	90892-4EA0A	87.00	re	
5 STRIKER-TAIL GA	90570-4EA0A	31.70	X un	
6 A LOCK LIFT	90502-4EA1B	116.70	? X un	
7 WEATHER STRIP	90830-4EA0B	158.70	X un	
8 DOOR BACK	X0100-HV0MB	2936.80	bt	
9 A PIN BACK DOOR NO PLATE	90810-4ES0H	336.00	? X un v de	
10 RUBBER-DUM	G2716-89900	60.20	re	
11 GLASS-TAIL GATE	90300-HV00A	930.00	re	
12 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 re
13 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00	re	
14 CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00	re	
15 RETAINER-BUMPER RH REAR	79184-4EA0A	23.80	X un	
16 RETAINER-BUMPER LH REAR	79185-4EA0A	23.80	re	
17 BRACKET-BUMPER RH	85220-4EA0A	35.90	X un	
18 BRACKET-BUMPER LH	85221-4EA0A	35.90	re	
19 STAY ASSY-REAR RH	H5210-4EAMA	126.00	? X	} X un
20 STAY ASSY-REAR LH	H5211-4EAMA	126.00	? X	
21 REINF-BUMPER RR	H5030-4EAMA	619.20	? X	
22 ENERGY ABSORBER	85090-HV00A	126.40	? X	
23 FINISHER-REAR BUMPER TOW	85071-HV00A	16.80	X un	
24 FASCIA-RR BUMP	85022-HV00H	717.00	de	
25 CLIP END PANEL \$1.20 EA X 02	01553-05323	2.40	re	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC2763Z

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 CLIP END PANEL \$1.20 EA X 04	01554-00181	4.80	new	
27 PLATE-LUGGAGE	84992-4EA0A	63.50	7x	
28 FENDER LH REAR ARC	93829-4EA0A	483.00	7x	un
29 ORNAMENT ASSY LH REFLECTOR	26565-JJ90A	55.00	7x	
30 C/LAMP GROMMET \$25.70 EA X 04	76848-83P00	102.80	new	un
31 GROMMET C/LAMP \$1.90 EA X 02	76848-35F00	3.80	7x	un
32 CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60	7x	un
33 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 ant
34 LAMP COMB RR,LH	26555-HV00A	323.70	7x	un
35 LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90	new	
36 SUNDRIES	NPN			un 100.00 ?
37 REAR W/SCREEN SEALANT	SEALANT - 4			80.00 new
SUB TOTAL		7908.60	7.60	394.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1581.72	2.28	0.00
GRAND TOTAL		6326.88	5.32	394.40
OVERALL TOTAL		6726.60		

LEGEND: REMARKS(OK) - APPROVED, REMARKS(X) - NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMC2763Z

TOTAL LABOUR CHARGES	4448.00
TOTAL SPARE PARTS CHARGES	6726.60
GRAND TOTAL	11174.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0376/2018
DATE : 06-SEP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR LEONG HOON SENG
ADDRESS : BLK 6 PETIR ROAD
#14-07
S(678267)
TELEPHONE NO : 68935866/90702500

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBA1624P
VEHICLE NO : SMC2763E
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2640945A
CHASSIS NO : SJMF6AJ11U2310490
MILEAGE : 1 KM
DATE IN : 06/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 03/09/2018

Tanpak

DIS

#100x07
= \$7000.452
= \$749/-

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC27632

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240.00
3 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100.00
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
6 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
7 ZZ/001	CHECK LIGHTING	48.00	48.00
8 ZZ/002	R/I DVR TO ASSIST REPAIR	120.00	120.00
9 ZZ/003	TRANSFER TAILGATE MECHANICAL PARTS	80.00	80.00
10 ZZ/004	SUPPLY AND RENEW PRIVATE HIRER DECAL	20.00	20.00
11 ZZ/005	REPAIR END PANEL, LH REAR FENDER AND RENEW TAILGATE, REAR BUMPER	1400.00	840.00
12 ZZ/006	S/PAINT REAR BUMPER(2 TONE), END PANEL, TAILGATE, LH REAR FENDER	1500.00	1100.00
TOTAL LABOUR CHARGES		4448.00	3168.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC27632

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	CLIP ANTENNA \$3.80 EA X 02	01553-89900		7.60		X
2	CLIP END PANEL \$1.20 EA X 04	01554-00181	4.80			OK
3	PLATE-LUGGAGE	84992-4EA0A	63.50			X
4	FENDER LH REAR ARC	93829-4EA0A	483.00			X
5	ORNAMENT ASSY LH REFLECTOR	26565-JJ90A	55.00			X
6	C/LAMP GROMMET \$25.70 EA X 04	76848-83P00	102.80			X
7	GROMMET C/LAMP \$1.90 EA X 02	76848-35P00	3.80			X
8	CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60			X
9	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	OK
10	LAMP COMB RR,LH	26555-HV00A	323.70			X
11	LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90			OK
12	SUNDRIES	NPN			100.00	X
13	ANTENNA-SMART KEYLESS	285E5-JK60A	53.50			X
14	EMBLEM-REAR	90890-4EA0A	59.70			OK
15	EMBLEM	90892-4EA0A	87.00			OK
16	STRIKER-TAIL GA	90570-4EA0A	31.70			X
17	A LOCK LIFT	90502-4EA1B	116.70			X
18	WEATHER STRIP	90830-4EA0B	158.70			X
19	DOOR BACK	K0100-HV0MB	2936.80			OK
20	A FIN BACK DOOR NO PLATE	90810-4ES0H	336.00			OK
21	RUBBER-DUM	G2716-89900	60.20			OK
22	GLASS-TAIL GATE	90300-HV00A	930.00			OK
23	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	OK
24	GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00			OK
25	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00			OK

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/S/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC27632

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 RETAINER-BUMPER RH REAR	79184-4EA0A	23.80			X
27 RETAINER-BUMPER LH REAR	79185-4EA0A	23.80			OK
28 BRACKET-BUMPER RH	85220-4EA0A	35.90			X
29 BRACKET-BUMPER LH	85221-4EA0A	35.90			OK
30 STAY ASSY-REAR RH	H5210-4EAMA	126.00			X
31 STAY ASSY-REAR LH	H5211-4EAMA	126.00			X
32 REINF-BUMPER RR	H5030-4EAMA	619.20			X
33 ENERGY ABSORBER	85090-HV00A	126.40			X
34 FINISHER-REAR BUMPER TOW	85071-HV00A	16.80			X
35 FASCIA-RR BUMP	85022-HV00H	717.00			OK
36 CLIP END PANEL \$1.20 EA X 02	01553-05323	2.40			OK
37 REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
SUB TOTAL		5432.50	0.00	294.40	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1086.50	0.00	0.00	
GRAND TOTAL		4346.00	0.00	294.40	
OVERALL TOTAL		4640.40			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMC27632

NETT ITEM	5432.50
LESS 20.00%)	-1086.50
NETT AMOUNT	4346.00
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	294.40
LESS .00%)	0.00
SPECIAL NETT AMOUNT	294.40
TOTAL LABOUR CHARGES	3168.00
TOTAL SPARE PARTS CHARGES	4640.40
TOTAL CHARGES	7808.40
ADD 7 % GST	546.59
GRAND TOTAL	8354.99

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Sep 2018		15 Sep 2018 13:30 Edit Adj Rpt	S\$7,808.40 Edit Estimates	S\$7,808.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LEONG HOON SENG								
Vehicle Reg. No.:	SMC2763Z	Date of Loss:	03/09/2018 00:00 - :59 [2 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04342C02	Policy/Cover Note No.:	DMCVSN3005261800						
Vehicle Reg. No. (Insured):	GBA1624P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road, 589622 Bukit Timah - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/09/2018]								
Adj Asg. Remarks:	EST \$11,174.60, ASSIGN XING QUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMC2763Z (SNM18D04342C02)
[GBA1624P]

TP

LEONG HOON SENG
Sep 3 2018 12:00AM

[-]

Tan Chong Motor Sales Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 16:17	Odometer Reading	 Load JPG	☒
2	24/09/18 16:17	Chassis Number	 Load JPG	☒
3	24/09/18 16:17	General View	 Load JPG	☒
4	24/09/18 16:17	General View	 Load JPG	☒
5	24/09/18 16:17	General View	 Load JPG	☒
6	24/09/18 16:17	General View	 Load JPG	☒
7	24/09/18 16:17	General View	 Load JPG	☒
8	24/09/18 16:17	General View	 Load JPG	☒
9	24/09/18 16:17	General View	 Load JPG	☒
10	24/09/18 16:17	General View	 Load JPG	☒
11	24/09/18 16:17	General View	 Load JPG	☒
12	24/09/18 16:17	General View	 Load JPG	☒
13	24/09/18 16:17	General View	 Load JPG	☒
14	24/09/18 16:17	General View	 Load JPG	☒
15	24/09/18 16:17	General View	 Load JPG	☒
16	24/09/18 16:17	General View	 Load JPG	☒
17	24/09/18 16:17	General View	 Load JPG	☒
18	24/09/18 16:17	General View	 Load JPG	☒
19	24/09/18 16:17	General View	 Load JPG	☒
20	24/09/18 16:17	General View	 Load JPG	☒
21	24/09/18 16:17	General View	 Load JPG	☒
22	24/09/18 16:17	General View	 Load JPG	☒
23	24/09/18 16:17	General View	 Load JPG	☒
24	24/09/18 16:17	General View	 Load JPG	☒
25	24/09/18 16:17	General View	 Load JPG	☒
26	24/09/18 16:17	General View	 Load JPG	☒
27	24/09/18 16:17	General View	 Load JPG	☒
28	24/09/18 16:17	General View	 Load JPG	☒
29	24/09/18 16:17	General View	 Load JPG	☒
30	24/09/18 16:17	General View	 Load JPG	☒
31	24/09/18 16:17	General View	 Load JPG	☒
32	24/09/18 16:17	General View	 Load JPG	☒
33	24/09/18 16:17	General View	 Load JPG	☒
34	24/09/18 16:17	General View	 Load JPG	☒
35	24/09/18 16:17	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/09/18 16:17	General View	 Load JPG	☒
37	24/09/18 16:17	General View	 Load JPG	☒
38	24/09/18 16:17	General View	 Load JPG	☒
39	24/09/18 16:17	General View	 Load JPG	☒
40	24/09/18 16:17	General View	 Load JPG	☒
41	24/09/18 16:17	General View	 Load JPG	☒
42	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
43	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
44	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
45	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
46	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
47	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
48	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
49	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
50	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
51	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
52	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
53	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
54	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
55	30/04/19 11:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/09/18 13:29	EMAIL FM TAN CHONG	 Load PDF	
2	15/09/18 13:29	REPAIR EST	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016888/T1SBS2

Date: 02/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3005261800

Claimant Vehicle No: SMC2763Z Insured Vehicle No: GBA1624P

Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: SNM18D04342C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC2763Z

Make & Model: NISSAN QASHQAI, 1.2 DIG-T (A) Engine No: HRA2640945A

Reg. Date: 28/06/2018 (Man. Year: 2018) Chassis No: SJNFEAJ11U2310490

Colour: Brown Odometer: 8769 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,006.60	4,920.40	2,086.20	29.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,168.00	2,888.00	1,280.00	30.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,174.60	7,808.40	3,366.20	30.12
+ GST 7.00/7.00% (S\$)	782.22	546.59	235.63	30.12
Nett Amount (S\$)	11,956.82	8,354.99	3,601.83	30.12

INSPECTION

Date of Assignment: 15/09/2018

Date Inspected: 19/09/2018 Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah)
911, Bukit Timah Road
Singapore 589622

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 May 2019)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC2763Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*CLIP ANTENNA	Not Necessary	7.60 FL	*- FL
2	1		*ANTENNA - SMART KEYLESS	Not Necessary	53.50 FN	*- FN
3	1		*EMBLEM - REAR	Necessary	59.70 FN	*59.70 FN
4	1		*EMBLEM	Necessary	87.00 FN	*87.00 FN
5	1		*STRIKER - TAIL GA	Not Necessary	31.70 FN	*- FN
6	1		*A LOCK LIFT	Not Necessary	116.70 FN	*- FN
7	1		*WEATHER STRIP	Not Necessary	158.70 FN	*- FN
8	1		*DOOR BACK	Bent	2,936.80 FN	*2,936.80 FN
9	1		*A FIN BACK DOOR NO PLATE	Deformed	336.00 FN	*336.00 FN
10	1		*RUBBER - DUM	Necessary	60.20 FN	*60.20 FN
11	1		*GLASS TAIL - GATE	Necessary	930.00 FN	*930.00 FN
12	4		*GROMMET BUMPER	Necessary	10.00 FN	*10.00 FN
13	2		*CANOE RIVET BUMPER	Necessary	13.00 FN	*13.00 FN
14	1		*RETAINER - BUMPER RH REAR	Not Necessary	23.80 FN	*- FN
15	1		*RETAINER - BUMPER LH REAR	Necessary	23.80 FN	*23.80 FN
16	1		*BRACKET - BUMPER RH	Not Necessary	35.90 FN	*- FN
17	1		*BRACKET - BUMPER LH	Necessary	35.90 FN	*35.90 FN
18	1		*STAY ASSY - REAR RH	Not Necessary	126.00 FN	*- FN
19	1		*STAY ASSY - REAR LH	Not Necessary	126.00 FN	*- FN
20	1		*REINF - BUMPER FR	Not Necessary	619.20 FN	*- FN
21	1		*ENERGY ABORBER	Not Necessary	126.40 FN	*- FN
22	1		*FINISHER - REAR BUMPER TOW	Not Necessary	16.80 FN	*- FN
23	1		*FASCIA - RR BUMP	Deformed	717.00 FN	*717.00 FN
24	2		*CLIP END PANEL	Necessary	2.40 FN	*2.40 FN
25	4		*CLIP END PANEL	Necessary	4.80 FN	*4.80 FN
26	1		*PLATE - LUGGAGE	Not Necessary	63.50 FN	*- FN
27	1		*FENDER LH REAR ARC	Not Necessary	483.00 FN	*- FN
28	1		*ORNAMENT ASSY LH REFLECTOR	Not Necessary	55.00 FN	*- FN
29	4		*C/LAMP GROMMET	Not Necessary	102.80 FN	*- FN
30	2		*GROMMET C/LAMP	Not Necessary	3.80 FN	*- FN
31	2		*CLIP C/LAMP	Not Necessary	9.60 FN	*- FN
32	1		*LAMP COMB RR, LH	Not Necessary	323.70 FN	*- FN
33	1		*LAMP COMB RR, LH TAILGATE	Cracked	215.90 FN	*215.90 FN
34	2		*GROMMET BUMPER	Necessary	4.40 FS	*4.40 FS
35	1		*REVERSE SENSOR (J11 & T32)	Cut	210.00 FS	*210.00 FS
36	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
37	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
38	1		*REVERSE SENSOR	Necessary	110.00 FS	*110.00 FS
39	1		*ULTRAMAX SOLAR FILM - REAR W/SCREEN	Necessary	150.00 FS	*150.00 FS
40	1		*PRIVATE HIRER DECAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$) 8,590.60 6,006.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items 30.00/30.00% (S\$)		2.28	0.00
			- Nett Item Discount on N Items 20.00/20.00% (S\$)		1,581.72	1,086.50
				Total Parts (S\$)	7,006.60	4,920.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE / INSTALL & TEST REAR REVERSE SENSOR CAMERA.	New	120.00	120.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	New	360.00	240.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	New	300.00	100.00
4	RENEW REAR WINDSCREEN GLASS ASSY.	New	240.00	240.00
5	CHECK LIGHTING.	New	48.00	48.00
6	R/I DVR TO ASSIST REPAIR.	New	120.00	120.00
7	TRANSFER TAILGATE MECHANICAL PARTS.	New	80.00	80.00
8	REPAIR END PANEL, LH REAR FENDER AND RENEW TAILGATE, REAR BUMPER.	New	1,400.00	840.00
9	S/PAINT REAR BUMPER (2 TONE), END PANEL, TAILGATE, LH REAR FENDER.	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			4,168.00	2,888.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >