



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLP2699U

Date of Accident : 14 September 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Goh Kai Meng (Wu Jiemin)

Date : 14 September 2018

Estimate To Repair SDN6616M - Honda Civic 1.8L A
Chassis No : JHMFD16306S207872

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s bootlid reflector <i>CNE</i>	\$ 152.80
02	1 pc	bootlid centre emblem badge <i>neu 30.60</i>	\$ 49.60
03	1 pc	n/s rear lamp <i>CNE</i>	\$ 268.70
04	3 pc	rear lamp clip holder @ \$12.50 <i>11</i>	\$ 37.50
05	1 pc	n/s rear lamp panel <i>D</i>	\$ 100.60
06	1 pc	rear bumper <i>D.S</i>	\$ 658.70
07	2 pc	rear bumper side retainer @ \$46.90 <i>30.00</i>	\$ 93.80
08	10 pc	rear bumper clips @ \$5.90 <i>neu 30.00</i>	\$ 59.00
09	2 pc	rear bumper side holder @ \$28.60 <i>11</i>	\$ 57.20
10	1 pc	rear end panel <i>3.0.0.0</i>	\$ 355.40
11	1 pc	rear end panel inner trim <i>11</i>	\$ 252.80
12	1 pc	rear end panel inner trim clips <i>11</i>	\$ 3.80
13	1 pc	n/s rear fender air vent <i>7m</i>	\$ 38.40
Less 20 %			\$ 2,128.30
			\$ 425.66
			\$ 1,702.64
<u>SPECIAL NETT ITEMS</u>			
14	1 pc	rear bumper lower spoiler <i>D.S</i>	\$ 900.00
15	1 pc	rear bumper parking sensor <i>11</i>	\$ 350.00
			\$ 1,250.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check electrical lighting concerned.	\$ 60.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
06		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,270.00
Total			\$ 5,222.64

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display the damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

not allowed

2/5 & 3100

4 days

17/9/18

highlighted the 4

Marcus

17/09/18 0900h

1729
1383.20
800
X
50
80
50
20
700
800
2480
3893.2

4 sum

2/5 & 3100 x 4 days

17/09/18

June