

13/02/11

INS. CASE OWNER:

FC

CCP ASM
AXA1801 6897, 6

LKK:

IDAC:

Surveyor:

0602

DOI:

ASSIGNMENT

17/1/18

Date / Time:

Registered in Merimen:

17/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKZ 4403C

Name of Insured:

MUHAMMAD LATIPRAHA BIN MUSEA

Insured Tel No.:

HP: 97705454

Excess Sec II :SS

D.O.A: 7/1/18

Is driver the owner?

(YES) NO

Nature of Accident:

Claim No.:

S8MOON01 / 68714

Policy No.:

0187854011

Make / Model:

Suzuki

Place of Accident:

Ple Tuds Tuds

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKZ 4403C

SLN 58734

SYB 2972A



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Elite

Tp



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/Time

DATE / PIC

16/1/18
TIN

SLN 58734 - CCU / 01/18/18 / RMKS: 001-1/1/18

SKZ 4403C - X

Muhammad Latip

20/12/18

3 veh cc. 01 last car

21/1/19

No PS

TP press lanya & submit Independent

to de paper sury.

30/5/19

File press to clear.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	20/12/18
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	28
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>
LOR + LOU	<input type="checkbox"/>	LOR + LO	<input type="checkbox"/>
[Tick only one]			
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
30/5/191) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$250.00

Surveyor

Xhd,

REF:

AXA

965 IF

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Elite Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$75K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV58134

Yr Regn:

09 May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C

1496

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

027627

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK81007719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 / 60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17-09-18

Survey held at

W/S

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/9

Estimate later given

45# 4600 Cred # 4000/4700

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos:

) Others:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18016897/Gub3		
8 SHENTON WAY #24-01 AXA TOWERSIN:GAPORE 068811		Date : 17-09-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 4403C	Veh. Inspected	SLN 5813Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/09/2018	Inspection Date	17/09/2018	
Survey held at	ELITE AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Hsiao Tong (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 16 January 2019 11:55 AM
To: 'Xin Yi'; Hsiao Tong (LKKAUTO)
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg; Admin A; assignments
Subject: RE: SLN 5813Y [Our file ref: 19.26173 PD-O]
Attachments: TPPD LITIGATION LOD - AHMAD MUSTAAMAM BIN ISMAIL.PDF

Dear Xin Yi,

Thank you for your email.

Dear Hsiao Tong,

Kindly assist. Our Ref: CC4/ASM18016897/Gpb3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yi [mailto:xinyi@seahong.com.sg]
Sent: Wednesday, 16 January, 2019 10:08 AM
To: 'Admin-D (LKKAUTO)' <admin-d@lkkauto.com>
Cc: 'Chee Kiong' <cheekiong@seahong.com.sg>; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg
Subject: SGK 5813K [Our file ref: 19.26173 PD-O]

Dear Catherine,

CLAIMANT :	AHMAD MUSTAAMAM BIN ISMAIL
VEHICLE NUMBER :	SGK 5813K
ALLEGED ACCIDENT DATE :	03 SEPTEMBER 2018
AXA VEHICLE NUMBER :	SKZ 4403C

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Attn: Gao Gao

62x64315

Vehicle Number : SLN5813Y

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81007719

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID / huc	1	\$ 1193.00
2	BOOT LID LAMP LH & RH X	2	\$ 790.00
3	BOOT LID "H" LOGO X	1	\$ 38.00
4	BOOT LID CHROME GARNISH X	1	\$ 383.00
5	BOOT LID LOCK & / hT	1	\$ 157.50
6	BOOT LID WEATHERSTRIP ?	1	\$ 168.50
7	BOOT LID SCREEN INNER SEAL / SMC	1	\$ 120.00
8	BOOT LID "SHUTTLE" EMBLEM / el	1	\$ 55.00
9	REAR BUMPER / el	1	\$ 1150.60
10	REAR BUMPER RETAINER LH & RH X	2	\$ 60.00
11	REAR BUMPER REFLECTOR LH & RH X	2	\$ 100.00
12	REAR BUMPER REFLECTOR COVER LH & RH X	2	\$ 90.00
13	TOWING CAP X	1	\$ 16.50
14	REAR BUMPER LOWER LID ?	1	\$ 450.00
15	END PANEL ?	1	\$ 560.80
16	TAIL LAMP LH & RH X	2	\$ 1041.00
17	BOOT LID STOPPER LH & RH X	2	\$ 40.00
18	BOOT LID ABSORBER LH & RH X	2	\$ 330.00
19	BOOT LID INNER TRIM COVER ?	1	\$ 320.00
20	END PANEL UPPER GARNISH ?	1	\$ 280.00
21	REAR BUMPER CLIPS / MC	10	\$ 50.00
22	REAR NUMBER PLATE LIGHT X	2	\$ 100.00
23	REAR BUMPER INNER SPONGE LH & RH ?	2	\$ 180.00
			\$ 7673.90

Discount Less 20% \$ 1534.78
 List Prices Total \$ 6,139.12

S/N	Special Nett Items:	Qty	
1	REAR NUMBER PLATE WITH HOLDER / SCR	1	\$ 60.00 40
2	REVERSE SENSOR / DM	2	\$ 350.00 200
			\$
	Special Nett Total		\$ 410.00
	Spare Part's Total Price		\$ 6549.12

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLN5813Y

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81007719

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR BOOT FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 400
2	TO SPRAY PAINTING ON BOOT LID, REAR BUMPER, END PANEL, FLOOR PANEL, REAR LH FENDER.	\$ 1800.00 400
3	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTION.	\$ 50.00 2800
4	TO DRILL 2 PCS SENSOR HOLES AND REPLACE SENSORS AND TEST FUNCTION.	\$ 120.00 40
5	TO REMOVE & INSTALL BOOT COMPARTMENT TRIMMINGS & FITTINGS TO ENABLE REPAIRS.	\$ 100.00 60
6	TO CHECK & RESET E.C.U. AFTER ACCIDENT REPAIRS AND REMOVE FAULT CODES.	\$ 280.00 X 00

Labour Total \$ 4350.00

Parts & Labour Total \$ 10899.12

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLN5813Y

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81007719

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BONNET <i>X Repair</i>	1	\$ 920.80
2	BONNET OUTER RUBBERSTRIP <i>X</i>	1	\$ 27.40
3	BONNET INNER TRIM <i>X</i>	1	\$ 140.00
4	BONNET INNER TRIM CLIPS <i>X</i>	10	\$ 50.00
5	FRONT BUMPER <i>/ Cut</i>	1	\$ 1050.00
6	FRONT BUMPER CLIPS <i>/ n/c</i>	10	\$ 50.00
7	FRONT BUMPER RETAINER LH & RH <i>X</i>	2	\$ 40.00
8	FRONT GRILLE <i>?</i>	1	\$ 300.00
9	FRONT GRILLE LOGO <i>?</i>	1	\$ 50.00
10	FRONT GRILLE BASED <i>?</i>	1	\$ 250.00
11	HEADLAMP LH & RH <i>? 1850 ?</i>	2	\$ 4500.00
12	HEADLAMP LOWER BRACKET LH & RH <i>?</i>	2	\$ 76.00
13	FRONT BUMPER CENTER GRILLE <i>?</i>	1	\$ 140.00
14	FRONT BUMPER SIDE COVER LH & RH <i>X</i>	2	\$ 100.00
15	FRONT BUMPER LOWER LID <i>/ re</i>	1	\$ 145.00
16	BONNET LOCK <i>X</i>	1	\$ 135.00
17	FRONT BUMPER REINFORCEMENT <i>?</i>	1	\$ 420.90
			\$ 8395.10

Discount Less 20% \$ 1679.02
 List Prices Total \$ 6,716.08

S/N	Special Nett Items:	Qty	
1	FRONT NUMBER PLATE WITH HOLDER <i>/ Cut</i>	1	\$ 60.00 <i>40</i>
	Special Nett Total:		\$ 60.00
	Spare Part's Total Price		\$ 6776.08

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLN5813Y

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81007719

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REMOVE & REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE.	\$ 1200.00 400
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT BUMPER LOWER LID & BOTH FRONT FENDERS.	\$ 1800.00 400
3	TO CHECK ELECTRICAL WIRINGS & FOCUS HEADLIGHTS.	\$ 150.00 30

Labour Total \$ 3150.00

Parts & Labour Total \$ 9926.08

6 Days.

lumpsum repair.

After repair photos.

Eno Qian - 8288 0822

17/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

<< Service Request Details

Claim

S8M00UB1

Reference

None 

Loss Date

September 3, 2018

Request Date

September 14, 2018

Due Date

September 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17092018 @ 1:20pm
Christy veh in
G12

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SLN5813Y

Make

TPVD HONDA

Model

Service Address

...

Primary Contact/Insured

BIN MISRAN MUHAMMAD HATDROHA
BLK 534, JURONG WEST ST 52, #07-455, 640534, Singapore
92305454
hatdraha@hotmail.com

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Hsiao Tong (LKKAUTO)

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Wednesday, 19 September 2018 3:09 PM
To: Thin Thin (LKKAUTO)
Cc: cst@axa.com.sg
Subject: Re: FW: Accident Involving Of Vehicle No: SLN 5813Y & SLB 2973A

Hi Thin Thin,

Good day! As time does not permit us to understand the status of liability, as we have waited quite awhile for an answer. Our client may consider taking his car away from our side, rejecting direct settlement, and claim third party through legal means.

Please understand our position and perhaps give us a more absolute answer, so as to continue direct settlement. Hopefully, we can get an answer by earliest tomorrow morning.

Thks and regards,

Ivan Lim
Elite Automotive Pte Ltd

On Wed, 19 Sep 2018, 09:49 Elite Automotive, <elite.automotive13@gmail.com> wrote:
Hi Thin Thin,

Good day! Kindly refer to attached estimate and advise liability on this case. Thanks!

Regards,

Christy


On 18 September 2018 at 17:56, Thin Thin (LKKAUTO) <thinthin@lkkauto.com> wrote:

Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.



Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Tuesday, 18 September 2018 5:49 PM

To: 'Elite Automotive' <elite.automotive13@gmail.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: FW: Accident Involving Of Vehicle No: SLN 5813Y & SLB 2973A

Hi Thin Thin,

Please revert.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

From: Elite Automotive [<mailto:elite.automotive13@gmail.com>]

Sent: Tuesday, 18 September 2018 4:56 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: Re: FW: Accident Involving Of Vehicle No: SLN 5813Y & SLB 2973A

Hi Thin Thin,

Any update about the liability?

Regards,

Christy

On 18 September 2018 at 11:14, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Christy,

Thank you for the email.

This case is handle by Thin Thin.

Dear Thin Thin,

FYNA. [CC4/ASM18016897/ub3](#)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elite Automotive [mailto:elite.automotive13@gmail.com]

Sent: Tuesday, 18 September 2018 10:51 AM

To: sur@lkkauto.com

Subject: Accident Involving Of Vehicle No: SLN 5813Y & SLB 2973A

Hi Thin Thin,

Good day! We as spoken on phone just now, kindly advise liability on this case. Thanks!

Regards,

Christy

--

Regards,

--

Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

21 DEC 2018

MUHAMMAD HATDRAHA BIN MISRAN
BLK 767 WOODLANDS CIRCLE
#06-340
SINGAPORE 730767

Dear Sir/ Mdm

OUR REF : CC4/ASM18016897/Gpb3

YOUR REF : SKZ 4403C

**ACCIDENT INVOLVING SKZ 4403C/ SLN 5813Y/ OTHERS ALONG/AT PIE TOWARDS
TUAS PASIR LABA ON 03/09/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ELITE AUTOMOTIVE acting on behalf of the owner of SLN 5813Y against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

ADVANCE

ADVANCE LAW LLC

Advocates & Solicitors
Commissioner for Oaths
Notary Public
UEN/GST Reg no.: 201310208H

Email: admin@advlawllc.com

430 Lorong 6 Toa Payoh
#11-01 Orangetree Building
Singapore 319402
Tel: (65) 6323 5488 (5 lines)
Fax: (65) 6258 5521
(65) 6225 7738

Business Hours: Mon to Fri
9.00am to 6.00pm

Directors:
DANNY TEO KIM SOON (MD)
DAVID HK FONES

Senior Associates:
SIM HJI SHIEN, ADELINE

Associates:
TAN S-IU HUA VANESSA

Consultant:
WONG CHEE MUN

We do not accept service of Court documents by fax transmission.

Your insured : SKZ 4403C
Our ref : DT/mic/100466/PD

Date: 8 January 2019

M/s AXA
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn : Motor Claims Department

BY HAND



Dear Sirs,

ACCIDENT INVOLVING SLN 5813Y & SKZ 4403C ON 3.9.18 ALONG KJE/TUAS


We act for **AHMAD MUSTAAMAM BIN ISMAIL** in this matter and have been instructed by him to claim damages against you and/or your driver in connection with an accident along **PIE** on **23.9.2018** involving our client's motor vehicle no. **SGK 5813Y** and **SKZ 4403C** driven by you and/or your driver and others at the material time.

We are instructed that the accident was caused by you and/or your driver's negligent in driving and/or management of your vehicle. As a result of the accident, our client's said motor vehicle was badly damaged and our client has been put to loss and expense, particulars of which are as follows:

1. LTA search fee	:	\$ 7.49
2. Costs of repairs (incl GST)	:	\$9,202.00
3. Loss of use (PRI-2 X \$60)	:	\$ 120.00
4. Loss of use (\$60 x \$12)	:	\$ 720.00
5. Survey fee	:	\$ 881.00
6. Costs	:	\$ 900.00
7. Incidentals	:	\$ 80.00
		<u>\$11,910.49</u>

We enclose the following documents:-


1. LTA search;
2. Accident report;
3. Final repair bill;
4. Survey report together with invoice;
5. Colour-scan photos of the damaged motorcar no. SLN 5813Y



Please note that you or your insured driver should send us an acknowledgement of receipt within 14 days of your receipt of your letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,


ADVANCE LAW LLC

Enquire Vehicle & Owner Information (Vehicle No. SKZ4403C As At 03 Sep 2018 / 07:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: DT/MLC/100466/PD

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S9022279A

Owner Name: MUHAMMAD HATDRAHA BIN MISRAN

Registered Address Type: HDB / HUDC

Registered Block/House No.: 767

Registered Street Name: WOODLANDS CIRCLE

Registered Unit No.: # 06 - 340

Registered Building Name: -

Registered Postal Code: 730767

Current Vehicle Details

Vehicle No.: SKZ4403C

Make Description/Mode: SUZUKI / SWIFT SPORT 1.6 M

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Sukdave Singh has successfully logged out.

Your last login date and time was 03 Jan 2019, 15:18:43.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)
1	Vehicle	SLX1933H	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
2	Vehicle	SKZ4403C	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
3	Vehicle	SGV8199J	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
4	Vehicle	XD3151Y	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
5	Vehicle	S.N9004M	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands (S) 757322

Tel : 63397378/ 86606722 Fax: 63397475

Reg No: 201700196D GST Reg No: 201700196D

Date : 15/12/18

OUR REF : TP/SLN 5813Y/18

M/S :AHMAD MUSTAMAM BIN ISMAIL

BLK 658 WOODLANDS RING ROAD

#07-120

SINGAPORE 730658

Statement Of Claim On Veh No : SLN 5813Y
MODEL : HONDA SHUTTLE

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

	\$8,600.00
7%GST	\$602.00
	<u>\$9,202.00</u>



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9651F
Vehicle Details	
Vehicle No.:	SLN5813Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B3539036
Chassis No.:	GK81007719
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,554.00
Original Registration Date:	09 May 2017
First Registration Date:	09 May 2017
Transfer Count:	0
Actual ARF Paid:	\$9,554.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2027
PARF Rebate Amount:	\$7,165.00
Intended COE Rebate Details	
COE Expiry Date:	08 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$41,280.00
Total Rebate Amount:	\$48,445.00

The information contained herein is correct as at 14 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/09/2018 13:41
Date Of Accident	03/09/2018 07:00
Exact Location Of Accident	KJE /TUAS BEFORE PIONEER RD NORTH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN5813Y
Insured/Policyholder	
Name Of Registered Owner	AHMAD MUSTAMAM BIN ISMAIL
NRIC No	S1249651F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81123843
Alternative Phone No	OFFICE-81123843

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-002574
Cover Note Number	

Driver

Name of Driver	SHAH RIDZWAN BIN AHMAD MUSTAMAM
NRIC No	S8816634E
Date Of Birth	09/05/1988
Occupation	INDOOR
Date Of Driving Pass	15/08/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	+65-81123843
Fax Number	
Contact Number	
Email Address	BURNSCARS_N_MEMORIES@HOTMAIL.COM

Address	HDB WOODLANDS, 658 WOODLANDS RING ROAD #07-120
Postcode	730658
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along KJE/Tuas just before PIONEER RD NORTH Exit, car in front of me suddenly jammed brake. I managed my car to stop in time. Car SKZ4403C that was behind me couldn't stop in time & hit onto rear of my car SLN5813Y. Due to the important, my car SLN5813Y moved forward & had slight contact onto rear of car SJB2973A that was in front of me. No injuries involved. (Total 03 vehicles involved in chain collision)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ4403C
Vehicle Make/Model/Colour	SUZUKI / SWIFT SPORT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD HATDRAHA
NRIC/Passport Number	S9022279A
Contact Number	92305454
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJB2973A
Vehicle Make/Model/Colour HONDA / STREAM
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TOH CHEE WEI
NRIC/Passport Number S8825109A
Contact Number 81000225
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

WORLDWIDE

1. The Commission has been informed that the Government of the Republic of the Philippines has agreed to accept the findings and recommendations of the Commission's report on the human rights situation in the Philippines, and to take the necessary steps to implement them. The Commission has also been informed that the Government of the Republic of the Philippines has agreed to accept the findings and recommendations of the Commission's report on the human rights situation in the Philippines, and to take the necessary steps to implement them.

1. The first step in the process of identifying a problem is to determine the nature of the problem. This involves a thorough understanding of the situation and the factors that are contributing to the problem. It is important to gather as much information as possible and to consider all possible causes of the problem.

2. The second step is to identify the goals of the problem-solving process. This involves determining what you want to achieve and what you are willing to sacrifice in order to achieve it. It is important to set realistic goals and to be prepared to adjust them as you learn more about the problem.

3. The third step is to develop a plan of action. This involves identifying the steps that you need to take in order to solve the problem. It is important to be specific and to include details about how you will implement each step.

4. The fourth step is to implement the plan. This involves putting the plan into action and monitoring progress. It is important to stay focused and to be flexible in the face of obstacles.

5. The fifth step is to evaluate the results. This involves assessing the effectiveness of the solution and determining whether the problem has been solved. It is important to be honest and to be willing to accept responsibility for the outcome.

Date: _____ / _____ / _____ Driver's Signature: _____ and the Commissioner: _____ Date: _____

The History of the County of York

Volume II

Common Statement

ACCIDENT STATEMENT (2000 characters)

I was travelling along KJE/Tuas just before PIONEER RD NORTH Exit, car in front of me suddenly jammed brake. I managed my car to stop in time. Car SKZ4403C that was behind me couldn't stop in time & hit onto rear of my car SLN5813Y. Due to the important, my car SLN5813Y moved forward & had slight contact onto rear of car SJB2973A that was in front of me. No injuries involved.

(Total 03 vehicles involved in chain collision)


Taxi Voucher No

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 September 2018 10:27 am

Date/Time

5 September 2018 10:27 am

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



TAX INVOICE

Bill to : Ahmad Mustamam Bin Ismail

C/O : Elite Automotive Pte Ltd
280 Woodlands Industrial Park E5 #01-17
Harvest @ Woodlands
Singapore 757322
Tel: 6339 7378
Contact: Mr Ivan Lim

Fax: 6339 7475
HP: 9388 2885


Invoice No : TAS-1810-1167
Date : 25-Oct-18
Report No : T-EA-180922/5813Y
Terms : COD

S/N	Descriptions	Amount (S\$)
1	<p>Service Rendered In Respect of:</p> <p>Vehicle Number : SLN 5813 Y Vehicle Make/Model : Honda Shuttle Date of Inspection : 22-Sep-18 Date of Accident : 03-Sep-18</p> <p>Appraisal fees include transportation and follow-up inspection.</p> <p>Submission of appraisal report by hand.</p> <p>Photography services including storage of media and submission of color photograph copies by hand.</p> <p>SINGAPORE DOLLARS EIGHT HUNDRED AND EIGHTY-ONE ONLY</p>	\$ 881.00
Total		\$ 881.00

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".
All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services



Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1613 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



VEHICLE ASSESSMENT REPORT

Report No : T-EA-180922/5813Y

Date : 25-Oct-18

REFERENCE

Assigned By : Ahmad Mustamam Bin Ismail
Name of Workshop : Elite Automotive Pte Ltd
Place of Inspection : 280 Woodlands Industrial Park E5 #01-17 Harvest @ Woodlands Singapore 757322
Date of Assignment : 21-Sep-18
Date of Accident : 03-Sep-18
Date of Inspection : 22-Sep-18

PARTICULARS OF DAMAGED VEHICLE

Vehicle Reg No	: SLN 5813 Y	Chassis No	: GK81007719
Year of Reg	: May-17	Odometer/km	: 27627
Make/Model	: Honda Shuttle	Engine No	: L15B3539036
Vehicle Colour	: White	Engine Capacity	: 1496 cc
Vehicle Type	: MPV	Transmission Type	: Auto

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

General Condition	: Good		
Body Paint Work	: Good	Footbrake	: Serviceable
Steering	: Serviceable	Handbrake	: Serviceable
Front Undercarriage	: Serviceable	Rear Undercarriage	: Serviceable

TIRES CONDITION	Tire Brand	Size	Tread Balance
Front RH	: Yokohama	: 185/60 R15	: 80%
Rear RH	: Yokohama	: 185/60 R15	: 80%
Front LH	: Yokohama	: 185/60 R15	: 80%
Rear LH	: Yokohama	: 185/60 R15	: 80%


Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.
* Denotes damaged components.

SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact c
portions.

For further detail of the damages, please refer to our schedule and 13
attached.



Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SLN 5813 Y on 22-Sep-18 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for **SGD 18,476.40** as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to **SGD 10,752.40** and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of **SGD 8,600.00** nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Twelve (12)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,
Treasure Appraisal Services



Dixon Yee T W
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within **Fourteen (14) days** from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1619 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



APPRAISEMENT SCHEDULE

Vehicle Registration No: SLN 5813 Y

Report No: T-EA-180922/5813Y

S/N	Descriptions	Condition	Qty	Repairer's Estimate	Our Assessment
LIST ITEMS					
1	Front bumper cover ✓	Damaged	1 pc	\$ 1,050.00	\$ 1,050.00 ✓ cut
2	Front bumper reinforcement X	Repaired	1 pc	\$ 420.90	\$ X
3	Front RH bumper retainer X	Necessary	1 pc	\$ 15.40	\$ 15.40 X
4	Front LH bumper retainer X	Necessary	1 pc	\$ 15.40	\$ 15.40 X
5	Front bumper clip ✓	Necessary	1 set	\$ 35.00	\$ 35.00 ✓ nec
6	Front grille base assy ✓	Damaged	1 pc	\$ 395.00	\$ 395.00 ✓
7	Front chrome grille assy X	Damaged	1 pc	\$ 302.50	\$ 302.50 ✓
8	Front grille "H" symbol emblem ✓	Necessary	1 pc	\$ 23.40	\$ 23.40 ✓
9	RH headlamp assy X	Reusable	1 pc	\$ 2,250.00	\$ X
10	LH headlamp assy X	Reusable	1 pc	\$ 2,250.00	\$ X
11	Bonnet panel X R	Damaged	1 pc	\$ 920.80	\$ 920.80 X R
12	Bonnet lock assy X	Reusable	1 pc	\$ 135.00	\$ X
13	Tailgate panel ✓	Damaged	1 pc	\$ 1,193.00	\$ 1,193.00 ✓
14	Tailgate "H" symbol emblem X	Necessary	1 pc	\$ 38.00	\$ 38.00 ✓
15	Tailgate "SHUTTLE" emblem ✓	Necessary	1 pc	\$ 55.00	\$ 55.00 ✓
16	Tailgate chrome garnish X	Reusable	1 pc	\$ 383.10	\$
17	Tailgate RH lamp assy X	Reusable	1 pc	\$ 520.50	\$
18	Tailgate LH lamp assy X	Reusable	1 pc	\$ 520.50	\$
19	Tailgate RH hinge X	Damaged	1 pc	\$ 50.00	\$ 50.00
20	Tailgate LH hinge X	Damaged	1 pc	\$ 50.00	\$ 50.00
21	Tailgate RH lifter X	Damaged	1 pc	\$ 165.00	\$ 165.00
22	Tailgate LH lifter X	Damaged	1 pc	\$ 165.00	\$ 165.00
23	Tailgate lock assy ✓	Damaged	1 pc	\$ 157.10	\$ 157.10 ✓
24	Tailgate striker X	Damaged	1 pc	\$ 27.50	\$ 27.50 ✓
25	Tailgate opening weather strip ✓	Damaged	1 pc	\$ 168.50	\$ 168.50 ✓
26	Rear bumper cover ✓	Damaged	1 pc	\$ 1,180.60	\$ 1,180.60 ✓
27	Rear RH bumper retainer X	Damaged	1 pc	\$ 26.50	\$ 26.50
28	Rear LH bumper retainer X	Damaged	1 pc	\$ 26.50	\$ 26.50
29	Rear bumper clip ✓	Necessary	1 pc	\$ 39.00	\$ 39.00 ✓
30	Rear end panel X repair.	Damaged	1 pc	\$ 560.80	\$ 560.80
31	Rear end panel garnish ✓	Damaged	1 pc	\$ 155.50	\$ 155.50
				\$ 13,295.50	\$ 6,815.50
Less Discount : 20%				\$ 2,659.10	\$ 1,363.10
List Parts Sub-Total :				\$ 10,636.40	\$ 5,452.40
SPECIAL NETT ITEMS					
1	Front number plate with holder ✓	Damaged	1 set	\$ 50.00	\$ 50.00 40
2	Rear number plate with holder ✓	Damaged	1 set	\$ 50.00	\$ 50.00 40
3	Reverse parking sensor assy ✓	Damaged	1 pc	\$ 350.00	\$ 280.00 200
4	Reverse camera assy X	Damaged	1 pc	\$ 480.00	\$ 420.00
Special Nett Parts Total :				\$ 930.00	\$ 800.00 280

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
 HP: (65) 9833 1618 Fax: (65) 6747 1017
 Email: treasureappraisal@gmail.com
 Reg No: 53218791A



S/N	Descriptions	Condition	Qty	Repairer's Estimate	Our Assessment
Parts Total :				\$ 11,566.40	\$ 6,252.40

S/N	Labour Descriptions	Repairer's Estimate	Our Assessment	
1	To furnish towing service to workshop.	\$ 60.00	\$ 60.00	X
2	Re-focus headlamp assy set.	\$ 60.00	\$ 40.00	X NN
3	Diagnose, replace and/or repair to rectify front electrical system for proper functioning.	\$ 60.00	\$ 30 40.00	30 X
4	Diagnose, replace and/or repair to rectify rear electrical system for proper functioning.	\$ 60.00	\$ 40.00	X NN
5	Transfer boot lid / tailgate mechanism and wiring assy to facilitate body repairs.	\$ 150.00	\$ 80.00	60
6	Dismantle, replace and/or re-install reverse sensor assy and rectify for proper functioning.	\$ 150.00	\$ 80.00	40
7	Dismantle, replace and/or re-install reverse camera assy and rectify for proper functioning.	\$ 150.00	\$ 120.00	40
8	Dismantle replace and/or re-install rear windscreen / tailgate glass assy to facilitate body repairs.	\$ 150.00	\$ 120.00	100
9	Dismantle and re-install rear interior upholstery; trimming and garnish/es to facilitate body repairs.	\$ 200.00	\$ 180.00	60
10	To carry out front portions accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,200.00	\$ 660.00	400
11	To carry out rear portions accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,200.00	\$ 880.00	400
12	Dismantle, replace, repair and/or re-install tailgate spoiler assy including sealant to facilitate body repairs.	\$ 150.00	\$ 120.00	X NN
13	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on front portions affected areas.	\$ 1,200.00	\$ 600.00	400

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
 HP: (65) 9833 1618 Fax: (65) 6747 1017
 Email: treasureappraisal@gmail.com
 Reg No: 53218791A



S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
14	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on rear portions affected areas.	\$ 1,600.00	\$ 1,100.00
15	To furnish and apply under-sealing & rust proofing coats on accident affected area.	\$ 400.00	\$ 320.00
16	Conduct water leakage tests to ensure proper air and water sealing.	\$ 120.00	\$ 60.00
Labour Total :		\$ 6,910.00	\$ 4,500.00
Parts & Labour Total :		\$ 18,476.40	\$ 10,752.40

400
 X
 X } m

Note: The repairer has agreed to undertake the repairs at our adjusted amount of SGD 8,600.00 on a *Contractual Lump Sum Basis corresponding to supply of all parts, labour and spray painting charges.

N.B: *Under Contractual Lump Sum Basis, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is Twelve (12) working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services

Dixon Yee
 Automobile Appraiser

5221.68
 5572.88
 20% 4450
 46w.
 6Days.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18016897/Gpb3s2		
C/O: SEAH ONG & PARTNERS LLP 36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877		Date : 30-05-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 4403C	Veh. Inspected	SLN 5813Y	
Policy No.	GA378540/1	Coverage (\$)	0.00	
Claim No.	19.26173 PD-O	Excess (\$)	0.00	
Assign From		Assign Date	17/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GK81007719	Colour	WHITE	
Odometer	027627	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/09/2018	Inspection Date	17/09/2018	
Survey held at	ELITE AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5813Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	CUT	1,050.00	1,050.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	420.90	-
1	FRONT RH BUMPER RETAINER	NOT NECESSARY	15.40	-
1	FRONT LH BUMPER RETAINER	NOT NECESSARY	15.40	-
1	SET FRONT BUMPER CLIP	NECESSARY	35.00	35.00
1	FRONT GRILLE BASE ASSY	DAMAGED	395.00	395.00
1	FRONT CHROME GRILLE ASSY	NOT NECESSARY	302.50	-
1	FRONT GRILLE "H" SYMBOL EMBLEM	NECESSARY	23.40	23.40
1	RH HEADLAMP ASSY	NOT NECESSARY	2,250.00	-
1	LH HEADLAMP ASSY	NOT NECESSARY	2,250.00	-
1	BONNET PANEL	TO REPAIR SEE LABOUR	920.80	-
1	BONNET LOCK ASSY	NOT NECESSARY	135.00	-
1	TAILGATE PANEL	DAMAGED	1,193.00	1,193.00
1	TAILGATE "H" SYMBOL EMBLEM	NOT NECESSARY	38.00	-
1	TAILGATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	TAILGATE CHROME GARNISH	NOT NECESSARY	383.10	-
1	TAILGATE RH LAMP ASSY	NOT NECESSARY	520.50	-
1	TAILGATE H LAMP ASSY	NOT NECESSARY	520.50	-
1	TAILGATE RH HINGE	NOT NECESSARY	50.00	-
1	TAILGATE RH LIFTER	NOT NECESSARY	165.00	-
1	TAILGATE LH LIFTER	NOT NECESSARY	165.00	-
1	TAILGATE LOCK ASSY	DAMAGED	157.10	157.10
1	TAILGATE STRIKER	NOT NECESSARY	27.50	-
1	TAILGATE OPENING WEATHER STRIP	DAMAGED	168.50	168.50
1	REAR BUMPER COVER	DAMAGED	1,180.60	1,180.60
1	REAR RH BUMPER RETAINER	NOT NECESSARY	26.50	-
1	REAR LH BUMPER RETAINER	NOT NECESSARY	26.50	-
1	REAR BUMPER CLIP	NECESSARY	39.00	39.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	560.80	-

Report Ref No. CC4/ASM18016897/Gpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL GARNISH	DAMAGED	155.50	155.50
1	TAILGATE LH HINGE	NOT NECESSARY	50.00	-
	LESS 20% DISCOUNT		-2,659.10	-890.42
			10,636.40	3,561.68
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT NUMBER PLATE WITH HOLDER (SN)	DAMAGED	50.00	40.00
1	SET REAR NUMBER PLATE WITH HOLDER (SN)	DAMAGED	50.00	40.00
1	REVERSE PARKING SENSOR ASSY (SN)	DAMAGED	350.00	200.00
1	REVERSE CAMERA ASSY (SN)	NOT NECESSARY	480.00	-
			930.00	280.00
	<u>LABOUR</u>			
	TO FURNISH TOWING SERVICE TO WORKSHOP.	NOT NECESSARY	60.00	-
	RE-FOCUS HEADLAMP ASSY SET.	NOT NECESSARY	60.00	-
	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		60.00	30.00
	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	60.00	-
	TRANSFER BOOT LID / TAILGATE MECHANISM AND WIRING ASSY TO FACILITATE BODY REPAIRS.		150.00	60.00
	DISMANTLE, REPLACE AND/OR RE-INSTALL REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.		150.00	40.00
	DISMANTLE, REPLACE AND/OR RE-INSTALL REVERSE CAMERA ASSY AND RECTIFY FOR PROPER FUNCTIONING.		150.00	40.00
	DISMANTLE REPLACE AND/OR RE-INSTALL REAR WINDSCREEN / TAILGATE GLASS ASSY TO FACILITATE BODY REPAIRS.		150.00	100.00
	DISMANTLE AND RE-INSTALL REAR INTERIOR UPHOLSTERY; TRIMMING AND GARNISH/ES TO FACILITATE BODY REPAIRS.		200.00	60.00

Report Ref No. CC4/ASM18016897/Gpb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT FRONT PORTIONS ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND/OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION. INCLUSIVE OF THE REPAIR OF BONNET PANEL.		1,200.00	400.00
	TO CARRY OUT REAR PORTIONS ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND/OR REPAIR, RECONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	400.00
	DISMANTLE, REPLACE, REPAIR AND/OR RE-INSTALL TAILGATE SPOILER ASSY INCLUDING SEALANT T FACILITATE BODY REPAIRS.	NOT NECESSARY	150.00	-
	TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON FRONT PORTIONS AFFECTED AREAS.		1,200.00	400.00
	TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON REAR PORTIONS AFFECTED AREAS.		1,600.00	400.00
	TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA.	NOT NECESSARY	400.00	-
	CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND WATER SEALING.	NOT NECESSARY	120.00	-
			6,910.00	1,930.00
GRAND TOTAL			18,476.40	5,771.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CC4/ASM18016897/Gpb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.