

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8425M

DATE 14/9/2018 16:52

MAKE :

MODEL :

HYUNDAI IONIQ

Whole Right Side

PP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover XXXX ✓			\$ 418.30
	Front Bumper Bracket (RH) ?			\$ 28.00
	Front Bumper Side Bracket Support ?			\$ 12.00
	Front Fender (RH) ✓			\$ 490.70
	Front Fender Shield (RH) ?			\$ 114.70
	Front Fender Retainer ?			\$ 41.40
	Front Wheel Rim (RH) ✓			\$ 351.90
	Front Wheel Hub Cap (RH) X			\$ 346.40
	Front Wheel Bearing ?			\$ 454.00
	Front Shock Absorber (Assy) (RH) ?			\$ 372.50
	Front Shock Absorber Mounting (RH) ?			\$ 206.90
	Front Shock Absorber Fork (RH) ?			\$ 112.20
	Front Suspension Upper Arm (RH) ?			
	Front Drive Shaft (RH) ?			\$ 936.70
	Rack & Pinion Assy ?			\$ 887.40
	STG Tie End ?			\$ 91.50
	Stabilizer Bar ?			\$ 246.80
	Stabilizer Bar Bush (LH) ?			\$ 22.30
	Stabilizer Bar Link ?			\$ 74.90
	Stabilizer Bracket ?			\$ 10.50
	Front Suspension Lower Arm (RH) ?			\$ 296.80
	Knuckle Arm (RH) ?			\$ 363.60
	Front Handbag RH ✓			
	Front Parcel Shelf (RH) ✓			
	SUB TOTAL			\$ 5,879.50
	LESS 20%			\$ 1,175.90
	DISCOUNTED TOTAL			\$ 4,703.60
	Front Fender Sticker (RH) X			\$ 100.00
	Front Tyre (RH) ✓ 50%			\$ 216.00
				\$ 316.00

Nett

Nett

AXIA

SH 8425M

FZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (RH) X Rep			\$ 1,768.30	
	Rear Fender Inner Lining (RH) X			\$ 73.60	
	Rear Windscreen Moulding X			\$ 28.20	
	Rear Door (RH) /			\$ 1,789.90	
	Rear Door Outer Handle (RH) X Rep			\$ 78.00	
	Rear Door Gear/Regulator (RH) X			\$ 229.90	
	Front Door (RH) /			\$ 1,797.20	
	Front Door Gear / Regulator (RH) ?			\$ 250.40	
	Front Door Power Motor ?			\$ 289.20	
	Rear Wheel Hup-Cap (RH) X			\$ 134.10	
	SUB TOTAL			\$ 6,438.80	
	LESS 20%			\$ 1,287.76	
	DISCOUNTED TOTAL			\$ 5,151.04	
	Rear Windscreen Sealant X			\$ 46.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) /			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH) /			\$ 75.00	Nett
				\$ 201.00	
	Labour Charge				
	Panel Beating			\$ 1,600.00	
	Spray Painting Charge			\$ 1,250.00	1200
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	20
	Towing Charge - KING DOOR			\$ 150.00	120
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	X
	Transfer of Door		\$ 120.00	\$ 240.00	100
	Remove/Refix Undercarriage (FRT)			\$ 400.00	100?
	Front Wheel Alignment			\$ 120.00	60
	TOTAL LABOUR			\$ 4,150.00	
	ESTIMATE TOTAL			\$ 14,521.64	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

1 calli 16/06/17

17/9/18 1050h.

5 Bp

PIP

Before Paint Photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: