

J

Vehicle: SKF2385P

Make & Model: Toyota Mark X
Chassis No: GRX120-3052579

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper			781.50	D.S ✓
2	Rear Bumper Retainer (Left & Right)	2	141.70	283.40	not o/s, pc
3	Rear Bumper Clip			30.00 SN	re ✓
4	Right Rear tail lamp			475.50	Scr ✓
5	Right Rear Tow Cover			61.10	M.S ✓
6	Right Rear Fender			972.50	RX
7	Reverse Sensor			\$200 SN	17X
8	EXHAUST PIPE CHROME GARNISH	1/5		182.00	7W1 ✓

25%

P-1641.8
 252
 1231.35
 S.N - 30
 labour - 880
 2141.35

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour					
1	Check Wiring			\$ 100.00	20
2	Panel Beating			\$ 500.00	400
3	Paintwork			\$ 600.00	400
4	Remove & Refit Rear Windscreen			\$ 120.00	114X
5	Interior Upholstery			\$ 100.00	60

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-30
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

not about
 200
 HCS
 32.
 17/9/18

Repair Sum \$ 1900