

Labour					
1	Check Wiring			\$ 100.00	20
2	Panel Beating			\$ 500.00	400
3	Paintwork			\$ 600.00	400
4	Remove & Refit Rear Windscreen			\$ 120.00	114X
5	Interior Upholstery			\$ 100.00	60

**STYTECH AUTO PTE. LTD.**  
 2 Kaki Bukit Ave 2 #02-30  
 Kaki Bukit Autohub Singapore 417921  
 Tel: 6444 8125 Fax: 6445 3310  
 GST Reg. No.: 201601539K  
 Co. Reg. No.: 201601539K

not done  
 20  
 HCS  
 32.  
 17/9/18

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle: SKF2385P

Make & Model: Toyota Mark X

Chassis No: GRX120-3052579

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper				Dis /
2	Rear Bumper Retainer (Left & Right)	2			not o/s, p.c
3	Rear Bumper Clip				m /
4	Right Rear tail lamp				Scr /
5	Right Rear Tow Cover				n.s /
6	Right Rear Fender				R X
7	Reverse Sensor			\$200 SN	17X
8	Exhaust Chrome garnish RH				m /