

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Withheld
L1 Imp @ 3700h
Recovery After Pains

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: 13.09.2018

Accident Date : 11.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

承接汽车烧焊喷漆及
代理各种车辆赔偿

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan Sylphy" Reg. No. SJZ7712C Claiming Against Your Insured Reg. No. SLB7872B		
1pc	Front Bumper 541.00		CM 622.00 N
12pcs	Front Bumper Clips	2.60	na 31.20 N
1pc	Front Bumper Top Retainer RH		n17 37.00 N
1pc	Front Bumper Bracket		R 172.00 N X
1pc	Front Bumper Reinforcement 561.90		R 620.00 N
1pc	Front Bumper Sponge		su 231.00 N X
1pc	Front Bumper Fog Lamp Cover		na 143.00 N
1pc	Front Bumper Corner Retainer RH		CM 82.00 N
2pcs	Front Bumper Mouldings	56.00	na 112.00 N
1pc	Front Bumper Beam		R 245.00 N X
1pc	Headlamp Assy RH		mg-mt 550.00 N
1pc	Grille		mg-cm 362.00 N
1pc	Grille Emblem 331.70		na 73.00 N
1pc	Support Panel		R 557.00 N X
1pc	Support Panel Top Garnish 371.90		CM 417.00 N
12pcs	Support Panel Top Garnish Clips	2.60	na 31.20 N
1pc	Wiper Tank 168.00		na 246.00 N
1pc	Wiper Tank Motor 181.40		shay 225.70 N
1pc	Air Con Condenser Side Air Guide		cm 112.00 N
1pc	Bonnet Stopper RH		su 13.00 N X
	Less 10%		4,882.10
			488.21
			4,393.89
1pc	Front Bumper Fog Lamp 306.90		mg-cm 333.70 SN
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 201
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		na 90.00 X
	To Remove / Refit Air Con Condenser & Refill Gas		na 120.00 X
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member Inner Panel, Bonnet, Front Fender Etc. Cnt, Weld Support and Parts Replacement		900.00 500
	To Respray Affected Areas		1,100.00 800
		Total :	6,967.59