

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Withheld  
L1 Imp @ ?  
Recovery After Pain*

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 13.09.2018

Accident Date : 11.09.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

| 数量<br>Quantity | 货名<br>DESCRIPTION                                                                                                                                     | 单价<br>Unit Price | 银 Amount 额<br>\$ cts. |
|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-----------------------|
|                | Estimate Cost Of Repair To "Nissan Sylphy" Reg. No. SJZ7712C<br>Claiming Against Your Insured Reg. No. SLB7872B                                       |                  |                       |
| 1pc            | Front Bumper                                                                                                                                          |                  | CM 622.00 N           |
| 12pcs          | Front Bumper Clips                                                                                                                                    | 2.60             | na 31.20 N            |
| 1pc            | Front Bumper Top Retainer RH                                                                                                                          |                  | n/i 37.00 N           |
| 1pc            | Front Bumper Bracket                                                                                                                                  |                  | na 172.00 N           |
| 1pc            | Front Bumper Reinforcement                                                                                                                            |                  | na 620.00 N           |
| 1pc            | Front Bumper Sponge                                                                                                                                   |                  | na 231.00 N           |
| 1pc            | Front Bumper Fog Lamp Cover                                                                                                                           |                  | na 143.00 N           |
| 1pc            | Front Bumper Corner Retainer RH                                                                                                                       |                  | na 82.00 N            |
| 2pcs           | Front Bumper Mouldings                                                                                                                                | 56.00            | na 112.00 N           |
| 1pc            | Front Bumper Beam                                                                                                                                     |                  | R 245.00 N            |
| 1pc            | Headlamp Assy RH                                                                                                                                      |                  | ng 550.00 N           |
| 1pc            | Grille                                                                                                                                                |                  | ng 362.00 N           |
| 1pc            | Grille Emblem                                                                                                                                         |                  | na 73.00 N            |
| 1pc            | Support Panel                                                                                                                                         |                  | R 557.00 N            |
| 1pc            | Support Panel Top Garnish                                                                                                                             |                  | CM 417.00 N           |
| 12pcs          | Support Panel Top Garnish Clips                                                                                                                       | 2.60             | na 31.20 N            |
| 1pc            | Wiper Tank                                                                                                                                            |                  | na 246.00 N           |
| 1pc            | Wiper Tank Motor                                                                                                                                      |                  | na 225.70 N           |
| 1pc            | Air Con Condenser Side Air Guide                                                                                                                      |                  | na 112.00 N           |
| 1pc            | Bonnet Stopper RH                                                                                                                                     |                  | na 13.00 N            |
|                | Less 10%                                                                                                                                              |                  | 4,882.10              |
|                |                                                                                                                                                       |                  | 488.21                |
|                |                                                                                                                                                       |                  | 4,393.89              |
| 1pc            | Front Bumper Fog Lamp                                                                                                                                 |                  | 333.70 SN             |
|                | To Conduct Front Electrical Check, Locking System, Adjust,<br>Focus Headlamp etc                                                                      |                  | 30.00 2ol             |
|                | To Remove / Refit, Radiator System, Bleed, Refill Coolant                                                                                             |                  | na 90.00 X            |
|                | To Remove / Refit Air Con Condenser & Refill Gas                                                                                                      |                  | na 120.00 X           |
|                | Labour Charge - Panel Beating, Repairing Of Front Chassis Member<br>Inner Panel, Bonnet, Front Fender Etc. Cnt, Weld Support and Parts<br>Replacement |                  | 900.00 5od            |
|                | To Respray Affected Areas                                                                                                                             |                  | 1,100.00 8od          |
|                | <b>Total :</b>                                                                                                                                        |                  | <b>6,967.59</b>       |

LKK Auto Consultants hence notify  
the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date: