

08/11/13

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6427C Yr Regn: 9 Mar 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima C.C. 1600Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 375108 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAGM414MF5588261

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 14/9/18 D.O.I. 14/9/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21-9-18	L/S \$1,600
	DUA-14-9-18
	15 SAT
	16 SUN
	17
	OUT-18 1PM
	R(\$2,555.70/64%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18016918/K1jb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 17-09-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 257B		Veh. Inspected	SHC 6427C
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	17/09/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/09/2018		Inspection Date	14/09/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18016918/K1jb3

Date: 17.09.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC6427C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.09.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,455.70
Revised Estimate Amount	: S\$	2,005.90
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Gary Shi

From: Gary Shi
Sent: Wednesday, 14 November, 2018 10:50 AM
To: 'Joy Irene (LKKAUTO)'
Subject: RE: LOD / Accident involving SHC6427C & SJY257B on 14.09.18 (China Taiping case)
Attachments: SHC6427C - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6427C, our client agreed to direct settle the above claims at \$2124.88

We enclosed hereby Discharge voucher & ATA for your kind attention.

Kindly let us have your settlement sum of S\$2124.88 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, 14 November, 2018 9:28 AM
To: Gary Shi
Subject: RE: LOD / Accident involving SHC6427C & SJY257B on 14.09.18 (China Taiping case)

WITHOUT PREJUDICE

Dear Gary,

DV and ATA attached for your necessary action.

Thank you.

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Tuesday, 18 September 2018 4:28 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJY257B (OI : CTI - SNM18D04460C02) AND SHC6427C (TP : LKK REF - CC3/CTI18016918/K1jb3) on 14.09.2018
Attachments: leeSZ_SNM18D04460C01-SJY257B-LKKDirectSettlementAccidentLtr_CLCR95.970.pdf, MCHM18119569-SJY257B.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 17 September, 2018 7:05 PM
To: Claims Dept of CTI
Cc: Irene Tay; Lucas Lee; Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJY257B (OI : CTI - TBA) AND SHC6427C (TP : LKK REF - CC3/CTI18016918/K1jb3) on 14.09.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 6427C at M/s Premier Automotive Services Pte Ltd.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaping.com

Co. Reg. No. 200206384E

Our Reference: **SNM18D04460/C01/7**

Date: **18 SEPTEMBER 2018**

via Ordinary & Registered Mail

**WONG LIANG TANG
BLK 829 YISHUN STREET 81
#05-514
SINGAPORE 760829**

Dear Sir / Madam

**ACCIDENT INVOLVING SJY257B AND SHC6427C ON 14 SEPTEMBER 2018
ALONG GOMBAK DRIVE SLIP ROAD TOWARDS UPP BUKIT TIMAH ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC6427C**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY

Ref : CC3/CTI18016918/K1JB3

Contact No : 68412409

via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0166A) - LQ BUSINESS PTE LTD

F01/LKKDS-2013

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	09 Mar 2015 / 10:20:28	Receipt No.:	AACCK001-AX239-150309-000015
Asset Type:	Vehicle	Transaction Amount:	\$65,354.00
Asset ID:	SHC6427C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150309102028658767		

Vehicle No.:	SHC6427C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Mar 2015
Original Registration Date:	09 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588261
Engine No.:	D4FDEH313505
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,158.00
Minimum PARF Benefit:	\$8,473.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Mar 2015 10:20:28
COE No.:	2015030901002144M
COE Expiry Date:	08 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	08 Mar 2023

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	09 Mar 2015 / 10:20:28	Receipt No.:	AACCK001-AX239-150309-000015
Asset Type:	Vehicle	Transaction Amount:	\$65,354.00
Asset ID:	SHC6427C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150309102028658767		

Vehicle No.:	SHC6427C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Mar 2015
Original Registration Date:	09 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588261
Engine No.:	D4FDEH313505
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,158.00
Minimum PARF Benefit:	\$8,473.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Mar 2015 10:20:28
COE No.:	2015030901002144M
COE Expiry Date:	08 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	08 Mar 2023

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

- | | |
|---|---------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHC6427C |
| Chassis Number | : KNAGM414MF5588261 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 20 Oct 2017 |
| 4. Expiry Date of Insurance | : 19 Oct 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| (a) The Policyholder. | |
| (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use* | |
| (a) Use as a Taxi. | |
| (b) Use for social domestic and pleasure purposes. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered Inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6427 C

1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	—	\$	29.00
1 pc	Boot lid lower garnish	X	\$	290.00
1 pc	Rear bumper	—	\$	696.00
1 pc	Rear bumper lower cover	—	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge	X	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00
1 pc	Rear bumper reflector n/s	X	\$	46.00

LKK Auto Consultants and notify
To request below:
• To display on road
• Parts prices are not to be based on
• Third party survey is not to be based on
• No illegal modification
• Supplementary insurance is subject to the insurance company
Less 10%
Acknowledged by Repairer
Signature:
Date:

S/NETT

1 set	Rear bumper clips	—	\$	48.00
1 set	Bootlid lower garnish clips	—	\$	60.00
1 set	Bootlid stickers	—	\$	100.00
1 set	Reverse sensor	—	\$	280.00
1 pc	Rear bumper top protector	—	\$	80.00

Sundry

To check for wiring and to focus head lamps

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc

To putty and spray painting on bootlid lower garnish, rear bumper, end panel

To apply rustproofing on the repaired and replaced panels.

\$	48.00
\$	60.00
\$	100.00
\$	280.00
\$	80.00
\$	50.00
\$	80.00
\$	120.00
\$	180.00
\$	300
\$	750.00
\$	360
\$	600.00
\$	80.00
\$	4,455.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

21/9/18
Landed LPS \$1600/3 days

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6427 C

1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	/	\$	29.00
1 pc	Boot lid lower garnish	X rep	\$	290.00
1 pc	Rear bumper	/	\$	696.00
1 pc	Rear bumper lower cover	/	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge	X	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00
1 pc	Rear bumper reflector n/s	X	\$	46.00
			\$	2,253.00
			\$	225.30
			\$	2,027.70
S/NETT				
1 set	Rear bumper clips	/	\$	48.00
1 set	Bootlid lower garnish clips	/	\$	60.00
1 set	Bootlid stickers	/	\$	100.00
1 set	Reverse sensor	/	\$	280.00 200
1 pc	Rear bumper top protector	/	\$	80.00 50
			\$	50.00 20
			\$	80.00 X
			\$	120.00 30
			\$	180.00 X
			\$	300
			\$	750.00
			\$	360
			\$	600.00
			\$	80.00 X
			\$	4,455.70



(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

[e-Services \(/content/policehubhome/homepage.html\)](#)[Log in ↗](#)

Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number	S7077888B
Status of Qualified Driving Licence	Valid
Class(es) of Qualified Driving Licence	2B,3
Expiry Date	Valid for life unless revoked,suspended or disqualified

Provisional Driving Licence

You are not a valid Provisional Driving Licence Holder.

[HOME \(https://www.police.gov.sg/\)](https://www.police.gov.sg/)
[ABOUT US \(https://www.police.gov.sg/about-us\)](https://www.police.gov.sg/about-us)
[SGSECURE \(https://www.police.gov.sg/sgsecure\)](https://www.police.gov.sg/sgsecure)
[I-WITNESS \(https://www.police.gov.sg/iwitness\)](https://www.police.gov.sg/iwitness)
[COMMUNITY PROGRAMMES \(https://www.police.gov.sg/community-programme\)](https://www.police.gov.sg/community-programme)
[RESOURCES \(https://www.police.gov.sg/resources\)](https://www.police.gov.sg/resources)
[NEWS & PUBLICATIONS \(https://www.police.gov.sg/news-and-publications\)](https://www.police.gov.sg/news-and-publications)
[JOIN US \(https://www.police.gov.sg/join-us\)](https://www.police.gov.sg/join-us)
[FAQS \(https://va.ecitizen.gov.sg/ctf/CustomerPages/SPF/explorefaq.aspx\)](https://va.ecitizen.gov.sg/ctf/CustomerPages/SPF/explorefaq.aspx)
[CONTACT US \(https://www.police.gov.sg/content/contact-us\)](https://www.police.gov.sg/content/contact-us)
[E-FEEDBACK \(/content/policehubfeedback/efeedback.html\)](/content/policehubfeedback/efeedback.html)
[SITEMAP \(https://www.police.gov.sg/sitemap\)](https://www.police.gov.sg/sitemap)

[Privacy Statement \(https://www.police.gov.sg/content/privacy-statement\)](https://www.police.gov.sg/content/privacy-statement) | [Terms of Use \(https://www.police.gov.sg/content/terms-of-use\)](https://www.police.gov.sg/content/terms-of-use) .
© 2018 Singapore Police Force. A Member of The Home Team (<https://www.mha.gov.sg>).




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18016918/K1jb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 19-11-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 257B	Veh. Inspected	SHC 6427C	
Policy No.	DMPCSN3043471803	Coverage (\$)	0.00	
Claim No.	SNM18D04460/C01/7	Excess (\$)	0.00	
Assign From		Assign Date	14/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5588261	Colour	SILVER	
Odometer	375108	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/09/2018	Inspection Date	14/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6427C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
1	REAR BUMPER REFLECTOR N/S	SERVICEABLE	46.00	-
	LESS 10% DISCOUNT		-225.30	-93.10
			2,027.70	837.90
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NECESSARY	60.00	60.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			618.00	478.00
LABOUR				
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-

Report Ref No. CC3/CTI18016918/K1jb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH.		750.00	300.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		600.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,810.00	690.00
GRAND TOTAL			4,455.70	2,005.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CC3/CT118016918/K1jb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.