

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

14-Sep-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6427 C

1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	/	\$	29.00
1 pc	Boot lid lower garnish	X repair	\$	290.00
1 pc	Rear bumper	/	\$	696.00
1 pc	Rear bumper lower cover	/	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge	X	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket	X	\$	36.00
1 pc	Rear bumper reflector n/s	X	\$	46.00

LKK Auto Consultants hence notify  
the following:  
• To resurvey before spray painting  
• To display damaged parts during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification is allowed  
• Supplementary items must be resurveyed and  
is subject to final approval from the company  
Less 10%  
Acknowledged by Repairer  
Signature:  
Date:

### S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	Bootlid lower garnish clips	/	\$	60.00
1 set	Bootlid stickers	/	\$	100.00
1 set	Reverse sensor	/	\$	280.00 200
1 pc	Rear bumper top protector	/	\$	80.00 50
	Sundry	4's	\$	50.00 20
	To check for wiring and to focus head lamps	After Repair	\$	80.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		\$	300 750.00
	To putty and spray painting on bootlid lower garnish, rear bumper, end panel		\$	360 600.00
	To apply rustproofing on the repaired and replaced panels.		\$	80.00 X
			\$	4,455.70

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )