

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 217B**AAD1809-124**

Not Authenticated
Resurvey By paint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 217B
 VF1ABL15AUC281593
 RENAULT
 LATITUDE
 13.9.2018
QBE Insurance

PART		LIST
1 BUMPER COVER FRT	\$	<i>Br</i> 1,259.42 ✓
1 BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1 BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1 BUMPER RETAINER FRT LH	\$	<i>Br</i> 151.41 ✓
1 BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1 BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77
1 BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1 BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1 BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 } X
1 BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21
1 BUMPER BEAM FRT	\$	<i>R</i> 914.08
1 HEADLAMP LH	\$	<i>Sn</i> 1,184.43
1 HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
1 FENDER PANEL FRT LH	\$	<i>Br</i> 783.83 ✓
1 WHEELARCH FRT LH	\$	<i>Sn</i> 278.84 X
1 FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79 X
1 FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1 DOOR PANEL FRT LH	\$	<i>Br</i> 2,844.66 ✓
1 RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1 RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1 RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1 RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36 } X
1 RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1 RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1 FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1 FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1 AIR CLEANER BOX	\$	<i>Sn</i> 464.20
1 AIR CLEANER HOSE	\$	<i>Sn</i> 175.85

Trans-cab Auto Services Pte Ltd

AAD1809-124

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 217B

1	LOWER ARM LH L70Y	\$	685.76	?
1	KUNCKLE ARM LH L70Y	\$	846.98	?
1	ABSORBER FRT LH L70Y	\$	360.54	?
1	DOOR PANEL FRT LH	\$	2,844.66	} X
1	DOOR HINGE UPPER LH	\$	261.28	
1	DOOR HINGE LOWER LH	\$	300.55	
1	DOOR CHECK FRT LH	\$	194.77	
1	DOOR LOCK FRT LH	\$	908.75	
1	DOOR CATCH FRT LH	\$	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	477.76	
1	DOOR HANDLE COVER FRT LH	\$	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	133.60	
1	DOOR REGULATOR FRT LH	\$	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97	
1	DOOR HARNESS WIRE	\$	2,670.00	

TOTAL	\$	30,142.73
10%	\$	3,014.27
	\$	27,128.45

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	30.50	X
1	FRONT LEFT TYRE	\$	300.00	?
1	FRONT LEFT TYRE RIM	\$	380.00	✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	60.00
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	13.50
1	DOOR CHECK BOLT	\$	22.69	X
1	DOOR GUIDE SCREW	\$	10.85	X
1	DOOR HINGE BOLT	\$	10.85	X

Trans-cab Auto Services Pte Ltd**AAD1809-124**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 217B

1	DOOR HINGE NUT RH	\$	<i>sin</i> 14.60	} X
1	DOOR CHECK BOLT	\$	<i>sin</i> 22.69	
1	DOOR CHECK NUT	\$	<i>sin</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>sin</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>sin</i> 10.06	

\$ 1,219.63

TOTAL PARTS \$ 28,348.08

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>500l</i> 3,500.00
Putty and spray painting of the affected portion.	\$	3,000.00 <i>660l</i>
To rust-proofing of the affected areas.	\$	170.00 <i>60l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>60l</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>20l</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-124

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 217B

To vacuum, replace, refix and recharge Air
Intercooler

\$ *na* 170.00 *X*

To transfer of front door fittings, attachment and
perform water seepage test.

\$ 380.00 *601*

TOTAL \$ 9,090.00

Over All Total \$ 37,438.08

LUMP SUM (REPAIR DAY)~~10 DAYS~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: