

INSRS: WSP: Tel: Liability: RMKS: *premium* INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:

Payee 3: (Strike if N/A)	SS	Name 3:	✓	✓
--------------------------	----	---------	---	---

CONFIDENTIAL

REF:

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03/08 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLS777A- Yr Regn: 2018 / July.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi S5 cc 2995Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 1492 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF58JA116432Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 255/35R19.R: 255/35R19.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I: 18/09/18.Survey held at: Premium.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPA19.

31/4/19 Confirm 2-B-2 #4913.60 with 3 working days.

(Red. # 6058.80
55.1.)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

\$ + RS. \$

Phone

Other

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18016923/wb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-09-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 4209P	Veh. Inspected	SLS 777A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/09/2018	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1073/2018/GW
Date	:	17-Sep-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 4209 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Loy Chung Kian
Address	:	72 Elias Road #16-23 Singapore 519944
Telephone	:	(HP) +65 97357155
Type of Claim	:	Third Party Claims
Policy No.	:	1800090520
Vehicle No	:	SLS 777 A
Model Code	:	Audi S5 SB 3.0 TFSI
Model / Year	:	Jul-18
Engine No	:	CWG 088006
Chassis No	:	WAUZZZF58JA116432
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Sep-18
Place of Accident	:	Puggol Way Towards TPE Airport

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 777 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓ /	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500 ✓ /	
3	To respray rear bumper.	\$ 900.00 550 ✓ /	
4	To remove and renew rhs rear exhaust silencer. To align to position.	S/N \$ 480.00 x.	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓ /	
6	To carry out ceramic coating	S/N \$ 800.00 ?? x	
TOTAL LABOUR CHARGES		: <u><u>3,782.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 777 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>2chd</i>	\$ 2,357.00	✓ 1885.60
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 142.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	\$ 191.00	+
4	REAR BUMPER SPOILER <i>new</i>	\$ 155.00	+
5	REAR BUMPER TRIM <i>new</i>	\$ 287.00	+
6	REAR BUMPER CENTRE TRIM <i>lit</i>	\$ 587.00	✓ 469.60
7	REAR BUMPER CORNER TRIM-LH/RH <i>new</i>	2 \$ 584.00	+
8	REAR BUMPER TRIM-LH/RH <i>new</i>	2 \$ 70.00	+
9	REAR LIGHT REFLECTOR-LH/RH <i>new</i>	2 \$ 70.00	+
10	REAR BUMPER CARRIER <i>new Best</i>	\$ 786.00	628.40
11	REAR BUMPER GUDIE SECTION-LH/RH <i>2 new</i>	2 \$ 74.00	+
12	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>2 new</i>	2 \$ 38.00	+
13	REAR BUMPER SENSOR <i>new new</i>	2 \$ 421.00	+
14	REAR BUMPER SENSOR SEAL RING <i>new</i>	4 \$ 14.00	+
15	REAR SILENCER WITH EXHAUST FLAP <i>new</i>	\$ 1,034.00	+
16	REAR SILENCER DUAL CLIP <i>new</i>	\$ 43.00	+
17	REAR SILENCER BRACKET <i>new</i>	\$ 37.00	+
18	SUNDRIES <i>2 new new</i>	\$ 300.00	+
TOTAL SPARE PARTS CHARGES		: \$ 7,190.00	
TOTAL LABOUR CHARGES		: \$ 3,782.00	
GRAND TOTAL		: \$ 10,972.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/TP/1073/2018/GW
Date	25-Sep-18
Service Advisor	Jeffery Tan
Pages	1
Regn No	SLS 777 A
Model No	Audi S5 SB 3.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To carry out paint protection (Provided by owner) S/N	\$ 328.00	✓
TOTAL		\$ 328.00	

For Premium Automobiles Pte Ltd

Adrian Ling
SLS

Authorised Signature



INVOICE

BILL TO :

Name : Loy Chuan Kian
Contact Number : 9735 7155

DATE : 6 August 2018

INVOICE : INV00434

Vehicle Make/Model/Colour : Audi / S5 / Blue

Vehicle Registration Number : SLS 777 A

Payment Mode : CASH / NETS / CREDIT

DESCRIPTION		AMOUNT	
Silver Package		\$	1,318.00
Discount on Package -	15%	\$	(197.70)
Paintwork Restoration		\$	350.00
Promotion Inclusive Ceramic PRO Umbrella			
Warranty Number - KR020170136			
+ Ceramic PRO Care - Newly Applied +			
✓ Do not use Shampoo for the 1st 3 days			
✓ Keep the surface dry. If surface get wet, Dab the surface dry with a lightly damp Microfiber towel. Do Not use Wiping motion.			
✓ In event any substances land on the surface, clean up as soon as possible			
+ Basic Care for Owners +			
✓ Weekly wash with Quality Shampoo and dry with clean chamois cloth.			
✓ Remove bird dropping, tree saps as soon as possible. Soften the substances with tissue soaked with water. Gently lift the substances off. Do not rub or use force.			
✓ Apply Ceramic PRO SPORT after shampoo wash every fortnightly			
Ceramic PRO Prestige card will be mailed to the address provided on warranty registration.			
+ Please register your warranty online to be effective within 14 days http://www.ceramicpro.com.sg/warranty-register/			
TOTAL :		\$	1,470.30
Total Paid :		\$	1,470.30

8 Kaki Bukit Avenue 4, #04-19, Premier @ Kaki Bukit, Singapore 415875
T: +65 9658 8936 | E: info@ace-gk.com

BILL TO :

Name : Premium Automobiles Pte Ltd
 Contact Number : Attn : Kee Siang

DATE : 21 September 2018

Vehicle Make/Model/Colour : Audi / S5 / Blue
 Vehicle Registration Number : SLS 777 A

DESCRIPTION	AMOUNT
<p>Ceramic PRO Silver Package Panel Recoat</p> <p>Recoat (Rear Bumper)</p>	<p>\$ 328.00</p>
<p>◆ Car Care - Newly Applied ◆</p> <p>✓ Do not use Shampoo for the 1st 3 days</p> <p>✓ Keep the surface dry. If surface get wet, Dab the surface dry with a lightly damp Microfiber towel. Do Not use Wiping motion.</p> <p>✓ In event any substances land on the surface, clean up as soon as possible</p> <p>◆ Basic Care for Owners ◆</p> <p>✓ Weekly wash with Quality Shampoo and dry with clean chamois cloth.</p> <p>✓ Remove bird dropping, tree saps as soon as possible. Soften the substances with tissue soaked with water. Gently lift the substances off. Do not rub or use force.</p>	
	<p>\$ 328.00</p>

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/TP/1073/2018/GW
Date	25-Sep-18
Service Advisor	Jeffery Tan
Pages	1
Regn No	SLS 777 A
Model No	Audi S5 SB 3.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To carry out paint protection (Provided by owner) S/N	\$ 328.00	\$ 328.00
TOTAL		\$ 328.00	\$ 328.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Henry

Surveyed Date

: 18/09/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1073/2018/GW
Date : 17-Sep-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 4209 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 12 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loy Chung Kian
Address : 72 Elias Road
#16-23
Singapore 519944
Telephone : (HP) +65 97357155
Type of Claim : Third Party Claims
Policy No. : 1800090520
Vehicle No : **SLS 777 A**
Model Code : Audi S5 SB 3.0 TFSI
Model / Year : Jul-18
Engine No : CWG 088006
Chassis No : WAUZZZF58JA116432
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Sep-18
Place of Accident : Puggol Way Towards TPE Airport

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 777 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,050.00	\$ 500.00
3	To respray rear bumper.		\$ 900.00	\$ 550.00
4	To remove and renew rhs rear exhaust silencer. To align to position.	S/N	\$ 480.00	
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
6	Supplementary		\$ 328.00	\$ 328.00
7	To carry out ceramic coating	S/N	\$ 800.00	
TOTAL LABOUR CHARGES		:	<u>4,110.00</u>	<u>1,930.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 777 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,357.00	\$ 1,885.60
2	REAR BUMPER FIXING PARTS	\$ 142.00	
3	REAR BUMPER SECURING STRIP	\$ 191.00	
4	REAR BUMPER SPOILER	\$ 155.00	
5	REAR BUMPER TRIM	\$ 287.00	
6	REAR BUMPER CENTRE TRIM	\$ 587.00	\$ 469.60
7	REAR BUMPER CORNER TRIM-LH/RH	2 \$ 584.00	
8	REAR BUMPER TRIM-LH/RH	2 \$ 70.00	
9	REAR LIGHT REFLECTOR-LH/RH	2 \$ 70.00	
10	REAR BUMPER CARRIER	\$ 786.00	\$ 628.40
11	REAR BUMPER GUDIE SECTION-LH/RH	2 \$ 74.00	
12	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 38.00	
13	REAR BUMPER SENSOR	2 \$ 421.00	
14	REAR BUMPER SENSOR SEAL RING	4 \$ 14.00	
15	REAR SILENCER WITH EXHAUST FLAP	\$ 1,034.00	
16	REAR SILENCER DUAL CLIP	\$ 43.00	
17	REAR SILENCER BRACKET	\$ 37.00	
18	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 7,190.00	\$ 2,983.60
TOTAL LABOUR CHARGES		\$ 4,110.00	\$ 1,930.00
GRAND TOTAL		\$ 11,300.00	\$ 4,913.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 13 May 2003

NP 428A



Licence No: S8022411G

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number
Name: S 8 0 2 2 4 1 1 G

KWA WAN LING, PATRICIA

Birth Date: 29 Jul 1980
Issue Date: 28 Apr 2003



0004318298

BREAKDOWN OF PAYMENT

Vehicle No: SLS 777 A

Accident on 14/09/2018 at Punggol way towards TPE AIRPORT

Involving vehicle/s SKR 4209 P

1) Repair cost \$ 5,257.55 Payable to: Premium Automobiles Pte Ltd

2) ~~GIA~~/LTA search fee \$ 7.45 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 300.00 Payable to: Loy Chung Kian

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18016923/wb3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/1073/2018/JT

11 Dec 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 777 A, Audi S5 SB 3.0 TFSI qu

With reference to the above-mentioned vehicle, no. **SLS 777 A**, claimant, **Mr. Loy Chung Kian**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013238 – S\$5,257.55
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. GIA search fee S\$2.00
6. Loss of Use – S\$300.00 (S\$100.00 x 3 working days)

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 777 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016923/wb3

20 September 2018

Daimler Fleet Management Singapore Pte Ltd

1 Gateway Drive
#15-08 Westgate Tower
Singapore 608531

Dear Sir/Madam,

ACCIDENT INVOLVING SKR 4209P AND SLS 777A ON 14 /9/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)


I, Loy Chung Kian (the third party claimant) of 72 Elias Road #16-23
Singapore 519944 (address), owner of SLS 777 A (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLS 777 A that was damaged pursuant to the accident which occurred on 14/09/2018
(date) along Punggol Way towards TPE Airport (location) involving vehicle no/s
SKR 4209 P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 28 (day) of SEPT (month) 2018 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)



RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$557.55 (Repair Cost), S\$300.00 (Loss of ~~rental~~ use), S\$7.45 (Disbursement), for vehicle no. SLS 777 A that was damaged pursuant to the accident which occurred on 14/09/2018 (date) along Punggol Way towards TPE Airport (location) involving vehicle no/s SKR 4209 P. This is pursuant to the inspection conducted on 18/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Loy Chung Kian ("the third party claimant") of vehicle no. SLS 777 A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLS 777A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22 (day) of 4 (month) 20 19 (year)

LWP



Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone 6384 2223
Fax 6471 1723
Page 1 11:48

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone 6384 2223
Fax 6471 1723

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
Service Appointment
24-hour breakdown service
Email: customerservice@premiumautos.com.sg
6384 2223
6471 1723

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013238 Date : 05/12/2018 Order : SLS0777A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS0777A (V 38970) Regn Date: 26/07/2018 Mileage: 1636 WIP No.: 25087
Model: S5 SPORTBACK 3.0 TFSI qu tiptr Chassis: WAUZZZF58JA116432 Engine: CAG 088006 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	368.00	1.00	368.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER, REORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO CARRY OUT CERAMIC COATING (BY OWNER)	328.00	1.00	328.00
X	ABW6853551 RWA	(A) (SK) HOLDING (25/09)	1.00	587.00	469.60
X	ABW0807309	BRACKET	1.00	785.50	628.40
X	ABW6807067AAGRU	COVER	1.00	2357.00	1,885.60

Parts	2,983.60	Sub-Total	4,913.60
Labour	328.00	7% GST	343.95
Sublet	1,602.00	Grand Total	5,257.55
Menus	0.00		
Lubricant	0.00		

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Sep 2018 / 10:25:34

Receipt Date/Time : 15 Sep 2018 / 10:25:21

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180915-000290

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKR4209P				
As at 14 Sep 2018/16:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKR4209P Enquiry Fee 20180915102427052034	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4694	Credit Card: Visa /MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7622351C



Name

LOY CHUNG KIAN
(LI ZHONGJIAN)

黎 忠 健

Race

CHINESE

Date of birth

23-07-1976

Sex

M

Country/Place of birth

SINGAPORE

S7622351C

REPUBLIC OF SINGAPORE DRIVING LICENCE

Reference Number: S7622351C

Name

LOY CHUNG KIAN
(LI ZHONGJIAN)

Birth Date: 23 Jul 1976

Issue Date: 29 May 2003



1000E24415J

5550339



NRIC No: S7622351C



Date of issue

15-01-2016

Address

72 ELIAS ROAD
#16-23
SINGAPORE 519944

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B Motorcycles not exceeding 200 cc
Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

19 Mar 1998
02 Sep 1999



License No: S7622351C

NP 428A

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Sep 2018 Edit Reg		18 Sep 2018 00:00 Edit Adj Rpt	S\$4,913.60 Edit Estimates	S\$4,913.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. , Co. Reg. No.: 1998037782									
Main Claimant: LOY CHUNG KIAN , ID: S7622351C									
Vehicle Reg. No.: SL5777A		Date of Loss: 14/09/2018 16:00 - :59 [1 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9855919572SG		Policy/Cover Note No.: 0999994749 (Comprehensive)							
Vehicle Reg. No. (Insured): SKR4209P		Policy No. (Claimant): 1800090520							
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS777A (9855919572SG)

[SKR4209P]

TP

LOY CHUNG KIAN

Sep 14 2018 4:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>	
Letters/Correspondences										1 per page <input type="button" value="v"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Photos/Images										3 per page <input type="button" value="v"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
2	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
3	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
4	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
5	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
6	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
7	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
8	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
9	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
10	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
11	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
12	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
13	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
14	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
15	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
16	16/11/18 10:15	General View						1 Load JPG		<input checked="" type="checkbox"/>	
17	16/11/18 10:15	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
18	16/11/18 10:15	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
19	16/11/18 10:15	Reinspection Photo						1 Load JPG		<input checked="" type="checkbox"/>	
Documentation										1 per page <input type="button" value="v"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/09/18 17:56	TP GIA REPORT						1 Load PDF			
2	19/09/18 19:14	TP ESTIMATE- MARKED						1 Load PDF			
3	03/05/19 08:47	WORKSHOP INVOICE						1 Load PDF			
4	03/05/19 08:47	AUTHORISATION TO ACT FORM						1 Load PDF			
5	03/05/19 08:47	Release Voucher						1 Load PDF			
6	03/05/19 08:47	LTA SEARCH						1 Load PDF			
7	03/05/19 08:47	TP IC						1 Load PDF			
8	03/05/19 08:47	LETTER TO OI						1 Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	18/09/18 10:27	OI GIA REPORT						1 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKR4209P (Insd veh)	Model:	AUDI S5 3.0 TFSI QUATTRO
	SLS777A (TP veh)		(A)
Date of Accident:	14/09/2018		

Global Sum Settlement	: <input type="checkbox"/> Yes	: <input checked="" type="checkbox"/> No	
Repair Estimate	: \$		12,091.00
Final Repair Cost	: \$		5,257.55
Loss of Use	: \$		300.00
			3.00 days at \$100.00 per day
Rental (if any)	: \$		0.00
			days
LTA / GIA Search Fee	: \$		7.45
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		5,565.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	5,265.00
2)	Loy Chung Kian (Li ZhongJian)	: \$	300.00
3)		: \$	

JOANNE LEE KHANG MIN

03 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18016923/AWB3Q2

Date: 03/05/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994749
Claimant Vehicle No :	SLS777A	Insured Vehicle No :	SKR4209P
Date of Loss:	14/09/2018	Nature of Claim:	TP
		Claim No:	9855919572SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS777A	Engine No:	CWG088006
Make & Model:	AUDI S5, 3.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZF58JA116432
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	1492 km
Colour:	Blue		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,190.00	2,983.60	4,206.40	58.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	1,930.00	2,180.00	53.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,300.00	4,913.60	6,386.40	56.52
+ GST 7.00/7.00% (S\$)	791.00	343.95	447.05	56.52
Nett Amount (S\$)	12,091.00	5,257.55	6,833.45	56.52
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,565.00		

INSPECTION

Date of Assignment:	18/09/2018		
Date Inspected:	18/09/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,357.00 FS	*1,885.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	142.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	191.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	155.00 FS	*- FS
5	1		*REAR BUMPER TRIM	Not Necessary	287.00 FS	*- FS
6	1		*REAR BUMPER CENTRE TRIM	Cut	587.00 FS	*469.60 FS
7	2		*REAR BUMPER CENTRE TRIM -LH/RH	Not Necessary	584.00 FS	*- FS
8	2		*REAR BUMPER TRIM -LH/RH	Not Necessary	70.00 FS	*- FS
9	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	70.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Bent	786.00 FS	*628.40 FS
11	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	74.00 FS	*- FS
12	2		*REAR BUMPER UPPER GUIDE SECTION -LH/RH	Not Necessary	38.00 FS	*- FS
13	2		*REAR BUMPER SENSOR	Not Necessary	421.00 FS	*- FS
14	4		*REAR BUMPER SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
15	1		*REAR SILENCER WITH EXHAUST FLAP	Not Necessary	1,034.00 FS	*- FS
16	1		*REAR SILENCER DUAL CLIP	Not Necessary	43.00 FS	*- FS
17	1		*REAR SILENCER BRACKET	Not Necessary	37.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,190.00** **2,983.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CARRY OUT PAINT PROTECTION (PROVIDED BY OWNER)	New	328.00	328.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
3	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY REAR BUMPER	New	900.00	550.00
5	TO REMOVE AND RENEW RHS REAR EXHAUST SILENCER .TO ALIGN TO POSITION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO CARRY OUT CERAMIC COATING	New	800.00	0.00
Gross Labour Cost (S\$)			4,110.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >