

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/1073/2018/GW  
**Date** : 17-Sep-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 4209 P

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Loy Chung Kian  
**Address** : 72 Elias Road  
#16-23  
Singapore 519944  
**Telephone** : (HP) +65 97357155  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1800090520  
**Vehicle No** : **SLS 777 A**  
**Model Code** : Audi S5 SB 3.0 TFSI  
**Model / Year** : Jul-18  
**Engine No** : CWG 088006  
**Chassis No** : WAUZZZF58JA116432  
**Mileage** : -  
**Date In** : -  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 14-Sep-18  
**Place of Accident** : Puggol Way Towards TPE Airport

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLS 777 A

| S/n                         | Nature of Jobs                                                                                                   | Estimated Charges               | Surveyor's Recommendation |
|-----------------------------|------------------------------------------------------------------------------------------------------------------|---------------------------------|---------------------------|
| 1                           | To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage. | S/N \$ 360.00 ✓                 |                           |
| 2                           | To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.   | \$ <del>1,050.00</del> 500      |                           |
| 3                           | To respray rear bumper.                                                                                          | \$ <del>900.00</del> 550.       |                           |
| 4                           | To remove and renew rhs rear exhaust silencer. To align to position.                                             | S/N \$ 480.00 ✗.                |                           |
| 5                           | To carry out diagnostic check.                                                                                   | S/N \$ 192.00 ✓                 |                           |
| 6                           | To carry out ceramic coating                                                                                     | S/N \$ 800.00 ??                |                           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                  | <b>: <u><u>3,782.00</u></u></b> |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLS 777 A

| S/N                              | Parts Description                                  | Damaged Parts & Prices |         |
|----------------------------------|----------------------------------------------------|------------------------|---------|
|                                  |                                                    | S/Nett                 | Remarks |
| 1                                | REAR BUMPER <i>rehd</i>                            | \$ 2,357.00            | ✓       |
| 2                                | REAR BUMPER FIXING PARTS <i>ne a</i>               | \$ 142.00              | ✗       |
| 3                                | REAR BUMPER SECURING STRIP <i>ne a</i>             | \$ 191.00              | ✗       |
| 4                                | REAR BUMPER SPOILER <i>ne a</i>                    | \$ 155.00              | ✗       |
| 5                                | REAR BUMPER TRIM <i>ne a</i>                       | \$ 287.00              | ✗       |
| 6                                | REAR BUMPER CENTRE TRIM <i>cut</i>                 | \$ 587.00              | ✓       |
| 7                                | REAR BUMPER CORNER TRIM-LH/RH <i>ne a</i>          | 2 \$ 584.00            | ✗       |
| 8                                | REAR BUMPER TRIM-LH/RH <i>ne a</i>                 | 2 \$ 70.00             | ✗       |
| 9                                | REAR LIGHT REFLECTOR-LH/RH <i>ne a</i>             | 2 \$ 70.00             | ✗       |
| 10                               | REAR BUMPER CARRIER <i>ne a</i>                    | \$ 786.00              | ✗       |
| 11                               | REAR BUMPER GUDIE SECTION-LH/RH <i>3 not</i>       | 2 \$ 74.00             | ✗       |
| 12                               | REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>3 not</i> | 2 \$ 38.00             | ✗       |
| 13                               | REAR BUMPER SENSOR <i>not ne a</i>                 | 2 \$ 421.00            | ✗       |
| 14                               | REAR BUMPER SENSOR SEAL RING <i>ne a</i>           | 4 \$ 14.00             | ✗       |
| 15                               | REAR SILENCER WITH EXHAUST FLAP <i>ne a</i>        | \$ 1,034.00            | ✗       |
| 16                               | REAR SILENCER DUAL CLIP <i>ne a</i>                | \$ 43.00               | ✗       |
| 17                               | REAR SILENCER BRACKET <i>ne a</i>                  | \$ 37.00               | ✗       |
| 18                               | SUNDRIES ?                                         | \$ 300.00              | ?       |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                                    | <b>\$ 7,190.00</b>     |         |
| <b>TOTAL LABOUR CHARGES</b>      |                                                    | <b>\$ 3,782.00</b>     |         |
| <b>GRAND TOTAL</b>               |                                                    | <b>\$ 10,972.00</b>    |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Hing-  
Surveyed Date : 18/09/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant