

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8472 M

Sundry	\$	50.00 X
To check wheel alignment	\$	80.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the n/s rocker panel garnish	\$	250.00 ¹⁰⁰
To putty and spray painting on n/s rocker panel garnish	\$	250.00 ¹⁸⁰
To apply rustproofing on the repaired and replaced panels.	\$	100.00 X
	\$	<u>730.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahir (LKK)
18/9/18 1005h
2 hrs
4s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: