

CHUNNI MOTOR WORK PTE LTD

To Survey by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHA 1700G

DATE : 14.09.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille broken			\$ 282.10	✓
	Radiator Grille U Moulding Cnt			\$ 108.90	✓
	Front Bumper Cover distorted			\$ 538.80	✓
	Front Bumper Sponge & torn			\$ 136.30	✓
	Front Bumper Reinforcement & bt			\$ 504.10	✓
	Front Bumper Bracket Top (LH/RH) HH HH	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) HH	\$	20.10	\$ 40.20	X
	Headlamp Support Panel Assy Rnded			\$ 1,023.00	✓
	Hcadlamp (LH/RH) broken even	\$	797.90	\$ 1,595.80	✓
	Radiator & bt			\$ 814.80	✓
	Radiator Fan Blade,Cowling,Motor Assy HH			\$ 651.30	X
	Radiator Bracket HH	\$	6.20	\$ 12.40	X
	Horn Unit (RH) HH			\$ 83.10	X
	Aircon Condenser & bt			\$ 1,089.90	✓
	Inter Cooler & bt			\$ 771.50	✓
	Inter Cooler Mounting (2 PCS) HH			\$ 24.80	X
	Wiring-ECM HH broken			\$ 3,107.80	✓
	SUB TOTAL			\$ 10,829.60	
	LESS 20%			\$ 2,165.92	
	DISCOUNTED TOTAL			\$ 8,663.68	
	Front Number Plate bt			\$ 25.00	Nett ✓
	Front No Plate Trim Cover SL			\$ 30.00	Nett X
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 50.00	HH
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard			\$ 200.00	150/-
	Remove/Refix Fuse Box			\$ 180.00	50/-
	TOTAL LABOUR			\$ 1,880.00	

QIV

Parts Description/ Labour


Type

Unit Price

Amount

Page 2 of 3

SHA 1700G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 1000/-
	Spray Painting Charge			\$ 1,250.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Fuel Tank			\$ 150.00 40/-
	TOTAL LABOUR			\$ 3,890.00
	ESTIMATE TOTAL			\$ 22,114.38
17/09/2018 @ 1630h Not Attached 2/Smk  2 KK Auto  10 days				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				