

22/03/2002

ASS. REC. BY:

REF:

CS/ICS18016939/TTHbz

Special Instruction:

Survivor:
Insured:

Taufik

ASSIGNMENT (Office)

From (Person):

Janie Goh

of

ICS

Date/Time:

17092018 12:16pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 8200X

Insured:

SKN 982867

at Workshop m/s

Hong Seng Motor

Tel:

6123 7469

of

Blk 1106 Bukit Merah Lane 2 #01-08

Policy No:

Claim No:

PMPC1800350H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13092018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

17092018 349pm

Person Contacted:

Mr. Teo

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

10/10-

lump sum \$4100. 5days. Cred: 1526.70, 27%

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 17 September, 2018 12:16 PM
To: leongseng; 'assignments'
Cc: ECICS Claims; Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: RE: accident involving FBH8200X/SKN9528G on 13/9/18 - request for survey
Attachments: IMG_20180915_0002.pdf; GIA Accident Report - FBH8200X.PDF

Without Prejudice

Hi C S Teo

Thank you for your email.
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange TP survey.
Our claim no DMPC1800159H/CT and case handler is Ms Crystabelle Tan.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: leongseng [mailto:leongseng@singnet.com.sg]
Sent: Saturday, 15 September, 2018 12:31 PM
To: ECICS Claims
Subject: accident involving FBH8200X/SKN9528G on 13/9/18 - request for survey

Dear Sir/Mdm

Pls be informed that FBH8200X had appointed us to do a 3rd party property claim for him.

Pls find enclosed FBH8200 accident report, signed authorised/request for survey letter.

Pls arrange your appointed surveyor to conduct damage survey at our workshop at your early convenience.

Thanks

c s 'teo
Leong Seng Motor
62737469

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

From: leongseng <leongsen@singnet.com.sg>
Sent: Wednesday, 26 September 2018 3:11 PM
To: SUR
Subject: FBH8200 marked estimate
Attachments: IMG_20180926_0004.pdf

Dear Sir/mdm

Pls find enclosed FBH8200X marked estimate,

Kindly check and advice us on your recommended COR.

Pls find below are our working on COR

parts	\$5173.00
less 10%	(\$ 517.30)
	\$4655.70
net items & labour	\$ 530.00
sub total	\$5185.70
less 20%	(\$1037.14)
	\$4148.56

Based on our above working, we will like to request for Lump sum repair of \$4100.00

Kindly consider and keep us posted of your decision.

Thanks

c s teo

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/09/2018 14:53
Date Of Accident	13/09/2018 20:00
Exact Location Of Accident	ALONG AYE TOWARDS TUAS BEFORE CLEMENTI AVE 2 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH8200X
Insured/Policyholder	
Name Of Registered Owner	TANG HAN SHEN
NRIC No	S9245478I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92292112
Alternative Phone No	OFFICE-92292112

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R15-150CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D17MTMC01001816
Cover Note Number	

Driver

Name of Driver	TANG HAN SHEN
NRIC No	S9245478I
Date Of Birth	08/12/1992
Occupation	INDOOR
Date Of Driving Pass	27/07/2011
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92292112
Fax Number	
Contact Number	OFFICE-92292112
EMail Address	NOEMAIL



**SINGAPORE
POLICE FORCE**



T/20180914/2044

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20180914/2044

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/09/2018 11:18		Vide Report No.:		Station Diary No.: 85	
Informant's Particulars					
Name of Informant: TANG HAN SHEN			Address: APT BLK 694 JURONG WEST CENTRAL 1 #11-13 SINGAPORE 640694		
ID Type / ID No.: NRIC NO / S92454781			Contact No.: Home/Office: Mobile: 92292112		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 08/12/1992	Type of Informant: Rider.		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SOCIAL CONSULTANT			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/09/2018 20:00	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE TOWARDS TUAS, BEFORE CLEMENTI AVENUE 2 EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBH8200X	Motorcycle	YAMAHA	YZF-R15 MANUAL	Red	Seriously Damaged	0
SKM9528G	Car				Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
FBH8200X	TENET SOMPO INSURANCE PTE. LTD.	D17MTMC0100181 6	17/10/2017	16/10/2018	

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH8200X

Model : R15

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy		\$ 265.00		cut
2	Headlamp stay		\$ 190.00		Rp
3	Top cowling		\$ 330.00		cut
4	Top cowling inner cover		\$ 125.00		cut
5	Windshield		\$ 175.00		cut
6	Mirror		\$ 80.00		cut
7	Clutch lever		\$ 25.00		cut
8	Handle bar		\$ 180.00		bc
9	Front signal lamp		\$ 50.00		dig
10	Side cowling		\$ 280.00		cut
11	Front fender		\$ 165.00		cut
12	Front fork assy		\$ 870.00		? btr
13	Fork under bracket		\$ 285.00		? btr
14	Front wheel rim		\$ 460.00		dd
15	Front wheel bearing	2	\$ 50.00		? nu
16	Front wheel axle		\$ 95.00		? btr
17	Front footrest		\$ 75.00		cut
18	Brake pedal Gear pedal		\$ 98.00		xbt
19	Rear footrest		\$ 50.00		cut
20	Rear footrest bracket		\$ 185.00		dd
21	Side stand		\$ 90.00		bc
22	Tail cowling	2	\$ 520.00		cut
23	Tail centre cover		\$ 85.00		cut
24	Rear fender		\$ 120.00		cut
25	Rear swing arm		\$ 380.00		dd
26	swing arm bush		\$ 85.00		nu
27	Rear signal lamp		\$ 50.00		cut
28	Rear no plate			\$ 15.00	nu
29	Front no plate			\$ 15.00	cut
30	HP holder			\$ 70.00	cut
31	Towing 2 way			\$ 100.00	so
32	Repair alignmenmt			\$ 250.00	100 7ph
33	Labour			\$ 350.00	200
34					
35					
36					
37					
38					
39					

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495449
17/9/18 @ 1745
Resurvey after repair.
5 days
1 sur @ 1845 hours

19/9/18

Less 10%

\$ 5,363.00 \$ 800.00
\$ 536.30
\$ 4,826.70

5626.70

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH8200X

Model : R15

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy		\$ 265.00		Cut
2	Headlamp stay		\$ 190.00		Rp
3	Top cowling		\$ 330.00		Cut
4	Top cowling inner cover		\$ 125.00		cut
5	Windshield		\$ 175.00		cut
6	Mirror		\$ 80.00		cut
7	Clutch lever		\$ 25.00		cut
8	Handle bar		\$ 180.00		bt
9	Front signal lamp		\$ 50.00		dig
10	Side cowling		\$ 280.00		cut
11	Front fender		\$ 165.00		cut
12	Front fork assy ←		\$ 870.00	bt	?
13	Fork under bracket ←		\$ 285.00	bt	?
14	Front wheel rim		\$ 460.00		dd
15	Front wheel bearing ←	2	\$ 50.00	nr	?
16	Front wheel axle ←		\$ 95.00	bt	?
17	Front footrest		\$ 75.00		cut
18	Brake pedal Gear pedal		\$ 98.00		xbt
19	Rear footrest		\$ 50.00		cut
20	Rear footrest bracket		\$ 185.00		dd
21	Side stand		\$ 90.00		bt
22	Tail cowling	2	\$ 520.00		cut
23	Tail centre cover		\$ 85.00		cut
24	Rear fender		\$ 120.00		cut
25	Rear swing arm		\$ 380.00		dd
26	swing arm bush		\$ 85.00		rec
27	Rear signal lamp		\$ 50.00		cut
28	Rear no plate			\$ 15.00	nr
29	Front no plate			\$ 15.00	cut
30	HP holder			\$ 70.00	cut
31	Towing 2 way			\$ 100.00	so
32	Repair alignmenmt			\$ 250.00	150? photo
33	Labour			\$ 350.00	200
34	Tanjung 97495+49				
35	"wp"				
36	17/9/18 @ 1745				
37	Repair after repair				
38	5 days				
39	1 sup @ 1100/1000				

\$ 5,363.00 \$ 800.00

\$ 536.30

\$ 4,826.70

5626.70

Less 10%

Repair 24/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018 15:28 Edit Reg		17 Sep 2018 00:00 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 0 , Co. Reg. No.: 0, Email: EMAIL@EMAIL.COM									
Main Claimant: TANG HAN SHEN , ID: S92454781									
Vehicle Reg. No.: FBH8200X		Date of Loss: 13/09/2018 20:00 - :59 [58 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC1800359H		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SKN9528G		Policy No. (Claimant):							
		Excess:							
Repairer: Leong Seng Motor Pte Ltd - Bukit Merah (HQ) Blk 1006 Bukit Merah Lane 2, #01-08, 159762 Bukit Merah - Tel: 62737469									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBH8200X (DMPC1800359H)

[SKN9528G]

TP



















































TANG HAN SHEN












































Sep 13 2018 8:00PM

[0]

Leong Seng Motor Pte Ltd - Bukit Merah

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
20	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
21	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
22	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
23	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
24	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
25	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
26	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
27	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
28	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
29	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
30	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
31	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
32	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
33	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
34	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
35	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
36	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
37	11/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
71	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
81	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	11/10/18 10:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18016939/T1TBE2

Date: 22/10/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle
No : FBH8200X

Insured Vehicle No : SKN9528G

Date of Loss: 13/09/2018

Nature of Claim:

TP

Claim No: DMPC1800359H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBH8200X

Make & Model: YAMAHA YZF-R15, 150cc (M)

Engine No: 1CK4010422

Reg. Date: 16/10/2013 (Man. Year: 2013)

Chassis No: ME11CK048D2010419

Colour: Red

Odometer: 46192 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17

Rear Tyre Size:

130/70 R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,926.70	4,755.70	171.00	3.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	430.00	270.00	38.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,626.70	5,185.70	441.00	7.84
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	5,626.70	4,100.00	1,526.70	27.13

INSPECTION

Date of Assignment: 17/09/2018

Date Inspected: 17/09/2018 Inspected At:

Leong Seng Motor Pte Ltd - Bukit Merah (HQ)

Blk 1006 Bukit Merah Lane 2, #01-08
Singapore 159762

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	YAMAHA YZF-R15 150cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH8200X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY	Cut	265.00 FL	*265.00 FL
2	1		*HEADLAMP STAY	Repair	190.00 FL	*- FL
3	1		*TOW COWLING	Cracked	330.00 FL	*330.00 FL
4	1		*TOW COWLING INNER COVER	Cracked	125.00 FL	*125.00 FL
5	1		*WINDSHIELD	Cut	175.00 FL	*175.00 FL
6	1		*MIRROR	Cut	80.00 FL	*80.00 FL
7	1		*CLUTCH LEVER	Cut	25.00 FL	*25.00 FL
8	1		*HANDLE BAR	Bent	180.00 FL	*180.00 FL
9	1		*FRONT SIGNAL LAMP	Distorted	50.00 FL	*50.00 FL
10	1		*SIDE COWLING	Cut	280.00 FL	*280.00 FL
11	1		*FRONT FENDER	Cut	165.00 FL	*165.00 FL
12	1		*FRONT FORK ASSY	Bent	870.00 FL	*870.00 FL
13	1		*FORK UNDER BRACKET	Bent	285.00 FL	*285.00 FL
14	1		*FRONT WHEEL RIM	Dented	460.00 FL	*460.00 FL
15	2		*FRONT WHEEL BEARING	Necessary	50.00 FL	*50.00 FL
16	1		*FRONT WHEEL AXLE	Bent	95.00 FL	*95.00 FL
17	1		*FRONT FOOTREST	Cut	75.00 FL	*75.00 FL
18	1		*GEAR PEDAL	Bent	98.00 FL	*98.00 FL
19	1		*REAR FOOTREST	Cut	50.00 FL	*50.00 FL
20	1		*REAR FOOTREST BRACKET	Dented	185.00 FL	*185.00 FL
21	1		*SIDE STAND	Bent	90.00 FL	*90.00 FL
22	2		*TAIL COWLING	Cracked	520.00 FL	*520.00 FL
23	1		*TAIL CENTRE COVER	Cut	85.00 FL	*85.00 FL
24	1		*REAR FENDER	Cut	120.00 FL	*120.00 FL
25	1		*REAR SWING ARM	Dented	380.00 FL	*380.00 FL
26	1		*SWING ARM BUSH	Necessary	85.00 FL	*85.00 FL
27	1		*REAR SIGNAL LAMP	Cut	50.00 FL	*50.00 FL
28	1		*REAR NO PLATE	Necessary	15.00 FS	*15.00 FS
29	1		*FRONT NO PLATE	Cut	15.00 FS	*15.00 FS
30	1		*HP HOLDER	Cracked	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,463.00	5,273.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	536.30	517.30
Total Parts (\$\$)	4,926.70	4,755.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING 2 WAY	New	100.00	80.00
2	REPAIR ALIGNMENT	New	250.00	150.00
3	LABOUR	New	350.00	200.00
Gross Labour Cost (\$\$)			700.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >