

ASS. REC. BY:

REF: CS/C748016942/Urbm2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

Maiman

From (Person): Jowyn Tay of CIL Date/Time: 17092018 4:26pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 8114Y Insured: GT 3833E

at Workshop m/s Think One Autocare Tel: 9128 8486

of 18 Delu Ave 2

Policy No: DMCVSN6019861812 Claim No: SNM78 D01447700

Sum Insured: Excess:

Make of Veh: D.O.A. 10092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 19-09-2018 @ 4pm

Date/Time: 17092018 5:21pm Person Contacted: Karen H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 8114Y - X
	GT 3833E - X

REF: CTL

Signature:

maximen

ASSIGNMENT

From:

Date: 19092018

Estimated Cost:

OD TP/WS / TP RES / GD RES / EVA / INV / MV

To inspect Vehicle No:

YP8114Y

at Workshop m/s:

Think One

of

18 Delm Ave 2

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

4pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 38951

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP8114Y

Yr Regn:

1217

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mof center

c.c 2998

Colour:

S. blue

A/C: Insured / Std / NI / NA

Sp. Reading

12263

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FER50543047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/75R16

R:

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6/6

R/Bal.

mm

L/Bal.

6/6

mm

L/Bal.

6/6

mm

D.O.A.

10/9/18

D.O.I.

19/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: 5/11/18 Action/Instruction: Confirmed N/S & 1100 with logins, 3 days

Red: 817,369.50, 941

RECEIVED 05 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

☒

Final Report

1) typist

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Report Format: Tr

Lump Sum / LB: (\$

1100

210

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		17 Sep 2018 16:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: THINK ONE LEASING PTE LTD									
Vehicle Reg. No.: YP8114Y									
Date of Loss: 10/09/2018 00:00 - :59									
Claim Type: TP / SNM18D04477C02									
Policy/Cover Note No.: DMCVSN6019861812									
Vehicle Reg. No. (Insured): GT3833E									
Policy No. (Claimant):									
Excess: S\$0.00									
Repairer: Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/09/2018]									
Adj Asg. Remarks: NO EST, ASSIGN MARCUS CHUA AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail 									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5609M
Vehicle Details	
Vehicle No.:	YP8114Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER 3.0 A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	4P10B92056
Chassis No.:	FEB50543047
Maximum Power Output:	-
Open Market Value:	\$38,166.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$1,909.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,000.00
COE Rebate Amount:	\$38,951.00
Total Rebate Amount:	\$38,951.00

The information contained herein is correct as at 19 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2018 09:11
Date Of Accident	10/09/2018 14:30
Exact Location Of Accident	BLK 7 NORTH BRIDGE ROAD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP8114Y
Insured/Policyholder	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	201115609M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER 3.0A
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5070244660-03
Cover Note Number	

Driver

Name of Driver	WONG KIAN HONG
NRIC No	S9246938G
Date Of Birth	28/11/1992
Occupation	OUTDOOR
Date Of Driving Pass	25/07/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97129050
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 52 LORONG 6 TOA PAYOH #09-50
Postcode	310052
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE 10.09.2018 AT ABOUT 1430HR. I PARK MY VEHICLE AT THE SAID LOCATION. VEHICLE GT3833E COLLIDE AT MY FRONT LEFT SIDE WHILE TURNING. NO INJURIES INCURRED. DRIVER ADMITTED HE'S AT FAULT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT3833E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	GOODS VEHICLE
Name of Driver	YIP PAK FOH
NRIC/Passport Number	S2049481F
Contact Number	122 FABER DRIVE
Address	129431
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Think One Autocare Pte Ltd
18 Defu Lane Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4888



B - GT3833E

4P81147

Driver admitted he's at fault.

I/We declare the foregoing particulars are true in every respect.



Driver's Signature
(If driver is not the policyholder)
Date & Time:

11/9/18 0916

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE IDENTITY CARD NO. S9246938G		REPUBLIC OF SINGAPORE DRIVING LICENCE	
	Name WONG KIAN HONG 黄建鸿		59246938G WONG KIAN HONG 28 Nov 2012 25 Jul 2017
	Race CHINESE Date of birth 28-11-1992 Country/Place of birth SINGAPORE	Sex M	002707220A 

5512158  NRIC No. S9246938G  Date of issue 27-07-2015 Address APT BLK 52 LORONG 6 TOA PAYOH #09-60 SINGAPORE 310052	YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES <table border="1"> <thead> <tr> <th>Class</th> <th>Description</th> <th>Effective Date</th> </tr> </thead> <tbody> <tr> <td>Class 3A</td> <td>Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg</td> <td>25 Jul 2017</td> </tr> </tbody> </table> NP 428A  Licence No: S9246938G	Class	Description	Effective Date	Class 3A	Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg	25 Jul 2017
Class	Description	Effective Date					
Class 3A	Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg	25 Jul 2017					

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

Not Attached
Chair
1/5/1100/c
3dy.
19/9/10
Tehpc. After rep

YP8114Y Mitsubishi Fuso

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,690.00 X
2	1	Front bumper left bracket	\$ 123.00 X
3	1	Front bumper reinforcement	\$ 367.00 X
4	1	Front left bumper lamp <i>pod cut</i>	\$ 185.00 /
5	1	Front grille assy	\$ 387.00 X
6	1	Front grille emblem	\$ 85.00 X
7	1	Front panel assy	\$ 1,023.00 X
8	1	Front panel Fuso embelm	\$ 180.00 X
9	1	Front left headlamp	\$ 786.00 X
10	1	Front left signal lamp	\$ 107.00 /
11	1	Front left side lamp	\$ 124.00 /
12	1	Front left corner panel	\$ 284.00 /
13	1	Front left step side garnish	\$ 280.00 X
14	1	Front dashboard panel assy	\$ 2,886.00 X
15	1	Front air con evaporator assy	\$ 2,634.00 X
16	1	Front air con blower motor	\$ 1,198.00 X
17	1	Front left door panel assy	\$ 2,652.00 X
18	1	Front left door inner board	\$ 412.00 X
19	1	Front left door lock mechanism	\$ 305.00 X
20	1	Front left door lock catch	\$ 77.00 X
21	1	Front left door outer weatherstrip	\$ 288.00 X
22	1	Front left door inner weatherstrip	\$ 288.00 X
23	1	Front left door glass moulding	\$ 285.00 X
24	1	Front left door outer handle	\$ 176.00 X
25	1	Front left door inner lower garnish	\$ 226.00 X
26	1	Front left door regulator with motor assy	\$ 578.00 X

Less 25%

\$ 17,626.00
\$ 4,406.50
\$ 13,219.50

200
252
525

Special Nett Items

1	6	Front grille clips	\$ 30.00 X
2	10	Front left door inner board clips	\$ 30.00 X
3	1	Front left door company sticker	\$ 50.00 /
4	1	Front left wheel rim	\$ 850.00 X
5	6	Front left door lower garnish clips	\$ 30.00 X
6	1	Front no plate	\$ 80.00 X
			\$ 1,070.00

Total parts

\$ 14,289.50

50

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

YP8114Y Mitsubishi Fuso

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 1,400.00	400 380
2	To putty and spray painting front left portion.	\$ 1,400.00	400
3	To check wiring and focus front headlamp.	\$ 50.00	20
4	To remove and install air con system including evaporator assy to facilitate the repair and refill gas.	\$ 1,350.00	X
5	To apply anti rust proofing to front left affected area.	\$ 1,120.00	X
6	To remove and install front dashboard assy to facilitate the repair.	\$ 1,350.00	X
7	To transfer front left door glass to new door.	\$ 1,80.00	X
8	To remove and install front left door lock mechanism.	\$ 1,80.00	X
9	To check door central locking for function.	\$ 1,80.00	X
10	To balance front left wheel.	\$ 1,50.00	X
11	To conduct wheel alignment.	\$ 1,100.00	X
12	Towing service.	\$ 1,120.00	X
		\$ 4,180.00	

820

Total parts : \$ 14,289.50

Total labour : \$ 4,180.00

Total repair cost : \$ 18,469.50

1385

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016942/URBN2

Date: 12/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN6019861812		
Claimant Vehicle No :	YP8114Y	Insured Vehicle No :	GT3833E		
Date of Loss:	10/09/2018	Nature of Claim:	TP	Claim No:	SNM18D04477C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP8114Y	Engine No:	4P10B92056
Make & Model:	MITSUBISHI CANTER, 3.0 D (M)	Chassis No:	FEB50543047
Reg. Date:	29/12/2017 (Man. Year: 2015)	Odometer:	12263 km
Colour:	Silver		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/75R16	Rear Tyre Size:	205/75R16 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,289.50	575.00	13,714.50	95.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	820.00	3,360.00	80.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,469.50	1,395.00	17,074.50	92.45
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	18,469.50	1,100.00	17,369.50	94.04
+ GST 7.00/7.00% (S\$)	1,292.87	77.00	1,215.87	94.04
Nett Amount (S\$)	19,762.37	1,177.00	18,585.37	94.04

INSPECTION

Date of Assignment:	17/09/2018		
Date Inspected:	19/09/2018	Inspected At:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Nov 2018)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP8114Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Repair	1,690.00 FL	*- FL
2	1		*FRONT BUMPER LEFT BRACKET	Not Necessary	123.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	367.00 FL	*- FL
4	1		*FRONT LEFT BUMPER PAD	Cut	185.00 FL	*185.00 FL
5	1		*FRONT GRILLE ASSY	Not Necessary	387.00 FL	*- FL
6	1		*FRONT GRILLE EMBLEM	Not Necessary	85.00 FL	*- FL
7	1		*FRONT PANEL ASSY	Not Necessary	1,023.00 FL	*- FL
8	1		*FRONT PANEL FUSO EMBLEM	Not Necessary	180.00 FL	*- FL
9	1		*FRONT LEFT HEADLAMP	Not Necessary	786.00 FL	*- FL
10	1		*FRONT LEFT SIGNAL LAMP	Broken	107.00 FL	*107.00 FL
11	1		*FRONT LEFT SIDE LAMP	Cracked	124.00 FL	*124.00 FL
12	1		*FRONT LEFT CORNER PANEL	Dented/Cut	284.00 FL	*284.00 FL
13	1		*FRONT LEFT STEP SIDE GARNISH	Not Necessary	280.00 FL	*- FL
14	1		*FRONT DASHBOARD PANEL ASSY	Not Necessary	2,886.00 FL	*- FL
15	1		*FRONT AIR CON EVAPORATOR ASSY	Not Necessary	2,634.00 FL	*- FL
16	1		*FRONT AIR CON BLOWER MOTOR	Not Necessary	1,198.00 FL	*- FL
17	1		*FRONT LEFT DOOR PANEL ASSY	Repair	2,652.00 FL	*- FL
18	1		*FRONT LEFT DOOR INNER BOARD	Not Necessary	412.00 FL	*- FL
19	1		*FRONT LEFT DOOR LOCK MECHANISM	Not Necessary	305.00 FL	*- FL
20	1		*FRONT LEFT DOOR LOCK CATCH	Not Necessary	77.00 FL	*- FL
21	1		*FRONT LEFT DOOR OUTER WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
22	1		*FRONT LEFT DOOR INNER WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
23	1		*FRONT LEFT DOOR GLASS MOULDING	Not Necessary	285.00 FL	*- FL
24	1		*FRONT LEFT DOOR OUTER HANDLE	Not Necessary	176.00 FL	*- FL
25	1		*FRONT LEFT DOOR INNER LOWER GARNISH	Not Necessary	226.00 FL	*- FL
26	1		*FRONT LEFT DOOR REGULATOR WITH MOTOR ASSY	Not Necessary	578.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	6		*FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*-FS
28	10		*FRONT LEFT DOOR INNER BOARD CLIPS	Not Necessary	30.00 FS	*-FS
29	1		*FRONT LEFT DOOR STICKER	Necessary	50.00 FS	*50.00 FS
30	1		*FRONT LEFT WHEEL RIM	Not Necessary	850.00 FS	*-FS
31	6		*FRONT LEFT DOOR LOWER GARNISH CLIPS	Not Necessary	30.00 FS	*-FS
32	1		*FRONT NO PLATE	Not Necessary	80.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,696.00	750.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,406.50	175.00
Total Parts (\$\$)	14,289.50	575.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS	New	1,400.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT LEFT PORTION	New	1,400.00	400.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
4	TO REMOVE AND INSTALL AIR CON SYSTEM INCLUDING EVAPORATOR ASSY TO FACILITATE THE REPAIR AND REFILL GAS	New	350.00	-
5	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	120.00	-
6	TO REMOVE AND INSTALL FRONT DASHBOARD ASSY TO FACILITATE THE REPAIR	New	350.00	-
7	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR	New	80.00	-
8	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM	New	80.00	-
9	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	-
10	TO BALANCE FRONT LEFT WHEEL	New	50.00	-
11	TO CONDUCT WHEEL ALIGNMENT	New	100.00	-
12	TOWING SERVICE	New	120.00	-
Gross Labour Cost (S\$)			4,180.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >