



GST / ROC Company No : 201101753C

Third Party Insurer : Aik AXA
 Insured's Veh No : SJX6844Y
 Date of accident : 12/09/2018
 Estimate To Repair : MAZDA 5
 Vehicle No : SLV1858K
 Chassis No : JM6CW1071H0126743
 Quotation No : AR/QO18/09-1001
 Quotation Date : 14/09/2018

Grab Rentals Pte Ltd
 18 Sin Ming Lane
 #01-08 Midview City
 Singapore 573960

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT BUMPER <i>deep cut</i>	\$1,055.40
2	1PC	FRT BUMPER RETAINER RH <i>set</i>	\$22.50
3	10PC	FRT BUMPER CLIPS <i>new</i>	\$85.00
4	1PC	FRT RH FENDER <i>new</i>	\$307.00
5	1PC	FRT RH SPORTS RIM <i>new</i>	\$110.90
6	1PC	RH HEADLAMP	\$1,411.40
LESS 20%			\$2,992.20
			\$598.44
			\$2,393.76
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		WHEEL ALIGNMENT	\$60.00
3		LABOUR CHARGE	\$300.00
4		SPRAY PAINTING	\$450.00
Total			\$840.00
Sub Total			\$3,233.76
GST (7.00%)			\$226.36
Total			\$3,460.12

Handwritten notes:
 ✓
 ✓
 ✓
 ✓
 ✓
 ✓
 20
 60
 280
 400

Handwritten notes:
 not added
 h/s
 327
 the price after repair
 18/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Please conduct the survey at
 Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
 GARY 8338 8418