

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1087/2018/GW
Date : 20-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: FT 5721 T

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Kwek Jing Ping
Address : Blk 1 F Cantoment Rd
Singapore 085601
Telephone : HP +65 98397652
Type of Claim : Third Party Claim
Policy No. : 5102221559
Vehicle No : **SLE 5399 Z**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Jul-16
Engine No : CZC 55614
Chassis No : WAUZZZ8V6G1098857
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Sep-18
Place of Accident : Maju Drive Opposite Maju Camp

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle SLE 5399 Z .**

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer lhs front and rear door's multi-lock system and power window devices. Check fuction and renew if necessary.	S/N \$ 560.00 ✓
2	To dismantle and renew lhs front and rear doors. To repair lhs rear fender. Re-organize lhs crash management components. Reinstall all parts removed. ✓ ✓	\$ 2,400.00 1200 1800
3	To respray lhs front and rear doors, door handle and lhs rear fender. ✓	\$ 2,700.00 1800 600 * 3 = 1800 Handle : 100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5399 Z.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-LH <i>Dented</i>	TBC	✓
2	FRONT DOOR OUTER DOOR SEAL-LH <i>re</i>	\$ 139.00	✓
3	BONDING AGENT	\$ 43.00	?
4	CLEANING SOLUTION	\$ 64.00	?
5	DOOR ATTACHMENT PARTS	\$ 206.00	?
6	FORNT DOOR SEAL INNER-LH <i>re in</i>	\$ 139.00	x
7	FRONT DOOR CATCH-LH <i>2 re in</i>	\$ 92.00	X
8	FORNT DOOR CATCH COVER-LH	\$ 13.00	x
9	FRONT DOOR EXTERIOR HANDLE-LH <i>Repair</i>	\$ 207.00	X
10	FRONT DOOR HANDLE HOUSING-LH <i>Repair</i>	\$ 26.00	x
11	FRONT DOOR MOUNTING BAR <i>re in</i>	\$ 143.00	x
12	REAR DOOR-LH <i>Dented</i>	\$ 2,190.00	✓
13	REAR DOOR OUTER DOOR SEAL-LH <i>re</i>	\$ 139.00	✓
14	BONDING AGENT	\$ 43.00	?
15	CLEANING SOLUTION	\$ 64.00	?
16	APPLICATOR	\$ 7.00	?
17	REAR DOOR SEAL INNER-LH <i>re in</i>	\$ 165.00	x
18	DOOR ATTACHMENT PARTS	\$ 110.00	?
19	REAR DOOR CATCH <i>3 re in</i>	\$ 82.00	x
20	REAR DOO CATCH COVER	\$ 14.00	x
21	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 4,186.00	
TOTAL LABOUR CHARGES		\$ 5,852.00	
GRAND TOTAL		\$ 10,038.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 21/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised

LKK Auto Consultants notify the Repairs of the following:

- To resurface/repair/repaint
- To display damaged parts during survey
- Parts are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal trading is allowed
- Supplementary items must be approved and is subject to approval from Insurance and Company

05 Sept
Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant