

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL: 6441 5655 FAX: 6441 5355/6243 8121
 R.O.C No: 200104141D GST Reg. No. 20-0104141-D

*Not Approved
 MKK
 2/3 \$3500/-
 20/9/18
 the photo attached*

TO : SXXX5326G
 SEOW SHEE KAH
 BLK 33 CHAI CHEE AVENUE
 #25-246
 SINGAPORE 461033
 TEL: 96286797 FAX: 96286797
 PH: 96286797
 ATTN :

ESTIMATE BILL

Number : EB00004950
Date : 17/09/2018
Case No : AD00009972
Vehicle No : SGL6852Y
Chassis: JN1BAAC11Z0001712
Year of Mfr 2006
Policy No 5055395942-05
Model : NISSAN LATIO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	END PANEL <i>body</i>	1.0	434.40	10	390.96
2	END PANEL TOP GARNISH <i>del/awl</i>	1.0	92.00	10	82.80
3	REAR BUMPER <i>DIS</i>	1.0	532.40	10	479.16
4	REAR BUMPER RETAINER RH <i>buf</i>	1.0	36.60	10	32.94
5	REAR BUMPER RETAINER LH <i>buf</i>	1.0	36.60	10	32.94
6	REAR BUMPER CLIP <i>per</i>	5.0	4.40	10	19.80
7	TAILAMP RH <i>11</i>	1.0	279.00	10	251.10
8	TAILAMP LH <i>04</i>	1.0	279.00	10	251.10
9	BOOTLID <i>body</i>	1.0	787.50	10	708.75
10	BOOTLID CHROME	1.0	270.60	10	243.54
11	BOOTLID EMBLEM <i>rec</i>	1.0	59.70	10	53.73
12	BOOTLID LOGO - LATIO <i>rec</i>	1.0	80.90	10	72.81
13	BOOTLID HINGE LH <i>buf</i>	1.0	58.40	10	52.56
14	BOOTLID HINGE RH <i>buf</i>	1.0	58.40	10	52.56
15	BOOTLID SENSOR LOCK <i>1m</i>	1.0	123.20	10	110.88
16	BOOTLID WEATHERSTRIP <i>1m</i>	1.0	80.30	10	72.27
17	BOOTLID SPONGE <i>11</i>	1.0	37.00	10	33.30
Nett Price - Parts Sub Total					2,941.20
18	SPARE TYRE PANEL - REPAIR <i>rec</i>	1.0		252.18	
19	REAR FENDER LH - REPAIR <i>rec</i>	1.0			
20	REAR FENDER RH - REPAIR <i>rec</i>	1.0			
21	REVERSE SENSOR <i>smub</i>	1.0	280.00	0	280.00
22	REAR NUMBER PLATE <i>buf</i>	1.0	30.00	0	30.00
23	REAR NUMBER PLATE HOLDER <i>buf</i>	1.0	30.00	0	30.00
Special Nett Price - Parts Sub Total					340.00
Parts Total					3,281.20
24	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
25	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
26	ANTI-RUST COATING	1.0	300.00	0	300.00
27	WIRING	1.0	80.00	0	80.00
28	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,330.00

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Acknowledged by Repairer

Page 1 of 2

* N = Item not subjected to GST

Signature:
Date:

Issued by : Anyisia

