

U2 SPRAY PAINTING PTE LTD

Block 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800
HP: 96583371

TP/AXA

vic

18th September 2018

TAN GEK SING

Bk 25 Kaki Bukit Rd 4

06-43 SYNERGY @KB

Singapore 417800

JN1BAAC1120000586

Accident date: 16TH SEPTEMBER 2018

Estimated repair cost for vehicle no: SGG8659C NISSAN LATIO 1.5LSR '06

S/n	Qty	Items	U/price	Amount
1	1	front fender -LH <i>Dented</i>		\$755.00 627.20
2	1	Front fender inner trim <i>new</i>		\$253.00 X
3	1	Front bumper <i>Dented</i>		\$536.00 ✓
4	2	Front Bumper Side Bracket <i>new LH</i>	\$58.10	\$116.20 34.20
5	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 30
6	1	Front bumper fog lamp cover <i>new</i>		\$120.10 X
7	1	Front bumper inner sponge <i>new</i>		\$207.20 X
			Subtotal :-	<u>\$2,037.50</u>

S/n	Qty	Items/Nett	U/price	Amount
1	1	Front headlamp -LH <i>new</i>		\$320.10 ✓
2	1	Front emble logo <i>new</i>		\$35.20 ✓
3	1	Front bumper towing cover <i>new</i>		\$49.20 X
4	1	front LH kunckle arm bearing		\$374.30 X
5	1	front LH lower arm		\$151.20 X
6	1	front LH stab bar <i>new</i>		\$467.60 X
7	1	front LH upper arm		\$91.10 X
8	1	front LH shock absorber		\$302.20 X
9	1	front LH kunckle arm		\$376.80 X
			Subtotal :-	<u>\$2,167.70</u>

355.30

319.77

S/n	Qty	Items/S.Nett	U/price	Amount
1	1	front Rim -LH <i>ut</i>		\$450.00 380
2	1	Front tyre -LH <i>NE NE</i>		\$350.00 X.
Subtotal :-				<u>\$800.00</u>

380

Labour charges

To remove & re-fix cushion	\$100.00 X
To remove & re-fix front undercarriage	\$250.00 X
To check wheel alignment computer	\$120.00 80
To Check Wiring System	\$80.00 30
Tuff Kote	810 \$120.00 X
Panel beating	\$600.00 300
Spray painting	\$600.00 400.
Subtotal :-	<u>\$1,870.00</u>

Total:- \$6,875.20

total: 2368.95
h/s : 1.9K ✓
04 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: