

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7663K - AXA**AAD1809-126***Not Authorised
C/Sys &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7663K

KL1LA69RJBB078285

CHEVROLET

EPICA 2.0

13.9.2018

AXA**PART****LIST**

1	1	Front Fender RH	\$	R	837.60	X
2	1	Front Fender Liner RH	\$	Sm	47.00	X
3	1	Front Fender Inner Wheel House Panel RH	\$	R	1,437.00	X
4	1	Front Fender LH	\$	R	837.60	✓
5	1	Front Fender Liner LH	\$	Sm	47.00	X
6	1	Front Fender Inner Wheel House Panel LH	\$	R	1,437.00	X
7	1	Front Bumper	\$	CM	1,202.00	✓
8	1	Front Bumper Lower Absorber	\$	CM	180.00	✓
9	1	Front Bumper Reinforcement	\$	R	356.00	✓
10	1	Front Bumper Retainer RH	\$	R	102.00	X
11	1	Front Bumper Retainer LH	\$	Dit	102.00	✓
12	1	Front Bumper Lower Grille	\$	Dit	78.00	✓
13	1	Front Bumper Lower Stiffener	\$	R	134.37	X
14	1	Front Bumper Bracket LH	\$	R	10.00	X
15	1	Front Bumper Bracket RH	\$	R	10.00	X
16	1	Bumper Fog Lamp Cover RH	\$	R	32.40	X
17	1	Bumper Fog Lamp Cover LH	\$	Dit	32.40	✓
18	1	Bonnet	\$	R	1,250.00	✓
19	1	Bonnet hinge RH	\$	R	36.00	X
20	1	Bonnet hinge LH	\$	R	36.00	X
21	1	Bonnet Moulding	\$	R	161.97	✓
22	1	Bonnet Lock	\$	R	60.00	X
23	1	Bonnet cable	\$	Sm	125.00	X
24	1	Front Support Panel Assy	\$	R	1,222.32	X
25	1	Headlamp RH	\$	mgm	816.00	✓
26	1	Headlamp LH	\$	wt / mgm	816.00	✓
27	1	Windscreen Washer Tank - Filler Neck	\$	And	4.80	X
28	1	Windscreen Washer Tank	\$	Sm	62.00	X
29	1	Windscreen Washer Tank Motor	\$	Sm	51.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-126

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7663K - AXA

30	1	Washer Tank Hose	\$	<i>Sm</i>	21.00	X
31	1	Radiator Assembly	\$	<i>Sm</i>	618.00	X
32	1	Radiator upper hose	\$	<i>Sm</i>	30.00	X
33	1	Radiator lower hose	\$	<i>Sm</i>	120.00	X
34	1	Radiator Grille (Grille A-Rad)	\$	<i>Sm</i>	367.00	✓
35	1	Radiator Grille Top Cover	\$	<i>Sm</i>	45.02	X
36	1	Fan Blade(A/C)	\$	<i>Sm</i>	536.00	X
37	1	Fan Blade(Radiator)	\$	<i>Sm</i>	634.00	X
38	1	Aircon Condenser	\$	<i>Sm</i>	600.00	✓
39	1	Aircon hose - condenser to compressor	\$	<i>Sm</i>	450.00	X
40	1	Aircon hose - compressor to evaporator	\$	<i>Sm</i>	624.00	X
41	1	Aircon hose - condenser to evaporator	\$	<i>Sm</i>	580.00	X

TOTAL	\$	11,505.28
10%	\$	1,150.53
	\$	10,354.75

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$	<i>Sm</i>	24.00	✓
2	2	Front Windscreen Sealant	\$	<i>Sm</i>	100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	<i>Sm</i>	100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	<i>Sm</i>	10.00	X
5	1 Set	Front licence plate with holder	\$	<i>Sm</i>	192.00	20.00
6	1 Set	Radiator Grille clip	\$	<i>Sm</i>	35.00	✓
7	1 Set	Front Fender Liner clip RH	\$	<i>Sm</i>	30.00	X
8	1 Set	Louver Cowl Top clip	\$	<i>Sm</i>	30.00	X
9	2	Bonnet stopper	\$	<i>Sm</i>	15.00	X

TOTAL	\$	536.00
--------------	-----------	---------------

TOTAL PARTS	\$	10,890.75
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	20.00
---	----	--------	-------

Trans-cab Auto Services Pte Ltd**AAD1809-126**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7663K - AXA

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 ⁵⁰⁰¹
Towing Fees.	\$	120.00 ⁵⁰¹
Putty and spray painting of the affected portion.	\$	4,500.00 ⁸⁰⁴
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00 ⁿⁿ X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 ⁴ X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 ⁴ X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 ⁴ X
To check steering geometry and computer wheel alignment	\$	220.00 ⁴ X
To transfer of tire, rim and on wheel balancing.	\$	170.00 ⁴ X
To replace, refix and top up coolant for radiator	\$	170.00 ⁴ X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00 ^{*1001}
To rust-proofing of the affected areas.	\$	170.00 ⁶⁰¹

TOTAL \$ 11,980.00**Over All Total \$ 22,870.75****Repair Days**~~15~~ Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: