

Surveyor:

DOI:

Date / Time:

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act: NO AT

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 1/9

S\$ 6,500.00

(Agreed / Assessed) BOLA S/N No.:

6 days

Reduction:

67 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

80

If NO or B 28, Ass. Lin:

Repair Cost: (w/60)

S\$ 6,900.00

COI WITH STOP LINE

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

420.00

x 7

(days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

61.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 7,406.00

Global Sum S\$:

-

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 7,406.00

Name 1:

ETHOZ GROUP LIMITED

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

REF: LPC

ASSIGNMENT

From: Date: 18/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 4766C

at Workshop n/s: Ethoz

of: Tampines

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

QPR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Ven No: SLJ 4766C Yr Regn: 1216

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make: neta 3 C.C. 1496

Colour: KROMA A/C: Insured / Std / NI / NA

Sp. Reading: 114565 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BM42A860342480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 15/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/7/51086 Lys. 2nd. Rep 7700
net 16914

19/9/18 confid L/S & 6500 with AM/CA;

CRAB: 413,000.24 (67%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Photos

Other

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

TOTAL



HIGHEST PRICE FOR YOUR CAR
OR GET \$100 CASH

Sell My Car With O

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

06/2017 Mazda 3 1.5A@572K 100% \$0 Down-payment



PHV DEAL!! No Hidden Cost! \$0
Down. Cash Less Than \$2500.
\$790 Monthly. Call Now
Privilege Group Pte Ltd



Browse by Category ▼

« Back (1 2 3) Next »

Sort by

43 vehicles

mazda 3

Advertiser

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Search Selection

mazda 3

Any

Any

2016

Any

**Mazda 3 1.5A Deluxe****\$73,800**

\$8,320 /yr

16-Sep-2016

1,496 cc

26

1 Owner, Confirm Non Grab/Uber/Leasing Car! Agent Serviced With Proof, Last On Jul 18. Genuine Low Mileage Done 26
Condition. Road Tax Till Mar 19. 100% Accident Free. Call Now!

Lake View Credit Pte Ltd

Posted: 18-Sep-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

**Mazda 3 1.5A****\$59,800**

\$7,450 /yr

18-Jan-2016

1,496 cc

43

Graded A by **STRA**

3 Years/100,000Km Warranty By Agent. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company
And Competitive Trade In Price! Call Now To Find Out More

Autolink Holdings Pte Ltd

Posted: 18-Sep-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

**Mazda 3 1.5A****\$66,800**

\$7,740 /yr

20-Jun-2016

1,496 cc

58

\$7k Drive Away. Only 7k Depre! Full Maintained And Warranty Of 3 Years By Eurokars. Sporty Grey Unit With Black Leather
And Handling, Comes With Upgraded Front Bumper Worth Of ...

Euro Performance Asia Pte Ltd

Posted: 17-Sep-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

**Mazda 3 1.5A****\$60,900**

\$7,420 /yr

17-Mar-2016

1,496 cc

Elegant White, With Sunroof, One Owner Only, Serviced By Agent, Low Maintenance Cost, Very Well Maintained, With W
Minimum Down Payment, Flexible In-House Loan Packages Availab...

Prime Motor & Leasing

Posted: 17-Sep-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

Compare

Car Selling

Car Ownership

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4531H
Vehicle Details	
Vehicle No.:	SLJ4766C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520367938
Chassis No.:	JM6BM42A8G0342480
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,600.00
Original Registration Date:	13 Dec 2016
First Registration Date:	13 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$11,600.00 5800
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2026
PARF Rebate Amount:	\$8,700.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$42,386.00
Total Rebate Amount:	\$51,086.00

The information contained herein is correct as at 19 Sep 2018

OK

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Ng Boon Kai
CLAIM DEPARTMENT
DID : 6654_7617
FAX :

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Items

1	BONNET <i>see</i>	1,185.60	<i>/</i>
1	BONNET HINGE RH <i>see</i>	62.70	<i>/</i>
1	BONNET HINGE LH <i>see</i>	62.70	<i>/</i>
1	BONNET WEATHER STRIP(OUTER) <i>see</i>	74.70	<i>/</i>
1	BONNET WEATHER STRIP(INNER) <i>see</i>	69.40	<i>/</i>
1	BONNET LOCK <i>17</i>	232.90	<i>x</i>
1	BONNET LOCK CABLE <i>17</i>	189.20	<i>x</i>
1	FRONT GRILLE TOP GARNISH <i>17</i>	123.60	<i>x</i>
1	FRONT GRILLE BASE <i>17</i>	141.20	<i>x</i>

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE LOGO 11	61.40	X
1	FRONT GRILLE CHROME MOULDING RH 11	208.30	X
1	FRONT GRILLE CHROME MOULDING LH 11	208.30	X
1	FRONT BUMPER 11, 3	1,089.50	/
1	FRONT BUMPER BRACKET RH 11	58.70	/
1	FRONT BUMPER BRACKET LH 11	58.70	X
1	FRONT BUMPER SIDE RETAINER RH 11	35.40	/
1	FRONT BUMPER SIDE RETAINER LH 11	35.40	/
1	FRONT BUMPER INNER GARNISH 11	185.90	X
1	FRONT BUMPER LOWER AIR GRILLE COVER RH 11	37.80	X

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER LOWER AIR GRILLE COVER LH 11	37.80	X
1	FRONT BUMPER TOWING COVER 11	42.70	X
1	FRONT BUMPER REINFORCMENT 34	664.70	/
10	FRONT BUMPER CLIPS 11	55.00	/
1	FOG LAMP COVER RH 11	68.70	/
1	FOG LAMP COVER LH 11	68.70	X
1	FRONT SIGNAL LAMP RH 11	223.90	/
1	FRONT SIGNAL LAMP LH 11	223.90	X
1	HEADLAMP RH 11	910.60	/
1	HEADLAMP L/H 11	910.60	X

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	HEADLAMP SIDE PANEL RH <i>24 3uc</i>	235.60	<i>✓</i>
1	FROTN CHASSIS RH <i>5uc 2</i>	RESTORE	<i>X</i>
1	FROTN SUPPORT PANEL <i>cm</i>	553.10	<i>2</i>
1	A/C CONDENSOR <i>11</i>	1,250.60	<i>X</i>
1	CONDENSOR SIDE GARNISH RH <i>11</i>	61.40	<i>X</i>
1	RADIATOR <i>11</i>	1,251.80	<i>X</i>
1	WIPER WASHER TANK <i>DIS</i>	146.70	<i>✓</i>
1	WIPER WASHER TANK NECK <i>2</i>	77.40	<i>✓</i>
1	WIPER WASHER MOTOR <i>Daye</i>	112.30	<i>✓</i>
1	ENGINE LOWER COVER <i>11</i>	338.90	<i>X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT FENDER RH <i>2uc</i>	394.20	/
1	FRONT FENDER L/H <i>R</i>	394.20	X
1	FROTN FENDER TOP GARNISH RH <i>11</i>	73.40	X
1	FRONT FENDER INNER SHIELD RH <i>To. n</i>	155.30	//
10	FRONT FENDER INNER SHILED CLIPS <i>ren</i>	55.00	X
1	FRONT WHEEL HOUSE PANEL RH <i>R</i>	703.60	X
1	FRONT WHEEL HOUSE EXTENSION PANEL RH <i>Bed</i>	252.90	X
1	FROTN DOOR RH <i>1</i>	RESTORE	X
1	A-PILLAR RH <i>R</i>	RESTORE	X
1	FRONT SHOCK ABSORBER RH <i>11</i>	404.70	X

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT ABSORBER TOP MOUNTING RH 11	122.70	X
1	FRONT KNUCKLE ARM RH 11	451.80	X
1	FRONT WHEEL HUB & BEARING RH 11	637.90	X
1	FRONT LOWER ARM RH 11	570.60	X
1	FRONT STABILIZER LINK RH 11	90.20	X
1	FRONT TIE ROD END RH 11	170.60	X
1	FRONT ABS SENSOR RH 11	176.50	X
1	FRONT DRIVE SHAFT RH 11	1,570.60	X
1	FRONT CROSS MEMBER 11	2,117.80	X
1	FRONT CROSS MEMBER BRACKET RH R	112.50	X

6781.8
5430.24

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	19810.30	
	Discount 20% On Parts	(3962.06)	
	<u>Special Nett Item</u>		
1	COOLANT <i>nu</i>	25.00	/
1	BRAKE FLUID (1 LITRE) <i>11</i>	55.00	X
1	FRONT TRYE RH <i>su</i>	250.00	X
1	FRONT SPORT RIM RH <i>cut</i>	350.00	/
	Sub Total	680.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	1,200.00	900

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	LABOUR TO SPRAY PAINT AFFECTED AREAS	1,400.00	1180
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	20
	TO RUST PROOF AFFECTED AREA	80.00	✓
	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS	120.00	100
	TO CONDUCT CHASSIS ALIGNMENT	17 250.00	x
	TO REMOVE & REFIT BOTHFRONT UNDERCARRIAGE INCLUDING FRONT CROSS MEMBER	17 350.00	x
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	80.00	60
			8715

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Monday, 17 September, 2018 4:23 PM
To: assignments
Subject: FW: Survey for vehicle No SLJ4766C TP CLAIMS

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

17092018 @ 4:44pm
Boon Kai vehin
manus.

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 17 September 2018 3:29 PM
To: Ng Boon Kai <BoonKai.Ng@ethozgroup.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Survey for vehicle No SLJ4766C TP CLAIMS

Our Ref : 18/18/18/VP05/020913

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/020913

Dear Boon Kai,

We shall be appointing LKK Auto Consultants Pte Ltd to survey the vehicle.

Aside to LKK – Attn:Catherine/Nivitha
Kindly proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ng Boon Kai [<mailto:BoonKai.Ng@ethozgroup.com>]
Sent: Monday, 17 September, 2018 3:22 PM
To: GERALD POH WEE BIN
Cc: Jimmy Goh
Subject: Survey for vehicle No SLJ4766C TP CLAIMS

Hi,

Appreciate if you could arrange survey for the above mentioned vehicle .

Your insured:SJF8923J

DOA: 15/09/2018

Thanks,

Best regards,

Boon Kai
Executive
Motor Claims Operation

ETHOZ

ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID: 6654 7617 | Fax: 6654 7648

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 28 September, 2018 8:47 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Vivian Lau (LKKAUTO)
Subject: RE: Survey for vehicle No SLJ4766C TP CLAIMS
Attachments: 28092018084510.pdf

Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 27 September, 2018 5:54 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO)
Subject: RE: Survey for vehicle No SLJ4766C TP CLAIMS

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/18/VP05/020913
LKK REF: CC4/LPC18016994/Uwa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SLJ 4766C

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ng Boon Kai [<mailto:BoonKai.Ng@ethozgroup.com>]

Sent: Monday, 17 September, 2018 3:22 PM

To: GERALD POH WEE BIN

Cc: Jimmy Goh

Subject: Survey for vehicle No SLJ4766C TP CLAIMS

Hi,

Appreciate if you could arrange survey for the above mentioned vehicle .

Your insured:SJF8923J

DOA: 15/09/2018

Thanks,

Best regards,

Boon Kai
Executive
Motor Claims Operation

ETHOZ

ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID: 6654 7617 | Fax: 6654 7648

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Final Settlement

Your Ref : 18/18/18/VP05/020913
Our Ref : OCR/15092018/TP-9964

Date : 13/06/2019

LONPAC INSURANCE BHD.
BLK 100 BEACH ROAD
-#19-00 SHAW TOWER
Singapore - 189702

Attn : MOTOR CLAIMS DEPARTMENT

**Subject : ACCIDENT INVOLVING VEHICLE NUM: SLJ-4766-C, SJF8923J ON
15/09/2018 AT TEMBELING ROAD X KOON SENG ROAD**


Dear Sir/Madam,

We refer to the above matter.

Enclosed herewith duly signed Discharge Voucher, Letter of Authorization & Final Invoice for your necessary action. Kindly forward your cheque amount of **S\$7,406.00** made payable to **ETHOZ Group Ltd** being full and final settlement.

Thank you.

Yours faithfully,


Yee Jing Yeu
CLAIM DEPARTMENT
DID : 6654 7562
FAX : 6654 7540
EMAIL : jingyeu.yee@ethozgroup.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18016994/Uha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 20-06-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJF 8923J	Veh. Inspected	SLJ 4766C
Policy No.	Z18VP05018892	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020913	Excess (\$)	0.00
Assign From	GERALD	Assign Date	17/09/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM42A8G0342480	Colour	BROWN
Odometer	114565	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	FALKEN	6 mm
L/H Front Tyre	205/60 R16	FALKEN	6 mm
R/H Rear Tyre	205/60 R16	FALKEN	6 mm
L/H Rear Tyre	205/60 R16	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/09/2018	Inspection Date	18/09/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4766C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	1,185.60	1,185.60
1	BONNET HINGE RH	BENT	62.70	62.70
1	BONNET HINGE LH	BENT	62.70	62.70
1	BONNET WEATHER STRIP (OUTER)	NECESSARY	74.70	74.70
1	BONNET WEATHER STRIP (INNER)	NECESSARY	69.40	69.40
1	BONNET LOCK	NOT NECESSARY	232.90	-
1	BONNET LOCK CABLE	NOT NECESSARY	189.20	-
1	FRONT GRILLE TOP GARNISH	NOT NECESSARY	123.60	-
1	FRONT GRILLE BASE	NOT NECESSARY	141.20	-
1	FRONT GRILLE LOGO	NOT NECESSARY	61.40	-
1	FRONT GRILLE CHROME MOULDING RH	NECESSARY	208.30	208.30
1	FRONT GRILLE CHROME MOULDING LH	NOT NECESSARY	208.30	-
1	FRONT BUMPER	DISTORTED	1,089.50	1,089.50
1	FRONT BUMPER BRACKET RH	BENT	58.70	58.70
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	58.70	-
1	FRONT BUMPER SIDE RETAINER RH	BENT	35.40	35.40
1	FRONT BUMPER SIDE RETAINER LH	BENT	35.40	35.40
1	FRONT BUMPER INNER GARNISH	NOT NECESSARY	185.90	-
1	FRONT BUMPER LOWER AIR GRILLE COVER RH	NOT NECESSARY	37.80	-
1	FRONT BUMPER LOWER AIR GRILLE COVER LH	NOT NECESSARY	37.80	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	42.70	-
1	FRONT BUMPER REINFORCEMENT	BENT	664.70	664.70
10	FRONT BUMPER CLIPS	NECESSARY	55.00	55.00
1	FOG LAMP COVER RH	CRACKED	68.70	68.70
1	FOG LAMP COVER LH	NOT NECESSARY	68.70	-
1	FRONT SIGNAL LAMP RH	CRACKED	223.90	223.90
1	FRONT SIGNAL LAMP LH	NOT NECESSARY	223.90	-
1	HEADLAMP RH	BROKEN	910.60	910.60
1	HEADLAMP L/H	NOT NECESSARY	910.60	-
1	HEADLAMP SIDE PANEL LH	BUCKLED	235.60	235.60

Report Ref No. CC4/LPC18016994/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT CHASSIS RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT SUPPORT PANEL	CRACKED	553.10	553.10
1	A/C CONDENSOR	NOT NECESSARY	1,250.60	-
1	CONDENSOR SIDE GARNISH RH	NOT NECESSARY	61.40	-
1	RADIATOR	NOT NECESSARY	1,251.80	-
1	WIPER WASHER TANK	DISTORTED	146.70	146.70
1	WIPER WASHER TANK NECK	DEFORMED	77.40	77.40
1	WIPER WASHER MOTOR	DAMAGED	112.30	112.30
1	ENGINE LOWER COVER	NOT NECESSARY	338.90	-
1	FRONT FENDER RH	BUCKLED	394.20	394.20
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	394.20	-
1	FRONT FENDER TOP GARNISH RH	NOT NECESSARY	73.40	-
1	FRONT FENDER INNER SHIELD RH	TORN	155.30	155.30
10	FRONT FENDER INNER SHIELD CLIPS	NECESSARY	55.00	55.00
1	FRONT WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	703.60	-
1	FRONT WHEEL HOUSE EXTENSION PANEL RH	BENT	252.90	252.90
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	A-PILLAR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	404.70	-
1	FRONT ABSORBER TOP MOUNTING RH	NOT NECESSARY	122.70	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	451.80	-
1	FRONT WHEEL HUB & BEARING RH	NOT NECESSARY	637.90	-
1	FRONT LOWER ARM RH	NOT NECESSARY	570.60	-
1	FRONT STABILIZER LINK RH	NOT NECESSARY	90.20	-
1	FRONT TIE ROD END RH	NOT NECESSARY	170.60	-
1	FRONT ABS SENSOR RH	NOT NECESSARY	176.50	-
1	FRONT DRIVE SHAFT RH	NOT NECESSARY	1,570.60	-
1	FRONT CROSS MEMBER	NOT NECESSARY	2,117.80	-
1	FRONT CROSS MEMBER BRACKET RH	TO REPAIR SEE LABOUR	112.50	-

Report Ref No. CC4/LPC18016994/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,962.06	-1,357.56
			15,848.24	5,430.24
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NECESSARY	25.00	25.00
1	LITRE BRAKE FLUID (SN)	NOT NECESSARY	55.00	-
1	FRONT TYRE RH (SN)	SERVICEABLE	250.00	-
1	FRONT SPORT RIM RH (SN)	CUT	350.00	350.00
			680.00	375.00
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR .INCLUSIVE OF THE REPAIR OF FRONT CHASSIS RH,FRONT FENDER L/H,FRONT WHEEL HOUSE PANEL RH,FRONT DOOR RH,A-PILLAR RH AND FRONT CROSS MEMBER BRACKET RH .		1,200.00	900.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS.		1,400.00	1,180.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	20.00
	TO RUST PROOF AFFECTED AREA .		80.00	80.00
	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS.		120.00	100.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT BOTH FRONT UNDERCARRIAGE INCLUDING FRONT CROSS MEMBER.	NOT NECESSARY	350.00	-
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT.		80.00	60.00
			3,510.00	2,340.00
	GRAND TOTAL		20,038.24	8,145.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CC4/LPC18016994/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.