

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Ng Boon Kai
CLAIM DEPARTMENT
DID : 6654_7617
FAX :

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000119 Accident Date : 15/09/2018

Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	BONNET <i>see</i>	1,185.60	<i>/</i>
1	BONNET HINGE RH <i>see</i>	62.70	<i>/</i>
1	BONNET HINGE LH <i>see</i>	62.70	<i>/</i>
1	BONNET WEATHER STRIP(OUTER) <i>see</i>	74.70	<i>/</i>
1	BONNET WEATHER STRIP(INNER) <i>see</i>	69.40	<i>/</i>
1	BONNET LOCK <i>17</i>	232.90	<i>/</i>
1	BONNET LOCK CABLE <i>17</i>	189.20	<i>/</i>
1	FRONT GRILLE TOP GARNISH <i>17</i>	123.60	<i>/</i>
1	FRONT GRILLE BASE <i>17</i>	141.20	<i>/</i>

Date : 17/09/2018
 To : LONPAC INSURANCE BHD.
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
 Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE LOGO 11	61.40	X
1	FRONT GRILLE CHROME MOULDING RH one	208.30	X
1	FRONT GRILLE CHROME MOULDING LH 11	208.30	X
1	FRONT BUMPER 11	1,089.50	X
1	FRONT BUMPER BRACKET RH 11	58.70	X
1	FRONT BUMPER BRACKET LH 11	58.70	X
1	FRONT BUMPER SIDE RETAINER RH 11	35.40	X
1	FRONT BUMPER SIDE RETAINER LH 11	35.40	X
1	FRONT BUMPER INNER GARNISH 11	185.90	X
1	FRONT BUMPER LOWER AIR GRILLE COVER RH 11	37.80	X

Date : 17/09/2018
 To : LONPAC INSURANCE BHD.
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
 Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER LOWER AIR GRILLE COVER LH 11	37.80	X
1	FRONT BUMPER TOWING COVER 11	42.70	X
1	FRONT BUMPER REINFORCMENT 34	664.70	/
10	FRONT BUMPER CLIPS nu	55.00	/
1	FOG LAMP COVER RH en	68.70	/
1	FOG LAMP COVER LH 11	68.70	X
1	FRONT SIGNAL LAMP RH en	223.90	/
1	FRONT SIGNAL LAMP LH 11	223.90	X
1	HEADLAMP RH 570	910.60	/
1	HEADLAMP L/H 11	910.60	X

Date : 17/09/2018
 To : LONPAC INSURANCE BHD.
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
 Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	HEADLAMP SIDE PANEL RH <i>24 3uc</i>	235.60	<i>✓</i>
1	FROTN CHASSIS RH <i>Asic 2</i>		<i>X</i>
1	FROTN SUPPORT PANEL <i>CM</i>	553.10	<i>✓</i>
1	A/C CONDENSOR <i>11</i>	1,250.60	<i>✓</i>
1	CONDENSOR SIDE GARNISH RH <i>11</i>	61.40	<i>X</i>
1	RADIATOR <i>11</i>	1,251.80	<i>X</i>
1	WIPER WASHER TANK <i>DIS</i>	146.70	<i>✓</i>
1	WIPER WASHER TANK NECK <i>DE</i>	77.40	<i>✓</i>
1	WIPER WASHER MOTOR <i>Denge</i>	112.30	<i>✓</i>
1	ENGINE LOWER COVER <i>11</i>	338.90	<i>X</i>

RESTORE

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT FENDER RH <i>3uc</i>	394.20	/
1	FRONT FENDER L/H <i>R</i>	394.20	X
1	FROTN FENDER TOP GARNISH RH <i>11</i>	73.40	X
1	FRONT FENDER INNER SHIELD RH <i>To, n</i>	155.30	//
10	FRONT FENDER INNER SHILED CLIPS <i>ren</i>	55.00	X
1	FRONT WHEEL HOUSE PANEL RH <i>R</i>	703.60	/
1	FRONT WHEEL HOUSE EXTENSION PANEL RH <i>Bed</i>	252.90	/
1	FROTN DOOR RH <i>2</i> RESTORE		X
1	A-PILLAR RH <i>R</i> RESTORE		X
1	FRONT SHOCK ABSORBER RH <i>11</i>	404.70	X

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT ABSORBER TOP MOUNTING RH 11	122.70	X
1	FRONT KNUCKLE ARM RH 11	451.80	X
1	FRONT WHEEL HUB & BEARING RH 11	637.90	X
1	FRONT LOWER ARM RH 11	570.60	X
1	FRONT STABILIZER LINK RH 11	90.20	X
1	FRONT TIE ROD END RH 11	170.60	X
1	FRONT ABS SENSOR RH 11	176.50	X
1	FRONT DRIVE SHAFT RH 11	1,570.60	X
1	FRONT CROSS MEMBER 11	2,117.80	X
1	FRONT CROSS MEMBER BRACKET RH R	112.50	X

6781.8
5430.24

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	19810.30	
	Discount 20% On Parts	(3962.06)	
	<u>Special Nett Item</u>		
1	COOLANT <i>ru</i>	25.00	/
1	BRAKE FLUID (1 LITRE) <i>11</i>	55.00	X
1	FRONT TRYE RH <i>su</i>	250.00	X
1	FRONT SPORT RIM RH <i>cul7</i>	350.00	/
	Sub Total	680.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	1,200.00	900

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	LABOUR TO SPRAY PAINT AFFECTED AREAS	1,400.00	1180
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	20
	TO RUST PROOF AFFECTED AREA	80.00	✓
	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS	120.00	100
17	TO CONDUCT CHASSIS ALIGNMENT	250.00	x
17	TO REMOVE & REFIT BOTHFRONT UNDERCARRIAGE INCLUDING FRONT CROSS MEMBER	350.00	x
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	80.00	60
			8715

Date : 17/09/2018
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000119 Accident Date : 15/09/2018
Vehicle No : SLJ-4766-C Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

2/5 @ 6500/-

3510.00

Link to the Repairer's home notify the Repairer following:

- To resurvey if the repairer supply painting
- To display a target part(s) during resurvey
- The prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

20,038.24

Remarks:

Not Authorised

SUB TOTAL

GST 7.0 % 1,402.68

TOTAL 21,440.92

Surveyor's name: Marcus Han

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 18/9/18

Take photo before painting.
6 days.